ROAD TEST

MODIFICATIONS					

PRELIMINARY CHECK

Car checked over, oiled etc., and in satisfactory condition for First Road Test.

Routined Engine Gear box PSP
Rear axle OK Lgs Glycol checked.

Sign. AJ AN.
Date 9. 1 64
As per Schedule No. 1

FIRST ROAD TEST

Car given First Road Test, and all matters requiring attention entered on Test Card.

Sign. K. Broadhead
Date 9-1-64.

SHOP WORK AFTER FIRST ROAD TEST

All matters requiring attention as per Test Card attended to.

Sign. K. Broadhead
Date 10-1-64
Routine adjustments carried out in accordance with Schedule No. 3

SECOND ROAD TEST

Car given Second Road Test. All matters requiring attention after First Road Test checked and satisfactory.

Sign. K. Broadhead
Date 10-1-64

SHOP WORK AFTER SECOND ROAD TEST

All matters requiring attention as per Test Card attended to.

Sign. K. Broadhead
Date 14-1-64

FINAL ROAD TEST

Car road tested, and up to standard in all respects mechanically.
All matters entered on Test Card satisfactory.

Sign. 6. D Dickinson
Date 15-1-64.

FLUID LEVELS

All fluid levels checked, and topped up if necessary.

Sign. G Hales
Date 15-1-64
in accordance with Schedule No. 1A.

ELECTRICAL CHECK Electrical check after panel lamp & Head lamps set

All electrical fittings & wiring up to standard.
All electrical items mentioned on Test Card attended to.

Sign. 7. L E Davies
Date 20/1/64

REFRIGERATION

All Refrigeration checked, and satisfactory after charging, to Schedule No.

Sign. 8.
Date

BODY CHECK

All body fittings checked.
All body creaks, rattles, etc., eliminated.

Sign. 9. J Bolchover
Date 17-1-64
NON ELECTRICALLY CHECKED

INSPECTION

Car inspected and complete to Specification. All modifications checked and recorded in Car History Book. All entries and spaces in Test Cards and above correctly signed for.

Sign. 10. J Whitworth
Date 18-1-64
All danger points checked in accordance with Inspection Instruction No. 5/1

NOTE: 6, 7, 8, 9 & 10. Personnel signing in these spaces are to sign also inside the Front Cover.

TEST CARD

Chassis No. LSF4223. Engine No. Quality Works O/N.

Date	MATTERS REQUIRING ATTENTION	Rectified		Fitter's/Tester's Signature
		Adj.	Changed	
	30-1-64			
	Edges Polishing + Overspray			
	Front boot catches - Left door fitter flange			
	Wood stain fall tables - finishers.			
R.H.2	O/S/F wing through			
"	front O/S area fettle	✓		
"	O/S/F centre pillar right through			✓
"	O/S/R door sill through			✓
"	for effect O/S/R steel arch			✓
"	in boot & matched O/S/R wing			✓
"	brackets on boot lid			✓
"	door effect fitted fettle fit			✓
"	N/S quarter panel through			✓
"	N/S/F door through			✓
	Ready to polish 7.55 31-1-64			

Date	MATTERS REQUIRING ATTENTION	Rectified		Fitter's/Tester's Signature
		Adj.	Changed	
	Aerial Test at Body Label			
	+ Water Lst bottom of Vent Glass & Frame	OK	—	DW
	+ Lens effect RS Refl.			DH
	OSF offmount fouling Radiator			
	OSF Door Hand & Elec			
	OSF Sill seal loose			EMC
	OS & post weath seal loose			EMC
10/	Front Door fouling at Pay			
	2d Rear Footbox			
31.1.64	Fd Boot Handle			
DH	Fd Boot Door Trim Pad			
	NSR Sill Rail Loose			EMC
	NSF Sill & NS B post Rech Loose			EMC
	Name plates			
	Roster Check			
	RF Arm Rest			

RR 372 C.

CHASSIS LSFO

TEST CARD

Chassis No. 223 Engine No. Works O/N.

Date	MATTERS REQUIRING ATTENTION	Rectified Adj.	Rectified Changed	Fitter's/Tester's Signature
9-1-64	Paint Etc			JS
K Bradshaw	Tighten road wheels.		✓	
9-1-64	Check tyre pressures.		✓	
30 miles.	Engine Improve T.O.		✓	
	Gearbox Flanges hanging on K.D for easy.		✓	
	Steering No pre load		✓	
	No spring on right lock		✓	
	PS pump mounts on locks? SEE OVERLEAF.			
	Seats re L.C noisy		✓	
	Valances fouling chassis.		✓	
	Carry out S. Led 3.		✓	
	Gearbox filled with oil.			JS.
	Brake sponge 2"		✓	
	Standing height 1-250.		✓	
	Ignition reset to 2° BTDC		✓	
	Fit new set at 2000		✓	

Date	MATTERS REQUIRING ATTENTION	Rectified		Fitter's/Tester's Signature
		Adj.	Changed	
10-1-64	Steering, Rattle in centre position			
K Brodshaw	Lot. Check gearload. Transfer gears adjusted ✓			
2 Jan Lo.	Something Sounding steering column when braking hard, or accelerating. Mon wheel pos. 2 air right. PS pump leaking, at front seal	✓	✓	
	Gearbox K D still too easy. Reposition selector lever.	✓	✓	
+12mth Lo				
13-1-64.	PS pump howls at high revs		✓	
	B Bon L cylinder drain tap leaking.		✓	
14-1-64	44 0/0 in. 18% dec.			
Dombo.	PSP gravel boarding: change ✓			
K Brodshaw.	Loads decal not detecting ✓			
	Engine knocking under load. Check ignition timing ✓			
+12mth Lo				
15/1/64	Change petrol in tank. Generally satisfactory with exception of temperature, Check thermostat for foreign matter ✓			
	Inspect for leaks. Check load meter	✓	✓	
	Hand to Otter			EK
	Body section.			

RR 372 C.

Date	MATTERS REQUIRING ATTENTION	Rectified		Fitter's/Tester's Signature
		Adj.	Changed	
	Body Test			
Bodytest 12/1/64	Crack from centre Quarter Panel	✓		DY
	* Set Door Set N/S/F w/frame to rear	✓		DY
11/1/64	Wind noise round N/S/F of channels			DY
	Refit Seal in - not central	✓		DY
	Wind noise o/s/f top corner of channel			DY
	Mark			
	Fit			
	Firestone WW 8.20 X 15 Tubeless Tyres LY 4122			
17/1/64	Check Wheelnuts & Greasenipples			AJS
	" End float front Hubs			
	" Tyre Pressures			
	Clean Steering Wheel & Shutters			
	* Check End float NSF excessive ✓		H STEELE G. SALISBURY.	
	Routine Check on			DS
	front & Rear Standing Lights -		accepted	
	Bonnet Hood contains both bottom			
	seals Clamping			
	Re position Sunday unit - screen seal to			DS
	unit 7th	18/1/64		

RR 372 C.

TEST CARD

Chassis No. LSFU223 Engine No. Works O/N.

Date	MATTERS REQUIRING ATTENTION	Rectified		Fitter's/Tester's Signature
		Adj.	Changed	
9/1/64	Choke suction lift 14¼"			

BODY (678) 1.5FV.

TEST CARD

Chassis No. 223. Engine No. Works O/N.

Date	MATTERS REQUIRING ATTENTION	Rectified Adj.	Rectified Changed	Fitter's/Tester's Signature
15-1-64	Tighten Bonnet Stay Screws. Secure n/s/r Bonnet.	✓		RH
	Set n/s/f Door, Frame close 'B' Post Top.	✓		RH
	Secure Lower n/s 'B' Post Trim Pad	✓		RH
	Clear n/s/r Frame to Cant Rail/Qtr. Panel Radius.	✓		RH
	Stick to corner Foot Lights Close Battery Edge, Vibe Gaiter	✓		RH
	Stick Pads o/s Glove Box	✓		RH
1( )64	WATER TESTS	✓		
R Bright 15 miles	Boot Door Very bad leak all along Rh seal	✓		RH
	N.S.F. Door Buzz from glass if wet	✓		RH
	O.S.F. Door Fill gap at waist with sealer	✓		RH
	Sticking panel still in front	✓		RH
	N.S.R. Door Rattle if banged	✓		RH
	Leaking from pillar when door closed	✓		RH
	Small loose object in door	✓		RH
	Check arm rest screws	✓		RH
	* FIT PANEL Break o/s rear comp. SQUEAK HANDLE BUTTON	✓		RH
	O.S.R. Door Rattle if banged	✓		RH
	Pad away from wing O.S.F	✓		RH
	Check seat belts	✓		RH
	Windscreen Rh front corner of frame N.S.F. door.	✓		RH
	Creak from Rh centre of fascia	✓		RH
(E)	Heater balance control cracked faulty	✓		SEE OVER
	O/S/F DOOR FAILS TRIM PANEL	✓		RH

Elec Circuit check after panel beat-

Date	MATTERS REQUIRING ATTENTION	Rectified Adj.	Rectified Changed	Fitter's/Tester's Signature
EHEG	Radio, balance control & switch faulty			
	rear speaker		✓	F Bowes
	Clock not working			
	Feed wire not connected to clock,	rectified		F Bowes
R.T.W.	Fuel warning light glass cracked	rectified		Works
	Aerial lead not in tray clip	rectified		F Bowes
	Speaker cable from radio to short			
	will not fit in clip.			
	Heater & Fog light set to right.	✓		F Bowes
20/11/64	Heat Temp control set			F Bowes

ENGINE GEARBOX T2159

TEST CARD

Chassis No. Engine No. S2214 Works O/N.

Date	MATTERS REQUIRING ATTENTION	Rectified Adj.	Rectified Changed	Fitter's/Tester's Signature
31.12.63	ENGINE OIL PRESSURES 18 lbs sq.in. at T.O.		✓	RBJones
RBJones	45 lbs sq.in. at 40 MPH			
	ENGINE INHIBITED AFTER TEST DTD.791.B.		✓	A.Sheath
	ENGINE FILLED WITH ENERGOL SAE.20.		✓	
	GEARBOX OIL PRESSURES 80 lbs sq.in, FORWARD		✓	
	170 lbs sq.in. REVERSE		✓	RBJones
	GEARBOX FILLED WITH MOBILOIL WA.389		✓	
	SPARKING PLUGS FITTED & GAPPED (TYPECHAMPN16Y)			A.Sheath
	CYLINDER HEAD FLOW CHECKED AT FOUR POINTS.		✓	
	TORUS PAN REMOVED & CHECK FOR OIL		✓	RBJones
	ENGINE, GEARBOX & UNITS FREE FROM LEAKS		✓	
	'A' 4 TAPPET COLLAPSED		✓	RBJones
	'B' BANK W/TAP LEAKING		✓	RBJones
	TIMING GEARS			
	OIL PUMP			
	VALVE GEAR			PASS
	GEARBOX			

ORDER REF. CA.7129

SERIAL No.

CHASSIS SPECIFICATION

Rota No.

Chassis Type [illegible] CLOUD III Engine No. 8U.111.P Chassis No. L.[illegible]

W/O 3010 Series PL.10053/P Body No. 7678

Battery Changed Body Style Silver Cloud III Saloon C/Builder Hooper & Co.

L.H. Rear Spring UR.3022 R.H. Rear Spring UR.3021

Steering Position Left Hand.

Lock No [illegible]/L. 510 Radio No. Model. P.T.I. H.11905

PAINTING DETAILS & LINES. Single Gold line.

BLACK PEARL. Valspar. 171/1093.

TRIMMING DETAILS.

Beige Hide. UR.3234 with Beige piping. UR.3234

Pure Woodcloth. 1023 AS. Cumberland Stone Carpet. 732

SPECIAL FEATURE.

FOR USA EXPORT.

To be built to the U.S.A. Specification issue 4 - plus.

L.H. Electric Windows.

Roof Aerial.

Firestone White sided tubeless tyres UR.4122

Plain Smoke glass throughout.

Indicator on boot door not required.

CUSTOMER Hooper & Co. (Coachbuilders) Ltd. SP 4.12.63.

SCV223

SFU223

☐ ☐ ☐ ☐ Set Tabulator Stops.

Modifications incorporated additional to Series Specification.

6104/RRL ✓ 5237/RNL ✓

[redacted] ✓

[redacted] ✓

6181/RRL ✓

6154/RRL ✓

5175/RRL ✓

6225/RRL ✓

5941/RRL ✓

6245/RRL ✓

[redacted] ✓

5175/RRL ✓

4258/RRL ✓

Rod Springs. Part/Mfr's & Serial Nos. LH 26799/1213 RH 27705/1123

Front Springs. Part/Mfrs & Numbers. LH 1105/6 RH 1105/6

Carburetter No. T.2159/3 Mods. 1-36

Axle. Nos. 7461 Ratio. 13/40 Gears. FG. 854

Master Cylinders. WO.151 - WO.264

Brakes [redacted] Rear. D.S.2

Engine Sequence No. B.2214

Cylinder Bores.

A1	A2	A3	A4
J	K	K	K

B1	B2	B3	B4
J	K	K	J

Crankshaft. Journals. Standard /—[illegible]

Pins. Standard /—[illegible]

Valve Guide Bores.

Exhaust. Standard +.005

Inlet. Standard +.005

COACHBUILT

[illegible]

WIRE

RR.5615.1

SFU223

CHASSIS ASSEMBLY - Operations to be signed for by the Fitter.

SFU223

CHASSIS ASSEMBLY - Operations to be signed for by the Fitter.

Fit Battery Cable	J.M.C	Identify Engine	A.E.D
Brackets & Tinning	G.S.	Fit & Set Brake Servo	
Fit Rear Springs	G.S.K.	Prop. Shaft—Front 75 lb. ft. Torque	G.S.
2 Bolts	J.P.	—Rear 45-50 lb. ft. Torque	
Axle U Bolts 60-65 lb. ft. Torque	J.P.S.	Set Ram for Alignment	G.S.
Rear Assembly	G.S.	Check Ram Clearance	
Stabiliser	W.K.	Fit Petrol Tank	W.H.
Torque tighten Yoke Pin Nuts 250 lb. ft. Torque	C		
		Fit Gear Control Linkages	G.S.
Fit Front Shock Dampers	W.L.K.		
Toe In LH .031 RH 092	L.H. S.A.	Fit Brake Hoses	
Caster LH .054 RH 051	L.H. S.A.	Bleed Brakes	L.H.
Camber LH .041 RH 048	L.H. S.A.	Set Brakes	L.H.
Ball Pin Height LH 9 7/8 RH 9 7/8	R.C.	Fit Exhaust System & Earth Straps	A.E. & D.
Front Susp. Friction LH 35 lbs RH 30 lbs	L.H. S.A.		
		Fit Wiring Looms	
Front Sub-assembly			
Front Springs & Washers	L.H.	Blow out Exhaust System	A.E. & D.
Front Stabilizer Bar	W.H.		
Freedom of Centre Steering Lever		Fit Radiator & check all studs	R.C.
Rear Shock Dampers	D.T.M.		
Locking & Sealing of Front Hubs	W.H. S.S.		
Fit Steering Column & Box	(2)		
Fit Petrol Pump & Pipes AC/3861		COACHBUILT	
Fit Master Cylinders	L.H.S.A.	Fit & Set Handbrake	
Grease all points	S.S.	Fit Wiring	
Fit Brake Equaliser	H		

SFV223

CHASSIS ASSEMBLY

MODIFICATIONS					
6104 RE2	~~6278 RE2~~	~~6288 RE2~~			
	6278	6288			

Rear Springs. Poundage & Serial No. LH 26799 - 1213 RH 27705 - 1123

Front Springs. Poundage & Washers. LH 1105 - 3+3 RH 1105 - 3+3

Gearbox No. 12159-3 Mods. 1036 Axle Serial No. 7461 Ratio 13/40 Gears FG 854

Master Cylinders VO 151 - SO 264 Brake Linings. Front DS 2

Engine Seq. No. S 2214 SU 111 1" Rear DS 2

Rear Dampers. LH S3-2092 RH S3-2093 Steering Box S3-2181

Front Dampers LH S3-3921(A) RH S3-3922(A) Brake Servo P 7180

Chassis Seq. No. 3X2137 Frame No. 1856. Petrol Pump A6/3861

Rad. Matrix Nos. P111 178 2029

SNAGS	Corrected by
Broken clip on Battery Cable. PHS	@
	@

SHORTAGES	Fitted by
Body Nuts Dynamo PB Pump	

INSPECTOR. Sign here and inside Front Cover after inspecting to current Inspection Instruction, and checking that all recordable modifications have been entered, and all snags and shortages cleared. I. A Walker

A.R. 461. C/G.

International Vehicle Appraisers Network

VEHICLE APPRAISAL

William G. Krieger
(847) 352-8280
Cell: 847/354-0071

1660 Von Braun
Elk Grove Village, IL 60007
Email: hipogt@aol.com

www.i-van.org/krieger.htm

On July 29, 2013, an authorized inspector of the International Vehicle Appraisers Network, Bill Krieger of Elk Grove Village in Illinois, personally inspected and evaluated the vehicle described below for the purpose of providing an estimation of the vehicle's cash value today. He inspected the vehicle's exterior, interior, chassis, and engine compartment. The evaluation is based upon authenticity, preservation/ restoration, maintenance and/or replacement costs.

Vehicle Year and Make: 1964 Rolls-Royce Silver Cloud III

VIN: LSFU223 Body Style: four-door Saloon

Color: Sand

Interior (color/material): Cream leather

Vehicle Inspected at: Owner's location

Owner: Steve Partman Phone: 847/985-5219

Address: 1698 Gibson Drive, Elk Grove Village, IL 60007

Special Features

Odometer reading:(81,544) Vehicle is powered by a 6.2 liter V-8 developing 208 h. p. through a four-speed automatic transmission. This luxury, low volume, virtually had-built vehicle comes standard with these conveniences: power steering, triple system power brakes, air conditioning, power antenna, powered gas cap release, power windows, three “picnic” tables, rear window defroster, electronically adjustable shock absorbers, burled walnut interior trim, AM radio, adjustable arm rests, front and back center arm rests, tool kit, plug-in dash flashlight (needs no batteries), “gator” covered rear leaf springs, and rear opera mirrors. Aftermarket (Rolls-Royce approved) options are: alternator, Pioneer AM/FM/C/D stereo audio system with speakers in hidden front door compartments.

Comments

Engine/Engine Compartment: Engine compartment is in very good condition and detailed per factory specifications. There is no sign of rust, collision damage or repairs. Engine is again detailed per factory specifications as are the wiring harnesses. All harnesses are undamaged and located in factory-correct looms. Exhaust manifolds display some minor rusting but are completely serviceable.

Chassis: Underside of vehicle displays better-than-average dirt and grime for a forty-nine year old vehicle. The frame and floor display no rust, collision damage or repairs. There is some oil leakage but the owner states that this is not only common but a necessary operation of the powertrain of a Rolls-Royce. At any rate the oil leakage is minimal. Exhaust is in very good condition. Tires are B. F. Goodrich bias-ply 8.20 X 15" in very good condition but sidewall does display some minor wall cracks probably due to age of tires. Wheels are Rolls-Royce stamped steel with full factory-equipped stainless steel wheel covers in good condition with minor dents.

Interior: Luxurious, overstuffed leather front bucket seats are in excellent condition with minor creasing seen. Doors are also in very good condition with no sun, water damage, or waviness. Driver's door has a small wear spot above the arm rest. Rear seats are in pristine condition with no wear visible at all as are rear quarter panels. Also the rear doors are in excellent condition. Back of front seat has fold-out walnut tables also in excellent condition. Matching cream colored carpeting is in very good condition having protective matching floor mats. Headliner is in excellent condition with no creases, rips, dirt, or any wear at all. Window surrounds and instrument panel trim is burled walnut in excellent condition. Padded instrument panel is in excellent condition displaying no waviness, sun damage or deterioration. Instruments have easy-to-read faces and are, also, in excellent condition.

Exterior: Exterior paint has a very high gloss and is in excellent condition displaying no drips, runs, or poor preparation areas and has been applied in an expert manner. Owner commented that vehicle has aluminum (custom) body panels and was originally painted black but there is absolutely no sign of the previous color. Trunk lid, hood, and all four doors line up in an expert manner with the rest of the body. There is absolutely no waviness in any of the body panels or any sign of collision damage. Bumper chrome is in very good condition as is all of the stainless steel trim. Glass is scratch and crack-free with no stone chips.

(Appraisal of 1964 Rolls-Royce Silver Cloud III continued)

Summary/Comments

This example of the highly rare (only 2,376 Silver Cloud III vehicles were built from late 1962 to 1966) and exceptionally luxurious 1964 Rolls-Royce Silver Cloud II is in excellent condition that needs only minor cleaning and detailing to return to brand-new condition. This is a driven vehicle that displays almost no wear visible and has been carefully maintained by expert Rolls-Royce mechanics. I would rate this vehicle to be in number one minus condition (out of six).

After careful evaluation of this vehicle, based on my expertise and experience (and after consulting Old Cars Price Guide, NADA, The Production Figure Book for U.S. Cars, the Internet, reviewing the *International Vehicle Appraisers Network* database, etc., and after consulting with other Professional Appraisers, museums, and automotive experts, etc., when necessary, I appraise (estimate) this vehicle as having a cash value of $115,000.

I hereby state that I have no financial interest, ownership, or employment in/with any firm engaged in the purchase, sale, insurance or transport of motorized vehicles or in any firm engaged in the repair or restoration of motorized vehicles. I further state that I have received no compensation for this appraisal, from any source, other than my fee. Therefore I have no actual or potential conflict of interest in providing this appraisal.

Signed William G. Krieger William G. Krieger

CREDENTIALS

1. Certified Appraiser in the International Vehicle Appraisers Network (nationwide association). Appraisals accepted by every insurance company as well as banks, credit unions, IRS, and Courts of Law (expert Witness), etc.
2. Senior Master Judge for the Antique Automobile Club of America (AACA) with over 100 National Judging Credits. Served as Team Captain at AACA National Meets.
3. National Meet Judge for the Mustang Club of America, the Buick Club of America, the Classic Thunderbird Club International.
4. Has appeared in court as an expert witness.
5. Officer and newsletter editor of a regional Mustang Club of America car club - the Northern Mustang Corral located in Bourbonnais, Illinois. Has won several Golden Quill awards from Old Cars Weekly for the monthly newsletter "From The Corral."
6. Guest Speaker on Appraisals before many clubs and organizations. Guest Speaker on Classic Cars.
7. Owner/restorer of two AACA National Award winning vehicles: 1957 Ford Sunliner Convertible, 1954 Buick Special.
8. Owner/restorer of a 1965 Ford Mustang HiPo GT fastback that has won a Senior Grand National award in the AACA and won many gold awards in the Mustang Club of America.
9. Owner of Senior Gold Buick Club of America medal winning vehicle: 1954 Buick Special.
10. Member of Chicagoland Corvette Club and owner of a 1965 Corvette roadster.

Owner's Name
Partman,Steven

Chassis Number
LSFU223

Mileage
71779

Team Captain's Comments:

		Max Deduct	
☑	**CAR IN MOTION (*Test Optional*)**		
	DRIVE TRAIN (*Noise Rattles Smoothness*)	**4**	
	BRAKES (*Effectiveness*)	**4**	
	ROAD PERFORMANCE (*Power Pick Up*)	**4**	
	AFTER RUN TEST (*Idle Overheating Leaks*)	**4**	
		Total	

Class & Senior Totals

Class Deductions	**400**	39
Class Score		361
Senior Deduction	**100**	
Senior Total		

Coachwork Totals

Coachwork Deductions	**140**	22
Coachwork Total		118
Class Score		361
Total		479

SILVER CLOUD CI 1313

BODY PAINT AND BRIGHT WORK

Owner's Name
Partman,Steven

Chassis Number
LSFU223

BODY	Max Deduct		✓
Dings & Dents: Hood	1	1	✓
Door Alignment: Poor	1	1	✓
Door Gaps Large or tight	1	1	✓
Doors Hard to close	1		✓
EXTERIOR PAINT			
Paint Condition:	1		✓
Orange peel - poor finish	1		✓
Chip	1		✓
Scratch	1		✓
Worn paint	1		✓
Colour mismatch	1		✓
Stress cracks at leaded seams	1	1	✓
Striping Coachline:			
Poor or missing areas	1	1	✓
Colour mismatch	1		✓
Incorrect pattern or number	1		✓
Missing of trim rings	1		✓
EVERFLEX\CONVERTIBLE TOP			
Poor Appearance	1		✓
Tear	1		✓
Non authentic material	1		✓
Non functioning	1		✓
Tonneau cover missing	1		✓
Rear Window scratched or opaque	1		✓
GLASS			
Windscreen cracked	1		✓
Stone chips	1	1	✓
Pitted	1	1	✓
Separation in corners	1		✓
Door Windows scratched	1		✓
	TOTAL	7	

BRIGHTWORK	Max Deduct		✓
Door Handles: Worn	1	1	✓
Non Functioning	1		✓
Door locks: Worn	1	1	✓
Snow covers missing	1		✓
Non working key	1		✓
Window Frames: Worn	1	1	✓
Scratched	1	1	✓
Poor Appearance	1		✓
Out of alignment	1		✓
Bumper: Worn or dented	1		✓
Scratched	1		✓
Misaligned check ends	1		✓
Overrides: Scratched or dented	1	1	✓
Rubber gasket split or missing	1		✓
Trim Mouldings: Dented	1	1	✓
Bent or Scratched	1	1	✓
Poorly Fitted or Anchored	1		✓
Grill: Poor Appearance /Dirty	1		✓
Scratched	1	1	✓
Pitted	1		✓
Dented	1		✓
Poorly Fitted to Body	1		✓
Incorrect Hardware	1		✓
Poor Mascot	1		✓
Snow Packs: Poor condition	1		✓
Hub Caps: Scratched or bent	1	1	✓
Mismatched	1		✓
Poor appearance	1		✓
Mirrors Exterior: Poor or pitted finish	1		✓
Silver poor or stained	1		✓
	TOTAL	9	

SILVER CLOUD CLASSIC 1133

INTERIOR

Owner's Name
Partman,Steven

Chassis Number
LSFU223

INSTRUMENTS & ACCESSORIES	Max Deduct		✓
Ignition Light:			
Check without the engine running			
Non functioning Ignition light	1		
Oil level indicator: Non functioning	1		
Turn signal	2		
Hi beam warning light	1		
Instrument light	1		
Map lights	1		
Cigar Lighter	1		
Non working Oil press or Temp gauge	1		
Non working Radio	1		
Poorly fitted non standard equipment	1		
Non functioning Clock	1		
Interior Door Handle:			
poor or sticky operation	1		
locking device non functioning	1		
Electric Windows:			
Slow or noisy operation	1		
Non functioning	2		
Heater Switches:			
Non functioning	1		
Interior Light:			
Door switches non functioning	1		
Toggle switch non functioning	1		
Mirror box light non functioning	2		
Cubby Boxes: Dirty	1		
Incorrect material	1		
Ash Trays: Dirty	1		
Missing clips or poor operation	1		
Brake Pedal Rubbers: Worn	1		
Emergency Brake:			
Excessive travel or poor operation	1		
Dip Switch Rubber cover: Missing	1		
	TOTAL		

INTERIOR	Max Deduct		✓
Headliner: Dirty or Stained	1		
Sagging or Torn	1		
Parcel Shelf: Stained or Dirty	1		
Non authentic Material	1		
Seats: Hard or stained	1		
Dirt in pleats	1		
Cracked or Torn	1		
Faded	2		
Non authentic Material	1		
Door panels: Dirty or stained	2		
Scratched or shrunk	1		
Loose or missing clips	1		
Arm rests dirty or worn	1		
Door Seals: Poor or flat	1		
Cut or Missing	1		
Non authentic	1		
Brightwork: Scratched or worn	1		
Lock cover Plates loose	1		
Lock cover Plates missing	1		
Treadplate scratched or worn	1		
Treadplate Rubbers cut or scraped	1		
Carpets: Dirty	1		
Holes or Shrunk	1		
Poor Binding	1		
Non authentic materials	1		
Poor Fit New Carpets	1		
Steering Wheel: Cracked or damaged	1		
Foot Pad: Worn or Holes	1		
Non authentic Materials	1		
Interior Wood: Cracked or Chipped	2		
Water Damage to Veneer	1		
Poor Condition	1		
Mirror Boxes: Poor silver	1		
	TOTAL		

Rear screen

SILVER CLOUD CLASS 113

ENGINE COMPARTMENT

Owner's Name
Partman,Steven

Chassis Number
LSFU223

STEERING PUMP	Max Deduct		✓
Power Steering Pump: Noisy	2		✓
Leaks or low fluid	1		✓
Incorrect hose on return line	1		✓
Incorrect high pressure hose	1		✓
Missing filter inside reservoir	1		✓
Incorrect hose clamps return line	1		✓
Poor or incorrect finish	2		✓
	TOTAL		

AIR CONDITIONING	Max Deduct		
Compressor: Incorrect or Noisy 1/2 - 1	1		✓
Hoses: Poor condition 1/2-1	2		✓
Leaks Oil showing at couplings 1/2	1		✓
Non-authentic 1/2-1	2		✓
High pressure pipes:			
Bent or kinked 1/2-1	2		✓
Missing anchor clips 1/2 each	2		✓
Damaged or rounded unions 1/2 each	2		✓
Actuators: Missing 1	2		✓
Non function 1/2 each	1		✓
Rubber cap missing 1/2 each	1		✓
Return springs missing 1/2 each	1		✓
Summer bleed pipe missing 1/2-1	1		✓
Manual heater taps: Missing 1-2	1		✓
Leaking 1/2-1	1		✓
Non authentic:			
Equipment 1-2	2		✓
Finish 1	1		✓
	TOTAL		

FUEL SYSTEM	Max Deduct		✓
Carburetors: Leaks	2		✓
Choke Solinod: Poor wiring	1		✓
Cover: Missing or poor condition	1		✓
Flex Lines: Leaks	2		✓
Non authentic	2	2	✓
Air intake Hose: Split	2		✓
Non authentic	1		✓
Missing or non authentic clips	1		✓
Air Cleaner: Dirty	1		✓
Mounting incorrect or missing	1		✓
Non authentic finish	1		✓
	TOTAL	2	

ENGINE COMPARTMENT	Max Deduct		
Engine: Dirty	2		✓
Rocker covers oil leaks	2		✓
Poor cork seal inside oil filler cap	1		✓
Low oil level on dip stick	1		✓
Ground straps missing or disconnected	1		✓
Rubber grommet missing or deteriorated	1		✓
Non authentic finish	1		✓
Non authentic equipment or holes	1		✓
FUSE BOXES			
Cover cracked or broken	1		✓
Incorrect fuses	2		✓
Poor condition	1		✓
Dirty	1		✓
Incorrect wire	1		✓
Missing spare fuse wire	1		✓
	TOTAL		

SILVER CLOUD CLASS 113

CHASSIS AND UNDERSIDE

SILVER CLOUD MKIII

STEERING AND SUSPENSION	Max Deduct		✓
Suspension Joints: Missing seals	2		✓
Rust showing	2		✓
Lock Tabs missing	2		✓
Tie rod ends: Torn or missing boots	2		✓
Split pins missing	2		✓
Lock tabs missing at yokes	2		✓
Steering Box: Leaks	2	1	✓
Mounts: Swelled or perished	2		✓
Hoses: Leaking or poorly routed	2		✓
P/S ram leaking	1		✓
Non authentic: Finish	1		✓
Equipment	2		✓
Rebound rubbers missing or split	2		✓
Grease nipples missing or incorrect	2		✓
Sway bar links rubbers perished	1		✓
Incorrect bolts or spacers	1		✓
Road Springs coil bound	2		✓
	TOTAL	1	

BODY AND CHASSIS	Max Deduct		
Poor or rusted body mounts	2		✓
Poor or rusted rocker panels	2		✓
Missing drains trunk floor	1		✓
Damaged or missing jacking brackets	1		✓
Rusted or poor chassis legs	1		✓
Poor or missing undersheets	1		✓
Dirty chassis	1		✓
	TOTAL		

EXHAUST SYSTEM	Max Deduct		
Poor condition	1	1	✓
Missing ground straps	2		✓
Bent, torn or missing hangers	2		✓
Hitting chassis or floor	2		✓
Missing heat shield	1		✓
Leaks	2		✓
Non authentic: Equipment	2		✓
	TOTAL	1	

Chassis Number
LSFU223

Owner's Name
Partman,Steven

BRAKES	Max Deduct		✓
Rusted brake lines	2		✓
Damaged bleed nipples	2		✓
Leaking master cylinder	2		✓
Poor or perished brake hoses	4		✓
Compensator rubbers worn or perished	2		✓
Rubber boots torn or missing	1		✓
Return springs poor or missing	2		✓
Non authentic equipment and or finish	1		✓
	TOTAL		

FUEL SYSTEM	Max Deduct		
Fuel pump: Leak	2		✓
Poor or damaged fittings	2		✓
Fuel line: Leak	2		✓
Non authentic	2		✓
Non authentic finish	2		✓
Fuel flex hose: Leaks	2		✓
Gas Tank: Poor or leaking	2		✓
Non authentic	1		✓
Fuel filter: Leak	2		✓
Damaged	2		✓
Non authentic	2		✓
	TOTAL		

POWER TRAIN	Max Deduct		
Engine oil leaks	2		✓
Transmission fluid leaks	2		✓
Propshaft hanger springs poor or missing	2		✓
Gaiters: Poor or missing	2		✓
Differential leaks	2		✓
Shock absorbers leaking	2		✓
Non authentic or poor finish	2		✓
	TOTAL		

SILVER CLOUD CLASS 113

TYRES TRUNK AND STANDING HEIGHT

Owner's Name
Partman,Steven

Chassis Number
LSFU223

TRUNK TOOLS AND LIGHTS	Max Deduct		✓
Lights non working units:			
Side lights	1		✓
Headlamp low and high beam	1		✓
Tail lamp	1		✓
Brake lamp	1		✓
Reverse, licence plate	1	1	✓
Indicators	1		✓
Cracked or broken lens	1		✓
Tools: Missing from kit	1		✓
Large Tools: Jack, wheel wrench	1		✓
Bulbs: Missing from kit	1	1	✓
Battery: Wrong size	1		✓
No hold down	1		✓
Incorrect hold down	1		✓
Terminals corroded	1		✓
Incorrect terminal and wiring	1		✓
Missing Fly Nut	1		✓
Dirty	1		✓
Battery Cover:			
Missing Cracked	1		✓
Poor condition	1		✓
Poor condition or missing screws	1		✓
Check gas tank door Emergency Pull:			
Missing ring	1		✓
Non working	1		✓
Boot light: Non working	1		✓
Light Lens/ defuser Missing	1		✓
	TOTAL		2

TRUNK INTERIOR	Max Deduct		✓
Boot Lid Seal: Split or perished	1		✓
Seal missing	1		✓
Poor appearance	1		✓
Incorrect carpet	1		✓
Holes or worn spots	1	1	✓
Missing carpet clips	1		✓
Water stains	1	1	✓
Screws missing from side panels	1		✓
Incorrect screws	1		✓
Trunk lid out of adjustment Hard to close	1		✓
Trunk lid out of adjustment lid rattles	1		✓
Wire clips missing from R/S hinge	1	1	✓
Grommets missing from trunk lid	1	1	✓
Sagging or torn material on lid	1		✓
TYRES			
Wrong size or type mismatched	1		✓
Missing valve caps	1		✓
Poor or worn	1		✓
Spare tyre wrong position valve to match	1		✓
STANDING HEIGHT			
Rear suspension low 1/2 -1	1		✓
Front suspension low 1/2-1	1		✓
	TOTAL	4	✓

Original Tyres Sizes
Silver Cloud and S Type 8.20x15
Continental S Type 7.60x15
Replacement 225.75 R15
Check for Owners Manual deduct as missing tool
SC III and S 3 235-75 R15

SERIAL # LSFU223
1964 - RR Silver Cloud III

Handbook

for

The
Rolls-Royce Silver Cloud III



AZ COLLECTOR CARS

2725 N. Ogden Rd.
Mesa, AZ 85215
(480) 985-2675

CUSTOMER NO.	ADVISOR	TAG NO.	INVOICE DATE	INVOICE NO.
72925	ADAM 1115	U223	03/28/25	LICB257655

LABOR RATE	LICENSE NO.	MILEAGE	COLOR	STOCK NO.
		1	/	

YEAR / MAKE / MODEL	DELIVERY DATE	DELIVERY MILES
64/ROLLS-ROYCE/SILVER CLOUD III		

VEHICLE I.D. NO.	SELLING DEALER NO.	PRODUCTION DATE
L S F U 2 2 3		

F.T.E. NO.	P.O. NO.	R.O. DATE
		03/12/25

[redacted]

RESIDENCE PHONE	BUSINESS PHONE	COMMENTS
[redacted]		MO: 1

JOB# 1 CHARGES----------

LABOR----------

J# 1 50FOZ ENGINE ELECTRICAL TECH(S):1132 450.00

CLIENT INDICATES NO START - SUGGESTED POSSIBLE COIL FAILURE
DISCONNECT BATTERY, UNBOLT AND REMOVE IGNITION COIL FROM VEHICLE.
FIT NEW COIL IN POSITION, SECURE WITH HARDWARE. ATTACH SWITCHED POWER AND CONTACT BREAKER, FIT COIL WIRE TO DISTRIBUTOR.
RE-CONNECT BATTERY, TEST FIRE ENGINE, NO START ABILITY.
VERIFY 12V POWER SIGNAL AT COIL. ATTACH TEST LIGHT TO NEGATIVE SIDE OF COIL, TEST FIRE ENGINE. CONFIRM OPERATION OF POINTS.
CHECK FUSES, NO EXPIRED FUSES DISCOVERED.
REMOVE DISTRIBUTOR CAP, INSPECT CAP CONTACTS, ROTOR ARM AND POINTS SETS. POLISH ALL CAP TERMINALS AND ROTOR EDGE.
POLISH POINTS CONTACTS, CHECK GAP, SET TO FACTORY STANDARDS.
RE-FIT DISTRIBUTOR CAP, TEST FIRE ENGINE. ENGINE ROTATES MULTIPLE TIMES, BUT STARTS AND RUNS.
ATTACH SPARK TESTER, RAN ENGINE TO OBSERVE SPARK. SPARK SIGNAL APPEARS WEAK, MAY CONTRIBUTE TO HARD START ISSUES.
LIFT VEHICLE, REMOVE FUEL FILTER COVER, INSPECT CONTENTS OF FILTER FOR CONTAMINATION, NO VISUAL EVIDENCE OF DEBRIS IN FUEL.
OBSERVED ROCKER ARM NOISE DURING RUN TIME. CHECKED OIL LEVEL, TOPPED OFF AS NEEDED. CONSULTED WITH CLIENT REGARDING FINDINGS.
RECOMMENDED IGNITION SYSTEM RESTORATION - CLIENT APPROVES.
ORDER PARTS FOR DELIVERY.
CONDUCT VOLTAGE DROP TEST, ADDED ADDITIONAL GROUND WIRE TO PROVIDE ADEQUATE GROUND SOURCE.

PARTS	QTY	FP-NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	
	1	34-EXTJ	BATTERY	210.00	210.00	210.00
				TOTAL - PARTS		210.00

JOB# 1 TOTALS----------

LABOR	450.00
PARTS	210.00
JOB# 1 JOURNAL PREFIX LICB JOB# 1 TOTAL	660.00

JOB# 2 CHARGES----------

LABOR----------

J# 2+50FOZ11 IGNITION SYSTEM TECH(S):1132 450.00

Added Operation (4ADAMB @ 03/12/2025 09:41)
RESTORE IGNITION SYSTEM (POINTS SETS, CONDENSER, SPARK PLUGS, PLUG WIRES, DISTRIBUTOR CAP AND ROTOR ARM)
REMOVE SPARK PLUGS, DISCARD.
GAP NEW PLUGS TO SPEC, INSTALL INTO CYLINDER HEAD WITH ANTI-SEIZE.

REMOVE DISTRIBUTOR CAP, UNSCREW POINTS SETS AND CONDENSER FROM DISTRIBUTOR BODY,

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVES.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

CUSTOMER SIGNATURE

CUSTOMER COPY

[CONTINUED ON NEXT PAGE]

11:55am

The Reynolds and Reynolds Company ERAINTINVE
SF710150 Q (07/20)

AZ COLLECTOR CARS
2725 N. Ogden Rd.
Mesa, AZ 85215
(480) 985-2675

CUSTOMER NO.	ADVISOR	TAG NO.	INVOICE DATE	INVOICE NO.
72925	ADAM 1115	U223	03/28/25	LICB257655

LABOR RATE	LICENSE NO.	MILEAGE	COLOR	STOCK NO.
		1	/	

YEAR / MAKE / MODEL	DELIVERY DATE	DELIVERY MILES
64/ROLLS-ROYCE/SILVER CLOUD III		

VEHICLE I.D. NO.	SELLING DEALER NO.	PRODUCTION DATE
L S F U 2 2 3		

F.T.E. NO.	P.O. NO.	R.O. DATE	
		03/12/25	

[redacted]COM

RESIDENCE PHONE [redacted] BUSINESS PHONE

COMMENTS MO: 1

SET CYLINDER 1 TO TOP DEAD CENTER, INSTALL POINTS SETS TO BASE PLATE. SET POINTS GAPS TO FACTORY SPEC, INSTALL NEW CONDENSER.
ATTACH CONDENSER WIRE AND RETAINING NUT.
FIT ROTOR ARM, INSTALL NEW DISTRIBUTOR CAP.
IDENTIFIED SPARK PLUG WIRES TO BE MODIFIED TO FIT. NEW WIRES ARE EN ROUTE FROM PREFERRED SUPPLIER.

CYCLE ON KEY, CHECK FUNCTION OF CHOKE MECHANISM.
REMOVE FLOAT BOWL COVERS, VERIFY PROPER FUEL VOLUME IN FLOAT BOWLS, RE-FIT FLOAT BOWL COVERS.
ATTACH FUEL PRESSURE GAUGE TO FUEL INLET HOSE, VERIFY FUEL PRESSURE WITHIN FACTORY SPEC.

FUEL LINE AT PUMP CRACKED WHEN TOUCHED. REPLACED SECTION OF FUEL HOSE WITH NEW, SECURED WITH HOSE CLAMPS.

ATTACH DISTRIBUTOR LEADS, START, RUN ENGINE.
ENGINE FIRES IMMEDIATELY, NO PRESENCE OF MISFIRE AT THIS TIME.

AWAITING NEW DISTRIBUTOR LEADS TO COMPLETE IGNITION RESTORATION.

PARTS	QTY	FP	NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	
	8		N5YC	SPARK PLUG	5.58	5.58	44.64
	1		CD-3046P	ROTOR ARM	60.25	60.25	60.25
	1		CD-30440EM	DISTRIBUTOR	152.40	152.40	152.40
	1		CD-3049P	CONDENSER	49.43	49.43	49.43
	2		CD-3047P	POINTS SET	35.35	35.35	70.70
	1		ILS-S3-OEM	IGNITION LEA	363.28	363.28	363.28
	1		SHIPPING	SHIPPING	37.35	37.35	37.35
	1		3/8-X-12	FUEL HOSE	12.99	12.99	12.99
	1		4GA-BL	BATTERY CABL	12.50	12.50	12.50
						TOTAL - PARTS	803.54

JOB# 2 TOTALS

LABOR	450.00
PARTS	803.54
JOB# 2 JOURNAL PREFIX LICB JOB# 2 TOTAL	1253.54

MISC	CODE	DESCRIPTION	CONTROL NO	
JOB # A	SSAZ	SHOP SUPPLIES AZCC		75.00
			TOTAL - MISC	75.00

ESTIMATE

CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
ORIGINAL ESTIMATE OF $0.00 (+TAX)
APPROVED ADDITIONAL COST OF $2078.89 FOR TOTAL ESTIMATE OF $2078.89 (+TAX) ON 03/28/25 AT 11:55a
BY 1115 COMMENTS

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVES.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

CUSTOMER SIGNATURE

The Reynolds and Reynolds Company ERAINTINVE
SF710150 Q (07/20)

AZ COLLECTOR CARS

2725 N. Ogden Rd.
Mesa, AZ 85215
(480) 985-2675

CUSTOMER NO.	ADVISOR	TAG NO.	INVOICE DATE	INVOICE NO.
72925	ADAM 1115	U223	03/28/25	LICB257655

LABOR RATE	LICENSE NO.	MILEAGE	COLOR	STOCK NO.
		1	/	

YEAR / MAKE / MODEL	DELIVERY DATE	DELIVERY MILES
64/ROLLS-ROYCE/SILVER CLOUD III		

VEHICLE I.D. NO.	SELLING DEALER NO.	PRODUCTION DATE
L S F U 2 2 3		

F.T.E. NO.	P.O. NO.	R.O. DATE	
		03/12/25	

[redacted]

[redacted]

[redacted]

[redacted]

BUSINESS PHONE

COMMENTS

MO: 1

TOTALS----------

WE APPRECIATE YOU ENTRUSTING US WITH YOUR VEHICLE.
YOUR COMPLETE SATISFACTION IS OUR GOAL.
YOU MAY BE RECEIVING A SURVEY VIA EMAIL, IF FOR
ANY REASON YOU ARE UNABLE TO FILL OUT THE SURVEY
FOR YOU SERVICE ADVISOR BEING COMPLETELTY SATISFIED.

PLEASE REACH OUT TO OUR SERVICE MANGER AT:
480 813-4900 X40330

TOTAL LABOR....	900.00
TOTAL PARTS....	1013.54
TOTAL SUBLET...	0.00
TOTAL G.O.G....	0.00
TOTAL MISC CHG.	75.00
TOTAL MISC DISC	0.00
TOTAL TAX.....	90.35
TOTAL INVOICE $	**2078.89**

CUSTOMER SIGNATURE

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVES.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

CUSTOMER SIGNATURE

CUSTOMER COPY

[END OF INVOICE] 11:55am

The Reynolds and Reynolds Company ERAINTINVE
SF710150 Q (07/20)

ALBERS

Family owned & operated since 1963
HJGM, INC.

ALBERS MOTORCARS
Rolls-Royce & Bentley Specialists
360 SOUTH FIRST STREET
ZIONSVILLE, IN 46077
PH:(317)873-2360 FAX:(317)873-6860
www. albersrb.com

INVOICE

INVOICE NO. 407467
DATE 11/20/24
CUSTOMER ACCT. NO. [redacted]
TELEPHONE NO. [redacted]

BILL TO:

[redacted]

SHIP TO:

[redacted]

DATE	TIME	BY	CUSTOMER P.O. NUMBER	SPECIAL INSTRUCTIONS
11/20/2024	2:48:29 PM	GA		SO#: 255480

TERMS	SHIP VIA
Prepaid	UPS GRD RESIDENT.

QUANTITY REQUIRED	QUANTITY SHIPPED	QUANTITY B.O.	PART NUMBER	DESCRIPTION	EACH	TOTAL
1	1		UD1983R	IGNITION COIL - REPRODUCTION SCREW-IN TYPE COIL NEGATIVE GROUND ONLY	96.05	$96.05

SCHILSFU223

Payments Received:	$120.39
Deposits Applied:	$0.00

Subtotal:	$96.05
Discount:	$0.00
Freight:	$24.34
Misc Charge:	$0.00
Sales Tax:	$0.00
Total:	$120.39

SEE REVERSE SIDE OF CANARY SHIPPING COPY

[redacted]

ALBERS MOTORCARS
360 SOUTH FIRST STREET
ZIONSVILLE, IN 46077

Phone: (317) 873-2360
Fax: (317) 873-6860

Pick Ticket

Customer No.: PAR85249

Ship To: [redacted]

Bill To: [redacted]

Phone: [redacted]

SHIP VIA: UPS GRD RESI

Purchase Order Number	Required Date	Sales Person	Sales Order Number
	11/20/24	GA	255480

Item Number	Description	U/M	Location/Bin	Quantity Req	Pulled	Short
	********** SCIII LSFU223 **********				____	____
UD1983R	IGNITION COIL - REPRODUCTION SCREW-IN TYPE COIL NEGATIVE GROUND ONLY	EACH	WHSE1 02D 08	1	1	____

Retail Invoice
058169
Emailed on 10/21/2024
Emailed to smpartman@outlook.com

Firestone COMPLETE AUTO CARE™

since 1926

www.FirestoneCompleteAutoCare.com

Store# 784300
In: 10/21/24 03:44PM
Out: 10/21/24 03:44PM

Cust Status: Unspecified **Appt:** Unspecified **FINAL INVOICE**

FULTON RANCH - 4045 S AZ AVE, CHANDLER, AZ. 85248 - 480.883.2881

Service Advisor: 1 ISRAEL

[redacted]

CHANDLER, AZ 85249-3257

Wheel Lock:
Alt. Auth. Name & Phone:
N/A

Technician: 01 ISRAEL
Vehicle Details:

VIN #:
LIC #:
MILEAGE: 0

Description	Rev Hist /Article #	ID	Qty	Unit Price	Extended Price	Job Tota
STARTING/CHARGING SYSTEMS		01				**209.99**
64 ROLLS ROYCE						
24F-RP DHPLAT-24F-RP	7000459	01TN	1	209.99	209.99	
BATTERY CORE	7004413	01TN	1	10.00	10.00	
PRT-DISC Battery Core 100% Discount	7002461	01TN	-1	10.00	-10.00	

All parts are new unless otherwise specified.

Payment History:

[redacted]

226.37 00607D Sale

PIN NOT VERIFIED
226.37

Summary:

Parts	209.99
Labor	0.00
Shop Supplies	0.00
Sub-Total	209.99
Tax (7.80%)	16.38
Total	$226.37

Information on battery warranty, maintenance, and safety can be located at https://www.firestonecompleteautocare.com/maintain/batteries/battery-warranty-options/

WE SUPPORT PROFESSIONAL CERTIFICATION THROUGH THE NATIONAL INSTITUTE FOR AUTOMOTIVE SERVICE EXCELLENCE

I have received the above goods and/or services. If this is a credit card purchase, I agree to pay and comply with my cardholder agreement with the issuer.

Customer Signature

MOTORIST ASSURANCE PROGRAM
BUILDING TRUST THROUGH STANDARDS

Information on service warranty, maintenance, and safety can be located at https://www.firestonecompleteautocare.com/maintain/service-warranty-options/

ALBERS

Family owned & operated since 1963

HJGM, INC.

ALBERS MOTORCARS

Rolls-Royce & Bentley Specialists

360 SOUTH FIRST STREET

ZIONSVILLE, IN 46077

PH:(317)873-2360 FAX:(317)873-6860

www.albersrb.com

INVOICE

INVOICE NO. 395746

DATE 12/23/22

CUSTOMER ACCT. NO. [redacted]

TELEPHONE NO.

BILL TO:

[redacted]

SHIP TO:

[redacted]

DATE	TIME	BY	CUSTOMER P.O. NUMBER	SPECIAL INSTRUCTIONS
12/23/2022	23:59:42 PM	GA		SO#: 243114 MAILED 12/23/22

TERMS	SHIP VIA
Prepaid	PARCEL POST

QUANTITY REQUIRED	QUANTITY SHIPPED	QUANTITY B.O.	PART NUMBER	DESCRIPTION	EACH	TOTAL
				SILVER CLOUD III		
2	2		RH9162R	SC WIPER BLADE- REPRO. 10" STAINLESS BAYONETTE TYPE REPRODUCTION PART	22.00	$44.00
1	1		UB5142	(PQ2) * WIPER ARM BUMP STOP SCIII	20.40	$20.40

Subtotal:	$64.40
Discount:	$0.00
Freight:	$8.40
Misc Charge:	$0.00
Sales Tax:	$0.00
Total:	$0.00

Payments Received: $72.80

Deposits Applied: $0.00

395746

Albers Motorcars
360 S First St
Zionsville, IN 46077
317-873-2360

12/23/2022 16:05:54
Terminal ID: 005

Credit Sale

[redacted]

SHIPPING COPY FOR BUSINESS TERMS

Clover Privacy Policy
https://clover.com/privacy

BRITISH AUTOMOTIVE REPAIR
14850 N 83RD PL ST A-1, A-1
SCOTTSDALE, AZ 85260
4805965247

Cashier: DEBRA NEL

[redacted]

Total **$8,613.24**

CREDIT CARD SALE $8,613.24

[redacted]

Retain this copy for statement validation

21-Dec-2022 11:49:44A
$8,613.24 | Method: EMV

[redacted]

Clover Privacy Policy
https://clover.com/privacy

British Automotive Repair, LLC

14850 N 83rd Place, Suite A-1
Scottsdale, AZ 85260
Phone: 480-596-5247 Fax: 480-596-5240

12/21/2022 11:45:50 AM

Invoice #
10201

1964 Rolls Royce Silver Cloud Series III Gold
Odometer In: 90361 Odometer Out: 90503
License: 64ROLLS VIN: LSFU223

M

ıd lows present in pan surface. Ran pan over belt sander to knock down high sides. Washed pan in wash gasket adhesive, installed onto casing. Torqued all pan bolts to spec, lowered transmission onto pan, ware. Washed all torus components in solvent, inspected all parts for wear. Fit all 3 sections of torus and with snap rings. Installed locking tab washer, torqued retaining nut to spec. Turned unit around, placed d output nut to spec. Folded locking tab washers over both nuts to lock in position. Locked band inted threads for reference point in future service. Cleaned and polished all pressure regulator valve and new seals and washers, secured in place with blanking plug. Torqued plug to spec, placed gearbox in or install. Set gearbox onto transmission jack.

00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $510.00

---

il and road debris, washed away with brake wash. Blew dry with compressed air, inspected condition of es of torus. Applied gasket sealant to flywheel sealing surface, stuck gasket in place. Clocked torus in ıs, applied additional sealant layer to face of gasket. Jacked transmission into place, slid forward until all position of torus dowel pins and bellhousing dowel pins, pushed gearbox forward until mating surfaces bolts into bellhousing to secure transmission to engine block. Rotated engine over while installing all torus e, turned engine one full rotation while torquing each bolt to spec. Assembled throttle linkages and set in ı attempt to install brake servo onto gearbox, servo internals were observed to be crunchy and displayed :d brake servo, cleaned all parts in solvent. Re-sealed with felt washer, greased one way clutch bearings and nd secured clutch disc to backing plate, tightened hose clamp. Bolted starter motor in place within ware and attached wiring.

.50 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $935.00

Reviewed disassembly photos and compared to linkage schematic to insure correct orientation of throttle linkage and shifter linkage. Re-assembled linkages as depicted in Rolls Royce service manual, attached throttle linkage to foot pedal and throttle valve lever arm. Duplicated procedure for shift linkage, clamped both fulcrum points in place with retaining hardware. Fit brake servo connecting rod from brake linkage to pedal hinge. Lubricated hinges, verified range of motion by hand.

Labor: $425.00 **Hrs:** 2.50 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $425.00

12/06/22

Sealed brake servo with approved sealant, positioned servo onto gearbox in alignment with servo rods, clocked in position and bolted down with well-seal. Fit remaining bellhousing bolts, secured to engine block. Fit motor mount hardware and tightened all retaining bolts. Lowered vehicle, set gear selector in neutral position, selected neutral via manual lever on gearbox and attached shift linkage to pivot ball. Tightened retaining nut to pivot ball, tested all gear ranges via shift lever. Attached brake servo rods and fit clevis pins. Put battery tender on terminals in preparation for first start.

Labor: $340.00 **Hrs:** 2.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $340.00

12/07/22

Set baseline adjustment on brake servo to be road tested. Greased universal joints, slipped driveshaft into frame dwelling and installed output flange retaining hardware. Attached rear side of driveshaft to mating flange with rear shaft, loosely installed hardware.

Labor: $255.00 **Hrs:** 1.50 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $255.00

PAID

British Automotive Repair, LLC
14850 N 83rd Place, Suite A-1
Scottsdale, AZ 85260
Phone: 480-596-5247 Fax: 480-596-5240

12/21/2022 11:45:50 AM

Invoice # **10201**

[redacted]

1964 Rolls Royce Silver Cloud Series III Gold
Odometer In: 90361 Odometer Out: 90503
License: 64ROLLS VIN: LSFU223

Invoice

Continued From Previous Page

12/08/22

Torqued all driveshaft hardware, Fit anti vibrational center section to frame rail, secured with hardware and connected springs. Lowered vehicle, filled gearbox to capacity with approved fluid. Started and ran vehicle, selected each gear range to circulate fluid into all passages, shut down and inspected for leakage. No visual evidence of leakage detected. Supported rear end of vehicle on stands to elevate rear wheels. Ran vehicle through gears, verified shifting on rack. Cycled brake pedal, observed brake activation to come on late. Lifted vehicle, cycled servo to find inadequate travel of servo levers upon pedal depression. Removed servo from transmission, verified correct orientation. Adjusted levers to factory standards, reset servo tension as described in RR operations manual. Re-tested brake pedal with similar result. Removed rear brake linkage to test travel of handbrake lever. Adjusted rod to appropriate length, set rear brake adjusters until brake drag was felt. Re-attached rear linkage, turned adjusters out to set rear brake free-play. Started and ran vehicle, tested brakes again to test brake performance. Checked fluids and tire pressure to prepare vehicle for road test.

Labor: $1,105.00 **Hrs:** 6.50 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $1,105.00

12/09/22

Briefly drove vehicle around parking lot to assess road worthiness. Observed brake function to be below operational standards for road safety. Lifted vehicle and adjusted freeplay of brake linkages. Set baseline tension of throttle valve linkage based upon factory manual. Made first band adjustment post drive cycle. During band adjustment, rpm fluctuation did not match values depicted in band adjustment procedure. Adjusted idle to factory settings, repeat band adjustment.

Labor: $680.00 **Hrs:** 4.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $680.00

12/14/22

Removed brake linkage from vehicle, re-calibrated on bench per rolls royce assembly standards. Re-attached to vehicle. Test drive vehicle. Shift quality reveals behavior indicative of throttle valve adjustment required. Made minor adjustments between several test drives in effort to achieve ideal shift quality.

Labor: $680.00 **Hrs:** 4.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $680.00

12/15/22

With new linkage adjustments matching that of factory standards, shift pattern remains out of sync per expectations. Connected pressure gauge to line pressure port, started vehicle and set idle speed to factory standards. Tested line pressure to reveal adequate pressure in neutral range. In D4 and R, pressure is lower than spec. Removed pressure regulator plug and valve lineup, confirmed correct orientation of spring and valve assembly. Removed side cover, unbolted valve body. Air checked all clutch circuits and band passages with compressed air, observed all clutch packs to apply and release as designed. Verified movement and range of motion in all valve body spool valves, separated valve body halves and examined castings. Possible crack discovered in valve body casting, will warrant a dye check to confirm.

Labor: $1,105.00 **Hrs:** 6.50 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $1,105.00

12/16/22

Washed valve body casting, blew dry with compressed air. Sprayed down with dye check, confirmed valve body casting to be crack free. Removed throttle valve and inspected, identified correct orientation. T valve intermittently exhibited a slight hangup within bore when stroked. Polished valve in lathe with emery cloth, re-fit and tested. Re-assembled valve body and air checked, all valves are free and stroke as designed. Re-fit valve body onto transmission casing in alignment with lubrication pipes. Bolted valve body down and torqued hardware to spec. One lube tube fit slightly loose within respective bore, installed with bearing mount for added sealing capacity. Installed side cover, torqued hardware. Installed throttle linkage and shift linkage, secured with pinch bolts. Topped off fluid lost during valve removal, started and ran vehicle. Line pressure readings all read within spec for every gear range. Lowered vehicle, checked fluid levels, test drive. Transmission performance is satisfactory. Upon return, lifted vehicle, inspected for leaks. Verified proper transmission fluid level, checked tire pressure.

Labor: $1,020.00 **Hrs:** 6.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $1,020.00

PAID

British Automotive Repair, LLC

14850 N 83rd Place, Suite A-1
Scottsdale, AZ 85260
Phone: 480-596-5247 Fax: 480-596-5240

12/21/2022 11:45:50 AM

Invoice #
10201

[redacted]

1964 Rolls Royce Silver Cloud Series III Gold
Odometer In: 90361 Odometer Out: 90503
License: 64ROLLS VIN: LSFU223

Invoice

Continued From Previous Page

12/19/20

Removed front wheels, inspected brake components. Linings and wheel cylinder are in good working order. Excessive brake dust present within drums. Washed drums in wash machine, washed down shoes with brake wash. Blew all components dry with compressed air, reset factory brake adjustment. Identified fluid escape originating from master cylinder. Photographed condition of brake master and sent to client for clarity.

Labor: $595.00 **Hrs:** 3.50 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $595.00

12/20/22

Made final brake adjustment post test drive, secured cotter pins. Fit torus cover and fuel bowl relief bracket, secured hardware. During bracket installation, float bowl relief tube was observed to be wet with fuel. Cleaned underbody paneling, installed driver and passenger side coverings, fit hardware in place and tightened. Verified proper function of choke. Removed float bowl covers and tested floats once more. Passenger float bowl revealed lower fuel level than that of driver. Removed float bowl covers, tested needle and seat valves. Partial blockage present in fuel delivery orifice to driver side carburetor. Cleaned passage thoroughly, replaced both needle and seat valves with updated viton tip replacements. Re-attached float bowls, started and ran vehicle. Vehicle starts up noticeably easier.

Labor: $510.00 **Hrs:** 3.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $510.00

12/21/22

Cold start vehicle, startup behavior shows improvement from past. Conduct final test drive for road safety analysis and overall performance. Upon return, check all fluid levels and exterior lighting function. Set tire pressure to manufacturer standards.

Part Number	Description	Quantity	Sale	Extended
371-055	Needle/Seat valve	2.00	$26.24	$52.48
UG809R	Trans Pan Gasket	1.00	$6.56	$6.56
75200	Transmission Fluid	12.00	$13.12	$157.44
WHT002909R	Drain Plug Washer	1.00	$1.88	$1.88
10406	Octane Boost	1.00	$16.00	$16.00

Labor: $0.00 **Hrs:** 0.00 **Parts:** $234.36 **Sublet:**$0.00 **Job Total:** $234.36

Fuel

Labor: $0.00 **Hrs:** 0.00 **Parts:** $0.00 **Sublet:**$50.01 **Job Total:** $50.01

Fuel

Labor: $0.00 **Hrs:** 0.00 **Parts:** $0.00 **Sublet:**$50.00 **Job Total:** $50.00

PAID

Technician Work Sheet ***Service Writer : Encinas, Kristen***

1964 Rolls Royce - Silver Cloud Series III

Print Date: 12/16/2022

VIN # : LSFU223
Engine :
Lic # : **64ROLLS**

Hat # :
Color : **Gold**
Location :
Lic. State : **AZ**

Repair Order #
010201

[redacted]

Inspection Date : 6/09/22
Last Service : 12/05/22
Current Odometer : 90,361
Previous Mileage : 90,361
Elapsed Mileage : 0

Schedule :
Promised Date : 12/01/22 5:00 P.M.
Status :
Unit # :
Trans :
Brakes :
Manufacture Date : 6/09/22

	Part Number	Part Description	Qty	Part Location
☐	UG809R	Trans Pan Gasket	1.00	
☐	75200	Transmission Fluid	9.00	
☐	WHT002909R	Drain Plug Washer	1.00	
☐	10406	Octane Boost	1.00	

	Labor Description	Charged Hours
☐	12/01/22	3.00

Filed oil pan flat, noticeable highs and lows present in pan surface. Ran pan over belt sander to knock down high sides. Washed pan in wash machine, stuck gasket in place with gasket adhesive, installed onto casing. Torqued all pan bolts to spec, lowered transmission onto pan, installed bellhousing, torqued hardware. Washed all torus components in solvent, inspected all parts for wear. Fit all 3 sections of torus and ring gear to transmission, secured with snap rings. Installed locking tab washer, torqued retaining nut to spec. Turned unit around, placed vehicle in reverse range and torqued output nut to spec. Folded locking tab washers over both nuts to lock in position. Locked band adjustment locking nuts in place, painted threads for reference point in future service. Cleaned and polished all pressure regulator valve components, re-installed into pump and new seals and washers, secured in place with blanking plug. Torqued plug to spec, placed gearbox in neutral position. Gearbox is clear for install. Set gearbox onto transmission jack.
Technician : Bednarek

☐ 12/02/22 5.50

Cleaned rear of engine of residual oil and road debris, washed away with brake wash. Blew dry with compressed air, inspected condition of pilot bearing. Buffed mating surfaces of torus. Applied gasket sealant to flywheel sealing surface, stuck gasket in place. Clocked torus in position to match up with dowel pins, applied additional sealant layer to face of gasket. Jacked transmission into place, slid forward until all alignment holes lined up. Checked position of torus dowel pins and bellhousing dowel pins, pushed gearbox forward until mating surfaces connected. Installed two retaining bolts into bellhousing to secure transmission to engine block. Rotated engine over while installing all torus bolts loosely. Once all bolts in place, turned engine one full rotation while torquing each bolt to spec. Assembled throttle linkages and set in place to be attached to gearbox. In attempt to install brake servo onto gearbox, servo internals were observed to be crunchy and displayed poor range of motion. Disassembled brake servo, cleaned all parts in solvent. Re-sealed with felt washer, greased one way clutch bearings and re-assembled. Lubricated hinges and secured clutch disc to backing plate, tightened hose clamp. Bolted starter motor in place within bellhousing dwelling, torqued hardware and attached wiring.
Technician : Bednarek

☐ 12/05/22 2.50

Reviewed disassembly photos and compared to linkage schematic to insure correct orientation of throttle linkage and shifter linkage. Re-assembled linkages as depicted in Rolls Royce service manual, attached throttle linkage to foot pedal and throttle valve lever arm. Duplicated procedure for shift linkage, clamped both fulcrum points in place with retaining hardware. Fit brake servo connecting rod from brake linkage to pedal hinge. Lubricated hinges, verified range of motion by hand.
Technician : Bednarek

☐ 12/06/22 2.00

Copyright (c) 2022 Mitchell Repair Information Company, LLC Expanded 112119sp

echnician Work Sheet *Service Writer : Encinas, Kristen*

964 Rolls Royce - Silver Cloud Series III

Print Date: 12/16/2022

IN # : LSFU223
Engine :
Lic # : **64ROLLS**

Hat # :
Color : **Gold**
Location :
Lic. State : **AZ**

Repair Order #
010201

Labor Description	Charged Hours
Sealed brake servo with approved sealant, positioned servo onto gearbox in alignment with servo rods, clocked in position and bolted down with well-seal. Fit remaining bellhousing bolts, secured to engine block. Fit motor mount hardware and tightened all retaining bolts. Lowered vehicle, set gear selector in neutral position, selected neutral via manual lever on gearbox and attached shift linkage to pivot ball. Tightened retaining nut to pivot ball, tested all gear ranges via shift lever. Attached brake servo rods and fit clevis pins. Put battery tender on terminals in preparation for first start. Technician : Bednarek	
☐ 12/07/22 Set baseline adjustment on brake servo to be road tested. Greased universal joints, slipped driveshaft into frame dwelling and installed output flange retaining hardware. Attached rear side of driveshaft to mating flange with rear shaft, loosely installed hardware. Technician : Bednarek	1.50
☐ 12/08/22 Torqued all driveshaft hardware, Fit anti vibrational center section to frame rail, secured with hardware and connected springs. Lowered vehicle, filled gearbox to capacity with approved fluid. Started and ran vehicle, selected each gear range to circulate fluid into all passages, shut down and inspected for leakage. No visual evidence of leakage detected. Supported rear end of vehicle on stands to elevate rear wheels. Ran vehicle through gears, verified shifting on rack. Cycled brake pedal, observed brake activation to come on late. Lifted vehicle, cycled servo to find inadequate travel of servo levers upon pedal depression. Removed servo from transmission, verified correct orientation. Adjusted levers to factory standards, reset servo tension as described in RR operations manual. Re-tested brake pedal with similar result. Removed rear brake linkage to test travel of handbrake lever. Adjusted rod to appropriate length, set rear brake adjusters until brake drag was felt. Re-attached rear linkage, turned adjusters out to set rear brake free-play. Started and ran vehicle, tested brakes again to test brake performance. Checked fluids and tire pressure to prepare vehicle for road test. Technician : Bednarek	6.50
☐ 12/09/22 Briefly drove vehicle around parking lot to assess road worthiness. Observed brake function to be below operational standards for road safety. Lifted vehicle and adjusted freeplay of brake linkages. Set baseline tension of throttle valve linkage based upon factory manual. Made first band adjustment post drive cycle. During band adjustment, rpm fluctuation did not match values depicted in band adjustment procedure. Adjusted idle to factory settings, repeat band adjustment. Technician : Bednarek	4.00
☐ 12/14/22 Removed brake linkage from vehicle, re-calibrated on bench per rolls royce assembly standards. Re-attached to vehicle. Test drive vehicle. Shift quality reveals behavior indicative of throttle valve adjustment required. Made minor adjustments between several test drives in effort to achieve ideal shift quality. Technician : Bednarek	4.00
☐ 12/15/22 With new linkage adjustments matching that of factory standards, shift pattern remains out of sync per expectations. Connected pressure gauge to line pressure port, started vehicle and set idle speed to factory standards. Tested line pressure to reveal adequate pressure in neutral range. In D4 and R, pressure is lower than spec. Removed pressure regulator plug and valve lineup, confirmed correct orientation of spring and valve assembly. Removed side cover, unbolted valve body. Air checked all clutch circuits and band passages with compressed air, observed all clutch packs to apply and release as designed. Verified movement and range of motion in all valve body spool valves, separated valve body halves and examined castings. Possible crack discovered in valve body casting, will warrant a dye check to confirm. Technician : Bednarek	6.50

Sublet

☐

Copyright (c) 2022 Mitchell Repair Information Company, LLC Expanded 112119sp

British Automotive Repair, LLC

14850 N 83rd Place, Suite A-1
Scottsdale, AZ 85260
Phone: 480-596-5247 Fax: 480-596-5240

12/05/2022 4:25:19 PM
Invoice #
10059

[redacted]

1964 Rolls Royce Silver Cloud Series III Gold
Odometer In: 90361 Odometer Out: 90361
License: 64ROLLS VIN: LSFU223

Continued From Previous Page

11/30/22

Set band adjustments per Rolls Royce repair manual, double checked tolerances. Rotated gearbox to feel for resistance. Re-installed governor lubrication pipe, stuck gasket to side cover with gasket adhesive. Installed side cover, torqued hardware.

Labor: $170.00 **Hrs:** 1.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $170.00

11/30/22

I decided to clean every part of any dirt or debris for installment including every bolt and the surrounding area into the vehicle to make sure the bolts don't have issues or the parts do not have any issues going back on.

Part Number	Description	Quantity	Sale	Extended
UG464R	Outer Cushion	1.00	$41.00	$41.00
H75	Hyrdo Rev Pstn L/S Outer	1.00	$17.20	$17.20
H1411	Rear Hub Washer	2.00	$20.00	$40.00

Labor: $306.00 **Hrs:** 1.80 **Parts:** $98.20 **Sublet:**$0.00 **Job Total:** $404.20

BRITISH AUTOMOTIVE REPAIR
14850 N 83RD PL ST A-1, A-1
SCOTTSDALE, AZ 85260
4805965247

Cashier: Employee

Transaction **001917**

Total **$5,767.22**

CREDIT CARD SALE $5,767.22
VISA 3290

Retain this copy for statement validation

05-Dec-2022 4:25:03P
$5,767.22 | Method: KEYED
VISA XXXXXXXXXXX3290
MANUALLY ENTERED
Reference ID: 233900531972
Auth ID: 05102C
MID: ********6885
AthNtwkNm: VISA
SIGNATURE VERIFIED

Payment **X61SFW9E4GWPP**

Clover Privacy Policy
https://clover.com/privacy

Technician(s): Bednarek, Adam; Goetz, Carson

Labor Total:	$5,576.00
Parts Total:	$98.20
Shop Sup.:	$85.11
HazMat:	$0.00
Sub Total:	$5,759.31
Tax Total:	$7.91
Grand Total:	$5,767.22
Balance Due:	**$0.00**

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.
I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... **DATE**.....

Payment(s)
12/5/2022 4:24:39PM $5,767.22 Visa

British Automotive Repair, LLC
14850 N 83rd Place, Suite A-1
Scottsdale, AZ 85260
Phone: 480-596-5247 Fax: 480-596-5240

12/05/2022 4:25:19 PM
Invoice #
10059

[redacted]

1964 Rolls Royce Silver Cloud Series III Gold
Odometer In: 90361 Odometer Out: 90361
License: 64ROLLS VIN: LSFU223

Invoice

Continued From Previous Page

11/22/22

Fit reverse unit outer lip seal, installed piston into drum. Installed return springs, spring retainer and snap ring. Compressed springs, installed snap ring into groove, air checked reverse section through charge port, no evidence of bypass. Separated front and rear clutch units, inspected sealing rings, re-fit drums together and installed retaining snap ring. Fit front band over drum and wire tied in place for case loading procedure. Set main case on bench, lowered drum assembly into case, fit oil delivery sleeve into bore in alignment with bearing cap. Installed rear band atop drum surface in alignment with adjustment screw. Fit bearing cap into position atop oil delivery sleeve, installed hardware and torqued to spec. Bent over locking tab washer, stood transmission on end. Lowered rear planetary assembly into case in alignment with rear unit. Installed Stationary cone and locking tab, pressed rear planetary assembly into rear unit. Spun unit to feel for any drag. Assembled governor gear assembly, replaced sealing rings and set aside for installation.

Labor: $425.00 **Hrs:** 2.50 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $425.00

11/23/22

Assembled main unit into case, Installed reverse unit atop case with new gasket and sealing rings. Measured end nip as described in RR transmission overhaul manual. Fit governor drive gear, spacer and retaining ring to output shaft. Installed brake servo and speedometer drive into reverse unit, installed coverings with new gaskets. Fit output flange to output shaft, followed with end nip washer, abutment washer and locking tab washer, torqued nut to preliminary capacity. Installed band adjustment pegs and locking nuts. Flipped unit over, installed front drive gear with selective thrust washer to achieve adequate spacing between planetary and ring gear. Assembled front pump unit with new sealing washers, fit sealing gasket to flange and installed into case atop front drive gear. Installed drive gear thrust washer and abutment washer, secured with retaining snap ring. Fit front torus drive into pump to size sealing rings to mating surface. Flipped unit over to rest upon torus drive, fit parking pawl into position through side cover cavity. Installed governor drive with new sealing washers and fit to parking pawl in alignment with parking cam. Secured parking pawl hardware, bent over locking tab washer and torqued governor to side case. Test spun all shafts to feel for any unjust resistance, lubricated all mating gears with assembly lube. Band servos and valve body await rebuild and installation.

Labor: $765.00 **Hrs:** 4.50 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $765.00

11/28/22

Air checked front and rear drums. Applied air to orifice feed at reverse unit, torqued reverse housing. Loosened reverse unit and repeated process until output shaft turned freely as described in RR rebuild manual. Disassembled rear band servo, inspected all hard parts and washed in solvent. Replaced sealing rings, polished sealing bores and re-assembled rear servo with new gaskets. Disassembled front band servo, inspected all hard parts and washed in solvent. Replaced sealing rings and polished seal bores, re-assembled front servo. Installed lubrication pipe from front pump to front servo, installed front servo in alignment with band anchor and relief pipe from rear pump to front servo. Fit rear band servo in place, mated with front servo lube pipe and apply orifices. At this time there is mention of band release spring in installation guide that was not present within gearbox at time of disassembly. Sourced literature on the topic and compared to exploded view and disassembly photos.

Labor: $680.00 **Hrs:** 4.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $680.00

11/29/22

Identified return spring mentioned to be year specific to 1946-1956, not incorporated in the model year on hand. Completed installation of front and rear band servos. Fit lubrication pipes to servos, rear pump and governor. Torqued hardware to spec, disassembled valve body. Inspected all components and spring rates. Polished all valves, re-assembled valve body. Slipped valve body into position in alignment with lubrication pipes to governor, fit manual valve and bolted in place. Torqued valve body hardware, air checked servos and drums.

Labor: $595.00 **Hrs:** 3.50 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $595.00

British Automotive Repair, LLC

14850 N 83rd Place, Suite A-1
Scottsdale, AZ 85260
Phone: 480-596-5247 Fax: 480-596-5240

12/05/2022 4:25:19 PM
Invoice #
10059

[redacted]

PAID

1964 Rolls Royce Silver Cloud Series III Gold
Odometer In: 90361 Odometer Out: 90361
License: 64ROLLS VIN: LSFU223

Invoice

Vehicle Time In: 12/1/2022 9:18:26AM

Client states choke does not function properly - please investigate

Client states window switch on driver side has electric charge when touched - check ground

11/11/22

Set gearbox on bench for disassembly, drained unit into receptacle. Removed bellhousing and side cover, ran through wash machine. Removed lubrication pipes from valve body and band servos. Removed valve body, wrapped in towel and set aside. Removed brake servo from rear unit, unbolted reverse section and removed from main case. Unbolted and removed pump, set aside. Removed band servos and governor sleeve, stored on cart for later disassembly. Removed sub assemblies from main case, washed case in wash machine. Organized drums and planetaries on bench for further teardown and inspection. Began washing and inspecting internal components. Dried bellhousing, side cover and main case from wash machine, consulted with client regarding case restoration options. Laid coat of paint to main case to prevent rust and restore original finish.

Labor: $1,190.00 **Hrs:** 7.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $1,190.00

11/14/22

Disassembled front unit. Washed all parts, inspected for runability. All front unit components meet re-usability guidelines. Removed and replaced lip seals and bushings. Assembled front unit, installed new friction discs and steel plates to recondition to factory standards. Washed all planetary gearsets, inspected for re-usability. No evidence of planetary failure. Cleaned and buffed all thrust washers, checked for flatness. One thrust washer upon rear unit clutch hub was found to be compromised beyond re-usability guidelines. Relayed to service advisor to source appropriate replacement. Disassembled rear unit, washed all parts and inspected. Replaced bushings and seals, re-assembled rear unit with new friction discs and steel plates. Extracted bushing from center support lubrication sleeve and washed. Polished bushing surfaces in lathe, installed to sealing rings to lube sleeve. Re-assembled rear planetary gearset and hub units with new bushings. Pressed bearing and sleeve into position upon output shaft, set aside for later assembly. Fit clutch hub into rear unit, rotated hub to assess clutch clearance of rear unit. Stabbed front unit into input planetary hub to assess clutch clearance of front unit. All tolerances register within manufacturer specifications per Rolls Royce assembly manual. Disassembled pump, extracted pressure relief valve and slide spring. Washed all components, inspected for wear. Pump shows to be in good working condition. Flat stoned pump slide and rotor to promote flatness and proper pressure supply. Re-fit relief valve and slide spring, re-assembled pump to manufacturer standards. Pressed new seal into pump cover, fit sealing ring to retaining bore. Assembled pump in front hub and ring gear, inserted front planetary. Stacked front unit into planetary and lubrication sleeve into front unit. Installed rear unit into lubrication sleeve atop front unit to measure build height of internal components. All measurements fit within relative spec per manufacturer. Washed all lubrication pipes and filter, blew dry with compressed air. Inspected all components for wear, replaced parts as necessary. Disassembled reverse unit and brake servo. Washed all components and inspected for wear. Re-assembled brake servo and set aside for later installation. Inspected valve body prior to disassembly for any requirement for reconditioning. Valving behaves as expected, no visual evidence of broken springs or compromised valves, further evaluation with ensue upon disassembly.

Labor: $1,190.00 **Hrs:** 7.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $1,190.00

11/15/22

Disassembled reverse unit, cleaned all parts and inspected. Replaced lip seals and installed piston into casting. Fit return springs and spring retainer, secured with snap ring. Disassembled speedometer drive and governor assemblies, washed and inspected. Re-assembled for install.

Labor: $170.00 **Hrs:** 1.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $170.00

11/18/22

Upon delivery of thrust washer, measured thickness and physically compared to original. Thrust washer is a confirmed fit. Stuck washer in place and stacked geartrain for endplay measurement. Stack height of geartrain is within spec, transmission ready for final assembly.

Labor: $85.00 **Hrs:** 0.50 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $85.00

British Automotive Repair, LLC

14850 N 83rd Place, Suite A-1
Scottsdale, AZ 85260
Phone: 480-596-5247 Fax: 480-596-5240

11/07/2022 1:32:01 PM
Invoice #
9488

[redacted]

PAID

1964 Rolls Royce Gold
Odometer In: 90361 Odometer Out: 90361
License: 64ROLLS VIN: LSFU223

Invoice

Vehicle Time In: 11/1/2022 8:47:41AM

7/7/22

With the transmission out I found that some of the parts were starting to look rusty or extremely dirty. First I took the biggest panel an cleaned it then sandblasted the panel after to get any old rust spots off or dirt off to give it a better look. Next was the brake line I first started by cleaning them then scotchbrite them, then I polished the pieces out until it had a clean and restored look to almost new. Next was the two little pieces that connected to the transmission, I first started by cleaning them off, then i polished both pieces out till they had the original chrome look. Last was the rear main seal cover, I first started by taking a pad of scotchbrite to the piece to see how original2.5 it would of looked in a test spot and then decided to scotchbrite the whole thing to clean it up a bit.

Part Number	Description	Quantity	Sale	Extended
H102R1	Hydramatic Kit	1.00	$697.50	$697.50
H122A	Hydro Rear Band	1.00	$0.00	$0.00
H122C	Hydro Front Band	1.00	$0.00	$0.00
KH106A	Hydro Kit	1.00	$170.96	$170.96
0905	Dramatic Repair Manual	1.00	$43.75	$43.75

Labor: $425.00 **Hrs:** 2.50 **Parts:** $912.21 **Sublet:**$0.00 **Job Total:** $1,337.21

BRITISH AUTOMOTIVE REPAIR
1480 N 83RD PL ST A-1, A-1
SCOTTSDALE, AZ 85260
4805965247

Cashier: Employee

Transaction **001789**

Total **$1,430.70**

CREDIT CARD SALE $1,430.70
VISA 3290

Retain this copy for statement validation

07-Nov-2022 1:52:55P
$1,430.70 | Method: KEYED
VISA XXXXXXXXXXX3290
MANUALLY ENTERED
Reference ID: 231100529796
Auth ID: 07664C
MID: ********6885
AthNtwkNm: VISA
SIGNATURE VERIFIED

Payment T3E6BPSZZ4H78

Clover Privacy Policy
https://clover.com/privacy

Service Advisor: Encinas, Kristen
Technician(s): Bednarek, Adam; Goetz, Carson

Labor Total:	$425.00
Parts Total:	$912.21
Shop Sup.:	$20.06
HazMat:	$0.00
Sub Total:	$1,357.27
Tax Total:	$73.43
Grand Total:	$1,430.70
Balance Due:	**$1,430.70**

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.
I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... **DATE**.....

British Automotive Repair, LLC

14850 N 83rd Place, Suite A-1
Scottsdale, AZ 85260
Phone: 480-596-5247 Fax: 480-596-5240

07/05/2022 1:48:09 PM
Invoice #
9423

[redacted]

1964 Rolls Royce Gold
Odometer In: 90361 Odometer Out: 90361
License: 64ROLLS VIN: LSFU223

Invoice

Vehicle Time In: 7/5/2022 1:47:54PM

Client requests to remove gearbox

06/23/22

Lifted vehicle, took photos of linkage arrangements and servo rod position. Began detaching ancillaries for gearbox removal. Unbolted driveshaft for clearance.

Labor: $340.00 **Hrs:** 2.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $340.00

06/24/22

Remove all exterior gearbox linkages, remove driveshaft. Unbolt transmission from engine block, lowered transmission out of underbody. Remove torque converter from gear box, allow box to drain.

Labor: $1,190.00 **Hrs:** 7.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $1,190.00

BRITISH AUTOMOTIVE REPAIR
14850 N 83RD PL ST A-1, A-1
SCOTTSDALE, AZ 85260
4805965247

[redacted]

PAID
7/8/22
VISA

Service Advisor: Encinas, Kristen
Technician(s): Bednarek, Adam; Goetz, Carson

Labor Total:	$1,530.00
Parts Total:	$0.00
Shop Sup.:	$22.95
HazMat:	$0.00
Sub Total:	$1,552.95
Tax Total:	$0.00
Grand Total:	$1,552.95
Balance Due:	**$1,552.95**

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.
I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE Phone Payment **DATE** 7/8/22

British Automotive Repair, LLC

14850 N 83rd Place, Suite A-1
Scottsdale, AZ 85260
Phone: 480-596-5247 Fax: 480-596-5240

06/20/2022 1:21:48 PM

Invoice #
9385

[redacted]

1964 Rolls Royce Gold

Odometer In: 90357 Odometer Out: 90361
License: 64ROLLS VIN: LSFU223

Invoice

Vehicle Time In: 6/17/2022 11:52:21AM

Please see attached client list

06/13/22

Brought vehicle into bay, reviewed list of client request. Check fluids, test drive vehicle to verify gearbox malfunction. Contact client via telephone to discuss plan of attack for service. Positioned vehicle on rack, removed drain plug and allowed crankcase to drain of oil. Re-fit drain plug and torqued, removed oil filter housing and emptied. Washed out oil filter housing with solvent, replaced filter element and sealing rings. Installed filter housing and tightened down. Greased all zerk fittings in vehicle chassis. Removed transmission drain plug and allowed fluid to spill for oil analysis. Fluid quality smelled and appeared to show evidence of overheating. Note client mentioned gearbox being roughly 4 quarts low at some point. Re-fit drain plug and torqued. Lowered vehicle, filled crank case and transmission to capacity per manufacturer specification, lubricated speedometer cable. Started vehicle, allowed oil pressure to stabilize and inspected for leaks, none present. Inspected choke mechanism and throttle levers, discovered an intermittent throttle stick within pedal linkage. Topped off brake fluid, reviewed band adjustment procedure to ensure correct specifications. Performed band adjustment procedure via hycramatic service manual, test drive vehicle. Made minor adjustments to band clearance to achieve ideal shift quality. Some inconsistencies in behavior present regardless of band adjustment possibly suggesting soft part wear or damage within gearbox. Contacted client for approval to conduct oil pan inspection.

Labor: $1,020.00 **Hrs:** 6.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $1,020.00

06/14/22

Lifted vehicle, drained transmission fluid. Removed underbody paneling to gain access to transmission hardware. Removed pan bolts and lowered oil pan. Inspected contents of pan, no distinct evidence of failure. Evaluated internal components to find front band not sitting correctly on drum. Lowered vehicle, loosened band adjustment screw, lifted vehicle and re-aligned band. Scraped away gasket material from pan rail and mating surface, washed pan in wash machine. Removed filter and flushed with solvent, removed any debris from screen. Upon filter removal, pump pickup tube fell out of pump. Inspected o-ring, determined to be compromised. Replaced o-ring for better fitment to pickup tube. Re-fit filter, stuck gasket to pan rail and bolted oil pan in place. Lowered vehicle and filled transmission to capacity. Started and ran vehicle, set band adjustment once again. Test drive vehicle, shifts occur as designed, however shift timing incorrect per factory spec. Lifted vehicle, made kickdown adjustment. Second test drive pending.

Labor: $680.00 **Hrs:** 4.00 **Parts:** $0.00 **Sublet:**$0.00 **Job Total:** $680.00

06/15/22

Test drive vehicle, upon return lifted and made additional adjustment to throttle valve linkage. Test drive again and make final band adjustment for fine tuning. Front band adjustment does not affect idle speed as it should per Rolls Royce adjustment procedure indicating slippage of front band. Transmission shifts much better, and will shift on its own, however not consistently. When temperatures achieve operating range shift quality dwindles, further reinforcing the band diagnosis. Gearbox is determined to require overhaul.

Part Number	Description	Quantity	Sale	Extended
822387	Transmission Fluid	6.00	$12.06	$72.36

Labor: $425.00 **Hrs:** 2.50 **Parts:** $72.36 **Sublet:**$0.00 **Job Total:** $497.36

Firestone
COMPLETE AUTO CARE™

Israel Hope
Store Manager

4045 S Arizona Ave
Chandler, AZ 85248
Phone : 1.480.883.2881
Fax : 1.480.883.3392
FirestoneCompleteAutoCare.com

[redacted]

Firestone COMPLETE AUTO CARE™

Store# 784300
In: 03/03/21 01:27PM
Out: 03/03/21 01:27PM

.FirestoneCompleteAutoCare.com

FINAL INVOICE

S AZ AVE, CHANDLER, AZ. 85248 - 480.883.2881

Wheel Lock:

Alt. Auth. Name & Phone:

N/A

Technician: 01ISRAEL

Vehicle Details:

VIN #:
LIC #:
MILEAGE: 0

Description	Rev Hist /Article #	ID	Qty	Unit Price	Extended Price	Job Total
STARTING/CHARGING SYSTEMS		01				**144.99**
MTP27F INTERSTATE BATTERY	7006476	01TN	1	144.99	144.99	
BATTERY CORE	7004413	01TN	1	10.00	10.00	
PRT-DISC Battery Core 100% Discount	7002461	01TN	-1	10.00	-10.00	

All parts are new unless otherwise specified.

[redacted]

156.29 04721D Sale

PIN NOT VERIFIED
156.29

Summary:

Parts	144.99
Labor	0.00
Shop Supplies	0.00
Sub-Total	144.99
Tax (7.80%)	11.30
Total	$156.29

Information on **battery warranty, maintenance, and safety** can be located at
https://www.firestonecompleteautocare.com/maintain/batteries/battery-warranty-options/

ASE
VIB SUPPORT
PROFESSIONAL CERTIFICATION
AUTOMOTIVE SERVICE EXCELLENCE

I have received the above goods and/or services. If this is a credit card purchase, I agree to pay and comply with my cardholder agreement with the issuer.

Customer Signature

MOTORIST ASSURANCE PROGRAM
BUILDING TRUST THROUGH STANDARDS

HOW ARE WE DOING?
Tell us about your experience today!
Complete a 4-minute survey for a chance to win one of ten $50 gift cards each month!
Visit www.FirestoneSurvey.com within 4 days and enter Code 784300-030529

Information on service warranty, maintenance, and safety can be located at
https://www.firestonecompleteautocare.com/maintain/service-warranty-options/

Inv1_WP 08.13.2020 100

SCHAUMBURG AUTOMEDICS, INC.

503 LUNT AVENUE • SCHAUMBURG, IL 60193
Phone (847) 352-2886 • Fax (847) 352-0969
www.schaumburgautomedics.com

Schaumburg Automedics inc.
- Complete Automotive Repair & Maintenance -

FOR YOUR CAR'S HEALTH

AUTOCARE CENTER

AUTOMOTIVE SERVICE ASSOCIATION MEMBER

BBB ACCREDITED BUSINESS

AAA Approved Auto Repair

Repair Order # 0079378
Date 9/28/2016
Page: 1

Customer:	[redacted]	**Vehicle:**	1964 ROLL SILVER CLOUD 3
Address:		**License:**	CLOUDIX **UNIT:**
City:	L 60007-	**VIN:**	LSFU223
CELL:		**Engine:**	V8 - 283 **Trans:** AUTO
WORK:		**Mileage:**	86785 **P/D:**

Op	Tech	Description / Qty	Part Number	Part Description	Part Price	Labor	Parts	Subtotal
		Estimate Approvals:						
		Original Approval Date: 9/2/2016 6:26:00 PM Reason:						
		Amount: $270.91 Auth By: STEVE PARTMAN Contacted By Phone						
		Phone: (630) 470-3749 By: SB						

MS	001	055 CUSTOMER STATES....TIRE/WHEEL VIBRATING ..... THERE IS A SHAKING/VIBRATION AT VERY LOW SPEEDS 5MPH OR LESS ..... IT FEELS LIKE IT IS COMING FRONT THE DRIVER SIDE REAR ..... CHECK AND ADVISE				0.00		
TW	0	053 ROAD FORCE BALANCED ALL TIRES INCLUDING SPARE				249.00		249.00
DL	001	057 DIAGNOSE DRIVE LINE VIBRATION/NOISE,ROAD TEST VEHICLE AND THE TECHNICIAN FOUND				0.00		

Schaumburg Automedics inc.

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation

PD 10-7-16
3546

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control.
WARRANTY IS 36 MTH/36,000 MILES, WHICHEVER OCCURS FIRST AND MUST BE PERFORMED BY SCHAUMBURG AUTOMEDICS, INC., UNLESS SPECIFIED OTHERWISE!

CONSUMER RIGHTS NOTICE

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but shall not exceed (1) any price limited estimate or (2) any parts and labor estimate by more than 10%. Additional repairs may not be performed without your consent. You may waive your right to a written estimate and withdraw that you be notified if the price exceeds an amount you have specified.

You may waive your right to an estimate, which gives the motor vehicle repair facility the right to set the price without your permission. Your signature will indicate your selection.

- ☐ (a) I request an estimate in writing before you begin repairs.
- ☐ (b) Please proceed with the repairs, but call me for approval before continuing if the price exceeds $
- ☐ (c) I do not want an estimate, and you may set the price of repairs.

Signature:

Labor:	$249.00
Parts:	$0.00
Sublet:	$0.00
Other Fees:	$0.00
Supplies:	$19.92
Subtotal:	$268.92
Sales Tax:	$1.99
Paid By: **Total:**	$270.91
Pay Ref: **Paid:**	$0.00
Due:	$270.91

SCHAUMBURG AUTOMEDICS, INC.

503 LUNT AVENUE • SCHAUMBURG, IL 60193
Phone (847) 352-2886 • Fax (847) 352-0969
www.schaumburgautomedics.com

Schaumburg Automedics inc.
Complete Automotive — Repair & Maintenance

FOR YOUR CAR'S HEALTH

NAPA AUTOCARE CENTER · ASE CERTIFIED · ASA AUTOMOTIVE SERVICE ASSOCIATION MEMBER · BBB ACCREDITED BUSINESS · AAA Approved Auto Repair

Repair Order # 0078857
Date: 7/20/2016
Page: 1

Customer:	[redacted]	**Vehicle:**	1964 ROLL SILVER CLOUD 3
Address:		**License:**	CLOUDIX **UNIT:**
City:	60007-	**VIN:**	LSFU223
CELL:		**Engine:**	V8 - 283 **Trans:** AUTO
WORK:		**Mileage:**	85750 **P/D:**

Op	Tech	Description / Qty	Part Number	Part Description	Part Price	Labor	Parts	Subtotal
MS	001	02	CUSTOMER STATES.shakes above 55 mph,check tires and balance ..... CHECK FOR EXHAUST LEAK ..... PUT IN NOTES ..... BEFORE SHUTING THE VEHICLE OFF, YOU MUST DEPRESS THE BRAKE, APPLY E BRAKE, PUT THE CAR IN REVERSE, SHUT THE CAR OFF, PUT THE CAR IN NEAUTRAL ..... THERE IS NO PARK **********			0.00		
TW	005	057	ROTATE AND COMPUTER BALANCE TIRES (4),SET TIRE PRESSURE TO SPECS, CHECK BRAKES,AND TORQUE LUG NUTS TO MANUFACTURES SPECS.			0.00		
CS	000	057	FRONT END/REAR END INSPECTION:CHECK STEERING AND SUSPENSION FOR WORN PARTS AND THE TECHNICIAN FOUND ..... REAR LEAF SPRING BUSHINGS EXTREEMLY WORN AND FALLING APART, REAR SPRING TO SHACKLE AND SHACKLE TO FRAME BOLTS ARE LOOSE AND THREADS ARE DAMAGED AND WORN OUT ..... TECHNICIAN ALSO FOUND IDLER ARM IS ALSO WORN ..... RECOMMEND REMOVE REAR LEAF SPRINGS AND INSTALL NEW FRONT AND REAR BUSHINGS AND HARDWARE, REPLACE IDLER ARM, GREASE ALL GREASE FITTINGS, ALIGNMENT, AND TEST DRIVE VEHICLE ..... TECHNICIAN DID FIND SLIGHT PLAY IN BOTH FRONT KING PINS AND SLIGHT PLAY IN THE UPPER CONTROL ARM TO KNUCKLE BUSHINGS.			121.25		121.25
BR	000	057	BRAKE INSPECTION,AND ROTATE TIRES (IF NEEDED) INCLUDES:REMOVE ALL FOUR WHEELS AND MEASURE BRAKE PADS,BRAKE ROTOR,AND BRAKE SHOE THICKNESS AND/OR BRAKE DRUM DIAMETER. INSPECT FOR BRAKE FLUID LEAKS.INSPECT BRAKE HOSES AND HARDWARE. SET TIRE PRESSURE TO SPECS,ROAD TEST ..... TECHNICIAN FOUND FRONT UPPER			121.25		121.25

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation

PAID
JUL 20 2016
SCHAUMBURG AUTOMEDICS, INC.

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control.
WARRANTY IS 36 MTH/36,000 MILES, WHICHEVER OCCURS FIRST AND MUST BE PERFORMED BY SCHAUMBURG AUTOMEDICS, INC., UNLESS SPECIFIED OTHERWISE!

CONSUMER RIGHTS NOTICE

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but shall not exceed (1) any price limited estimate or (2) any parts and labor estimate by more than 10%. Additional repairs may not be performed without your consent. You may waive your right to a written estimate and require that you be notified if the price exceeds an amount you have specified.
You may waive your right to an estimate, which gives the motor vehicle repair facility the right to set the price without your permission. Your signature will indicate your selection.
☐ (a) I request an estimate in writing before you begin repairs.
☐ (b) Please proceed with the repairs, but call me for approval before continuing if the price exceeds $.
☐ (c) I do not want an estimate, and you may set the price of repairs.

Signature: _____ Date: _____

	Labor:	$4,860.94
	Parts:	$3,736.62
	Sublet:	$330.00
	Other Fees:	$0.00
	Supplies:	$39.87
	Subtotal:	$8,967.43
	Sales Tax:	$377.65
Paid By:	**Total:**	$9,345.08
Pay Ref:	**Paid:**	$0.00
	Due:	~~$9,345.08~~

9,150.92

SCHAUMBURG AUTOMEDICS, INC.

503 LUNT AVENUE • SCHAUMBURG, IL 60193
Phone (847) 352-2886 • Fax (847) 352-0969
www.schaumburgautomedics.com

FOR YOUR CAR'S HEALTH

...te Automotive –
...& Maintenance

NAPA AUTOCARE CENTER · ASE CERTIFIED · ASA AUTOMOTIVE SERVICE ASSOCIATION MEMBER · BBB ACCREDITED BUSINESS · AAA Approved Auto Repair

Repair Order # 0078857
Date: 7/20/2016
Page: 2

...mer: [redacted]
...dress:
City: IL 60007-
CELL
WORK

Vehicle: 1964 ROLL SILVER CLOUD 3
License: CLOUDIX **UNIT:**
VIN: LSFU223
Engine: V8 - 283 **Trans:** AUTO
Mileage: 85750 **P/D:**

Tech	Description / Qty	Part Number	Part Description	Part Price	Labor	Parts	Subtotal
	WHEEL CYLINDERS TO BE LEAKING ..... PASSENGER SIDE REAR BRAKE SHOES ARE WORN ON THE INNER PART OF THE SHOE TOWARDS THE BACKING PLATE, SHOES ARE WORN ALMOST TO THE RIVIT ..... THE FRONT BRAKES WERE ADJUSTED PROPERLY BUT THE REAR BRAKE ADJUSTMENT WAS VERY LOOSE ..... ALL BRAKE DRUMS HAD A LOT OF BRAKE DUST INSIDE ALL OF THEM ..... TECHNICIAN MEASURED ALL BRAKE DRUM DIAMETERS ..... RECOMMEND REPLACE ALL 4 FRONT WHEEL CYLINDERS, REPLACE REAR BRAKE SHOES, RESURFACE ALL 4 BRAKE DRUMS, CLEAN AND ADJUST FRONT AND REAR BRAKES, BLEED AND FLUSH BRAKE FLUID, TEST DRIVE, AND RECHECK FOR ANY OTHER BRAKE ISSUES.						
SU 005 053	MACHINE SHOP SERVICE: MEASURE ALL BRAKE DRUM DIAMETERS AND RESURFACE ALL 4 BRAKE DRUMS ..... AFTER MACHINING SPECIFICATIONS: R/F - 11.300 ..... R/R - 11.285 ..... L/F - 11.310 ..... L/R - 11.310			300.00			300.00
EX 005 057	REPAIR EXHAUST LEAK (REMOVE EXHAUST PIPE, CUT OUT THE BAD SECTION, WELD IN A NEW PIPE AND REINSTALL)			424.38			424.38
BR 001 057	CLEAN & ADJUST FRONT AND REAR BRAKES,INSTALL CHAMFER EDGE ON BRAKE SHOES,ROAD TEST,INCLUDES ROTATE TIRES & SET TIRE PRESSURE.(MOST CARS) ..... MUST ADJUST REAR BRAKES, TEST DRIVE VEHICLE TO BREAK IN REAR SHOES TO DRUMS, ADJUST REAR BRAKES FOR A SECOND TIME AND TEST DRIVE AGAIN.			303.13			303.13
BR 0 055	REPLACE 4 FRONT WHEEL CYLINDERS				727.50	1230.76	1958.26

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control.
WARRANTY IS 36 MTH/36,000 MILES, WHICHEVER OCCURS FIRST AND MUST BE PERFORMED BY SCHAUMBURG AUTOMEDICS, INC., UNLESS SPECIFIED OTHERWISE!

CONSUMER RIGHTS NOTICE

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but shall not exceed (1) any price limited estimate or (2) any parts and labor estimate by more than 10%. Additional repairs may not be performed without your consent. You may waive your right to a written estimate and require that you be notified if the price exceeds an amount you have specified.
You may waive your right to an estimate, which gives the motor vehicle repair facility the right to set the price without your permission. Your signature will indicate your selection.

- ☐ (a) I request an estimate in writing before you begin repairs.
- ☐ (b) Please proceed with the repairs, but call me for approval before continuing if the price exceeds $.
- ☐ (c) I do not want an estimate, and you may set the price of repairs.

Signature: _____ Date: _____

	Labor:	$4,860.94
	Parts:	$3,736.62
	Sublet:	$330.00
	Other Fees:	$0.00
	Supplies:	$39.87
	Subtotal:	$8,967.43
	Sales Tax:	$377.65
Paid By:	**Total:**	$9,345.08
Pay Ref:	**Paid:**	$0.00
	Due:	$9,345.08

SCHAUMBURG AUTOMEDICS, INC.

503 LUNT AVENUE • SCHAUMBURG, IL 60193
Phone (847) 352-2886 • Fax (847) 352-0969
www.schaumburgautomedics.com

Automotive – Maintenance

FOR YOUR CAR'S HEALTH

NAPA AUTOCARE CENTER · ASE CERTIFIED · ASA AUTOMOTIVE SERVICE ASSOCIATION MEMBER · BBB ACCREDITED BUSINESS · AAA Approved Auto Repair

Repair Order # 0078857
Date: 7/20/2016

[redacted]

Vehicle: 1964 ROLL SILVER CLOUD 3
License: CLOUDIX UNIT:
VIN: LSFU223
Engine: V8 - 283 Trans: AUTO
Mileage: 85750 P/D:

Tech	Description	Qty	Part Number	Part Description	Part Price	Labor	Parts	Subtotal
		4.00	WHEELCYLINDER	FRONT WHEEL CYLINDER	1230.76			
030	057			REPLACE REAR BRAKE SHOES,CLEAN & LUBE BACKING PLATES,ADJUST BRAKES & ROAD TEST. (MOST CARS)		424.38	461.54	885.92
		1.00	BRAKESHOES	REAR BRAKE SHOES (SET C	461.54			
004	057			FLUSH AND BLEED BRAKE FLUID SYSTEM AND INSPECT HYDRAULIC SYSTEM,ROAD TEST.		303.13	74.04	377.17
		2.00	GS720	BRAKE FLUID DOT4	52.00			
		4.00	6858	BRAKE BLEEDER SCREW	22.04			
CS 007	057			IDLER ARM, RENEW		303.13	102.86	405.99
		2.00	IDLERKIT	IDLER ARM KIT	102.86			
CS 005	057			REPLACE STABILIZER BAR BUSHINGS (ALL 3)		363.75	249.99	613.74
		3.00	SWBARBUSHING		249.99			
CS 0	057			INSTALL REAR LEAF SPRING BUSHINGS AND HARDWARE		1539.88	1600.00	3139.88
		4.00	FLEAFBUSHING	FRONT LEAF SPRING BUSHI	984.60			
		4.00	RLEAFSPRINGBUSHING	REAR LEAF SPRING BUSHIN	615.40			
AL 002	057			FRONT END ALIGNMENT - INCLUDES:SETTING MINOR CAMBER/CASTER ADJUSTMENT(S) & TOE-IN, & ROAD TEST. (MOST CARS) ..... TIE ROD REMOVAL WAS NECESSARY TO ADJUST FRONT TOE ..... FRONT CAMBER IS MAXIMUM ADJUSTED CROSS CAMBER IS .4 DEGREES.		363.75		363.75
CS 0	057			GREASE ALL GREASE FITTINGS, FRONT STEERING LINKAGE, DRIVESHAFT UJOINTS, CONTROL ARM BUSHINGS, KING PINS ..... CHECK ALL FLUID LEVELS, POWER STEERING		121.25	17.43	138.68

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control.
WARRANTY IS 36 MTH/36,000 MILES, WHICHEVER OCCURS FIRST AND MUST BE PERFORMED BY SCHAUMBURG AUTOMEDICS, INC., UNLESS SPECIFIED OTHERWISE!

CONSUMER RIGHTS NOTICE

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but shall not exceed (1) any price limited estimate or (2) any parts and labor estimate by more than 10%. Additional repairs may not be performed without your consent. You may waive your right to a written estimate and require that you be notified if the price exceeds an amount you have specified.
You may waive your right to an estimate, which gives the motor vehicle repair facility the right to set the price without your permission. Your signature will indicate your selection.

☐ (a) I request an estimate in writing before you begin repairs.
☐ (b) Please proceed with the repairs, but call me for approval before continuing if the price exceeds $.
☐ (c) I do not want an estimate, and you may set the price of repairs.

Signature: _____ Date: _____

	Labor:	$4,860.94
	Parts:	$3,736.62
	Sublet:	$330.00
	Other Fees:	$0.00
	Supplies:	$39.87
	Subtotal:	$8,967.43
	Sales Tax:	$377.65
Paid By:	Total:	$9,345.08
Pay Ref:	Paid:	$0.00
	Due:	$9,345.08

SCHAUMBURG AUTOMEDICS, INC.

503 LUNT AVENUE • SCHAUMBURG, IL 60193
Phone (847) 352-2886 • Fax (847) 352-0969
www.schaumburgautomedics.com

FOR YOUR CAR'S HEALTH

Repair Order # 0078857
Date: 7/20/2016
Page: 4

[redacted]
60007-

Vehicle:	1964 ROLL SILVER CLOUD 3		
License:	CLOUDIX	**UNIT:**	
VIN:	LSFU223		
Engine:	V8 - 283	**Trans:**	AUTO
Mileage:	85750	**P/D:**	

ch	Description Qty	Part Number	Part Description	Part Price	Labor	Parts	Subtotal
	FLUID WAS LOW, REAR SHOCKS WERE LOW, COOLANT WAS LOW, ALL OTHER FLUIDS WERE FULL. ALL FLUID WERE ADDED TO THAT WERE LOW.						
	1.00	ATFMG	PETRA MULTGRADE	6.95			
	0.50	10101	GLOBAL-COOLANT	10.48			
053	FUEL				30.00		30.00
05	THERE IS A CHATTERING IN THE BRAKE ASSIST SERVO OFF THE SIDE OF THE TRANSMISSION THAT OCCURS AT THE VERY END OF BRAKING. TRANSMISSION FLUID IS LEAKING INTO THE BRAKE ASSIST SERVO CAUSING THE FRICTION MATERIAL TO GLAZE, MUST REMOVE SERVO FOR INSPECTION AND REPLACE SEALS ON TRANSMISSION TO STOP FLUID FROM LEAKING INTO SERVO.				0.00		
				Discount -255.84		0.00	-255.84

450.00

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation

ereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you d/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at ur discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible damage or articles left in car in case of fire, theft or any other cause beyond our control.
ARRANTY IS 36 MTH/36,000 MILES, WHICHEVER OCCURS FIRST AND MUST BE PERFORMED BY CHAUMBURG AUTOMEDICS, INC., UNLESS SPECIFIED OTHERWISE!

CONSUMER RIGHTS NOTICE

u are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the es- nate, but shall not exceed (1) any price limited estimate or (2) any parts and labor estimate by more than 10%. ditional repairs may not be performed without your consent. You may waive your right to a written estimate and ire that you be notified if the price exceeds an amount you have specified.
u may waive your right to an estimate, which gives the motor vehicle repair facility the right to set the price hout your permission. Your signature will indicate your selection.
(a) I request an estimate in writing before you begin repairs.
(b) Please proceed with the repairs, but call me for approval before continuing if the price exceeds $
(c) I do not want an estimate, and you may set the price of repairs.

gnature: _____ Date: _____

	Labor:	$4,860.94
	Parts:	$3,736.62
	Sublet:	$330.00
	Other Fees:	$0.00
	Supplies:	$39.87
	Subtotal:	$8,967.43
	Sales Tax:	$377.65
Paid By:	**Total:**	$9,345.08
Pay Ref:	**Paid:**	$0.00
	Due:	$9,345.08

SCHAUMBURG AUTOMEDICS, INC.

503 LUNT AVENUE • SCHAUMBURG, IL 60193
Phone (847) 352-2886 • Fax (847) 352-0969
www.schaumburgautomedics.com

Schaumburg Automedics inc.
Complete Automotive – Repair & M[redacted]e

FOR YOUR CAR'S HEALTH

NAPA AUTOCARE CENTER · ASE CERTIFIED · ASA AUTOMOTIVE SERVICE ASSOCIATION® MEMBER · BBB ACCREDITED BUSINESS · AAA Approved Auto Repair

Repair Order # 0077101
Date: 8/12/2015
Page: 1

Customer:	[redacted]	**Vehicle:**	1964 ROLL SILVER CLOUD 3		
Address:		**License:**	CLOUDIX	**UNIT:**	
City:	0007-	**VIN:**	LSFU223		
CELL:		**Engine:**	V8 - 283	**Trans:**	AUTO
WORK:		**Mileage:**	85533	**P/D:**	

Op	Tech	Description / Qty	Part Number	Part Description	Part Price	Labor	Parts	Subtotal
		Service Requests: WAITING.... 4 TIRES.....ALIGNMENT						
MS	001	055 CUSTOMER STATES HE WOULD LIKE HIS TIRES MOUNTED AND BALANCED				0.00		
TW	002	051 MOUNT & COMPUTER BALANCE TIRE(S),CLEAN RIM,USE BEAD SEALER AND REPLACE VALVE STEM IF NEEDED, 5 TIRES.				158.25	21.40	179.65
		5.00	90415	VALVE STEMS	21.40			
AL	005	046 RACK & SET-UP FRONT END MACHINE & CHECK FRONT ALIGNMENT READINGS.VEHICLE WITHIN SPECS.				29.95		29.95

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation

Pd W/ CC
& COMBINED W/ PREVIOUS B/O

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control.
WARRANTY IS 36 MTH/36,000 MILES, WHICHEVER OCCURS FIRST AND MUST BE PERFORMED BY SCHAUMBURG AUTOMEDICS, INC., UNLESS SPECIFIED OTHERWISE!

CONSUMER RIGHTS NOTICE

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but shall not exceed (1) any price limited estimate or (2) any parts and labor estimate by more than 10%. Additional repairs may not be performed without your consent. You may waive your right to a written estimate and require that you be notified if the price exceeds an amount you have specified.
You may waive your right to an estimate, which gives the motor vehicle repair facility the right to set the price without your permission. Your signature will indicate your selection.
☐ (a) I request an estimate in writing before you begin repairs.
☐ (b) Please proceed with the repairs, but call me for approval before continuing if the price exceeds $
☐ (c) I do not want an estimate, and you may set the price of repairs.

Signature:_____ Date: _____

Labor:	$188.20
Parts:	$21.40
Sublet:	$0.00
Other Fees:	$0.00
Supplies:	$5.00
Subtotal:	$214.60
Sales Tax:	$2.38
Paid By: **Total:**	$216.98
Pay Ref: **Paid:**	$0.00
Due:	$216.98

SCHAUMBURG AUTOMEDICS, INC
503 Lunt Avenue
Schaumburg, IL 60193
847-352-2886

3/12/15 3:08 PM

Rolls Royce : Silver Cloud : 1963-66 (Silver Cloud III)

Front : Left

ıal	Before	Specified Range
°	0.1°	0.0° 0.5°
°	1.0°	0.5° 1.5°
2°*	-0.02°*	0.06° 0.13°
)°	5.0°	
)°	5.1°	

	Front : Right		
	Actual	Before	Specified Range
Camber	-1.2°*	-1.2°*	0.0° 0.5°
Caster	1.1°	1.1°	0.5° 1.5°
Toe	0.04°*	0.03°*	0.06° 0.13°
SAI	4.5°	4.5°	
Included Angle	3.3°	3.3°	
Turning Angle Diff.			

Front

	Actual	Before	Specified Range
Cross Camber	1.3°	1.3°	
Cross Caster	-0.2°	-0.2°	
Cross SAI	0.5°	0.5°	
Total Toe	0.02°*	0.01°*	0.12° 0.25°
Cross Turn Diff.			

Rear : Left

Actual	Before	Specified Range
-0.2°	-0.2°	
0.03°	0.04°	

	Rear : Right		
	Actual	Before	Specified Range
Camber	-0.3°	-0.3°	
Toe	-0.01°	0.00°	

Rear

	Actual	Before	Specified Range
Cross Camber	0.1°	0.1°	-0.5° 0.5°
Total Toe	0.02°	0.04°	
Thrust Angle	0.02°	0.02°	

* This value is not within specification. Tire wear, handling and safety problems may result.

INVOICE

Coker Tire Company
1317 Chestnut Street
Chattanooga, TN 37402-4418
(423) 265-6368

INVOICE	
10552049	
Invoice Date	Page
7/30/2015 14:15:17	1 of 2
ORDER NUMBER	
2075778	

Bill To:
[redacted]

Ship To:
[redacted]

Customer ID: 381024

PO Number	*Pick Ticket No*	*Order Date*	*Customer Service Representative*
	1604070	7/30/2015 10:49:58	MATTW

Ordered	*Shipped*	*Remaining*	*Disp.*	*Item ID*	*Item Description*	*Type*	*Unit Price*	*Extended Price*
					Order Note: for 64 silver cloud 5 820R15 american classic 3 1/4 ww [7/30/2015 11:09:23 - mattw]			
					Carrier: FedEx Ground			
5	5	0		700306	820R15 AMERICAN CLASSIC 3 1/4"WW	1.0	255.00	1,275.00
1	1	0		MATTW	We Appreciate Your Business! It was a pleasure helping you. If I can be of further assistance, please call me at 800-251-6336 ext 271 or email me at MattW@Coker.com.	1.0	0.00	0.00
1	1	0		NETP	SECOND CHANCE TIRE REPLACEMENT PROGRAM Did you know your product qualified for the 5 year Extended Tire Protection plan? It is a great way to protect your investment from road hazards. You have 30 days from your purchase date to protect your tires. Contact your sale representative today.	1.0	0.00	0.00

ORIGINAL

INVOICE

Coker Tire Company
1317 Chestnut Street
Chattanooga, TN 37402-4418
(423) 265-6368

INVOICE	
10552049	
Invoice Date	Page
7/30/2015 14:15:17	2 of 2
ORDER NUMBER	
2075778	

Ordered	Shipped	Remaining	Disp.	Item ID	Item Description	Type	Unit Price	Extended Price

[redacted]

SUB-TOTAL:	1,275.00
SHIPPING AND HANDLING:	106.21
TAX:	0.00
Visa / MC:	1,381.21
AMOUNT DUE:	**0.00**

U.S. Dollars

ORIGINAL

INVOICE

313-277-8577
(12/22/32)

No. 0120

TOM DZICZEK
6801 KINGSBURY
DEARBORN HTS., MI 48127

[redacted]

INVOICE DATE: 8 · 2 · 2013

CUSTOMER'S ORDER NO.:

SOL

SHIP TO:

SALESPERSON	SHIPPED VIA	TERMS	F.O.B.
TOM	UPS		

QTY. ORDERED	QTY. SHIPPED	DESCRIPTION	UNIT	AMOUNT
	2	OIL FILTER KIT LSFU223	27.00	54.00
	1	REVERSE LAMP SWITCH "		97.00
		UPS		13.50

PD 8-19-13
#3086

Thanks Steve

$164.50

adams
812

INVOICE

ALBERS

Family owned & operated since 1963
HJGM, INC.

CREWE
GENUINE PARTS

BENTLEY

BENTLEY ZIONSVILLE
360 SOUTH FIRST STREET
ZIONSVILLE, IN 46077
PH:(317)873-2360 FAX:(317)873-6860
www.bentleyzionsville.com

(317-873-2360 FAX 873-6860)

INVOICE

INVOICE NO. 291358
DATE 09/03/10
CUSTOMER ACCT. NO. MER60048
TELEPHONE NO. (847) 680-0813

BILL TO:

MERRIFIELD RESTORATION
27085 MEADOWWOODS
LANE
METTAWA, IL 60048

SHIP TO:

MERRIFIELD RESTORATION
27085 MEADOWWOODS
LANE
METTAWA, IL 60048

DATE	TIME	BY	CUSTOMER P.O. NUMBER	SPECIAL INSTRUCTIONS
9/3/2010	3:46:23 PM	RP		SO#: 133896 0354852781

TERMS	SHIP VIA
Prepaid	UPS GRD COMMERCIAL

QUANTITY REQUIRED	QUANTITY SHIPPED	QUANTITY B.O.	PART NUMBER	DESCRIPTION	EACH	TOTAL
1	1		UR 431	*SC FUEL FILLER HOSE	191.70	$191.70

Payments Received:	$184.06
Deposits Applied:	$0.00

Subtotal:	$191.70
Discount:	($19.17)
Freight:	$11.53
Misc Charge:	$0.00
Sales Tax:	$0.00
Total:	$0.00

hose 184.06
Gasket 6.00
Labor 175.00
365.00

SEE REVERSE SIDE OF CANARY SHIPPING COPY FOR BUSINESS TERMS

May 11, 2010

[redacted] 1964 Silver Cloud III Saloon - May 11, 2010

Lube Oil Filter	
Oil	26.00
Filter	21.00
Labor	**25.00**
Service Brakes	150.00
Fuel Sender Unit	302.57
Labor	**100.00**
Shipping	11.53
Clean Choke	**50.00**
Total	**$686.10**

Thank you

ALBERS

Family owned & operated since 1963
HJGM, INC.

CREWE
GENUINE PARTS

BENTLEY

BENTLEY ZIONSVILLE
360 SOUTH FIRST STREET
ZIONSVILLE, IN 46077
PH:(317)873-2360 FAX:(317)873-6860
www.bentleyzionsville.com

PAGE: 1

INVOICE

INVOICE NO. 288143
DATE 05/05/10
CUSTOMER ACCT. NO. NUT60045
TELEPHONE NO. (847) 234-3606

BILL TO:

TOM NUTTING SERVICE
365 CHILTERN DR
LAKE FOREST, IL 60045

SHIP TO:

MERRIFIELD RESTORATION
27085 MEADOWWOODS LANE
(847) 680-0813
LIBERTYVILLE, IL 60048

DATE	TIME	BY	CUSTOMER P.O. NUMBER	SPECIAL INSTRUCTIONS
5/5/2010	1:53:03 PM	CW		SO#: 130505 0353609591

TERMS	SHIP VIA
Prepaid	UPS GRD COMMERCIAL

QUANTITY REQUIRED	QUANTITY SHIPPED	QUANTITY B.O.	PART NUMBER	DESCRIPTION	EACH	TOTAL
				LSFU 223		
1	1		UR 358R	FUEL SENDING UNIT- REPRO. (SILVER CLOUD CARS) (PLUS 1-UE73618 GASKET)	299.00	$299.00
1	1		UE 73618	(PQ5) FUEL/OIL SENDER GASKET	3.57	$3.57
						$302.57

MK1 Motorsports

433-3 Plaza Dr
Westmont, Il 60559
630-325-6987

Customer Name: [redacted]

City, St, Zip:

Cell Phone:

REPAIR ORDER No: 1,347

Date: 4/29/2007

Make/Model:	Year:	Color:	VIN No:	License:	Mileage:	Comments
RR CLOUD 3	64	GOLD	LSFU		72,765	

Job:	Tech	Work	Part	Part $	Labor Hr
		LOF, CK REVERSE LIGHTS, REPAIR LOOSE CONNECTION	1)RH10003 $38.78 10)20W50 @$3.89	$77.68	1.50
		CK TRANS FLUID CK SHOCK FLUID, TOP UP CK FOR LEAKS			0.50
		HEATER DOES NOT BLOW HOT AIR; REBUILD UPPER CONTROL FLAP ACTUATOR , REBUILD BOTH WATER VALVE ACTUATORS, REPLACE 1 HEATER HOSE, CHANGE COOLANT	2)A/F @$12.98 1)HOSE $2.95	$15.93	8.00
		LOOSE WASHER HOSE UNDER DASH, OK TIGHTEN JET			0.50
		HARD START AFTER SITTING 5 DAYS , NFF			
		REPLACE BRAKE HOSE AT FRONT RESERVOIR, LEAKING	UR 4988 @ $34.18	$34.18	1.00

PAID

Payment Method | Check No | Date Paid

Drivers License No:

State | Exp. Date: | Date of Birth

Labor Amount:	805.00
Parts Amount:	127.79
Sublet Amount:	4.20
Supplies Amount:	
Total Amount:	$936.99
Adjustments:	
Sales Tax:	$8.63
Please Pay:	**$945.62**

Thank You for choosing
MK1
Motorsports

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose.Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.
CUSTOMER SIGNATURE

X _____

MK1 Motorsports

433-3 Plaza Dr
Westmont, Il 60559
630-325-6987

Customer Name: [redacted]

REPAIR ORDER No: 1,237

Date: 5/8/2006

Make/Model:	Year:	Color:	VIN No:	License:	Mileage:	Comments
RR CLOUD 3			LSFU223			

Job:	Tech	Work	Part	Part $	Labor Hr
		CK RUNNING COND. OK, MADE MINOR ADJUSTMENTS			0.30
		CHANGE TRANS FLUID	5) ATF @2.46	$12.30	1.00
		LOF	10) 20W50 @ 3.37 1) FILTER RH10003 @26.49	$60.19	1.00
		CK A/C & FAN---- REWIRE POWER FEED AND FUSE 1.5 CK HEATER CONTROL KNOBS, --- R+R SWITCH , LUBE 1.3 CK AIR VENTS --ELIMINATED FOR CUSTOM A/C	1)INLINE FUSE @ 2.49	$2.49	2.80
		REPLACE HEATER HOSE, CHANGE COOLANT ,ADD BARS LEAK, SMALL LEAK IN BOTTOM OF RADIATOR	1) BARS LEAK @ 2.98 1) A/F @11.69 1) HOSE @ 1.98	$16.65	1.50
		CK FOR NOISE ON HARD BUMPS-- REPLACE BUSHING IN REAR BRAKE LINKAGE CK FOR GAS LEAK WHEN FULL, NEED TO REMOVE TANK TO FIND LEAK			0.50

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose.Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.
CUSTOMER SIGNATURE

X _____

Payment Method	Check No	Date Paid

Drivers License No:

State	Exp. Date:	Date of Birth

Thank You for choosing
MK1 Motorsports

Labor Amount:	426.00
Parts Amount:	91.63
Sublet Amount:	
Supplies Amount:	
Total Amount:	$517.63
Adjustments:	
Sales Tax:	$6.19
Please Pay:	**$523.82**

INVOICE

[redacted]

pd 6-14-05
#1917

TOM DZICZEK
6801 KINGSBURY
DEARBORN HTS., MI 48127

No. 0052

INVOICE DATE: 6-7-05

CUSTOMER'S ORDER NO.:

SOLD TO:

[redacted]

SHIP TO:

SALESPERSON	SHIPPED VIA	TERMS	F.O.B.
TOM	UPS		

QTY. ORDERED	QTY. SHIPPED	DESCRIPTION	UNIT	AMOUNT
	4	FUEL PIPE NOTCHED GASKETS	$1.50	$6.00
	1	CONDENSER		$24.50
	1	PIGTAIL DISTRIBUTOR		$29.60
		UPS AIR 5-4-05		$12.75
		UPS 4 SAMPLE BYPASS HOSES		$7.25
	2	CARB NEEDLE/SEATS	$19.00	$38.00
		UPS 5-16-05		$7.25
	1	CHOKE SELENOID		$263.00
		UPS 5-24-05		$7.25
	2	OIL FILTERS	$23.00	$46.00
	1	OIL CAP GASKET		$7.75
	2	BRAKE RESERVOIR SEAL KITS	$12.00	$24.00
		UPS 6-7-05		$7.25
		TOTAL		$480.60

adams 812

PARTS INVOICE

CUST NO.	TAX EXEMPT NUMBER	CUST. P. O. NO.	SHIP VIA	PAY	SOLD BY	INVOICE DATE	INVOICE NO.
10114				VISA	KATHY MCKAVIS	05/06/05	94028 RRR

BILL TO

VISA

SHIP TO

[redacted]

PARTS DEPARTMENT HOURS MONDAY - FRIDAY 7:30 AM - 5:00 PM

SHIP QTY	B. O. QTY	PART NUMBER / DESCRIPTION	BIN	LIST	NET	AMOUNT
2	0	CD-3047 CONTACT SET	401	19.94	19.94	39.88

#1872

MAY - 6 2005

20% HANDLING CHARGE ON ALL RETURNS.
NO PARTS RETURNED AFTER 5 DAYS.
NO REFUNDS ON ELECTRICAL OR SPECIAL ORDER PARTS.
NO REFUNDS WITHOUT THIS INVOICE.
NO REFUNDS UNLESS PARTS RETURNED ARE IN ORIGINAL PACKAGE UNDAMAGED.

SUBTOTAL	39.88
TAX	3.30
FREIGHT	0.00
PAY THIS AMOUNT	43.18

NOTICE: ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PARTS.

Copyright © 1998 The Reynolds and Reynolds Company ERAINTPTDE CC8812737 (08/02)

CUSTOMER COPY

STEVE FOLEY Cadillac, Inc.

100 SKOKIE BLVD. • **NORTHBROOK, ILLINOIS 60062** • (847) 564-4090

16:03:59 PAGE 1 OF 1
NET503

INVOICE

[redacted]

No. 0029

TOM DZICZEK
6801 KINGSBURY
DEARBORN HTS., MI 48127

INVOICE DATE
4-13-05

CUSTOMER'S
ORDER NO.

SOLD TO: [redacted]

[redacted] IL [redacted]

SALESPERSON	SHIPPED VIA	TERMS	F.O.B.
TOM	UPS		

QTY. ORDERED	QTY. SHIPPED	DESCRIPTION	UNIT	AMOUNT
	1	UPPER RADIATOR HOSE		$65.00
	1	LOWER " "		$49.75
	1	THERMOSTAT GASKET		$7.00
	1	BY PASS GASKET		$9.00
		UPS		$9.75

PD 4-17-05
2555

Thank You

$140.50

INVOICE

adams

INVOICE

No. 0026

TOM DZICZEK
6801 KINGSBURY
DEARBORN HTS., MI 48127

INVOICE DATE: 4-5-05

CUSTOMER'S ORDER NO.:

SOLD T[redacted]

[redacted]

[redacted]

[redacted]07

[redacted] | SHIPPED VIA | TERMS | F.O.B.

TOM | UPS | |

[redacted]	QTY. SHIPPED	DESCRIPTION	UNIT	AMOUNT
	2	FUEL PUMPS	$168.00	$336.00
		UPS		$9.75
				$345.75

Steve
Let me know the
outcome.
Tom

MASTER ROLLS

VIN#	[redacted]	LIC#	CLOUD IX	DATE	8/25/04
CAR				MILEAGE	69,600
NAME					
ADDRESS					
CITY		STATE	IL	ZIP CODE	60007
PHONE		WORK#		PAGER	

QUAN	DESCRIPTION	PRICE EACH	LABOR	PARTS
1	WELD EXHAUST		$60.00	$0.00
1	CHOKE SYSTEM	$349.40		$349.40
2	FLASHERS	$36.33		$72.66
2	BUSHINGS FOR NOISE IN THE REAR	$17.83	$240.00	$35.66
1	OIL, FILTER, AND LUBE	$85.00		$85.00
1	SEAL FUEL PUMP	$20.20		$20.20
1	TOP UP REAR SHOCKS			$0.00
				$0.00
1	BRAKE FLUID	$10.00		$10.00
				$0.00
	NOTE: HEATER HOSES ARE OLD.			$0.00
	NEEDS LOW PRESSURE HOSES FOR BRAKE RES.			$0.00
	POWER STEERING IS LEAKING.			$0.00
	FUEL LEAK ON TOP OF TANK.			$0.00
	BELTS ARE O.K.			$0.00
	MAJOR TUNE-UP.			$0.00
		TOTAL	PARTS	$572.92
			LABOR	$300.00
			TAX	$48.70
	Hours of labour @ $60 an hour		TOTAL	$921.62

8/27/04

INVOICE#			
CHECK#		TAX	5.50%
DRV'S LIC#			

AUTHORIZATION\RELEASE-READ BEFORE SIGNING

I authorize MASTER ROLLS to perform the above service and install necessary parts. I give MASTER ROLLS and its employees permission to operate the above vehicle for the purpose of testing, inspection and delivery. An express mechanic's lien is hereby acknowledged on the above described vehicle to secure the amount due for storage, service and parts, I release MASTER ROLLS from all responsibility for loss and damages to the above described vehicle, and articles left therein.

I AGREE

To pay, all installments billed and all charges before my vehicle is released.

To pay $50 per day storage charge beginning second day after vehicle is ready.

To pay 1 1/2% interest monthly on my unpaid balance and to pay $100 service charge on my returned checks.

That if I leave my vehicle at MASTER ROLLS for over 30 days after service is completed, MASTER ROLLS may persue its statutory remedies which include selling the vehicle to pay the charges.

To pay MASTER ROLLS reasonable attorney's fees, court and other costs which it incurs to enforce its rights under this agreement.

SIGNATURE: _____.

MASTER ROLLS
5516 W. 110TH ST. UNIT #10
OAK LAWN, IL. 60453
PHONE: 1-708-424-8888
FAX:1-708-424-0245

REPAIR ORDER

VANTAGE MOTOR WORKS, INC.
1898 N.E. 151ST STREET
NORTH MIAMI, FL 33162
(305) 940-1161
FAX (305) 949-7481
MV #05065 MVR #95101388

VANTAGE
1898 NE 151 STREET
N MIAMI, FL 33162
305-940-1161

R/O # : **5385**
Name : VANTAGE
Date : 10/01/2004 2:03 PM
License # : LSFU-223
Make : ROLLS-ROYCE
Model : SILVER CLOUD
Year :
Mileage : 69233 Save Parts : NO
VIN : LSFU-223

LABOR	TECH	HRS	AMOUNT
PREPARE FOR RESALE - SOLD STEVE PARTMAN 5/04			.00
CHECK ALL OPERATIONS FOR DELIVERY	37		.00
REVIEW PAINT & BODY AND CORRECT AS REQUIRED. REMOVE MINOR DINGS. SAND & BUFF.	101		.00
LUBRICATE CHASSIS, CHANGE ENGINE OIL & FILTER LUBRICATE ALL LINKAGES & PIVOTS.	SHOP		.00
REPLACE WIPER BLADES, REPLACE SPARK PLUGS & POINTS, REPLACE ENGINE MOUNTS & GAITERS. CHECK ALL FLUIDS. INSTALL NEW TIRES. INSTALL NEW BATTERY.			.00
REARCH REAR SPRINGS TO PROPER HEIGHT			.00
REBUILD CALIPERS, REPLACE FRONT BRAKE LINES, ADJUST STEERING, CORRECT WIRING FOR HEADLIGHTS.	37		.00
RENEW CARPET	77		.00

PARTS All parts are new unless otherwise specified.		PRICE	QTY	AMOUNT
WILTON CARPET	WILTON CARPET (YARDS) TAN	.00	11	.00
UG13704	FRONT CALIPER BOLT	.00	1	.00
	GAS	.00	1	.00
WIPER REFILLS	WIPER REFILLS	.00	2	.00
TIRES	820x15 BF GOODRICH	.00	4	.00
SPARK PLUGS	SPARK PLUGS	.00	8	.00

REPAIR ORDER

NTAGE MOTOR WORKS, INC.
8 N.E. 151ST STREET
RTH MIAMI, FL 33162
5) 940-1161
X (305) 949-7481
V #05065 MVR #95101388

ANTAGE
898 NE 151 STREET
N MIAMI, FL 33162
05-940-1161

R/O # : **5385** Page : 2
Name : VANTAGE
Date : 10/01/2004 2:03 PM
License # : LSFU-223
Make : ROLLS-ROYCE
Model : SILVER CLOUD
Year :
Mileage : 69233 Save Parts : NO
VIN : LSFU-223

PARTS All parts are new unless otherwise specified.		PRICE	QTY	AMOUNT
OIL FILTER	OIL FILTER S/C II	.00	1	.00
OIL	MOTOR OIL	.00	10	.00
UE3476	REAR MOTOR MOUNTS	.00	2	.00
CD3047	IGNITION POINT	.00	2	.00
GAITERS	GAITERS	.00	1	.00
SRB335	STARTER SOLENOID	.00	1	.00
BATTERY	145 MEGATRON BATTERY	.00	1	.00

SUBLETS	AMOUNT
FLATBED FROM PALM BEACH TO VANTAGE	.00
REMOVE GOLD ON FLYING LADY	.00
TOWING TO AND FROM PRECISION SPRINGS	.00
RELINE BRAKE SHOES	.00
RENEW PINSTRIPE BY HAND	.00

PLEASE READ CAREFULLY. CHECK ONE OF THE STATEMENTS BELOW AND SIGN.
I UNDERSTAND THAT UNDER STATE LAW I AM ENTITLED TO A WRITTEN ESTIMATE. IF MY FINAL BILL WILL EXCEED $100.00

☐ I REQUEST A WRITTEN ESTIMATE.
☐ I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED $_____. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.
☐ I DO NOT REQUEST A WRITTEN ESTIMATE.

LABOR	0.00
PARTS	0.00
SUBLETS	0.00
Environmental Recycling	.00
SUB TOTAL	0.00
TAX	.00
TOTAL	**$ 0.00**

SIGNED X _____ DATE _____

I hereby authorize the above named business to perform the repair work listed above along with necessary materials. You & your employees may operate the above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs. Thereto it is understood that this company assumes no responsibility for loss or damage by theft or fire to vehicles placed with them for storage, sale, repair, or while road testing.

Authorized by :_____ Date :_____

PAGE 1

TAYLOR MOTORS, INC.

256 S.W. 33rd St. • Ft. Lauderdale, FL 33315
954 / 523-2410

NO GUARANTEE ON RUST REPAIRS

NAME [redacted] PHONE NO.	DATE 4-14-04		
	TIME	MAKE ROLLS	YEAR 1964 / BODY STYLE CLOUD III
	VEHICLE I.D. NO. LSFU 223	MILEAGE 04252.	TAG NO. NONE
ADDRESS	PAINT NO.	TRIM NO.	INSUR. CO.
CITY STATE ZIP CODE	PREPARED BY		

RE-PAIR	RE-PLACE	DESCRIPTION OF ESTIMATE	LABOR HRS.	PARTS	TOTAL
	1	BRAKE SERVO ADJUSTMENT TO TIGHT	.50		42 50
	2	D/C PIPE FITTING UNDER LEFT FRONT FENDER LEAKING	?	?	?
	3	FRONT AND REAR BRAKE SHOE'S ARE LESS THAN 1/16" FROM RIVITS	8 00	500 00	1180 00
	4	6 STEERING BALL JOINT BOOTS DAMAGED	4 00	120 00	460 00
	5	LEFT REAR INDICATOR BULB OUT	N/C	3 00	3 00
	6	GAS FILLER DOOR INOP.	?	?	?
	7	2ND TO 3RD GEARCHANGE NEEDS ADJUSTMENT.	?	?	?
	8	WINDSCREEN WASHERS INOP	?	?	?

Other Authorized Person Phone

Proposed Complete Date

Save Old Parts: Yes No (Core may apply)

_____month_____mile warranty on all parts and labor unless otherwise specified.

Intended Payment Method
CASH CHECK VISA MC AMEX

ESTIMATE/ DIAGNOSTIC FEE:

$_____/OR HOURLY AT

$_____ PER HOUR

A STORAGE FEE OF $_____ PER DAY MAY BE APPLIED TO VEHICLES WHICH ARE NOT CLAIMED WITHIN 3 WORKING DAYS OF NOTIFICATION OF COMPLETION.

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN:

I UNDERSTAND THAT, UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE IF MY FINAL BILL WILL EXCEED $100.

_____ I REQUEST A WRITTEN ESTIMATE.

_____ I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED $_____. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.

_____ I DO NOT REQUEST A WRITTEN ESTIMATE.

SIGNED _____ **DATE** _____

REMARKS COMPRESSION TEST A1 A2 A3 A4 B1 B2 B3 B4
135 135 140 135 135 135 135 130.

SHOP CHARGES	AMOUNT
BATTERY [s.403.7185] $1.50	
TIRE [s.403.718] $1.00	
WASTE OIL DISPOSAL $4.00	
WASTE OIL FILTER DISPOSAL $1.00	
SHOP SUPPLIES $5.00	

"This charge represents costs and profits to the motor repair facility for miscellaneous shop supplies or waste disposal." [s.559.904(4)]

_____ HRS. OF LABOR @ _____ PER HR.

GROSS PARTS _____ LESS DISC. _____% NET PARTS

THIS ESTIMATE IS BASED ON OUR INSPECTION AND DOES NOT COVER ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS BEEN STARTED. AFTER THE WORK HAS STARTED, WORN OR DAMAGED PARTS WHICH ARE NOT EVIDENT ON FIRST INSPECTION MAY BE DISCOVERED. NATURALLY THIS ESTIMATE CANNOT COVER SUCH CONTINGENCIES. PARTS PRICES SUBJECT TO CHANGE WITHOUT NOTICE. THIS ESTIMATE IS FOR IMMEDIATE ACCEPTANCE.

PAINT MATERIALS	
TOTAL SHOP CHARGE	
SUBLET	
SUBTOTAL	
SALES TAX	
ESTIMATE TOTAL	

ESTIMATE OF REPAIR

PAGE 2

TAYLOR MOTORS, INC.

256 S.W. 33rd St. • Ft. Lauderdale, FL 33315
954 / 523-2410

DATE 4-14-04

NO GUARANTEE ON RUST REPAIRS

TIME	MAKE ROLLS	YEAR 1964	BODY STYLE CLOUD III
NAME [redacted] PHONE NO. [redacted]81	VEHICLE I.D. NO. LSFU 223	MILEAGE 04252.	TAG NO. NONE
ADDRESS	PAINT NO.	TRIM NO.	INSUR. CO.
CITY STATE ZIP CODE	PREPARED BY		

RE-PAIR	RE-PLACE	DESCRIPTION OF ESTIMATE	LABOR HRS.	PARTS	TOTAL
	(9)	A/C COMPRESSOR HAS BEEN UPGRADED & SYSTEM HAS 134A FREON.			
	(10)	ALTERNATOR CONVERTION HAS BEEN DONE.			
	(11)	CAR HAS 5 NEW TIRES			
	(12)	" " NEW STAINLESS STEEL TAILPIPE & BOX			
	(13)	LEATHER IS VERY GOOD, BACK SEAT LIKE NEW			
	(14)	HEADLINER LOOKS NEW			
	(15)	ALL WOOD IN THE CAR IS VERY GOOD			
	(16)	PAINT JOB IS GOOD			
	(17)	UNDERSIDE OF CAR & CHASSIS HAS BEED STEAM CLEANED. COULD USE SOME BLACK PAINT.			

Other Authorized Person Phone

Proposed Complete Date

Save Old Parts: Yes No (Core may apply)

_____month_____mile warranty on all parts and labor unless otherwise specified.

Intended Payment Method
CASH CHECK VISA MC AMEX

ESTIMATE/ DIAGNOSTIC FEE:

$_____/OR HOURLY AT

$_____ PER HOUR

A STORAGE FEE OF $_____ PER DAY MAY BE APPLIED TO VEHICLES WHICH ARE NOT CLAIMED WITHIN 3 WORKING DAYS OF NOTIFICATION OF COMPLETION.

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN:

I UNDERSTAND THAT, UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE IF MY FINAL BILL WILL EXCEED $100.

_____ **I REQUEST A WRITTEN ESTIMATE.**

_____ **I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED $_____. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.**

_____ **I DO NOT REQUEST A WRITTEN ESTIMATE.**

SIGNED _____ **DATE** _____

REMARKS

SHOP CHARGES	AMOUNT
BATTERY [s.403.7185] $1.50	
TIRE [s.403.718] $1.00	
WASTE OIL DISPOSAL $4.00	
WASTE OIL FILTER DISPOSAL $1.00	
SHOP SUPPLIES $5.00	

"This charge represents costs and profits to the motor repair facility for miscellaneous shop supplies or waste disposal." [s.559.904(4)]

_____ HRS. OF LABOR @ _____ PER HR.

GROSS PARTS _____ LESS DISC. _____% NET PARTS

THIS ESTIMATE IS BASED ON OUR INSPECTION AND DOES NOT COVER ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS BEEN STARTED. AFTER THE WORK HAS STARTED, WORN OR DAMAGED PARTS WHICH ARE NOT EVIDENT ON FIRST INSPECTION MAY BE DISCOVERED. NATURALLY THIS ESTIMATE CANNOT COVER SUCH CONTINGENCIES. PARTS PRICES SUBJECT TO CHANGE WITHOUT NOTICE. THIS ESTIMATE IS FOR IMMEDIATE ACCEPTANCE.

PAINT MATERIALS	
TOTAL SHOP CHARGE	
SUBLET	
SUBTOTAL	
SALES TAX	
ESTIMATE TOTAL	

ESTIMATE OF REPAIR

TAYLOR MOTORS, INC. PAGE 3

256 S.W. 33rd St. • Ft. Lauderdale, FL 33315
954 / 523-2410

DATE 4-14-04

NO GUARANTEE ON RUST REPAIRS

NAME [redacted]

ADDRESS

CITY STATE ZIP CODE

TIME

MAKE ROLLS

YEAR 1964

BODY STYLE CLOUD III

VEHICLE I.D. NO. LSFU 223

MILEAGE 04252.

TAG NO. NONE

PAINT NO.

TRIM NO.

INSUR. CO.

PREPARED BY

REPAIR	REPLACE	DESCRIPTION OF ESTIMATE	LABOR HRS.	PARTS	TOTAL
	18	ENGINE HAS BEEN STEAM CLEANED			
	19	NO NIOSE IN ENGINE AT THIS TIME			
	20	ALL ELECTRIC. WINDOW ARE WORKING			
	21	ALL JACKING EQUIPMENT IS THERE & IN GOOD CONDITION.			
	22	HAND TOOL KIT IN TRUNK IS THERE & IN GOOD CONDITION			
	23	ALL DOOR SEALS & TRUNK SEAL IN GOOD CONDITION.			
	24	PINSTRIP ON HOOD COULD USE TOUCH UP.			

Other Authorized Person Phone

Proposed Complete Date

Leave Old Parts: Yes No (Core may apply)

_____month_____mile warranty on all parts and labor unless otherwise specified.

Intended Payment Method
CASH CHECK VISA MC AMEX

ESTIMATE/ DIAGNOSTIC FEE:

$_____/OR HOURLY AT

$_____ PER HOUR

A STORAGE FEE OF $_____ PER DAY MAY BE APPLIED TO VEHICLES WHICH ARE NOT CLAIMED WITHIN 3 WORKING DAYS OF NOTIFICATION OF COMPLETION.

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN:

I UNDERSTAND THAT, UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE IF MY FINAL BILL WILL EXCEED $100.

_____ **I REQUEST A WRITTEN ESTIMATE.**

_____ **I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED $_____. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.**

_____ **I DO NOT REQUEST A WRITTEN ESTIMATE.**

SIGNED _____ **DATE** _____

REMARKS

SHOP CHARGES	AMOUNT
BATTERY [s.403.7185] $1.50	
TIRE [s.403.718] $1.00	
WASTE OIL DISPOSAL $4.00	
WASTE OIL FILTER DISPOSAL $1.00	
SHOP SUPPLIES $5.00	

"This charge represents costs and profits to the motor repair facility for miscellaneous shop supplies or waste disposal." [s.559.904(4)]

_____ HRS. OF LABOR @ _____ PER HR.

GROSS PARTS _____ LESS DISC. _____% NET PARTS

THIS ESTIMATE IS BASED ON OUR INSPECTION AND DOES NOT COVER ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS BEEN STARTED. AFTER THE WORK HAS STARTED, WORN OR DAMAGED PARTS WHICH ARE NOT EVIDENT ON FIRST INSPECTION MAY BE DISCOVERED. NATURALLY THIS ESTIMATE CANNOT COVER SUCH CONTINGENCIES. PARTS PRICES SUBJECT TO CHANGE WITHOUT NOTICE. THIS ESTIMATE IS FOR IMMEDIATE ACCEPTANCE.

PAINT MATERIALS	
TOTAL SHOP CHARGE	
SUBLET	
SUBTOTAL	
SALES TAX	
ESTIMATE TOTAL	

ESTIMATE OF REPAIR

PLEAS EAD CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN:

I UNDERSTAND THAT, UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE IF MY FINAL BILL WILL EXCEED $100.

____ I REQUEST A WRITTEN ESTIMATE.

____ I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED $_____. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.

____ I DO NOT REQUEST A WRITTEN ESTIMATE.

SIGNED:_____ DATE:_____

*U/Used R/Rebuilt RC/Reconditioned NC/ No Chg/Warranty RD/Reduced/Warranty

QTY	PART NO	DESCRIPTION	*	PRICE	EXTEND

TAYLOR MOTORS, INC.
256 S.W. 33rd Street
Ft. Lauderdale, FL 33315
954 / 523-2410
ROLLS ROYCE & BENTLEY SPECIALISTS
Reg.# MV 19085

____month/_____mile warr. on all parts and labor unless otherwise specified.

Intended Payment Method
(CASH CHECK VISA MC AMEX)

Proposed Complete Date

Name: [redacted]

H[redacted]

Address:

Work Ph.

City State: Zip:

Date 4-14-04 Time

Other Authorized Person.

<Phone>

Year/Make 1964 Rols Model Cloud III

Tag NONE

Miles In 04252.

Save Old Parts: Yes No (One may apply)

Miles Out

Customer Complaint/Problem:

VIN # LSFU 223

LABOR CHARGES BASED ON:
( ) FLAT RATE_____ ( ) HOURLY RATE_____
( ) BOTH APPLY_____

ESTIMATE/DIAGNOSTIC FEE:
$_____ /OR HOURLY AT
$_____ PER HOUR

A STORAGE FEE OF $_____ PER DAY MAY BE APPLIED TO VEHICLES WHICH ARE NOT CLAIMED WITHIN 3 WORKING DAYS OF NOTIFICATION OF COMPLETION

The following repairs were made to your vehicle	Labor Charge
(1) CARRY OUT TEST & REPORT ON 1964 CLOUD III CHASSIS # LSFU 223. INCLUDING A COMPRESSION TEST.	2.50 HRS 212.50
NOTE THIS IS A VERY NICE CLEAN CAR.	

ESTIMATED REPAIR COST/SHOP SUPPLIES
$:

CHARGES:

PARTS: $

LABOR: $212.50

SUBLET/ OTHER $

**SHOP SUPPLIES $

***FEES $

Subtotal: $ 212.50

Tax: $ 12.75

TOTAL: $225.25

*This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal. **FS403 718 mandates a $1.00 fee for each new tire sold in the State of Florida. ***FS403 7185 mandates a $1.50 fee for each new or remanufactured battery sold in the State of Florida.

Estimate good for 30 days. Not responsible for damage caused by theft, fire or acts of nature. I hereby authorize the above repairs, including sublet work, along with the necessary materials. You and your employees may operate my vehicle for the purpose of testing, inspection and delivery at my risk. If I cancel repairs prior to their completion for any reason, a teardown and reassembly fee of $_____ will be applied.

X _____ Date _____

FROM : TAYLOR-MOTORS FAX NO. : 9545232410 Apr. 15 2004 08:57AM P5

INVOICE

INVOICE NO: 9611
INVOICE DATE: 05/08/01

[redacted]

FOREIGN CAR ENGINEERING
75 N. CONGRESS AVENUE
DELRAY BEACH, FL. 33445

TEL:(561) 276-0114 ~ FAX: (561) 274-9127

YEAR~MAKE	MODEL	TAG#	MILES	VIN#
1964 ROLLS ROYCE	SILVER CLOUD III			LSFU223

DESCRIPTION		PARTS	LABOR
PARTS:			
1 MASTER CYLINDER, FRONT - REBUILT		$ 300.00	
1 MASTER CYLINDER, REAR - REBUILT		$ 300.00	
FRONT SHOES, LEFT AND RIGHT - REBUILT	90@4	$ 360.00	
2 WHEEL CYLINDER SEALS, FRONT	18@2	$ 36.00	
2 WHEEL CYLINDER SEALS, REAR	10@2	$ 20.00	
1 TRANSMISSION SERVO - REBUILT		$ 754.10	
1 STEERING BOX REBUILT KIT		$ 154.00	
OIL AND FILTER		$ 45.00	
FLUSH COOLING SYSTEM AND RENEW		$ 75.00	
1 USED STEERING BOX, FOR PARTS		$ 490.00	
REFACE DRUMS	85@4	$ 340.00	
4 WHEEL BEARINGS	65@4	$ 260.00	
2 WHEEL BEARING SEALS	27@2	$ 54.00	
1 WATER PUMP - REBUILT		$ 770.00	
1 CARBURATOR KIT, LEFT AND RIGHT		$ 95.00	
LABOR:			
REMOVE & RENEW MOTOR AND SLAVE CYLINDERS, REPAIR RODS AND MOUNTING BRACKET	55@7		$ 385.00
REMOVE & RENEW FRONT BRAKE SHOES ASSBLY, REBUILT FRONT WHEEL CYLINDERS, LEFT AND RIGHT	55@8		$ 440.00
		SUBTOTAL:	
		SALES TAX @ 6.000%:	
		TOTAL:	

1323
1324

INVOICE

INVOICE NO: 9611
INVOICE DATE: 05/08/01

[redacted]

FOREIGN CAR ENGINEERING
75 N. CONGRESS AVENUE
DELRAY BEACH, FL. 33445

TEL: (561) 276-0114 ~ FAX: (561)274-9127

YEAR~MAKE	MODEL	TAG#	MILES	VIN#
1964 ROLLS ROYCE	SILVER CLOUD III			LSFU223

DESCRIPTION		PARTS	LABOR
REMOVE AND RECONDITION REAR BRAKE SHOES, REBUILD REAR WHEEL CYLINDERS, ADJUST EMERGENCY BRAKE SYSTEM, ADJUST ALL LINKAGES FOR BRAKING SYSTEM	55@10		$ 550.00
REMOVE AND INSTALL STEERING BOX	55@4		$ 220.00
REBUILD STEERING BOX	55@6		$ 330.00
INSTALL FRONT WHEEL BEARINGS, WITH SEALS, REPAIR HUBS	55@4		$ 220.00
FLUSH COOLING SYSTEM, RENEW BYPASS HOSES	55@3		$ 165.00
REMOVE AND RENEW WATER PUMP	55@4.3		$ 236.50
FLUSH OUT GAS TANK			$ 185.00
REBUILD CARBURATOR, SET CHOKE ASSEMBLY, CHECK FUEL LINE, RENEW INTAKE GASKETS	55@9		$ 495.00
REMOVE AND RENEW TRANS AXEL, FLUSH AND RENEW GEAR OIL			
REMOVE AND RENEW CYLINDER HEAD, RIGHT, REPAIR EX. LEAK, REPAIR MANIFOLD			
TOTAL:		$ 4,053.10	$ 3,226.50
	SUBTOTAL:		$ 7,279.60
	SALES TAX @ 6.00%:		$436.78
	TOTAL:		**$ 7,716.38**

ck 323
324

[redacted]

Trace ID:

CUSTOMER COPY

ALBERS

Family owned & operated since 1963

HJGM, INC.

CARS
alists
ET
73-6860

PAGE: 1

INVOICE

INVOICE NO. 409432
DATE 04/09/25
CUSTOMER ACCT. NO. CLA85022
TELEPHONE NO. (602) 245-7200

SHIP TO:

OMENADE
E CREEK ROAD
, 85022

CLASSIC PROMENADE
13023 N. CAVE CREEK ROAD
PHOENIX, AZ 85022

64 Eg, LSDA III LSFU223

DATE	TIME	BY	CUSTOMER P.O. NUMBER	SPECIAL INSTRUCTIONS
4/9/2025	2:51:44 PM	GA		SO#: 257585 413061015212

TERMS	SHIP VIA
Prepaid	FEDEXP SAVER 3 DAY

QUANTITY REQUIRED	QUANTITY SHIPPED	QUANTITY B.O.	PART NUMBER	DESCRIPTION	EACH	TOTAL
				LSFU223 RR SCIII		
1	1		RD7894R	OIL PSI SENDER- REPRODUCTION (SILVER CLOUD CARS) PLUS SUPPLY 1-UD8017R WASHER	165.58	$165.58
1	1		UD8017R	COPPER WASHER - REPRODUCTION	2.04	$2.04

Subtotal:	$167.62
Discount:	($33.52)
Freight:	$0.00
Misc Charge:	$0.00
Sales Tax:	$0.00
Total:	$134.10

Payments Received: $134.10
Deposits Applied: $0.00

SEE REVERSE SIDE OF CANARY SHIPPING COPY FOR BUSINESS TERMS