



# Eurocare #212

5345 Hwy 6 S

Missouri City, TX 77459

Phone: 832-612-3535 ~ Fax: 281-969-5460

Email: Eurocare212@eurocareimports.com

Website: www.eurocareimports.com

## Invoice




Plate TX LLG4224  
Description Brown 1983 Porsche 911 SC H6 3.0L 2999CC  
VIN A  
VIN 9117211324  
Odometer 198,907

Invoice # 13035  
Work Order # 15843  
Service Advisor Keianna Stewart  
Technician PP

Invoice Date 7/11/2025 4:21 PM  
Appointment 7/7/2025 5:00 PM  
Promised 7/7/2025 5:00 PM

## Concern

### Battery Concern

Customer notes car wont start, car has been sitting and has a fluid leak

Labor			\$0.00 *
		<b>Sub</b>	<b>\$0.00</b>

## Inspection

### Multi Point Inspection

Labor			\$0.00 *
		<b>Sub</b>	<b>\$0.00</b>

## Service

### Valve Cover Gasket(s), Upper & Lower

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor			\$1,349.70 *
Valve Cover Gasket Set Graphite	1 Unit	\$184.82 / Unit	\$184.82 *S
		<b>Sub</b>	<b>\$1,534.52</b>

### Engine Oil Sump Gasket

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor			\$337.42 *
Oil Sump Gasket	1 Unit	\$15.23 / Unit	\$15.23 *S
		<b>Sub</b>	<b>\$352.65</b>

### Lube, Oil & Filter Service - Synthetic Oil

Drain and refill engine oil, change engine oil filter and lubricate chassis grease fittings and friction points as required. Check and top off fluid levels, additional charges may apply where fluids are required. Reset of Computer Maintenance Schedule Complete a complimentary visual vehicle inspection.

Labor			\$0.00 *
OR - 10W30 OIL	11 Unit	\$14.27 / Unit	\$156.98 *S
Oil Filter Spin-On	1 Unit	\$22.49 / Unit	\$22.49 *S
		<b>Sub</b>	<b>\$179.47</b>

### Hood Lift Shock / Support

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor			\$0.00 *
Trunk Strut Rear, Engine Cover	2 Unit	\$66.68 / Unit	\$133.36 *S

**Disc Brake Pads, Rotors & Sensor (Rear)**

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor			\$337.42 *
Brake Pad Set-Rear R90	1 Unit	\$78.27 / Unit	\$78.27 *S
Brake Disc-Rear	2 Unit	\$291.88 / Unit	\$583.76 *S
Rear			
Valvoline - Brake stop squeal	1 Unit	\$19.95 / Unit	\$19.95 *S
		<b>Sub</b>	<b>\$1,019.40</b>

**Coupon**

Loyal Customer  
Labor Discount

	\$0.00 *
Discount	(\$90.00)
<b>Sub</b>	<b>(\$90.00)</b>

---


Total Parts		\$1,194.86
Total Labor		\$1,934.54
Total Before Taxes & Miscellaneous Charges		\$3,129.40
(*) Shop Supplies		\$281.65 S
(S) State Sales Tax	8.25 %	\$121.81
<b>Grand Total</b>		<b>\$3,532.86</b>

Total discounts applied is \$90.00

By signing below, I hereby authorize all of the repair work to be performed on the vehicle identified above, which may include the installation of parts and materials. I hereby authorize Eurocare and its employees to operate and drive the vehicle to the extent it deems necessary to inspect and/or test the vehicle. I acknowledge and agree that you shall not be responsible or liable for damage to or loss of the vehicle or any articles left in the vehicle for any reason except for intentional acts of Eurocare. Unless noted, all repair work shall carry a 60 month/50,000-mile prorated limited warranty. Warranty work shall only be performed by Eurocare. Unauthorized repairs shall not be honored. All refunds shall be in the form of in-store credits only.

I AM THE PERSON OR AGENT ON BEHALF OF THE PERSON RESPONSIBLE TO PAY FOR THE REPAIR OF THE MOTOR VEHICLE SUBJECT TO THIS REPAIR CONTRACT. I UNDERSTAND THIS VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH 9.609 TEXAS BUSINESS & COMMERCE CODE. IF A CHECK, MONEY ORDER OR CREDIT CARD TRANSACTION GIVEN FOR PAYMENT FOR REPAIR ON THE VEHICLE IS STOPPED, DISHONORED FOR LACK OF FUNDS, NO FUNDS OR BECAUSE THE MAKER OR CREDIT CARD HOLDER HAS NO ACCOUNT UPON WHICH IT IS DRAWN OR THE ACCOUNT HAS BEEN CLOSED. I AGREE TO PAY ALL COSTS FOR REPOSSESSION OR LIENS INCLUDING REASONABLE ATTORNEY FEES.

VALUED CUSTOMER      paid \$3,532.86 by Amex



Customer Signature

**Authorization(s)**

7/7/2025 5:14 PM      \$0.00

In Person / Other  
Authorized by





**Eurocare #212**

5345 Hwy 6 S

Missouri City, TX 77459

Phone: 832-612-3535 ~ Fax: 281-969-5460

Email: Eurocare212@eurocareimports.com

Website: www.eurocareimports.com

**Invoice**

Bill To

Mobile  
Email




Plate TX LLG4224  
Description Brown 1983 Porsche 911 SC H6 3.0L 2999CC  
VIN A  
VIN 9117211324  
Odometer 198,844 In / 198,847 Out

Invoice # 10415  
Work Order # 12680  
Service Advisor Kurt Schultz  
Technician PP

Invoice Date 1/31/2024 1:34 PM  
Appointment 1/30/2024 2:36 PM  
Promised 1/30/2024 2:36 PM

**Concern**

**Gauges Concern**

Customer notes the tachometer is not moving a all. It was moving up & down irratically for a while but now has no movement. Check and advise.

Labor

\$0.00 \*

Sub            \$0.00

**Tech Notes**

The tachometer is not moving due to the fuse being blown, 10amp, was replaced with a new fuse & tachometer is now working properly.

**Battery Concern**

Customer notes that the battery is acting up and he has had to remove and recharge the battery to get it to run long enough to get it here. Check and advise.

Labor

\$0.00 \*

Sub            \$0.00

**Tech Notes**

The Charging system is good, Alternator output is about 13.95 vt, the battery test faulty under volts, recommend replace the battery then recheck the Charging system.

**Inspection**

**Multi Point Inspection**

Labor

\$0.00 \*

Sub            \$0.00

**Service**

**Diagnose Gauges / Warning Light Concern**

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

Labor

\$165.00 \*

Sub            \$165.00

**Diagnose Battery Concern**

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

Labor

\$165.00 \*

Sub            \$165.00

**Fuse(s)**

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.



**Eurocare #212**

5345 Hwy 6 S


Missouri City, TX 77459

Phone: 832-612-3535 ~ Fax: 281-969-5460

Email: Eurocare212@eurocareimports.com

Website: www.eurocareimports.com

**Invoice**



Bill To

Mobile  
Email

Plate TX LLG4224  
Description Brown 1983 Porsche 911 SC H6 3.0L 2999CC  
VIN A  
VIN 9117211324  
Odometer 196,542 In / 196,580 Out

Invoice # 6199  
Work Order # 5441  
Service Advisor Kurt Schultz  
Technician Shop

Invoice Date 9/17/2021 3:26 PM  
Appointment 7/13/2020 4:27 PM  
Promised 7/13/2020 4:27 PM

**Service**

**Oil Thermostat**

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Re-test and verify repair as required. Perform final road test where applicable.

Labor			\$300.00 *
Oil Thermostat	1 Unit	\$576.07 / Unit	\$576.07 *S
Motor Oil	3 Unit	\$13.00 / Unit	\$39.00 *S
		<b>Sub</b>	<b>\$915.07</b>

**Customer Fuel**

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Fuel	1 Unit	\$45.00 / Unit	\$45.00 *S
Fuel System Cleaner	1 Unit	\$37.14 / Unit	\$37.14 *S
		<b>Sub</b>	<b>\$82.14</b>

**Belts General Service- Alternator Belt Replacement**

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Labor			\$180.00 *
Drive Belt	1 Unit	\$47.30 / Unit	\$47.30 *S
		<b>Sub</b>	<b>\$227.30</b>

**Fuel Pump Relay Wiring Repair & CSI Identification**

C.S.I. Identification and re-wiring to repair electrical short on fuel pump wires & the repair of the wiring harness relating to the air flap control switch.

Labor			\$1,875.00 *
Fuel Pump Relay	1 Unit	\$55.06 / Unit	\$55.06 *S
Relay Connector	1 Unit	\$92.53 / Unit	\$92.53 *S
		<b>Sub</b>	<b>\$2,022.59</b>

**Engine General Service- Timing & C/O Adjustment**

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Re-test and verify repair as required.

Labor			\$450.00 *
		<b>Sub</b>	<b>\$450.00</b>

**Coupon**

Loyal Customer  
Labor Discount

			\$0.00 *
Discount			(\$100.00)
<b>Sub</b>			<b>(\$100.00)</b>




Total Parts		\$892.10
Total Labor		\$2,705.00
Total Before Taxes & Miscellaneous Charges		<u>\$3,597.10</u>
(*) Shop Supplies*		\$145.32 S
(S) State Sales Tax	8.25 %	<u>\$85.59</u>
<b>Grand Total</b>		<b>\$3,828.01</b>

Total discounts applied is \$100.00

By signing below, I hereby authorize all of the repair work to be performed on the vehicle identified above, which may include the installation of parts and materials. I hereby authorize Eurocare and its employees to operate and drive the vehicle to the extent it deems necessary to inspect and/or test the vehicle. I acknowledge and agree that you shall not be responsible or liable for damage to or loss of the vehicle or any articles left in the vehicle for any reason except for intentional acts of Eurocare. Unless noted, all repair work shall carry a 60 month/50,000-mile prorated limited warranty. Warranty work shall only be performed by Eurocare. Unauthorized repairs shall not be honored. All refunds shall be in the form of in-store credits only.

I AM THE PERSON OR AGENT ON BEHALF OF THE PERSON RESPONSIBLE TO PAY FOR THE REPAIR OF THE MOTOR VEHICLE SUBJECT TO THIS REPAIR CONTRACT. I UNDERSTAND THIS VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH 9.609 TEXAS BUSINESS & COMMERCE CODE. IF A CHECK, MONEY ORDER OR CREDIT CARD TRANSACTION GIVEN FOR PAYMENT FOR REPAIR ON THE VEHICLE IS STOPPED, DISHONORED FOR LACK OF FUNDS, NO FUNDS OR BECAUSE THE MAKER OR CREDIT CARD HOLDER HAS NO ACCOUNT UPON WHICH IT IS DRAWN OR THE ACCOUNT HAS BEEN CLOSED. I AGREE TO PAY ALL COSTS FOR REPOSSESSION OR LIENS INCLUDING REASONABLE ATTORNEY FEES.



Invoice Signature. Signed on 9/17/2021 3:26 PM

Customer Signature



**Eurocare #212**

5345 Hwy 6 S

Missouri City, TX 77459

Phone: 832-612-3535 ~ Fax: 281-969-5460

Email: Eurocare212@eurocareimports.com

Website: www.eurocareimports.com

**Invoice**

Bill To



Mobile  
Email

Plate TX LLG4224

Description Brown 1983 Porsche 911 SC H6 3.0L 2999CC  
VIN A

VIN 9117211324

Odometer 196,389 In / 196,396 Out

Invoice # 3985  
Work Order # 5263  
Service Advisor Kurt Schultz  
Technician AM

Invoice Date 6/5/2020 4:09 PM  
Appointment 5/26/2020 11:58 AM  
Promised 5/26/2020 11:58 AM

**Service**

**Ignition Control Module**

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor

Ignition Control Module

1 Unit

\$1,391.64 / Unit

\$140.00 \*

\$1,391.64 \*S

Sub

**\$1,531.64**

Total Parts

\$1,391.64

Total Labor

\$140.00

Total Before Taxes & Miscellaneous Charges

\$1,531.64

(\*) Shop Supplies

\$137.85 S

(S) State Sales Tax

8.25 %


\$126.18

**Grand Total**

**\$1,795.67**

By signing below, I hereby authorize all of the repair work to be performed on the vehicle identified above, which may include the installation of parts and materials. I hereby authorize Eurocare and its employees to operate and drive the vehicle to the extent it deems necessary to inspect and/or test the vehicle. I acknowledge and agree that you shall not be responsible or liable for damage to or loss of the vehicle or any articles left in the vehicle for any reason except for intentional acts of Eurocare. Unless noted, all repair work shall carry a 36 month/36,000-mile prorated limited warranty. Warranty work shall only be performed by Eurocare. Unauthorized repairs shall not be honored. All refunds shall be in the form of in-store credits only.

I AM THE PERSON OR AGENT ON BEHALF OF THE PERSON RESPONSIBLE TO PAY FOR THE REPAIR OF THE MOTOR VEHICLE SUBJECT TO THIS REPAIR CONTRACT. I UNDERSTAND THIS VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH 9.609 TEXAS BUSINESS & COMMERCE CODE. IF A CHECK, MONEY ORDER OR CREDIT CARD TRANSACTION GIVEN FOR PAYMENT FOR REPAIR ON THE VEHICLE IS STOPPED, DISHONORED FOR LACK OF FUNDS, NO FUNDS OR BECAUSE THE MAKER OR CREDIT CARD HOLDER HAS NO ACCOUNT UPON WHICH IT IS DRAWN OR THE ACCOUNT HAS BEEN CLOSED. I AGREE TO PAY ALL COSTS FOR REPOSSESSION OR LIENS INCLUDING REASONABLE ATTORNEY FEES.



Customer Signature



**Eurocare #212**

5345 Hwy 6 S  
Missouri City, TX 77459

Phone: 832-612-3535 ~ Fax: 281-969-5460

Email: Eurocare212@eurocareimports.com

Website: www.eurocareimports.com

**Invoice**




Plate TX LLG4224  
Description Brown 1983 Porsche 911 SC H6 3.0L 2999CC  
VIN A  
VIN 9117211324  
Odometer 196,351 In / 196,365 Out

Invoice # 3934  
Work Order # 5151  
Service Advisor Kurt Schultz  
Technician TE

Invoice Date 5/20/2020 2:35 PM  
Appointment 4/27/2020 2:38 PM  
Promised 4/27/2020 2:38 PM

**Concern**

**Starting Concern**

Concern? = Customer notes vehicle was difficult to start and required starting fluid. Also died on him on the way here and thinks it may be bad gas due to sitting for a bit. Also note that the vehicle is a 1977 but the engine is a 1983. Check and advise. Customer notes that the oil gauge is always pegged wide open.

Conditions? =

Last Service? =

Labor

\$0.00 \*

Sub \$0.00

**Service**

**Diagnose Driveability Concern (Emission / Fuel / Ignition)**

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

Labor

\$420.00 \*

Sub \$420.00

**Engine General Service**

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor

\$406.00 \*

Auxillary Air Valve

1 Unit \$2,271.46 / Unit

\$2,271.46 \*S

Bosch - Auxiliary Air Device/Regulator

1 Unit \$1,580.00 / Unit

\$1,580.00 \*S

Sub \$4,257.46

**Electrical System General Service- Ignition Lead/Transformer Wire Replacement**

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Labor

\$322.00 \*

Distributor Primary Lead

1 Unit \$101.67 / Unit

\$101.67 \*S

Ignition Coil

1 Unit \$487.31 / Unit

\$487.31 \*S

Sub \$910.98

**Coupon**

VIP Customer Discount

Labor Discount

\$0.00 \*

Discount (\$200.00)

Sub (\$200.00)

Total Parts

\$4,440.44

Total Labor

\$948.00

Total Before Taxes & Miscellaneous Charges

\$5,388.44

(\*) Shop Supplies

\$484.96 S

(S) State Sales Tax

8.25 %


\$406.35

Grand Total

\$6,279.75

By signing below, I hereby authorize all of the repair work to be performed on the vehicle identified above, which may include the installation of parts and materials. I hereby authorize Eurocare and its employees to operate and drive the vehicle to the extent it deems necessary to inspect and/or test the vehicle. I acknowledge and agree that you shall not be responsible or liable for damage to or loss of the vehicle or any articles left in the vehicle for any reason except for intentional acts of Eurocare. Unless noted, all repair work shall carry a 36 month/36,000-mile prorated limited warranty. Warranty work shall only be performed by Eurocare. Unauthorized repairs shall not be honored. All refunds shall be in the form of in-store credits only.


I AM THE PERSON OR AGENT ON BEHALF OF THE PERSON RESPONSIBLE TO PAY FOR THE REPAIR OF THE MOTOR VEHICLE SUBJECT TO THIS REPAIR CONTRACT. I UNDERSTAND THIS VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH 9.609 TEXAS BUSINESS & COMMERECE CODE. IF A CHECK, MONEY ORDER OR CREDIT CARD TRANSACTION GIVEN FOR PAYMENT FOR REPAIR ON THE VEHICLE IS STOPPED, DISHONORED FOR LACK OF FUNDS, NO FUNDS OR BECAUSE THE MAKER OR CREDIT CARD HOLDER HAS NO ACCOUNT UPON WHICH IT IS DRAWN OR THE ACCOUNT HAS BEEN CLOSED. I AGREE TO PAY ALL COSTS FOR REPOSSESSION OR LIENS INCLUDING REASONABLE ATTORNEY FEES.



Customer Signature

Authorization(s)

4/28/2020 8:44 AM \$460.92





**Eurocare #212**

5345 Hwy 6 S

Missouri City, TX 77459


Phone: 832-612-3535 ~ Fax: 281-969-5460

Email: Eurocare212@eurocareimports.com

Website: www.eurocareimports.com

**Deposit Receipt**

Bill To



Mobile  
Email

Work Order # 5151

Plate TX LLG4224

Description Brown 1983 Porsche 911 SC H6 3.0L 2999CC

VIN A

VIN 9117211324


Odometer 0

Appointment 4/27/2020 2:38 PM

Promised 4/27/2020 2:38 PM

Deposit Date	Description	Method	Deposit Amount
5/4/2020 10:07 AM	Parts Deposit	American Express	\$3,294.07

\$3,294.07 paid by American Express



Thanks for the Business!

TEPA AUTO BODY & TOW  
640 Garcia Ave  
Pittsburg, Ca. 94565  
Ph 925 439 0217  
Tax Id 04-3789665  
ARD00239694

# Invoice

Number 1446

Date 12/1/2018

Customer



Vehicle Identification Number

Year	Make	Model	Plate#	Odometer
1977	Porsche	911		

Operation	Description	Hours	Rate	Tax1	Amount
Repair	Exteriro Bodywork	30.00	\$75.00		\$2,250.00
Repair	Door Alignments	2.00	\$75.00		\$150.00
Remove/Insta	Trims	19.00	\$75.00		\$1,425.00
Prep To Paint		20.00	\$75.00		\$1,500.00
Refinish		7.00	\$75.00		\$525.00
Materials			\$625.00		\$625.00
Windshield			\$375.00	✓	\$375.00
Tail Lights			\$425.00		\$425.00

Deposit	\$0.00
Sub Total	\$7,275.00
Sales Tax 9.00% on \$375.00	\$33.75
Amount Due	\$7,308.75
Total	\$7,308.75



The Lambda system does its job by adjusting the duty cycle of the frequency valve, which is plumbed into the lower portion of the fuel distributor control pressure circuit. A new version of the Fuel Distributor was required for this change. If the O2 sensor determines the mixture is too rich, it signals the frequency valve to reduce the duty cycle, which leans the mixture from the fuel distributor. If it is too lean, it increases the duty cycle. If the mixture is spot on (14.7:1 air-to-fuel), the duty cycle to the frequency valve is 50%. Note that the default duty cycle mode for a disconnected or non-operational O2 sensor is also 50%.

The O2 electronics box also has an enrichment function controlled through the throttle switch. This enrichment task is taken over from the vacuum operated WUR in the earlier CIS engines. The O2 sensor was installed with the '80 cars, and the vacuum operated WUR was discontinued. In '81, the O2 electronics were slightly changed from '80 and provided additional enrichment features. The electronics box also provides cold starting warm up enrichment in addition to the cold engine enrichment provided by the WUR.

The cold start enrichment by the Lambda system sets the frequency valve at 65% , overriding the input from the O2 sensor, until the engine temperature reaches 15°C. At temperatures in excess of 15°C, closed loop operation begins and the oxygen sensor takes over. The throttle valve switch also provides enrichment at WOT.

#### **Lambda operation - 1980**

[Space reserved for tables describing the 2 temperature based modes of operation of the '80 Lambda system.]

#### **Lambda operation - 1981 to 1983**

In 1981, an "Enrichment relay" was added to the Lambda control. An additional temperature switch was added at the engine as an input to the Enrichment Relay. The addition of this switch necessitated a change in the engine's wiring harness to the ECU from a 6-pin connector to a 12-pin connector. The additional switch is open until 35°C, and closed above this temperature. The Enrichment Relay operates as a functional part of the ECU to provide transient enrichment stages according to the positions of the throttle switches and engine temperature.

The 3 engine temperature based modes of operation of the '81 - '83 Lambda system are:

[Mode 1: Temperature less than 15°C](#)

[Mode 2: Temperature greater than 15°C but less than 35°C](#)

[Mode 3: Temperature greater than 35°C](#)

Material copyright 2009 - 2012 - Jim Williams