

WALTER'S


AUTO IMPORT REPAIR, INC.
BOSCH SERVICE CENTER

765-474-8645

"Service with a smile, That's our Style"
 Est. 1971

864 State Road 25 West • Lafayette, IN 47909
 1 Block of Intersection 25 South and new 231

NAME _____ DATE OF ORDER Nov. - 13.19
 ADDRESS _____
 CITY _____
 HOME PHONE _____ WORK PHONE _____



QTY.	PART NO. AND DESCRIPTION	AMOUNT	YEAR MAKE AND MODEL	SERIAL NUMBER	LICENSE NUMBER	SPEEDOMETER	DESCRIPTION OF WORK	AMOUNT
1	Camshaft used Rt side 645.00	300.00	04 Merc 380 SL			1095621		
1	Set Camshaft bearings Rt side	200.00					Diagnostic on Engine noise	
8	Rockers arms used Rt side 87.00 (35.00)	280.00					remove both valve covers	
1	Set Camshaft oilers	22.00					found out all rocker arms + camshaft worn Rt side.	NIC *
8	rockers arms used left side 87.00 (35.00)	280.00					Check + replace defect camshaft Rt side + all rocker arms both side.	840.00 *
1	Set Camshaft oilers	22.00					replace all damage camshaft oilers both side, reassemble valve covers both side	
2	valve cover gaskets	33.00						
		1137.00						
			REMARKS	LABOR				840.00
			2056.59 Cam + rockers	PARTS				1137.00
			1813.92 Chain + guide	TOWING CHARGE				
			1915.04 Exh. + starter	MACHINE WORK				
			1491.05 ign. + idle	TIRE DISPOSAL				
			513.09 brakes + A/C	SHIPPING/MISC.				
			7789.69	TIRE FEE				
				TAX				79.59
				HZRDS. MTRLS.				

TOTAL ACCESSORIES

No return on electrical parts and special orders.
 20% restocking charge on all other parts.
 Any car left at Walter's Auto Import Repair, Inc. over 30 days after repairs are completed will be subject to \$15.00 a day storage charge.

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

Thank You

paid

TOTAL ▶ 2056.59

PAY THIS AMOUNT

WALTER'S

IMPORT REPAIR, INC.

SERVICE CENTER

765-474-8645

"Service with a smile, That's our Style"
 Est. 1971
 State Road 25 West • Lafayette, IN 47909
 Block of Intersection 25 South and new 231

DATE OF ORDER
 NOV-13-19

NAME [REDACTED]
 ADDRESS [REDACTED]
 CITY [REDACTED] WORK PHONE [REDACTED]
 HOME PHONE [REDACTED]
 YEAR MAKE AND MODEL 04 MERZ 380 SL
 SPEEDOMETER 109562

QTY.	PART NO. AND DESCRIPTION	AMOUNT	SERIAL NUMBER	LICENSE NUMBER	DESCRIPTION OF WORK	AMOUNT
1	Chain guide	22.40				
1	Timing Chain	144.00				
1	Chain tensioner				found broken timing chain	
	460cc	405.00			* guide in cylinder Head left	
6	plugs	7.40			side upper	
					Remove + reinstall cooling fan,	
		615.80			housing cover power steering pump +	6.30.00
					bracket	
					replace timing chain, guide +	
					tensioner	
					adjust valve timing to sp	
					60hrs (50hrs)	525.00
					check + replace all plugs	NIC
REMARKS					LABOR	1155.00
					PARTS	615.80
					TOWING CHARGE	
					MACHINE WORK	
					TIRE DISPOSAL	
					SHIPPING/MISC.	
					TIRE FEE	
					TAX	43.12
					HZRDS. MTRLS.	

TOTAL ACCESSORIES

No return on electrical parts and special orders.
 20% restocking charge on all other parts.
 Any car left at Walter's Auto Import Repair, Inc. over 30 days after
 repairs are completed will be subject to \$15.00 a day storage charge.

I hereby authorize the above repair work to be done along with the
 necessary materials. You and your employees may operate above
 vehicle for purposes of testing, inspection or delivery at my risk. An
 express mechanics lien is acknowledged on above vehicle to secure
 the amount of repairs thereto. It is also understood that you will not be
 held responsible for loss or damage to cars or articles left in cars in cars
 in case of fire, theft or any other cause beyond your control.

Thank You

TOTAL 1813.92

WALTER'S AUTO REPAIR, INC. SERVICE CENTER

665-474-8645

"with a smile, That's our Style"

Est. 1971

1000 West • Lafayette, IN 47909
at the intersection of 25 South and new 231

DATE OF ORDER
Nov. 13.19

NAME [REDACTED]
ADDRESS [REDACTED]
CITY [REDACTED]
HOME PHONE [REDACTED] WORK PHONE [REDACTED]

PART NO. AND DESCRIPTION	AMOUNT	YEAR MAKE AND MODEL	SPEEDOMETER
9ts Castrol	64.00	04 Merc 380 SL	109561
1 OIL filter	10.50	SERIAL NUMBER	LICENSE NUMBER
1 Exhaust Resignator 760.00	675.00	DESCRIPTION OF WORK	
2 Clamps kits	22.00	oil change + filter	
1 Starter 424.00	350.00	Check + repair Exhaust & leaks	
		Remove complete Center Exhaust system + rear Muffler	
	1121.50	replace Center Resignator + reassemble complete Exh. system	
		5 hrs (4 hrs) 420.00	
		check + replace defect Starter 2 hrs 210.00	
TOTAL ACCESSORIES		REMARKS	LABOR 675.00
			PARTS 1121.50
			TOWING CHARGE
			MACHINE WORK
			TIRE DISPOSAL
		from New York	SHIPPING/MISC. 40.00
			TIRE FEE
			TAX 78.54
			HZRDS. MTRLS.

No return on electrical parts and special orders.
20% restocking charge on all other parts.
Any car left at Walter's Auto Import Repair, Inc. over 30 days after repairs are completed will be subject to \$15.00 a day storage charge.

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

Thank You

TOTAL 1915.04

PAY THIS AMOUNT

WALTER'S AUTO REPAIR, INC. SERVICE CENTER

765-474-8645

"Service with a smile, That's our Style"
Est. 1971

1000 State Road 25 West • Lafayette, IN 47909
at the intersection of 25 South and new 231

NAME		[REDACTED]		DATE OF ORDER	Nov. 14, 19
ADDRESS					
CITY					
HOME PHONE			WORK PHONE		
YEAR MAKE AND MODEL					
04 Merc 380 SL					
SERIAL NUMBER		LICENSE NUMBER		SPEEDOMETER	
PART NO. AND DESCRIPTION				AMOUNT	
1 ignition rotor				46.40	
1 COIL				74.00	
1 ignition module					
new 800.00 weld				325.00	
1 idle control unit					
rebuild 374.00				352.00	
				795.40	
DESCRIPTION OF WORK				AMOUNT	
Diagnostic check on Engine				}	
intermittent not starting				}	
found weak + no spark				}	
check + replace ignition rotor + ignition				}	
coil + ignitor module 50hrs (40hrs)				420.00	
Diagnostic check on Engine idle					
Engine idle is too high 1700 RPM					
Remove + reinstall kt side lower					
Dash panel cover, check + replace					
idle control unit John (20hrs)				220.00	
REMARKS				LABOR	
				640.00	
				PARTS	
				795.40	
				TOWING CHARGE	
				MACHINE WORK	
				TIRE DISPOSAL	
				SHIPPING/MISC.	
				TIRE FEE	
				TAX	
				55.65	
				HZRDS. MTRLS.	

TOTAL ACCESSORIES

No return on electrical parts and special orders.
20% restocking charge on all other parts.
Any car left at Walter's Auto Import Repair, Inc. over 30 days after repairs are completed will be subject to \$15.00 a day storage charge.

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

Thank You

TOTAL ▶ 1491.05

PAY THIS AMOUNT

WALTER'S

IMPORT REPAIR, INC.

SERVICE CENTER

765-474-8645

"Service with a smile, That's our Style"
Est. 1971

1000 State Road 25 West • Lafayette, IN 47909
Corner of Intersection 25 South and new 231

DATE OF ORDER
NOV-15-19

NAME: [REDACTED]
 ADDRESS: [REDACTED]
 CITY: [REDACTED] WORK PHONE: [REDACTED]
 HOME PHONE: [REDACTED]
 YEAR MAKE AND MODEL: 04 MERK 380 SL
 SERIAL NUMBER: [REDACTED] LICENSE NUMBER: [REDACTED] SPEEDOMETER: [REDACTED]

PART NO. AND DESCRIPTION	AMOUNT	DESCRIPTION OF WORK	AMOUNT
1 set brake pads rear	54.00		
1 1/2 lbs free em + sealer	33.00	Check out Car is to hard to push	
	87.00	found out both side need brake pads + calipers are frozen	
		free up both side rear calipers + replace brake pads 4 hrs (30 hrs)	315.00
		Remove + reinstall left side front brake pads + free up brake caliper	105.00
		evacuate + charge A/C system	
		REMARKS	LABOR 120.00
			PARTS 87.00
			TOWING CHARGE
			MACHINE WORK
			TIRE DISPOSAL
			SHIPPING/MISC.
			TIRE FEE
			TAX 6.09
			HZRDS. MTRLS.

TOTAL ACCESSORIES

No return on electrical parts and special orders.
 20% restocking charge on all other parts.
 Any car left at Walter's Auto Import Repair, Inc. over 30 days after repairs are completed will be subject to \$15.00 a day storage charge.

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

Thank You

TOTAL ▶ 513.09

PAY THIS AMOUNT

WALTER'S

AUTO IMPORT REPAIR, INC.

BOSCH SERVICE CENTER

765-474-8645

"Service with a smile, That's our Style"
Est. 1971

864 State Road 25 West • Lafayette, IN 47909
1 Block of Intersection 25 South and new 231

NAME _____
 ADDRESS _____
 CITY _____
 HOME PHONE _____ WORK PHONE _____
 DATE OF ORDER June 15-21

YEAR MAKE AND MODEL 85 380 SL
 SERIAL NUMBER _____ LICENSE NUMBER _____ SPEEDOMETER 109585

QTY.	PART NO. AND DESCRIPTION	AMOUNT	DESCRIPTION OF WORK	AMOUNT
1	fuel pump	284.00		
1	" filter	55.00		
6	Copper gaskets	3.00	Check out + repair Start Engine	
1	fuel pump relay	224.00	" + replace fuel pump	
1	Steering gear box	1450.00	" + " fuel filter	
		1250.00	" + " " pump relay	
1	97 power steering fluid	18.50	4 hours	440.00
			Check + replace defect Steering gear box	7 hrs 60 mins 660.00
		1834.50	Check out Odometer to work	
			Remove + reinstall Steering Wheel + Instrument Cluster, disassemble 200w found 3 defect gears + drive rodassy	220.00
	3707.95		REMARKS	LABOR 1320.00
	2971.58 Top			PARTS 1834.50
	984.43 Service			TOWING CHARGE
	<u>7663.96 Total</u>		out-side labor + parts on odometer drive gearassy	MACHINE WORK 375.00
	754.15 blower Motor		Insurance	TIRE DISPOSAL
	<u>8418.11 Total</u>			SHIPPING/MISC. 50.00
				TIRE FEE
				TAX 128.45
				HZRDS. MTRLS.

TOTAL ACCESSORIES _____
 No return on electrical parts and special orders.
 20% restocking charge on all other parts.
 Any car left at Walter's Auto Import Repair, Inc. over 30 days after repairs are completed will be subject to \$15.00 a day storage charge.

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

Thank You
 paid
TOTAL 3707.95
PAY THIS AMOUNT

WALTER'S

AUTO IMPORT REPAIR, INC.

BOSCH SERVICE CENTER

765-474-8645

"Service with a smile, That's our Style"

Est. 1971

864 State Road 25 West • Lafayette, IN 47909

1 Block of Intersection 25 South and new 231

NAME [REDACTED] DATE OF ORDER Aug 20, 21

ADDRESS [REDACTED]

CITY

HOME PHONE WORK PHONE

YEAR MAKE AND MODEL 85 380 SL

SERIAL NUMBER LICENSE NUMBER SPEEDOMETER

QTY.	PART NO. AND DESCRIPTION	AMOUNT	DESCRIPTION OF WORK	AMOUNT
<u>8 1/2</u>	<u>qts Castrol GTX</u>			
	<u>20W-50 950</u>	<u>80.75</u>		
<u>1</u>	<u>oil filter</u>	<u>10.50</u>	<u>oil change + filter</u>	<u>55.00</u>
<u>3 1/2</u>	<u>qts A.T. fluid</u>	<u>28.00</u>		
<u>1</u>	<u>A.T. filter kit</u>	<u>46.00</u>	<u>Remove + reinstall lower</u>	
<u>2</u>	<u>Lbs free oil</u>	<u>44.00</u>	<u>reinforcement cover, A.T. pan</u>	
<u>1</u>	<u>Antenna seal</u>	<u>14.50</u>	<u>replace filter kit + oil 4hrs</u>	<u>440.00</u>
		<u>223.75</u>	<u>Charge A/C system</u>	<u>85.00</u>
			<u>Remove + reinstall rear Antenna,</u>	
			<u>remove mouse nest, vacuum lines</u>	
			<u>Trunk, replace Antenna seal 1 1/2 hrs</u>	<u>165.00</u>
			REMARKS	LABOR <u>745.00</u>
				PARTS <u>223.75</u>
				TOWING CHARGE
				MACHINE WORK
				TIRE DISPOSAL
				SHIPPING/MISC.
				TIRE FEE
				TAX <u>15.68</u>
				HZRDS. MTRLS.

TOTAL ACCESSORIES

No return on electrical parts and special orders.
20% restocking charge on all other parts.
Warranty on parts and labor over 30 days after

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure

Thank You

TOTAL 984.43

Invoice

Invoice #: 00071009
Date: 3/21/2025
Ship Via:
Page: 1


Bill To:

Ship To:

Brad Moan

Check # 1013

Description	Amount	Tx
check ac 1985	\$140.00	
labor	\$500.00	
evacuate & charge	\$95.00	
134a	\$49.03	X
compressor manifold repair	\$87.50	X
drier 107-830-12-83ia	\$67.10	X
ac oil , orings, & shop supplies	\$15.00	X
compressor 58098or	\$520.00	X
diagnosis mode issue The dash would need removed - plastic broken at actuator	\$200.00	



812-372-2505 • 812-372-1442

Freight:	\$20.00
Sales Tax:	\$51.70
Total Amount:	\$1,745.33
Amount Applied:	\$0.00
Balance Due:	\$1,745.33
Your Order #:	
Shipping Date:	
Terms:	C.O.D.