City Racer LLC

03/30/22
Invoice for #20544

855 El Camino Real, Ste13A-176
Palo Alto CA 94301
United States

Item Details

Quantity	Item	Price
2 x	**Stainless Brake or Clutch Pedal Spring for '74 and Later Land Cruiser FJ40 FJ45**	$8.00
1 x	**Stainless Heater Blower Resistor Screw for Land Cruiser FJ40 FJ45 FJ55 HJ47**	$3.50
1 x	**Route Package Protection - $0.98**	$0.98

Payment Details

Subtotal price:	$20.48
Total tax:	$0.00
Shipping:	$6.15
Total price:	**$26.63**

Shipping Details

If you have any questions, please send an email to contact@cityracerllc.com

City Racer LLC

03/13/22
Invoice for #20226

855 El Camino Real, Ste13A-176
Palo Alto CA 94301
United States

Item Details

Quantity	Item	Price
1 x	**Route Package Protection - $3.15**	$3.15
2 x	**Stainless 75 mm Air Cleaner Hose Clamp for Land Cruiser FJ40 FJ55 FJ62 70 Series FJ80 Pick-up 4Runner**	$4.50
1 x	**OEM 12V Heater Blower Resistor for '74 and later Land Cruiser FJ40 FJ45 FJ55 - LHD / '79 and Later**	$109.00
1 x	**Air Cleaner Intake Hose for '79 to '84 Land Cruiser FJ40**	$75.00
1 x	**Air Cleaner Decal for '79 to '80 Land Cruiser FJ40 FJ45 FJ55**	$12.00

Payment Details

Subtotal price:	$208.15
Total tax:	$0.00
Shipping:	$14.66
Total price:	**$222.81**

Shipping Details

If you have any questions, please send an email to contact@cityracerllc.com

City Racer LLC

10/04/23
Invoice for #29197

35325 Fircrest Street
Newark CA 94560
United States

Item Details

Quantity	Item	Taxes	Price
1 x	**Route Package Protection - $2.75**	$0.00 Virginia State Tax	$2.75
1 x	**Firewall Grommet for '79 to '84 Land Cruiser FJ40**	$0.00 Virginia State Tax	$50.00
1 x	**Front Door Glass Run for '75 to '84 Land Cruiser FJ40 FJ45 Without Vent Window - Set of 2**	$0.00 Virginia State Tax	$80.00

Transaction Details

Type	Amount	Kind	Status
Credit Card	$146.10	authorization	success
Credit Card	$146.10	capture	success

Payment Details

Subtotal price:	$132.75
Total tax:	$0.00
Shipping:	$13.35
Total price:	**$146.10**

Shipping Details

Coyner Springs Service Center
4299 Blue Ridge Blvd
Blue Ridge, VA. 24064
Phone: 540-977-2869 Fax: 540-977-1090

INVOICE
44841

Fed- 541547407
State- 10-541547407

INVOICE

Printed Date: 03/07/2023 **Work Completed: 03/07/2023**

1979 Toyota - Land Cruiser - 4.2L, In-Line6 (258CI) VIN(F)
Lic # :
Odometer In : 50199
Odometer Out : 50199

VIN # : FJ40304026

Part Description / *Number*	Qty	Sale	Ext
Clutch Kit 1 EA LUKAU/Transmission Clutch Kit *16-006*	1.00	445.02	445.02
HUB OVERHAUL KIT *750990*	2.00	258.00	516.00
OIL SEAL 1 EA NATNL/Engine Crankshaft Seal *231004*	1.00	51.46	51.46
Moly-Graph Extreme Pressure Lithium Grease - 14 0z Size: 1 *SL3330*	1.00	19.30	19.30
Convenience Fee			104.37

Labor Description	Ext
79 TOYOTA LAND CRUISER FJ40 ORIGINAL IMPORT FROM JAPAN. CLUTCH SLIPS BETWEEN 3/4 REAR MAIN SEAL LEAK KNUCKLES FRONT AXLE REBUILD NEW LEAF SPRINGS AND SHOCK TO REPLACE THE CHAINS ON IT. DOES NOT MIND IF WE HAVE TO LOWER IT TO MAKE IT WORK. ALSO SAID IT HE NEEDS TO HE CAN GET THE SUSPENSION KIT RATHER THEN US. NOT SURE OF HIS BUDGET LOOKING FOR QUOTES	
check veh	130.00
machine flywheel	130.00
SPINDLE BEARING - Remove & Replace - Both - [Includes: Repack Wheel Bearings (where applicable).]	572.00
CRANKSHAFT MAIN OIL SEAL - Remove & Replace - Standard Trans FJ40,Rear - [Includes: R&I Transmission, Clutch (where applicable) and Flywheel.]	843.70
SHIPPING FOR PARTS E0268754 41529334	18.99
INSPECT CAR INSPECT CAR ACCORDING TO STATE REGULATIONS	20.00
Hazardous Materials	5.99

Org. Estimate 134.94 Revisions 2,171.57 Current Estimate 2,306.51

Revision # 1, Previous Estimate Amount: 134.94, Additional Cost: 2171.57, Revised Estimate: 2306.51 Parts: $514.34 Labor: $1545.70 Sublet: $0.00 Taxes & Fees: $111.53 Authorized by - Date - 2/7/2023. Time - 8:32 AM. Initiated By - Shop

Labor:	**1,714.69**
Parts:	**1,136.15**
HazMat:	**5.99**
SubTotal:	**2,856.83**
Tax:	**54.68**
Total:	**2,911.51**
Bal Due:	**$0.00**

[Payments - Visa - $2,911.51]

Customer Number : 10624

Vehicle Received: 2/2/2023

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Service Advisor : Trythall, Amber, Tech : Myers, Greg 02

Copyright (c) 2023 Mitchell Repair Information Company, LLC invhrs 5.12.2 N

Coyner Springs Service Center
4299 Blue Ridge Blvd
Blue Ridge, VA. 24064
Phone: 540-977-2869 Fax: 540-977-1090

REPAIR ORDER #
044841

Fed- 541547407
State- 10-541547407

REPAIR ORDER - RO

Scheduled : 01/27/2023 12:59 PM
Print Date : 2/8/2023

1979 Toyota - Land Cruiser - 4.2L, In-Line6 (258CI) VIN(F)
Lic # :

VIN # : FJ40304026
MFG Date : 1/27/2023
Current Odom : 50199
Elapsed : 0

Labor Requested / Part Description	Part #	Qty	Parts List	Extended
79 TOYOTA LAND CRUISER FJ40 ORIGINAL IMPORT FROM JAPAN.				
CLUTCH SLIPS BETWEEN 3/4				
REAR MAIN SEAL LEAK				
KNUCKLES FRONT AXLE REBUILD				
NEW LEAF SPRINGS AND SHOCK TO REPLACE THE CHAINS ON IT. DOES NOT MIND IF WE HAVE TO LOWER IT TO MAKE IT WORK.				
ALSO SAID IT HE NEEDS TO HE CAN GET THE SUSPENSION KIT RATHER THEN US. NOT SURE OF HIS BUDGET LOOKING FOR QUOTES				
check veh				*130.00*
machine flywheel				*130.00*
SPINDLE BEARING - Remove & Replace - Both - [Includes: Repack Wheel Bearings (where applicable).]				*572.00*
CRANKSHAFT MAIN OIL SEAL - Remove & Replace - Standard Trans FJ40,Rear - [Includes: R&I Transmission, Clutch (where applicable) and Flywheel.]				*843.70*
Clutch Kit 1 EA LUKAU/Transmission Clutch Kit	16-006	1.00	445.02	445.02
HUB OVERHAUL KIT	750990	2.00	258.00	516.00
OIL SEAL 1 EA NATNL/Engine Crankshaft Seal	231004	1.00	51.46	51.46
Convenience Fee				102.15
Hazardous Materials				5.99

Revision # 1, Previous Estimate Amount: 134.94, Additional Cost: 2171.57, Revised Estimate: 2306.51, Parts: $514.34 Labor: $1545.70 Sublet: $0.00 Taxes & Fees: $111.53 Authorized by - , Date - 2/7/2023, Time - 8:32 AM, Initiated By - Shop

Parts: 1,012.48 **Supplies:** 102.15 **HazMat:** 5.99
Labor: 1,675.70 **Tax:** 53.66 **Total:** 2,849.98
Deposit: 1,500.00 **Balance:** 1,349.98

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within____days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Authorized By_____ Date_____ Time_____

Service Advisor : Trythall, Amber

Copyright (c) 2023 Mitchell Repair Information Company, LLC ropartdetail2 dj 7.2.18

Roberts muffler service

1112 WEST MAIN STREET
SALEM, VIRGINIA 24153
387-2144

CUSTOMER'S ORDER NO. F5 DATE 1-6 2022

NAME

ADDRESS

SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MDS. RETD.	PAID OUT	Paid

QUAN	DESCRIPTION	PART NO	PRICE	AMOUNT
1	EXHAUST PIPE			
1	RESONATOR			
1	MUFFLER			
1	TAIL PIPE			
	CONVERTOR			
	CLAMPS			
	HANGERS			
	FLEX PIPE			
	Frt Pipe Gasket +			
	Studs			
	TOTAL P			
	LA			
	WASTE DISPOSAL			

All claims and returned goods MUST be accompanied by this bill.

RECEIVED BY:

TERMS: Net 30 days. All accounts not paid within 30 days will be subject service charge of 1½% per month. Finance charge is computed by a "per rate" of 1½% per month, which is an annual percentage rate of 18%.

Thank You

ROBERTS MUFFLER
1112 W MAIN ST
SALEM, VA 24153

SALE

MID: 7680 Store: 4616 Term: 5601
REF#: 00000003
Batch #: 010 RRN: 200619414479
01/06/22 14:49:25
Trans ID: 382006713652578
APPR CODE: 006300
VISA Chip
**********9965 **/**

AMOUNT $562.60

APPROVED

Visa Credit
AID: A0000000031010
TVR: 00 80 00 80 00
TSI: F8 00

CUSTOMER COPY

Princeton, WV * Hagerstown, MD * Brunswick, GA * Greer, SC

Page: 1

For terms and conditions please visit www.automotivefasteners.com/contact-us/terms

Thank you for your business!

Invoice

130483
1304839-
CAS31400
CAS31400
01/06/2022
01/06/2022
01/06/2022

Robert Duncan
House Account
NET
PICK-UP COUNTE

Price
3.920
1.124
4.960

SubTotal
Tax
Payments
Total USD

63691

962.43
2,312.50
293.40
178.42
746.75
66.56
813.31

The Sportscar Clinic
3328 Peters Creek Rd.
Roanoke, Va 24019
(540) 563-1133
Quality Import Car Service
www.wefiximports.com

Invoice # 63691

1979 Toyota Land Cruiser Base
VIN: FJ40-304028
Engine: L6 4.2L, 4227cc, OHV, GAS, CARB,
Trans: MAN

License # \
Odom: 50199
Color: Grey
Mfg. Date: 4/79
Unit #

Inv Date: 10/21/2021
Promised: 12/08/2021 @ 5:00pm
Service Writer: Matt Rahsman
Status: Complete
Driver:
PO #

Mobile

Vehicle Problems	Requests for Service	Services Performed		Qty	Price		Ext

Request for Service: Maintenance Inspection

Labor Service - Inspected drivetrain, brake system, suspension, tires, engine, cooling system, belts, hoses, fluids, etc. All checks ok except those listed below: 250.00
HVAC fans only work on high.
Brake and seat belt warning lights do not illuminate.
Brake hoses are aged, several hard brake lines have been replaced (rust?).
Brake fluid marginal.
Rear brake are saturated in fluid and need to be serviced. See below.
Rear axle seals are leaking causing brake issue. Needs to be addressed. See below.
Wear noted in several ball joints @ steering linkage.
Rear spring perches are starting to rust through.
Moderate rust noted in chassis, not structural at this time.
Transmission fluid is discolored and over filled. Rec. both transmission and diff. fluids as preventative.
Last oil service?
Exhaust leak noted at manifold to down pipe.
Rear wheel spacers installed with washers, not secure. Solution need to be explored. See below.
Fuel tank has been replaced and is a marginal fit. Hoses to tank (vents) are seeping/leaking. See below.
Fuel pump is after-market (elec.) and not properly secured, see below.

Rec. follow up inspections after car is driven more. 42TMF

Notes: Rear main leak noted?

Labor Service - Confirmed moderate oil leak from rear main seal area, transmission removal require for further diag. 42TMF 0.00

Notes: Address rear brakes and axle seals.

Labor Service - Removed rear brakes and axles, removed rear diff cover. Cleaned and dressed all surfaces. Replaced wheel seals and bearings. Resealed diff. cover. Installed new brake shoes and hardware. Filled differential with synthetic fluid and performed adjustments. Tested ok. 875.00

Parking brake is weak (separate unit), adjusted parking brake, ok. 42TMF

New	*088-100B*	*Differential bearing/seal set*	1.00	183.33	183.33
New	*081-15*	*Shoe set w/core*	1.00	127.08	127.08
New	*081-16*	*Brake hardware kit*	1.00	85.19	85.19
New	*RL 75/90 GEAR OIL*	*Synthetic Gear Oil*	3.00	29.34	88.02
Sublet	*SHIPPING*	*Shipping charges*	1.00	50.00	50.00

Notes: Relocate fuel pump and address tank hoses.

Labor Service - Accessed and replaced worn fuel tank hoses. 375.00
Relocated fuel pump properly and fabricated a proper mount. Added fuel filter and replaced hoses as needed. 42TMF

New	*33032*	*Fuel Filter*	1.00	10.98	10.98
New	*27008*	*Fuel hose 5/8*	1.00	7.70	7.70
New	*MISC*	*Misc. fuel hose and mounting.*	1.00	40.00	40.00

Notes: Address rear hub/wheel issues.

#201798 **Order coolfj40-201798 for coolfj40**

Date Fri Dec 31 08:05:00 CST 2021

Ship to

PAID

Bill to Same

Amazon-OrderReference-Id

Backorder Ship Order Complete

Free-Poster She's Barn Kept

GiftCertNumber

Model-Year-Type 1979 FJ40

E-Mail

Via UPS Ground Residential

Payment Visa

Item	Code	Qty	Unit Price
Gear Shift Boot - 4-Spd - '74-'84 - Aft Mrkt	A98273-50300	1	27.24
Shift Lever Inner Boot - 4-Spd - 9/73 to 8/87 - TOYOTA	53555-35011	1	19.02
Valve Cover Gasket - 2F - 1/75-7/80 - TOYOTA	61213-11010	1	36.82
Oil Filler Cap ~ Star Shape Threaded ~ 1/'79- 8/'87 ~ TOYOTA	13180-12010	1	17.96

Subtotal	101.04
Shipping	9.88
Tax	0.00
Total	110.92

Wood's Service Center Towing & Transportation
418 East Washington Ave.
Vinton, VA 24179-4518
(540) 982-3663

WE APPRECIATE YOUR BUSINESS

Invoice Order #0030755 Your Service Writer Today Is: PETE HITE Center: RETAIL **12/7/2021** **2:41 pm**

[redacted]

Service Requests:

Technician	Service Description	Parts	Labor	Job Total
	MISCELLANEOUS PARTS	**174.95**		**174.95**

Part Number	Part Description	Part Price Each	Quantity	Extended
MTP-24F	INTERSTATE BATTERY	174.95	1	174.95

Payments:
Cash, $184.22, on 12/07/21

Repair Order Notes

I hereby authorize the repair work to be done along with the necessary parts & materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control. WARRANTY IS 12 MONTHS OR 12,000 MILES WHICH EVER OCCURS FIRST, UNLESS SPECIFIED OTHERWISE! WARRANTY DOES NOT TRANSFER

Customer Signature: _____ **Date:** _____

TOTAL LABOR	$0.00
TOTAL PARTS	$174.95
TOWING	$0.00
Supply Charg	$0.00
SUBTOTAL	$174.95
OTHER FEES	$0.00
SALES TAX	$9.27
INVOICE TOTAL	**$184.22**
PAID	$184.22
DUE	$0.00

#200809 **Order coolfj40-200809 for coolfj40**

Date Mon Nov 8 21:47:50 CST 2021

Ship to

PAID

Bill to Same
Amazon-OrderReference-Id
Backorder Ship Available Parts
Free-Poster * * * --- Select One ---
GiftCertNumber
Model-Year-Type 1979 FJ40
E-Mail
Via UPS Ground Residential
Payment Visa

Item	Code	Qty	Unit Price
Gas Cap ~ Fits 10/'77 to 9/83 ~ TOYOTA	17310-74070	1	22.68
Hood Pad Kit - Rubber Cushion - 4ea front & 2ea side	A91464-50300 A93349-50300	1	19.31
Brake or Clutch Pad - 1ea - 1/79-8/87 - TOYOTA	36321-31010	2	8.19
Gas Pedal Pad - '63 - '84 - Aft Mrkt	K08VW016	1	3.99
License Plate Holder ~ Front FJ40 ~ TOYOTA	65101-70011	1	59.29
License Plate Bolt Kit - SST - Front - Bumper Mount	SST-BltKit-Lic-Frt-Bmpr	1	4.93

Subtotal	126.58
Shipping	12.98
Tax	0.00
Total	139.56

MB

Order coolfj40-200949 for coolfj40

#200949
Date Sun Nov 14 22:37:23 CST 2021
Ship to

PAID

Bill to

Amazon-OrderReferenceId [illegible]81-5339686
Backorder Ship Order Complete
Free-Poster Calendar 2022
GiftCertNumber
Model-Year-Type 1979 FJ40
E-Mail
Via UPS Ground Residential
Payment Amazon Payments

Item	Code	Qty	Unit Price
Door Packing #3 - Front Elbow Corner - Right & Left Sides - Pair - Aft Mrkt	A90300	1	11.85
Door Packing #2 - Front Corner - Right & Left Sides - Pair - Aft Mrkt	A90302	1	10.08
Door Packing #1 - Rear Corner - Right & Left Sides - Pair - Aft Mrkt	A90301	1	10.08
Gasket Kickout Vent Weatherstrip - Pair - Aft Mrkt	A95786-50301	1	10.18
Weatherstrip - Both Rear Ambulance Doors - Pair - FJ40 - 75-84 - "BEST" Select = Weatherstrip Only	A98291-60301-A98292-60301	1	98.85
Windshield Frame Inside Access Gasket - TOYOTA	00950-91003	1	6.10
Front Door Seal Kit - FJ40 Select = Prod Date 01/75-05/80	DrSealKit7584	1	197.95
3M Weather-strip Adhesive Remover / Cleaner - 15 oz.	76980	1	20.97
Hinge Screws - Windshield - Stainless - 79-84 - Aft Mrkt Select = 16 Screws 16 Washers(+$11.00)	Wind-Hinge-Scrw-7984	1	23.86
Air Filter - 1/75-8/87 - TOYOTA	67801-11010	1	28.51
Oil Filter - 3/69-4/96 ~ TOYOTA	Y0915-9ZZD3	1	5.82

(Continued...)

#200949 (continued)

Hose "E" - LOWER RADIATOR HOSE - 58-80 - TOYOTA	00916-91058	1	27.31
Hose "D" - LOWER INSIDE HOSE - '58-'80 - TOYOTA	00916-91056	1	22.63
Hose "C" ~ BYPASS HOSE ~ '58 to '87 ~ TOYOTA	66261-10011	1	19.67
Transaction ID P01-7469781-5339686		1	0.00

Subtotal	493.86
Shipping	31.58
Tax	0.00
Total	525.44

MB