

Repair Order Detail - Internal Copy

RO Number: 684540

RO Status: CLOSED

Vehicle: WDBBA48DXKA094629

Main:
1989 560SL

Click to View Cust Copy
Cell:

Mileage: 8,472
Service advisor: 4453
Tag number: T4936

Payment type: MC
Promised time: 07:00 PM
Promised date: 02/27/2023

Waiter: No
Estimate: 0.00
Customer Comments: No

A CUSTOMER STATES OIL CHANGE

00	CPME MAINT	0.50	35.00
Tech(s): 4530			
000-180-06-09-68		1 FILTER ELEMENT	6.27
915035-000025		1 SEAL RING	1.32
000-989-79-02-11-BIFU		9 MB 229.5 SAE 5W 40 1L	65.70
Pts:	73.29 Lbr:	35.00 Other:	0.00
Story: 8472 OIL AND FILTER CHANGED			Total Line A: 108.29

B CUSTOMER STATES REPLACE ENGINE AIR FILTER

00	CPME MAINT	0.20	14.00
Tech(s): 4530			
001-094-78-04		1 FILTER ELEMENT	35.20
Pts:	35.20 Lbr:	14.00 Other:	0.00
Story: 8472 REPLACED ENGINE AIR FILTER			Total Line B: 49.20

C MERCEDES MULTI POINT INSPECTION

MP	IPLM MERCEDES MULTI POINT INSPECTION	0.00	0.00
Tech(s): 4530			
Pts:	0.00 Lbr:	0.00 Other:	0.00
Story: 8472 COMPLETED MULTI POINT INSPECTION			Total Line C: 0.00

D** CUSTOMER STATES REPLACE WASHER RESERVOIR AND PUMP

00	CPME MAINT	1.00	70.00
Tech(s): 4530			
107-869-06-20		1 CONTAINER,W/WASHER FLUID	85.80
202-869-00-21		1 PUMP	33.55
123-997-36-81		1 GROMMET	2.20
107-860-01-47		2 NOZZLE,W/WASHER	26.40
108-987-05-40		1 RUBBER BUFFER	1.98
Pts:	149.93 Lbr:	70.00 Other:	0.00
Story: 8472 REPLACED WASHER RESERVOIR AND PUMP			Total Line D: 219.93

E** CUSTOMER STATES REPLACE BROKEN/WORN SHIFTER LINKAGE BUSHINGS

00	CPME MAINT	2.00	130.00
Tech(s): 4530			
115-992-03-10		2 BUSHING	5.28
1521559-00		1 MER LASER ETCHED POLISHED 304 STAINLESS	49.45
126-720-01-04		1 DOOR CATCH	83.60
116-990-00-31		4 RIVET	8.36
Pts:	146.69 Lbr:	130.00 Other:	0.00
Story: 8472 REPLACED SHIFTER LINKAGE BUSHINGS			Total Line E: 276.69

Repair Order Detail - Internal Copy

RO Number: 684540

RO Status: CLOSED

Customer: [REDACTED]
Phone(s): [REDACTED]
Vehicle: WDBBA48DXKA094629

Main:
1989 560SL

Click to View Cust Copy
Cell:

Mileage: 8,472
Service advisor: 4453
Tag number: T4936

Payment type: MC
Promised time: 07:00 PM
Promised date: 02/27/2023

Waiter: No
Estimate: 0.00
Customer Comments: No

~~~~~  
F\*\* CUSTOMER STATES REPLACE ALL BELTS ON ENGINE  
00 CPME MAINT 2.00 130.00  
Tech(s): 4530  
005-997-95-92 1 SET OF V BELT 10.56  
004-997-05-92 1 V BELT 10.12  
006-997-24-92 1 V BELT 9.57  
009-997-53-92 1 V BELT 9.68  
Pts: 39.93 Lbr: 130.00 Other: 0.00 Total Line F: 169.93  
Story: 8472 REPLACED ALL BELTS  
~~~~~

G** PERFORM BRAKE FLUID SYSTEM EXCHANGE PER MERCEDES-BENZ
RECOMMENDATIONS
BRK CPME PERFORM BRAKE FLUID 1.00 65.00
SYSTEM EXCHANGE PER
MERCEDES-BENZ
RECOMMENDATIONS
Tech(s): 4530
000-989-56-05-11-0111 1 BRAKE FLUID
Pts: 19.80 Lbr: 65.00 Other: 0.00 Total Line G: 84.80
Story: 8472 PERFORMED BRAKE FLUID SYSTEM EXCHANGE PER
MERCEDES-BENZ RECOMMENDATIONS
~~~~~

H\*\* CUSTOMER STATES REPLACE UNDERHOOD INSULATION MAT  
00 CPME MAINT 1.00 65.00  
Tech(s): 4530  
107-880-00-97 1 INSULATION 44.00  
107-682-03-26 1 INSULATION 74.80  
Pts: 118.80 Lbr: 65.00 Other: 0.00 Total Line H: 183.80  
Story: 8472 REPLACED UNDERHOOD INSULATION MAT  
~~~~~

I** LABOR TO INSTALL CUSTOMER PROVIDED SPARK PLUGS
00 CPME MAINT 1.50 97.50
Tech(s): 4530
0.00 Lbr: 97.50 Other: 0.00 Total Line I: 97.50
Story: 8472 REPLACED SPARK PLUGS WITH CUSTOMER PROVIDED PARTS
~~~~~

~~~~~  
Customer Pay
Labor
Parts 606.50
Lube 583.64
Sublet 0.00
Miscellaneous/Shop Charge 0.00
5.00

Repair Order Detail - Internal Copy

Deductible	0.00
Total Charges	1,195.14
Less Insurance/Adjustment	0.00
Sales Tax	83.66
Total	1,278.80

RO Status: CLOSED

Customer: [REDACTED]
Phone(s): [REDACTED]
Vehicle: WDBBA48DXKA094629

Main:
1989 560SL

Click to View Cust Copy
Cell:

Mileage: 9,125
Service advisor: 30007
Tag number: T4629

Payment type: MC
Promised time: 07:00 PM
Promised date: 11/05/2025

Waiter: No
Estimate: 0.00
Customer Comments: No

ITEM	QTY	UNIT	PRICE	TOTAL
ENGINE OIL AND FILTER CHANGE				
CPME OIL CHANGE	0.50			48.00
Tech(s): 30010				
000-989-51-07-11-BIFU				
9 MERCEDES BENZ GEO				74.43
229.5 5W40, 6X1L				
Pts: 74.43 Lbr: 48.00 Other: 0.00				
Total Line A:				122.43
Story: 9125 REQUESTED OIL CHANGE. CHANGED ENGINE OIL AND FILTER AND ADDED 8.5QTS OF OIL AS WELL AS TOPPED OFF COOLANT AND WASHER FLUID.				

B	00	REPLACE BATTERY	CPME	BATTERY	0.50	48.00
		Tech(s): 30010				
Pts:		0.00	Lbr:	48.00	Other:	0.00
		Story: 9125 REQUESTED REPLACE MAIN SYSTEM BATTERY.			Total Line B:	48.00
		SYSTEM BATTERY.			REPLACED MAIN	

Customer Pay	
Labor	
Parts	96.00
Lube	74.43
Sublet	0.00
Miscellaneous/Shop Charge	0.00
Deductible	8.52
Total Charges	0.00
Less Insurance/Adjustment	178.95
Sales Tax	0.00
Total	12.53
	191.48

Repair Order Detail - Internal Copy

RO Number: 817436

RO Status: CLOSED

Customer: [REDACTED]
Phone(s): [REDACTED]
Vehicle: WDBBA48DXKA094629

Main:
1989 560SL

Click to View Cust Copy
Cell:

Mileage: 9,125
Service advisor: 30007
Tag number: T4629

Payment type: MC
Promised time: 07:00 PM
Promised date: 11/05/2025

Waiter: No
Estimate: 0.00
Customer Comments: No

ITEM	QTY	UNIT	PRICE	TOTAL
ENGINE OIL AND FILTER CHANGE				
CPME OIL CHANGE	0.50			48.00
Tech(s): 30010				
000-989-51-07-11-BIFU				
9 MERCEDES BENZ GEO				74.43
229.5 5W40, 6X1L				
Pts: 74.43 Lbr: 48.00 Other: 0.00				
Story: 9125 REQUESTED OIL CHANGE. CHANGED ENGINE OIL AND FILTER				122.43
AND ADDED 8.5QTS OF OIL AS WELL AS TOPPED OFF COOLANT AND				
WASHER FLUID.				

B	REPLACE BATTERY				
00	CPME BATTERY		0.50		48.00
	Tech(s): 30010				
Pts:	0.00 Lbr:	48.00 Other:	0.00	Total Line B:	48.00
	Story: 9125 REQUESTED REPLACE MAIN SYSTEM BATTERY.			REPLACED MAIN	
	SYSTEM BATTERY.				

Customer Pay	
Labor	
Parts	96.00
Lube	74.43
Sublet	0.00
Miscellaneous/Shop Charge	0.00
Deductible	8.52
Total Charges	0.00
Less Insurance/Adjustment	178.95
Sales Tax	0.00
Total	12.53
	191.48

Repair Order Detail - Internal Copy

RO Number: 816123

RO Status: CLOSED

Customer: [REDACTED]
Phone(s): [REDACTED]
Vehicle: WDBBA48DXKA094629

Main:
1989 560SL

Click to View Cust Copy
Cell:

Mileage: 9,125
Service advisor: 30030
Tag number: T94629

Payment type: CASH
Promised time: 07:00 PM
Promised date: 09/24/2025

Waiter: No
Estimate: 0.00
Customer Comments: No

A	REPLACE FUEL PUMPS AND FILTERS			
00	CPME	MAINT	1.00	39.95
	Tech(s): 30010			
	007603-012102			
		2 SEALING RING		
Pts:	5.94	Lbr:	39.95	Other:
			0.00	Total Line A:
Story:	9125 REQUESTED REPLACED FUEL PUMPS AND FILTER. REPLACED			45.89
	FUEL PUMPS AND FILTER. REPLACED DAMAGED FUEL LINE AS WELL.			

B	REPLACE EXHAUST HANGERS .			
00	CPME	REPLACED EXHAUST HANGERS	0.50	19.97
	Tech(s):	30010		
Pts:	0.00	Lbr:	19.97	Other:
Story: 9125	REQUESTED	REPLACE EXHAUST HANGERS.	0.00	Total Line B:
EXHAUST AHNGERS.		REPLACED ALL 5		19.97

Customer Pay	
Labor	
Parts	59.92
Lube	5.94
Sublet	0.00
Miscellaneous/Shop Charge	0.00
Deductible	1.00
Total Charges	0.00
Less Insurance/Adjustment	66.86
Sales Tax	0.00
Total	4.68
	71.54