

Branch Avenue Tire and Auto Service
 3407 Branch Avenue
 Marlow Heights, MD. 20748-1225
 Phone - 301-894-8400 Fax - 301-894-5314

INVOICE

30092

Org. Est. # 079204
 54-1664686
 06966049

INVOICE

Work Completed Date : 10/31/2012

Print Date : 01/02/2013

1967 Buick - Riviera

430 CID

Lic # :

Odometer In : 32017

Unit # :

Vin # :

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
IGNITION WIRE SET				TIRE MOUNTING PACKAGE-4	0.80	44.00
SW 29896	1.00	38.32	38.32	Mount/Balance/Stems/Disposal-4 Tires		
A/C COMPRESSOR BELT				Labor to install belt set	0.60	33.00
DY 15625	1.00	20.97	20.97			
FAN & ALTERNATOR BELT				Labor to overhaul carburator and free up	4.00	220.00
DY 15495	1.00	18.09	18.09	binding secondary metering rod assembly,		
POWER STEERING BELT				and epoxy the welsh plugs		
DY 15415	1.00	16.64	16.64			
UPPER RADIATOR HOSE				Labor to install ignition parts, set dwell and	1.50	82.50
GAT 20980	1.00	35.21	35.21	timing		
LOWER RADIATOR HOSE						
GAT 20907	1.00	31.65	31.65	PERFORM LUBE, OIL, AND FILTER	0.20	11.00
RESISTER SPARK PLUG				Change engine oil and filter, lube where		
R44TS	8.00	3.72	29.76	applicable, top all fluids, adjust tire		
CARBURATOR OVERHAUL KIT				pressure and perform safety check		
ST481	1.00	45.70	45.70	Labor to install wheel cylinders and flex	2.00	110.00
P235/75/R15 Hankook Mileage Plus				hoses, then bleed and flush braking system		
1004576	4.00	116.84	467.36			
PREMIUM OIL FILTER				Labor to install sway bar links	0.80	44.00
OIL FILTER	1.00	5.00	5.00			
PREMIUM MODEL SPECIFIC API				Vehicle had a transmission service that is		
SVC CODE SJ ENGINE OIL				not detailed because in a billing error, it		
SJ ENGINE OIL	5.00	3.29	16.45	was charged twice on the 62 Impala.		
FRONT BRAKE FLEX HOSE				Hazardous Materials		10.00
150.66001	2.00	16.60	33.20			
LEFT REAR WHEEL CYLINDER						
134.62069	1.00	38.50	38.50			
RIGHT REAR WHEEL CYLINDER						
134.62070	1.00	38.50	38.50			
RIGHT FRONT WHEEL CYLINDER						
134.62033	1.00	38.50	38.50			
LEFT FRONT WHEEL CYLINDER						
W370174	1.00	38.50	38.50			
SWAY BAR LINK KITS						
K6217	2.00	10.14	20.28			
STRUT ROD BUSHING KIT						
K 5186	1.00	65.05	65.05			
REAR COIL SPRING SET						

Branch Avenue Tire and Auto Service
 3407 Branch Avenue
 Marlow Heights, MD. 20748-1225
 Phone - 301-894-8400 Fax - 301-894-5314

INVOICE

30092

Org. Est. # 079204
 54-1664686
 06966049

INVOICE

Work Completed Date : 10/31/2012

Print Date : 01/02/2013

1967 Buick - Riviera

430 CID

Lic # :

Odometer In : 32017

Unit # :

Vin # :

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
MC5245	1.00	148.14	148.14			
NEW FUEL PUMP (old pump is physically leaking oil)						
AF 40927	1.00	58.20	58.20			
REMAN STEERING BOX						
999	1.00	179.40	179.40			
Shop Supplies		40.00	40.00			

[Technicians : Crawford, Robert 52]

Org. Estimate \$1,209.16 Revisions \$0.00 Current Estimate \$ 1,209.16 Additional Cost Revised Estimate

Labor:	554.50
Parts:	1,423.42
Sublet:	0.00

Sub:	1,977.92
Tax:	83.01
Total:	2,060.93
Bal Due:	\$0.00

[Payments - Cash - \$851.77, Check - \$1209.16]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....

Written By: Crawford, Robert

Branch Avenue Tire and Auto Service
 3407 Branch Avenue
 Marlow Heights, MD. 20748-1225
 Phone - 301-894-8400 Fax - 301-894-5314

INVOICE

31870

54-1664686
 06966049

INVOICE

Print Date : 08/09/2013

1967 Buick - Riviera

430 CID

Lic # : 78155Z

Odometer In : 32084

Unit # :

Vin # :

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
CYLINDER HEAD GASKET SET				REPLACE CYLINDER HEAD GASKETS	10.00	550.00
HS 8494PT	1.00	88.04	88.04			
TIMING COVER GASKET SET				Install steering box (Paid for on last invoice)	1.00	55.00
TCS 45002	1.00	19.38	19.38			
INTAKE MANIFOLD GASKET				Labor to replace customers ignition switch	1.20	66.00
MS 96005	1.00	55.24	55.24			
POWER STEERING PRESSURE HOSE				Labor to install fuel lines	1.60	88.00
PMP 71307	1.00	46.68	46.68			
BULK RETURN LINE				PERFORM LUBE, OIL, AND FILTER	0.20	11.00
999	1.00	16.00	16.00	Change engine oil and filter, lube where		
10 Ft BULK FUEL LINE				applicable, top all fluids, adjust tire		
999	1.00	20.00	20.00	pressure and perform safety check		
PREMIUM OIL FILTER				Labor to replace pinion bearings	4.00	220.00
P033	1.00	5.00	5.00			
PREMIUM MODEL SPECIFIC API				Pressure test and resurface cylinder heads	N/A	295.00
SVC CODE SJ ENGINE OIL						
SJ ENGINE OIL	5.00	3.29	16.45	Replace A/C system evaporator	3.00	165.00
CRUSH COLLAR						
Ratech 3104	1.00	35.00	35.00	Evacuate and recharge A/C system (with	1.00	55.00
FRONT PINION BEARING				customers R-12)		
M88048	1.00	15.54	15.54			
FRONT BEARING RACE				Labor to remove and replace timing case	2.30	126.50
M88010	1.00	8.25	8.25	cover		
REAR PINION BEARING RACE						
M804049	1.00	14.16	14.16	Hazardous Materials		10.00
REAR PINION BEARING						
M804049	1.00	30.63	30.63			
REMANUFACTURED DISTRIBUTOR						
A1 30-1814	1.00	125.97	125.97			
AC THERMAN EXPANSION VALVE						
EX6069C	1.00	22.09	22.09			
Shop Supplies		40.00	40.00			

Branch Avenue Tire and Auto Service
3407 Branch Avenue
Marlow Heights, MD. 20748-1225
Phone - 301-894-8400 Fax - 301-894-5314

INVOICE
31870

54-1664686
06966049

INVOICE

Print Date : 08/09/2013

1967 Buick - Riviera
430 CID
Lic # : 78155Z
Unit # :
Vin # :
Hat # :

Odometer In : 32084

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
---------------------------	-----	------	----------	-------------------	-------	----------

[Technicians : Please Select, Technician; Tifft, Kevin 51; Crawford, Robert 52; Crawford, Matt 07]

Org. Estimate \$582.00	Revisions \$650.32	Current Estimate \$ 1,232.32	Additional Cost	Revised Estimate
Schiattareggia, Nick Cellular:301-801-9719 05/31/2013 - 12:05 <none>			\$650.32	\$1,232.32
Parts: \$207.71 Labor: \$396.00 Sublet: \$0.00 Taxes & Fees: \$46.61				

Labor:	1,346.50
Parts:	558.43
Sublet:	295.00

Sub:	2,199.93
Tax:	31.11
Total:	2,231.04
Bal Due:	\$0.00

[Payments - Check - \$2231.04]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....

Written By: Crawford, Robert

Branch Avenue Tire and Auto Service
 3407 Branch Avenue
 Marlow Heights, MD. 20748-1225
 Phone - 301-894-8400 Fax - 301-894-5314

INVOICE
34619

54-1664686
 06966049

INVOICE

Print Date : 05/02/2014

1967 Buick - Riviera

430 CID

Lic # : 78155Z

Odometer In : 32334

Unit # :

Vin # :

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
PREMIUM OIL FILTER				PERFORM LUBE, OIL, AND FILTER	0.20	13.00
OIL FILTER	1.00	5.00	5.00	Change engine oil and filter, lube where applicable, top all fluids, adjust tire pressure and perform safety check		
PREMIUM MODEL SPECIFIC API						
SVC CODE SJ ENGINE OIL				Labor to install pump	1.50	97.50
SJ ENGINE OIL	5.00	3.29	16.45			
POWER STEERING PUMP (no housing)				Install customers HEI distributor and wire set	1.50	97.50
A1 20-140	1.00	66.85	66.85	All fluids are Ok (including the differential)		
Shop Supplies		11.85	11.85	Hazardous Materials		10.00

[Technicians : Crawford, Robert 52]

Org. Estimate \$323.45	Revisions \$0.00	Current Estimate \$ 323.45	Additional Cost	Revised Estimate	Labor:	218.00
					Parts:	100.15
					Sublet:	0.00

					Sub:	318.15
					Tax:	5.30
					Total:	323.45
					Bal Due:	\$0.00

[Payments - Cash - \$323.45]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....

Written By: Crawford, Robert

Branch Avenue Tire & Auto Service
3407 Branch Avenue
Temple Hills, MD. 20748-1225
Phone: 301-894-8400 Fax: 301-894-5314

INVOICE

41660

Org. Est. # 110273
54-1664686
06966049

INVOICE

Print Date: 06/15/2016

1967 Buick - Riviera - 430 CID
Lic # : 78155Z - MD

Odometer In : 0

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Extended
				Install customers LF window motor	1.60	112.00

Org. Estimate 112.00 Revisions 0.00 Current Estimate 112.00

Labor:	112.00
Parts:	0.00
Sub:	112.00
Tax:	0.00
Total:	112.00
Bal Due:	\$0.00

[Payments - Cash - \$112.00]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____ Time _____

Written By: Crawford, Robert - Technicians : Crawford, Robert 52

Branch Avenue Tire & Auto Service
3407 Branch Avenue
Temple Hills, MD. 20748-1225
Phone: 301-894-8400 Fax: 301-894-5314

INVOICE

49827

54-1664686
06966049

INVOICE

Date: 10/17/2018

1967 Buick - Riviera - 430 CID

Lic # : 78155Z

Odometer In : 35111

VIN# :

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
---------------------------	-----	------	-----	-------------------	-------	-----

				Install right door window motor	1.50	120.00
--	--	--	--	---------------------------------	------	--------

Org. Estimate	130.80	Revisions	0.00	Current Estimate	130.80
---------------	--------	-----------	------	------------------	--------

Labor: 120.00

Parts: 0.00

SubTotal: 120.00

Tax: 0.00

Total: 120.00

Bal Due: \$0.00

[Payments - Cash - \$120.00]

Vehicle Received: 10/17/2018

Customer Number : 342

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. NOT RESPONSIBLE FOR DAMAGE, THEFT, OR LOSS OF VEHICLE, ITEMS IN VEHICLE, OR OTHERWISE WHEN VEHICLE IS LEFT OUTSIDE.

Signature _____ Date _____

Auto Ronnie, Inc
11801 Fingerboard Road
Monrovia, MD. 217709030
Phone - 301-831-3950 Fax - 301-831-3950

INVOICE
5070
Org. Est. # 005070

INVOICE

Print Date : 09/22/2014

1967 Buick - Riviera - 340 V8

Lic # : - MD

Odometer In : 33038

Unit # :

Vin # : 494877H939271

Hat # :

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
Window motor, Front shocks & Shipping				Pass. Side window & Front Shocks	2.60	234.00
WM600R- FS206G	1.00	265.65	265.65	R&R Door trim and replace motor, lube tracks. Replace front shocks nec. to cut off top bolts.		
Mufflers				Brakes	5.50	483.84
21314	2.00	91.57	183.14	Install front disc brake kit, Nec. to adjust caliper brackets to true caliper to rotors.replace master cylinder, install adjustable pressure control valve in rear brake line, bleed system.		
1/4 flar X1/8 pipe fitting				Rotors	1.00	87.97
124420	2.00	2.98	5.96	Machine rotors hubs to fit wheels, nec. to R&R studs.		
Brake Kleen				Brake booster	1.00	87.97
05088	1.00	6.24	6.24	Install new booster, has problem with pedal rod (Short about 3/4 to 1") Clean and paint old booster and reinstall.		
Brake Fluid				Lube, oil, and filter	0.22	16.42
Dot3	1.00	10.47	10.47	Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Preform basic safety inspection. Road test vehicle.		
Freon				A/C System	1.00	87.97
R134	2.50	21.18	52.95	Evacuate and recharge system, tighten lines add tracer die		
				Exhaust		585.00
				Install mufflers, make up and replace pipes from mufflers back.		
				NOTE: Diff. Ratio 2:50		
				Hazardous Materials		2.00

Org. Estimate \$ 2,141.04 Revisions \$ 0.00 Current Estimate \$ 2,141.04

Labor: 1,000.17
Parts: 524.41
Sublet: \$585.00

Sub: 2,109.58
Tax: 31.46
Total: 2,141.04
Bal Due: \$2,141.04

Handwritten signature

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. SMOG: I understand that I can have emission service and/or adjustments done elsewhere. I hereby waive this right. TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ___. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Signature _____ Date _____ Time _____

11/19/2018

Packing slip



Packing Slip

This is not an invoice

Ship to



Ship from

Michael Hart
600 Goldfish Farm Rd SE
Albany, OR 97322-5136
US

Message to nick_scat

Thanks for your purchase! We look forward to doing business with you again on eBay.

1968-1970 Buick GS, Lesabre, Skylark V8 USED power steering
pump pulley 1384927 (231536061964)

Price: \$64.99, Qty: 1 **\$64.99**

Subtotal: **\$64.99**

Shipping and handling: Free

Total: **\$64.99**

**K&N ENGINEERING INC.**

1455 CITRUS STREET

RIVERSIDE, CA 92507

United States

Ph: 951-826-4000

Fax: 951-826-4001

PACKING SLIP

NO. 6131591-01

DATE Oct-09-2017

PAGE 1 of 1

SHIP
TO

CUSTOMER NO.	CUSTOMER P.O. NUMBER	F.O.B. POINT		SHIP VIA	WEIGHT(lbs)
81515	C0778050	Freight Bill to Invoice		UPS	2.30
ORDER NO.	SUPPLIER NUMBER	ORDER DATE	SHIP DATE		
6131591		Oct-08-2017	Oct-09-2017		

LINE #	ORDER QTY.	SHIP QTY.	BACK ORDER	PART NUMBER (YOUR PART#) - DESCRIPTION
1	1	1	0	E-1360 - Replacement Air Filter - Special Order Air Filter

1 1 0

Tracking Number(s) - UPS : 1Z9310070391315030



Thanks for shopping Original Parts Group!

Toll Free in the USA
1-800-243-8355
International, 1-562-594-1000
Fax 1-562-594-1050

Order No: 120499342
Original Order Date: 06/01/2016
Customer No: 900355707

BILL TO:



SHIP TO:

NICK SCHIATTAREGGIA
10609 ROCK RUN DR
POTOMAC MD 20854-1701
(301) 894-1073

Page # 1
Print Date: 6/1/2016

GENERAL

Purchase Order No. Shipping VIA Entered By: Billing Terms Order Type Key Code
FedEx Home Delivery MH 0 Regular DEF

OPGI... Your #1 Source for quality restoration and performance!

Qty Ordered	Qty Shipped	Unit	Qty Bk.Ord	Product #	Product Description	List Price	Discount	Net Price	Ext Price	Bin Location	Pick Bin Qty
1	1	EACH		CE11601	Power Window Switch, 1963-77 GM Cars, Single-	36.99	0%	36.99	36.99	19B690	1
1	1	EACH		BR01461	Motor, Power Window, 1966-68 Riv/1961-68 A-Bo	191.99	0%	191.99	191.99	20D161	1

Vehicle Info/Year/Model/Body Style/Interior-Color/Engine/Transmission
1967, Buick Riviera, Standard Features, coupe



W6131206

Order # 120499342
Reset Code: 168918409
SHIP VIA: FedEx Home Delivery

Loyalty Points

Order Earned: 228
Total Earned: 228
Earned Value: Catalog Sub/1Year

Merchandise Charge: \$228.98
Ins/Shipping Charge: \$23.64
Sales Tax: \$0.00
Total: \$252.62
Amount Due: \$0.00

Payments
Visa

\$252.62 (*6108) ✓

PRICE ADV

As always, thanks for shopping OPGI, we sincerely appreciate your business



CARS, Inc. 205 Pearl Street, Neshanic Station, NJ 08853

Fax 908-369-7595
www.oldbuickparts.com

Customer:

Ship To:

Customer Copy

DATE: 11/26/2012 ORDER #: 27131

1967 RIV RIVIERA 2 DR HDTP

Paid by _____ Amount _____ Auth# _____

Last Catalog: 11/08/2012

Picked by MN Inspected By [Signature]

ORD	SHF	B/O	PART #	GROUP	DESCRIPTION	PRICE	UNIT	EXTENDED
1	1	X	EP644S	08.800	ENGINE PAINT, RED SPRAY	9.50	EACH	9.50
1	1	0	OL		ONLINE ORDER			
WD 1	1	0	211G	07.345	SHOCK ABSORBERS, SHIPPED FACTORY DIRECT	92.50	PAIR	92.50
1	1	0	TM640	04.081	TRANS MOUNT	37.75	EACH	37.75
1	1	0	WT100	02.480	WIRING TAPE 1"	11.00	EACH	11.00

==> 2013 ROA Riviera National Meet - Lexington, KY - June 24-27, 2013 <==

Subtotal:	150.75	SHIP. REDUCTION:	-1.90	S/H/I:	16.98	Total:	165.83
-----------	--------	------------------	-------	--------	-------	--------	--------


Thank You For Your Order. Kevin @ CARS, Inc.

**** RETURN POLICY ****

Inspect your parts immediately. No returns after 30 days.
Damages? Contact CARS, Inc. to file a claim. Do not return to CARS, Inc.
No returns without RMA. Please call for approval and RMA #.
Return prepaid & insured with a copy of your original receipt
Returns will be subject to a restocking fee. See catalog
Shipping/Handling/Insurance charges are not refundable

CARS, Inc.
205 Pearl St
Neshanic Station, NJ 08853
(908) 369-3666

Ship To:



Verizon Message Center

Thursday, Nov 29 at 9:24 AM

Subject: 1967 Buick Riviera Head Light Lamp Visor Actuator Auxillary Relay NOS

1967 Buick Riviera Head Light Lamp Visor Actuator Auxillary Relay NOS

1 (One) Head Light Lamp Visor Actuator Auxillary Relay

1967 Buick Riviera (9000 Series).

GM OEM # 1381074

\$125 and \$12 US shipping. UPS Fully Insured,

Professionally Wrapped & Boxed, and Tracking.

(I will have to purchase 1 Box & Special Wrapping).

Make the Payment for \$137.00 out to:

Greg Thomas

NO PAYPAL. NO CREDIT CARD.

Personal Check Company Check Cashiers Check US Postal Money Order.

US Postal Money Order ships the next day. All other forms of payment have to clear first.

*****Please include with payment the item or items you are purchasing.*****

Thank You,

Greg Thomas

In a message dated 11/28/2012 6:39:02 P.M. Central Standard Time [redacted] writes:

Ok.

Where do I send a money order to? I will make a copy of your email with my shipping address in the envelope.

Thanks, Nick



CARS, Inc. 205 Pe

Customer:

CARS INC.

205 PEARL ST

BRANCHBURG, NJ 08853

13:15:48

013

013

CREDIT CARD

VISA SALE

XXXXXXXXXXXX1971

0015

000615

015568

Manual

Online

Phone 369-3666

Fax 369-7695

www.carsparts.com

\$59.50

SALE AMOUNT

CUSTOMER COPY

DATE: 04/22/2013 ORDER #: 32382

Paid by Visa: xxxx xxxx xxxx 1971

Last Catalog: 11/08/2012

Picked by TR Inspected By MW

ENGINE: 430 TRANS: TH400 CARB: 4BBL

ORD	SHP	B/O	PART #	GROUP	DESCRIPTION	PRICE	UNIT	EXTENDED
1	1	0	ATO		ADD TO CURRENT ORDER?			
1	1	0	CARLISLE		CARLISLE SHOW DELIVERY			
1	1	0	DSB611	05.441	BEARING, DRIVE SHAFT CTR.	37.00	EACH	37.00
1	1	0	RAG660	05.399	AXLE GASKET	7.75	EACH	7.75
1	1	0	VCG676	00.423	VALVE COVER GASKETS	14.75	PAIR	14.75

1961 - Up GM Licensed Floor Mat Set (4 Piece) Now Available In Saddle/Brown
 ==> 2013 ROA Riviera National Meet - Lexington, KY - June 24-27, 2013 <==

Subtotal:	59.50	ATO SHIP ADJ:	-9.90	S/H/I:	9.90	Total:	59.50
-----------	-------	---------------	-------	--------	------	--------	-------

Thank You For Your Order. Eric @ CARS, Inc.

**** RETURN POLICY ****

Inspect your parts immediately. No returns after 30 days.
 Damages? Contact CARS, Inc. to file a claim. Do not return to CARS, Inc.
 No returns without RMA. Please call for approval and RMA #.
 Return prepaid & insured with a copy of your original receipt
 Returns will be subject to a restocking fee. See catalog
 Shipping/Handling/Insurance charges are not refundable

CARS, Inc.

205 Pearl St

Neshanic Station, NJ 08853

(908) 369-3666

Ship To:



CARS, Inc. 205 Pearl

Phone 908-369-2666

Customer:



CARS INC.

205 PEARL ST

BRANCHBURG, NJ 08853

11/08/2012

Merchant ID:

Terminal ID:

313240674884

14:21:05

000000001742913

02799577

CREDIT CARD

VISA SALE

XXXXXXXXXXXX1971

0007

000489

025173

Manual

Online

SALE AMOUNT

\$67.65

CUSTOMER COPY

Cus

DATE: 11/08/2012 ORDER #: 26611



Picked by

K

Inspected By

W

ORD	SHP	B/O	PART #	GROUP	DESCRIPTION	PRICE	UNIT	EXTENDED
1	1	0	CATRIV		CATALOG 1963-UP RIVIERA			
3	3	0	TM660	15.330	TRUNK MATERIAL	19.25	YARD	57.75

-*-

2012 GS NATIONALS - Bowling Green, KY - October 17-20, 2012

Subtotal: 57.75

S/H/I:

9.90

Total:

67.65

Thank You For Your Order. Melissa @ CARS, Inc.

**** RETURN POLICY ****

Inspect your parts immediately. No returns after 30 days.
Damages? Contact CARS, Inc. to file a claim. Do not return to CARS, Inc.
No returns without RMA. Please call for approval and RMA #.
Return prepaid & insured with a copy of your original receipt
Returns will be subject to a restocking fee. See catalog
Shipping/Handling/Insurance charges are not refundable


CARS, Inc.

205 Pearl St

Neshanic Station, NJ 08853

(908) 369-3666

Ship To:





Thanks for shopping Original Parts Group!

Toll Free in the USA
1-800-243-8355
International, 1-562-594-1000
Fax 1-562-594-1050

Order No: 106836510
Order Date: 11/02/2012
Customer No: 900355707

Loyalty Points

Order Earned: 194
Total Earned:
Earned Value:

Page # 1

Print Date 11/2/2012

BILL TO:

SHIP TO:

GENERAL

Purchase Order No. Shipping VIA
FedEx Home Delivery Published

Entered By:
JC

Billing Terms
0

Order Type
Regular

OPGI... Your #1 Source for quality restoration and performance!

Qty Ordered	Qty Shipped	Unit	Qty Bk.Ord	Product #	Product Description	List Price	Discount	Net Price	Ext Price	Bin Location	Pick Bin Qty
1	1	KIT		SB0550	SUNVISOR BUSHING/TIP KIT ✓	8.95	0%	8.95	8.95	10C005	1
2	2	EACH		216C250	64-72 UPPER RAD HOSE CLAMP X	9.99	0%	9.99	19.98	23C241	2
X 1	1	EACH		MCAK012	1967-69 MASTER CYLINDER LID KIT, W/ GASK ✓	32.99	0%	32.99	32.99	30A658	1
1	1	EACH		FH2500	1967-70 Riviera Rear Brake Hose ✓	14.99	0%	14.99	14.99	30B846	1
1	1	EACH		BR01473	66-67 Riviera Trunk Board Set ✓	79.99	0%	79.99	79.99	40C545	1
X 2	2	EACH		2516C50	1967-72 LOWER RADIATOR HOSE CLAMP X	10.99	0%	10.99	21.98	23C243	2
1	1	PR		DLN1001	1961-67 Door Lock Knob Ferrules pr ✓	8.72	0%	8.72	8.72	16C171	1
1	1	PR		DLN1000	1961-67 Chrome Door Lock Knob pr ✓	7.23	0%	7.23	7.23	16C175	1

Vehicle Info/Year/Model/Body Style/Interior-Color/Engine/Transmission
1967, Buick Riviera, Standard Features, coupe

Merchandise Charge: \$194.83
Ins/Shipping Charge: \$21.58
Sales Tax: \$0.00

W2066295



Order # 106836510
Reset Code: 5520277
SHIP VIA: FedEx Home Delivery Published

Total: \$216.41
Visa Prepayment: \$216.41
Amount Due: \$0.00

PRICES ADV * HLDY PROMO

As always, thanks for shopping OPGI, we sincerely appreciate your business


Invoice

BILL TO	

SHIP TO

[illegible]

Subtotal	27.74
6.50% Tax	0.00
Total	27.74



Verizon Message Center

Monday, Jun 24 at 11:48 AM

From: eBay <ebay@ebay.com>

Subject: Confirmation of your order of NOS 1967 Buick Riviera Ignition Switch 1116682...

Thanks for your purchase, nick_scot!



Here's your order confirmation

Hi nick_scot,

Here is a summary of your recent order. You can also view your updated [order details](#) in My eBay.

Thank you for shopping on eBay!

[Go to order details](#)

Order details

You completed checkout on Jun-24-13

Ship to:

Sam's Car Wash
3401 Branch Ave
Temple Hills, MD 20748-
1225 US

Payment details:

PayPal

Total:

\$106.91

Seller: [johnmeissinger](#) ([15180](#) ★)

Item title	Price	Shipping price	Qty	Item total
NOS 1967 Buick Riviera Ignition Switch 1116682 (item: 281117320010 transaction: 1059943216018)				
	Paid on Jun-24-13 USPS First Class Package	\$101.96 \$4.95	1	\$101.96
Estimated delivery: Thu. Jun. 27 - Mon. Jul. 1				

Subtotal

\$101.96

**RockAuto Order Confirmation
Order 18718348****Go to the RockAuto *Catalog***

Thursday, November 7, 2013 04:50 PM Central Time

Ship To:**Bill To:**

	Part Number	Part Type	Price EA	Core EA	Quantity	Total
1967 BUICK RIVIERA 7.0L 430cid V8						
ACDELCO	36516096 (36-516096)	Power Steering Pump	\$ 34.99	\$ 7.00	1	\$ 41.99
Shipping	Ground					\$ 9.40
Order Total						\$ 51.39
Gift Certificate or Store Credit	64E6ECC21CE6					-\$ 25.00
Visa						-\$ 26.39
Balance Due						\$ 0.00

Your Visa will be charged when your order ships. Your Card will be charged in US Dollars. If you live outside the US, the amount appearing on your bank statement may vary due to bank fees and conversion rates.

When the last item on your order ships, we will send an email listing tracking numbers for all the items on the order.

- [Gift Certificates](#)
- [Order Status & Returns](#)

To **CHECK ORDER STATUS** or **ARRANGE A RETURN**
visit <http://www.rockauto.com/orderstatus>

Please click on the part number above to check the RockAuto Advice Wiki for other customers' installation tips. After you complete your repair, please return to the Wiki and add your advice to help others.

Please print this page as your receipt.

If you have other concerns about your order, please reply to this email with the Order number above and as much detail as possible to help us assist you (the part number, pictures which illustrate your concern, etc.).

Thanks again for buying your auto parts at RockAuto!

www.RockAuto.com
service@rockauto.com
1-608-661-1376



ORDER SERVICE

Client:

Address:

Contact:

OS: 00102

Work: 67 Buick Riviera

Location: Brazilian Hot Rod

Item	Description	Un	Amount	Value	Total	Paid	Date	Actual Balance
1	Differential Bearings, seal, gasket	Pc	1.00	\$96.60	\$96.60			\$905.63
2	Shims	Pc	1.00	\$110.00	\$110.00			
3	Ring Bolts (10pcs) Kit	Pc	1.00	\$26.40	\$26.40			
4	Ring Bolts	Pc	2.00	\$2.64	\$5.28			
5	Parts cleaner spray	Pc	3.00	\$6.80	\$20.40			
6	Gear Oil	Qt	3.00	\$9.49	\$28.47			
					\$287.15			
				Tax	\$17.23			
				Parts Total	\$304.38			
1	Labor 9/21/20 Start 3:30/5:30	Hr	2.00	\$65.00	\$130.00			
	Labor 9/29/20 Start 11:30/12:45	Hr	1.25	\$65.00	\$81.25			
	Labor 11/12/20 Start 9:30/11 - 2:10/4:40	Hr	4.00	\$65.00	\$260.00			
	Labor 11/13/20 Start 9:30/11:30	Hr	2.00	\$65.00	\$130.00			
				Labor Total	\$601.25			
			9.25	Grand Total	\$905.63			

>BRAZILIAN HOT ROD - 20120 Beallsville Rd - Beallsville - MD - 20839 - +1 240 390 7645<



Lake Liberty
8550 Connecticut Ave
Chevy Chase, MD. 20815
Phone - 301-986-0560 Fax - 301-652-2656

ACDelco

INVOICE

46411

Org. Est. # 071473
MC Regist # 00501

INVOICE

Print Date : 10/14/2013

1967 Buick - Riviera

430-4 CI

Lic # :

Odometer In :

Unit # :

Odometer Out :

Vin # :

Hat # :

Cust ID : 8359

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
Antifreeze - Prestone All Makes ?				Radiator is leaking	N/C
AF2000	2.00	29.95	59.90		
R-134A FREON				A/C is not cold	N/C
R-134A	4.10	15.00	61.50		
A/C high side/low side fitting kit				67 Riviera A/C-coolant repair	2,415.00
VA-LH11	1.00	22.61	22.61	-R&R A/C compressor (customer supplied the part)	
Transmission fitting				-R&R A/C dryer/accumulator (customer supplied	
258650	2.00	8.02	16.04	part)	
Fan clutch				-R&R A/C condenser (customer supplied part)	
77247	1.00	113.20	113.20	-Replace all worn A/C o-rings	
Thermostat 185				-R&R radiator assembly install an aluminum	
60208	1.00	14.24	14.24	Griffen radiator	
Thermostat gasket				-Modified the existing factory parts to	
20894	1.00	3.14	3.14	accommodate the new radiator	
Griffin Thermal Products				-R&R fan clutch	
6-70006	1.00	495.00	495.00	-R&R thermostat and gasket (used 185 degree unit)	
BG A/C OIL DYE				-Install new coolant	
BG-7028	0.50	25.95	12.98	-Install new transmission fittings	
Shop Supplies		49.73	49.73	-Tighten power steering belt	
				-Repaired cracks on the fan shroud and repaint it	
				EVACUATE & RECHARGE AIR CONDITIONING	172.50
				SYSTEM	
				Replace both high side and low side fittings.	
				Evacuate A/C system to recover any remaining	
				refrigerant. Recharge system with refrigerant and	
				add oil dye to system in order to check for any	
				future leaks.	
				JC shop materials	45.00
				JC shop supplies	

Liberty™

Lake Liberty
8550 Connecticut Ave
Chevy Chase, MD. 20815
Phone - 301-986-0560 Fax - 301-652-2656

ACDelco

INVOICE

46411

Org. Est. # 071473
MC Regist # 00501

INVOICE

Print Date : 10/14/2013



1967 Buick - Riviera
430-4 CI

Lic # :

Odometer In :

Unit # :

Odometer Out :

Vin # :

Hat # :

Cust ID : 8359

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
---------------------------	-----	------	----------	-------------------	----------

[Technicians : Baschuk, Sean; SE/ JL,]

Org. Estimate	Revisions	Current Estimate	Additional Cost	Revised Estimate
---------------	-----------	------------------	-----------------	------------------

Labor:	172.50	90.00
Parts:	848.34	766.4
Sublet:	2,460.00	1720.

Sub:	3,480.84	2581.4
Tax:	47.92	462.
Total:	3,528.76	
Bal Due:	\$3,528.76	

[Payments -]

Montgomery County's 'Notice to Customer' and 'Customer Rights' are located on the back of this document or attachment.

SIGNATURE.....

Date..... Time.....

Written By: Elliott, Shawn

Page 2 of 2

01.17.07 Copyright Mitchell 1 Invoice1

PA# 3261

10/19/13

AMC

Air Manufacturing Corporation
1040 E. 4th Street
Graham, Texas 76450
940-549-0288/1-800-900-9560

Invoice

Date	Sale No.
8/21/2013	8791

Sold To	Ship To

Check No.	Payment Method	Rep	Ship Date	Ship Via	FOB	Project
	VISA	JWP	8/21/2013	BEST WAY	Graham	
Qty	Item	Description			Rate	Amount
1	21-2201	Compressor GM A6 1 Groove 210CC			70.00	70.00
1	31280	Condenser			395.00	395.00
1	804-213	ACCUMULATOR/DRIER 67 Riviera			285.00	285.00
2 CAUTIONS TOTAL						

Thank you for your business.

Subtotal \$750.00**Sales Tax (8.25%)** \$0.00**Total** \$750.00

AMC

Air Manufacturing Corporation
1040 E. 4th Street
Graham, Texas 76450
940-549-0288/1-800-900-9560

JW

Packing List

Date	Sale No.
5/30/2013	80426115058

Sold To	Ship To

Check No.	Payment Method	Rep	Ship Date	Ship Via	FOB	Project
	VISA	JWP	5/30/2013	BEST WAY	Graham	
Qty	Item		Description			
1	15-6169		Evaporator 67 Buick Riviera			
			TO PURCHASE ADDITIONAL PARTS GO TO THE AMC WEBSITE www.amcmfg.com			
Thank you for your business.					Sales Tax (8.25%)	\$0.00

\$345.00

Branch Avenue Tire & Auto Service

3407 Branch Avenue

Temple Hills, MD. 20748-1225

Phone: 301-894-8400 Fax: 301-894-5314

INVOICE**41267**

Org. Est. # 109811

54-1664686
06966049**INVOICE**

Print Date: 05/05/20

1967 Buick - Riviera - 430 CID

Lic # : 78155Z - MD

Odometer In :

Odometer Out : 3376

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Extende
R-134a REFRIGERANT R-134a	3.00	29.00	87.00	Replace POA valve, then evacuate and recharge A/C system	2.00	140.00
PREMIUM OIL FILTER OIL FILTER	1.00	5.30	5.30	PERFORM LUBE, OIL, AND FILTER	0.20	13.00
PREMIUM MODEL SPECIFIC API SVC CODE SJ ENGINE OIL SJ ENGINE OIL	5.00	3.29	16.45	Change engine oil and filter, lube where applicable, top all fluids, adjust tire pressure and perform safety check		
Shop Supplies			10.47	Hazardous Materials		13.00

Org. Estimate 291.52 Revisions 0.00 Current Estimate 291.52

Labor: 166.0

Parts: 119.2

Sub: 285.3

Tax: 6.2

Total: 291.5

Bal Due: \$0.0

[Payments - Cash - \$291.52]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____

Date _____

Time _____

Written By: Crawford, Robert - Technicians : Crawford, Robert 52

Page 1 of 1

Copyright (c) 2016 Mitchell Repair Information Company, LLC invhrs 1.191



Sunday, May 25 at 11:47 AM

From: "service@paypal.com" <service@paypal.com>

Subject: Receipt for your PayPal payment to Nelco Restoration Parts



May 25, 2014 08:46:53 PDT
Transaction ID: [44L039850D045601E](#)

Hello Nick Schiattareggia,

365
Stringer Rd
Rockmart, GA. 30153

You sent a payment of \$294.90 USD to Nelco Restoration Parts (nelcoresto@live.com)

Thanks for using PayPal. To see all the transaction details, log in to your PayPal account.

It may take a few moments for this transaction to appear in your account.

Seller
Nelco Restoration Parts
nelcoresto@live.com

Note to seller
You haven't included a note.

Shipping details
The seller hasn't provided any shipping details yet.

longer Rod
with
Down
brms
3/4"

One account. Countless benefits.

Your PayPal account is designed to make your life easier.

Log In

Description	Unit price	Qty	Amount
1967-70 Buick Riviera power brake booster & master cylinder New reproduction Item# 221299295401	\$249.95 USD	1	\$249.95 USD



Shipping and handling \$44.95 USD
Insurance - not offered ---
Total \$294.90 USD

Payment \$294.90 USD

Payment sent to nelcoresto@live.com

Issues with this transaction?

You have 45 days from the date of the transaction to open a dispute in the Resolution Center.

Balance Due	\$598.00
--------------------	-----------------


FRONT DISC BRAKE KIT CONVERSION FOR 1961-64 BUICK

WARNING:

Installation of any component or kit should be performed by persons experienced in the installation and proper operation of brake systems. It is also the responsibility of the person installing any brake component or kit to determine the suitability of the component or kit for that particular application.

NOTE:

After installation and before operating the vehicle a complete test of all brake operations under controlled conditions should be made. Make several stops in a safe area from low speed and gradually work up to normal speeds. **DO NOT DRIVE WITH UNTESTED BRAKES!** Always utilize safety restraints when operating the vehicle.




STEP 1:

Check kit to make sure all necessary parts are included to complete this project.


STEP 2:

Disassemble front brakes by removing brake drums, backing plates, & rubber brake line. Remove and clean all old grease and dirt from spindle it is important that spindle area is free from all foreign particles.



STEP 3:


Position pre-assembled caliper bracket in front of spindle. Insert $\frac{1}{2}$ " x 3" bolt through the lower hole and $\frac{7}{16}$ " x $2\frac{1}{2}$ " bolt through upper hole. Place $\frac{1}{4}$ " spacer between the caliper brackets. Tighten all caliper bracket bolts to 45-55 foot pounds. Make sure that cutout for caliper mounting is towards front of the car.



STEP 4:



Make sure that you pack wheel bearings with the appropriate grease. We recommend a high temperature, high quality bearing grease. There are two different options to pack your bearings. 1. Place a large dollop of grease on the palm of your hand with your other hand push the bearing into the grease until you see grease coming out of the other side of the bearing. 2. Using a "bearing packer" place bearing on the piston press down on cap until grease shows on top of the bearing. This is more effective with less mess.





STEP 6:


Place rotor face down and install greased wheel bearing followed by the grease seal. Slide rotor onto spindle, install packed outer bearing followed by spindle washer, and axle nut, be sure that inner bearing seats all the way onto spindle. Tighten castle nut until brake rotors moves freely but not loose. Then insert cotter pin through castle nut to secure followed by the dust cover.



STEP 7:

Mount caliper onto caliper bracket using supplied caliper bolts. Make sure pads are securely seated in caliper by bending tabs on brake pads and using anti-rattle clips. Torque caliper bolts to 30 foot pounds. **Be sure the bleeder screws are on top position!** Install brake hose to caliper using one copper washer on top of banjo bolt, and one copper washer on bottom of banjo bolt. Connect your brake hose to your original brake line

and secure brake hose. Repeat on opposite side. Bleed brakes, check for leaks, and test system.



CHECKLIST

- 2- Brake Rotors
- 2- Loaded Calipers
- 2- Hoses
- 2- C-Clips
- 2- Banjo Fittings
- 4- Copper Washers
- 2- Inner Bearings
- 2- Outer Bearings
- 2- Grease Seals
- 2- Castle Nuts
- 2- Spindle Washers
- 2- Cotter Pins
- 4-1/4" Spacers
- 4- 1/2"x 1 1/2' Bolts
- 2- 1/2"x 3" Bolts
- 6- 1/2" Locking Nuts
- 2- 7/16"x 2 1/2" Bolts
- 2- 7/16" Locking Nuts

NOTE: ALL NEW KITS ARE GUARANTEED FOR 1 YEAR FROM DATE OF PURCHASE TO BE FREE OF DEFECTS IN MATERIALS AND WORKMANSHIP. GUARANTEE COVERS REPLACEMENT OF DEFECTIVE OR INCORRECT PART (S) ONLY AND DOES NOT COVER INSTALLATION, LABOR, FREIGHT, OR INCIDENTAL DAMAGE. THIS IS A CONVERSION KIT SO MINOR MODIFICATIONS MAY BE NECESSARY FOR CORRECT INSTALLATION. WE DO NOT ACCEPT ANY LIABILITY FOR INCORRECT INSTALLATION OR DAMAGE TO VEHICLE OR PROPERTY.

JEGS HIGH PERFORMANCE
101 JEGS PLACE
DELAWARE, OH 43015
800-345-4545

FedEx Ground

1987

Commercial

Tracking Number : 043043279496070

Invoice : 716082060514
Weight : .61
Box : 1 OF 1

FREE HANDLING ON EVERYTHING!!!
This order has been scanned
and weighed electronically.

Sale Type A/R CHARGE

Sales Person : BAY

Order Ship

Qty	Qty	Part Number	Description	Unit Price	Extended

Contents of Carton No: 1					
1	1	555-63020	PROPORTIONING VALVE ADJ	39.99	39.99
0	0	999	008772091 EBAYORDER	.00	.00
0	0	999	5KU604010 EBAYPAYPALID	.00	.00
0	0	999	BAYSHIPPHONE3017650509	.00	.00
0	0	999	EMAIL nickscat1@ver	.00	.00

Box : 1 OF 1

Thank you for your order.

** PLEASE RETAIN YOUR INVOICE. See reverse side for return/exchange information **



Jeg's

1 OF 1

7:49:40 6/06/14

Performance items are not legal for sale or
use in CA on pollution controlled vehicles.

Sub-Total 39.99
FREE Handling .00

TOTAL 39.99

Pickticket# : 405137

Ctn# : 00099000000003391987 Wave#: 20140606002 Pack St: P25 Carton Type: BOX Carton Size: PAD



CARS, Inc. 205 Pearl Street, Neshanic Station, NJ 08853

Phone 908-369-3666
Fax 908-369-7595
www.oldbuickparts.com

Customer

Customer Copy

DATE: 04/07/2020 ORDER #: 83859

Paid by _____ Amount _____ Auth# _____

EMAIL: nickscat1@verizon.net

Picked by _____ Inspected By _____

ORD	SHP	B/O	PART #	GROUP	DESCRIPTION	PRICE	UNIT	EXTENDED
1	1		OL		ONLINE ORDER			
1	1		TFK400	04.197	TRANSMISSION FILTER KIT	15.00	EACH	15.00
1	1		TPG645	04.005	TRANSMISSION PAN GASKET	9.50	EACH	9.50

1957 & 1958 Gas Tanks Are in Due In Stock April 1, 2020

Subtotal:	24.50	S/H/I:	9.90	Total:	34.40
-----------	-------	--------	------	--------	-------

Thank You For Your Order. Gary K @ CARS, LLC

**** RETURN POLICY ****

CARS, LLC
205 Pearl St
Neshanic Station, NJ 08853
(908) 369-3666

Ship To:

Inspect your parts immediately. No returns after 30 days.
Returns? Contact CARS, LLC to file a claim. Do not return to CARS, LLC
Returns without RMA. Please call for approval and RMA #.
Prepaid & insured with a copy of your original receipt
Returns will be subject to a restocking fee. See catalog
Shipping/Handling/Insurance charges are not refundable