

Zulassungsbescheinigung Teil I
(Fahrzeugschein)

Nr. **AA-K-0-251/20-00089**

Europäische Gemeinschaft **(D)** Bundesrepublik Deutschland

Conveniente para permision - Cast I / Permiso de circulación. Parte I /
Dovolenie o registrac - Cast I / Registreringsattest. Del I /
Registrazioni - Cast I / Registro di immatricolazione. Parte I /
Mopet / Registration certificate. Part I / Certificat d'immatriculation. Partie I /
Prometna dozvola / Carta di circolazione. Parte I / Reģistrācijas apliecība.
I. daļa / Registrācijas liudzimas. I. daļa / Forgalmi engedély. I. Rész / Certificat
ta' Registrazzjoni. L-I Part / Kentekenbewijs. Deel I / Dowód Rejestracyjny.
Część I / Certificado de matrícula. Parte I / Certificat de Immatriculare Partea I /
Osvedčenie o evidencii. Cast' I / Prometno dovoljenje. Del I /
Rekisterintodistus. Osa I / Registreringsbeviset. Del I

A Amtliches Kennzeichen

AA KY635

C.1.1 Name oder Firmenname
AUTOHAUS RÖMER OHG

C.1.2 Vorname(n)

C.1.3 Anschrift
**KARLSTR. 2 /1
73433 AALEN**

C.1.4 Nächste HU
(Monat und Jahr): **AALEN**

09.2022 Datum: **07.09.2020**

C.4c Der Inhaber der Zulassungsbescheinigung wird nicht als Eigentümer des
Fahrzeugs ausgewiesen.

B	30.05.1995	2.1	0708	2.2	00000000-
J	01	4	0200		
E	WDB1240921F312194	3	6		
D.1	MERCEDES-BENZ				
	124 T				
D.2	-				
	-				
D.3	E36 AMG				
2	DAIMLER-BENZ (D)				
	PERSONENKRAFTWAGEN				
5	GESCHLOSSEN				
V.9	-				
14	SCHADSTOFFARM E2				
P.3	BENZIN				
10	0001	141	0414	R1	03606
22	ZU 15: A.AMG LM-RAD 7,5JX17H2 ET42 1244001302*ZU 15: A				
	.GEN. 205/60R15 91T M+S A.MERCEDES-BENZ RAD 7JX15H2 ET				
	41 A1244010902 WAHLW.A1244011302*M.AMG-MOTOR M104-3.6*				
	ACHSANTRIEB 3,0*AMG FAHRWERKSATZ (FEDERN UND ANGEF.STO				
	BDÄMPFER)*AMG-GESCHWINDIGKEITSMESSER ANZEIGEBEREICH 28				
	0KM/H*M.AMG SEITENSCHWELLER W124 TYP: 007124881, FRONT				
	SPOILER W124 TYP: 001124881				
	FORTSETZUNG S. BEIBLATT				
L	02	9	01	P.2 P.4	0200/05750
18	04765	--		19	1740--
20	1428	--		G	001690--
12	-		13	-	Q
V.7	-	F.1	002200	F.2	002200
7.1	01000	7.2	01200	7.3	-
8.1	01000	8.2	01200	8.3	-
U.1	83P	U.2	04000	U.3	74
O.1	-	O.2	-	S.1	005
15.1	225/45R17 91W				
15.2	225/45R17 91W				
15.3	-				
R	-			11	7
K	-				
6	-			17	E
21	-			16	FW486478



Europäische Gemeinschaft
Bundesrepublik Deutschland
Zulassungsbescheinigung Teil II

D

Свидетельство за регистрация - Част II / Permisso de circulacion, Parte II / Osvedčenie o registraci - Cast II / Registreringsattest, Del II / Registreenimistunnistus, Osa II / Άδεια κυκλοφορίας/Πιστοποιητικό Εγγραφής, Μέρος II / Registration certificate, Part II / Certificat d'immatriculation, Partie II / Prometna dozvola II / Carta di circolazione, Parte II / Reģistrācijas apliecība, II. daļa / Registrācijas liudzināšana, II. daļa / Forgalm engedely, II. rész / Certifikat ta' Registrazzjoni, It-II Parti / Kentekenbewijs, Deel II / Dowód Rejestracyjny, Część II / Certificado de matrícula, Parte II / Certificat de înmatriculare, Parte II / Osvedčenie o evidencii, Cast' II / Prometno dovoljenje, Del II / Bekräftigingsintyg, Osa II / Registreringsbeviset, Del II

Diese Bescheinigung nicht im Fahrzeug aufbewahren!

A	Amtliches Kennzeichen	AA KY635
B	Datum der Erstzulassung des Fahrzeugs	30.05.1995
C.3.1	Name oder Firmenname	AUTOHAUS RÖMER OHG
C.6.1	Vorname(n)	
C.3.2	Anschrift zum Zeitpunkt der Ausstellung der Bescheinigung	KARLSTR. 2 /1 73433 AALEN
C.6.3		
C.4c		
I	Datum	07.09.2020

Der Inhaber der Zulassungsbescheinigung wird nicht als Eigentümer des Fahrzeugs ausgewiesen.

LANDRATSAMT
OSTALBKREIS
KFZ-ZULASSUNGSBEHÖRDE
AALEN

Nur zur Nutzung des Sicherheitscodes im internetbasierten Zulassungsverfahren freilegen. Dokument nur unbeschädigt gültig.

FW486478

(Nummer der Zulassungsbescheinigung)

D.1	Marke	MERCEDES-BENZ
D.2	Typ	124 T
D.3	Variante	-
D.3	Version	-
D.3	Handelsbezeichnung(en)	E36 AMG
(2)	Hersteller-Kurzbezeichnung	DAIMLER-BENZ (D)
(2.1)	Code zu (2)	0708
E	Fahrzeug-Identifizierungsnummer	WDB1240921F312194
J	Fahrzeugklasse	01
(5)	Bezeichnung der Fahrzeugklasse und des Aufbaus	PERSONENKRAFTWAGEN GESCHLOSSEN
R	Farbe des Fahrzeugs	
P.1	Hubraum in cm³	03606
P.3	Kraftstoffart oder Energiequelle	BENZIN
K	Nummer der EG-Typegenehmigung oder ABE	-
(17)	Merkmal zur Betriebs-erlaubnis	E
(25)	Zusätzliche Vermerke der Zulassungsbehörde:	

(Fahrzeug-Identifizierungsnummer als Barcode)

(23) Raum für interne Vermerke des Herstellers

LANDRATSAMT
OSTALBKREIS
KFZ-ZULASSUNGSBEHÖRDE

Datum: 07.09.20
Unterschrift: E. E. E.

BISH. ZULASSUNGSBESCH. TEIL II / BISH. FAHRZEUGBRIEF
U ENTWERTET UND ZURÜCKGEGEBEN

NR.: FW486573



Leading Edge Autosport
 319 Westtown Rd Ste 1
 West Chester, PA. 19382
 Phone: 610-431-8459
 Precision, Performance, Perfection

INVOICE

5006

Org. Est. # 005445

Tax Resale # : 7124467

Date: 02/08/2021

Work Completed : 01/11/2021

INVOICE

biundo, mario

1995 Mercedes-Benz - e36 - 3.2l inline six

Lic # : 312194

Odometer In : 12491

allentown, pa

Cell 631-377-8877

VIN # : WDB124092 **1F312194**

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
left boot 124-811-01	1.00	145.35	145.35	rear brake feel like they are hanging up rear tires dry rot bad vibration in rear of vehicle		
right boot 124-811-04	1.00	243.53	243.53	Safety Check / Multi-Point Inspection Brakes- F: 5 R: 4 Tires- F: 9 R: 5 SI Due- na	0.39	44.95
gasket 126-271-11	1.00	9.78	9.78			
ATF Dextron 3 DexIII	6.00	4.25	25.50	replace both mirror boots	1.50	185.93
trans filter 126-277-02	1.00	29.96	29.96	perform transmission service, change filter, gasket, and fluid	1.50	185.93
Wiper Blade 26CA	1.00	15.95	15.95	replace both headlight wiper blades	0.80	99.16
bulb 9003	2.00	9.38	18.76	install right headlight rear cover, replace both headlight bulbs	1.00	123.95
rear cover cover	2.00	77.78	155.56	Lube Oil & Filter Change	0.21	24.95
5w40 Synthetic 5w40	8.00	7.55	60.40	replace all 4 brake hoses and flush system	3.00	371.85
oil filter 104-180-01	1.00	12.44	12.44	replace rear bake calipers, pads, and rotors	2.50	309.88
Brake Fluid - L DOT4	3.00	12.99	38.97	rebuild both rear calipers with shipping back		525.00
Brake Hose 171 428 00 35	2.00	18.32	36.64	replace drive belt	0.70	86.77
Brake Hose 204 428 04 35	2.00	22.08	44.16	Mount & Balance 4 Tires Dealer Rate	1.26	145.00
shipping calipers for rebuild shipping	1.00	25.00	25.00	replace air filter	0.30	37.19
Brake Pad Set w/ Shims 005 420 17 20-41	1.00	56.98	56.98	replace valve cover gasket	4.50	557.78
Brake Disc 124 423 10 12	2.00	87.08	174.16	sand blast valve cover and center section when removed, prime, and repaint factory silver	1.50	185.93
Brake Pad Sensor 140 540 12 17	2.00	4.94	9.88	replace rear pinion seal and nut	2.00	247.90
Drive Belt 6PK-2475	1.00	49.42	49.42	replace oil pressure switch	1.20	148.74
pa tire tax tire tax	4.00	1.00	4.00	ALIGNMENT ***Break Tie Rods Loose For Alignment***		169.00
kumho ecsta 225/45r17	4.00	99.95	399.80			
air filter air filter	1.00	57.38	57.38			



Leading Edge Autosport
319 Westtown Rd Ste 1
West Chester, PA. 19382
Phone: 610-431-8459
Precision, Performance, Perfection

INVOICE**5006**

Org. Est. # 005445

Tax Resale # : 7124467

Date: 02/08/2021

Work Completed : 01/11/2021

INVOICE**biundo, mario**

1995 Mercedes-Benz - e36 - 3.2l inline six

Lic # : 312194

Odometer In : 12491

allentown, pa

Cell 631-377-8877

VIN # : WDB124092 **1F312194****Part Description / Number****Qty****Sale****Ext****Labor Description****Hours****Ext**

valve cover gasket kit

1.00

89.38

89.38

gasket kit

1.00

25.99

25.99

high temp primer, paint, and clear

1.00

8.68

8.68

coat for valve cover

1.00

12.24

12.24

paint

1.00

19.95

39.90

pinion washer

1.00

44.88

44.88

washer

1.00

129.19

129.19

pinion nut

1.00

582.76

582.76

pinion nut

2.00

19.95

39.90

Gear Oil GL5

1.00

44.88

44.88

75W90

1.00

129.19

129.19

rear pinion seal

1.00

582.76

582.76

pinion seal

1.00

129.19

129.19

oil pressure switch

1.00

582.76

582.76

oil pressure

1.00

582.76

582.76

invoice past due one month 20% fee

1.00

582.76

582.76

added

1.00

582.76

582.76

failure to pay

1.00

582.76

582.76

[Payments - Check - \$2,500.00]

Share Your Experience! Leave Us A Review On Facebook!

I hereby authorized the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work must be performed in our shop & cannot exceed the original cost of repair. Any vehicle left on premises for any amount of time exceeding fourteen (14) days after work is completed will be subject to a \$75/ day storage fee. Any parts - new, used, or otherwise - left on premises for any amount of time exceeding thirty (30) days after work is completed will become property of Leading Edge Autosport LLC.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Share Your Experience! Leave Us A Review On Facebook!**Labor:** 2,755.91
Parts: 2,546.64
Sublet: 694.00**Sub:** 5,996.55
Tax: 0.00
Total: \$5,996.55
Bal Due: \$3,496.55

Vehicle Received: 11/22/2020

Customer Number : 1651

Signature _____ Date _____

Visit us on the web: www.Leadingedgeautosport.comEmail Address: Leadingedgeautosport@gmail.com



Europäische Gemeinschaft
Bundesrepublik Deutschland
Zulassungsbescheinigung Teil II
(Fahrzeugbrief)



Свидетелство за регистрация - Част II / Permis de circulație. Parte II / Osvědčení o registraci - Část II / Registeringsattest. Del II / Registeringsattest. Osa II /
Αντίστοιχο έγγραφο: Πρωτόκολλο Εγγραφής. Μέρος II / Registration certificate. Part II / Certificat d'immatriculation. Partie II / Prometna dozvola II / Carta di circolazione. Parte II /
Registrācijas apliecība. II. daļa / Registrācijas liudijimas. II. dalis / Forgalmi engedély. II. Rész / Certifikat ta' Registrazzjoni. It-II Parti / Kentekenbewijs. Deel II /
Dowód Rejestracyjny. Część II / Certificado de matrícula. Parte II / Certificat de Immatriculare. Parte II / Osvědčení o evidenci. Část II / Prometno dovoljenje. Del II /
Rekisterintodistus. Osa II / Registeringsbeviset. Del II

Diese Bescheinigung nicht im Fahrzeug aufbewahren!

A	Amtesliches Kennzeichen	AA KY635			
B	Datum der Erstzulassung des Fahrzeugs	30.05.1995	(1) Anzahl der Verhalter	-	(1) Anzahl der Verhalter
C.3.1 C.6.1	Name oder Firmenname	AUTOHAUS RÖMER OHG			
C.3.2 C.6.2	Vorname(n)				
C.3.3 C.6.3	Anschrift zum Zeitpunkt der Ausstellung der Bescheinigung	KARLSTR. 2 / 1 73433 AALEN			
C.4c	Der Inhaber der Zulassungsbescheinigung wird nicht als Eigentümer des Fahrzeugs ausgewiesen.				
I	Datum	07.09.2020	Datum		



LANDRATSAMT
OSTALBKREIS
KFZ-ZULASSUNGSBEHÖRDE
AALEN

← Nur zur Nutzung des Sicherheitscodes
im internetbasierten Zulassungsver-
fahren freilegen. Dokument nur
unbeschädigt gültig.

FW486478

(Nummer der Zulassungsbescheinigung)

(Fahrzeug-Identifizierungsnummer als Barcode)

D.1	Marke	MERCEDES-BENZ	(23) Raum für interne Vermerke des Herstellers	
	Typ	124 T		
D.2	Variante	-		
	Version	-		
D.3	Handelsbezeichnung(en)	E36 AMG		
(2)	Hersteller-Kurzbezeichnung	DAIMLER-BENZ (D)		
(2.1)	Code zu (2)	0708	(2.2) Code zu D.2 nach Hersteller	000 00000-
E	Fahrzeug-Identifizierungsnummer	WDB1240921F312194	(3) Prüfziffer nach Fahrzeug-Identifizierungsnummer	6
J	Fahrzeugklasse	01	(4) Art des Fahrzeugs	0200
(5)	Bezeichnung der Fahrzeugklasse und des Aufbaus	PERSONENKRAFTWAGEN GESCHLOSSEN		
R	Farbe des Fahrzeugs		(11) Code zu R	7
P.1	Hubraum in cm³	03606	P.2 P.4 Leistungsangabe in kW (Nennleistung) bei 1/min	0200/05750
P.3	Kraftstoffart oder Energieträger	BENZIN	(10) Code zu P.3	0001
K	Nummer der EG-Typgenehmigung oder ABE	-	(6) Code zu K	-
(17)	Merkmale zur Betriebserlaubnis	E		
(25)	Zusätzliche Vermerke der Zulassungsbehörde:			

LANDRATSAMT
OSTALBKREIS
KFZ-ZULASSUNGSBEHÖRDE

Datum:

07.09.20

Unterschrift:

Eckhardt

BISH. ZULASSUNGSBESCH. TEIL II / BISH. FAHRZEUGBRIEF
U ENTWERTET UND ZURÜCKGEGEBEN

NR.: FW486573

Zulassungsbescheinigung Teil I

(Fahrzeugschein)

AA-K-0-251/20-00089

Europäische
Gemeinschaft



Bundesrepublik
Deutschland

Свидетельство за регистрация - Част I / Permiso de circulación. Parte I /
Osvědčení o registraci - Část I / Registreringsattest. Del I /
Registrierungsbescheinigung. Teil I / Mica școale de înmatriculare. Partea I /
Registration certificate. Part I / Certificat d'immatriculation. Partie I /
Prometna dozvola I / Carta di circolazione. Parte I / Registrācijas apliecība.
daļa / Registrācijas liudzimas. I daļa / Forgalmi engedély. I. Rész / Certificat
ta' Registrazzjoni. L-I-Parti / Kentekenbewijs. Deel I / Dowód Rejestracyjny.
część I / Certificado de matrícula. Parte I / Certificat de înmatriculare. Partea I /
Osvedčenie o evidencii. Časť I / Prometno dovoljenje. Del I /
Rekisteröintodistus. Osa I / Registreringsbeviset. Del I

Ämtliches Kennzeichen:

AA KY635

1.1 Name oder Firmenname

AUTOHAUS RÖMER OHG

1.2 Vorname(n)

1.3 Anschrift

KARLSTR. 2 / 1
73433 AALEN

Nächste HU

(Monat und Jahr):

AALEN

09.2022

Datum:

07.09.2020

4c Der Inhaber der Zulassungsbescheinigung wird nicht als Eigentümer des
Fahrzeugs ausgewiesen.

B	30.05.1995	2.1	0708	2.2	00000000-	L	02	9	01	P.2 P.4	0200/05750	T	236	
J	01	4	0200			18	04765	--		19	1740--			
E	WDB1240921F312194	3	6			20	1428	--		G	001690--			
D.1	MERCEDES-BENZ					12	-		13	-	Q	-		
	124 T					V.7	-		F.1	002200	F.2	002200		
D.2	-					7.1	01000		7.2	01200	7.3	-		
	-					8.1	01000		8.2	01200	8.3	-		
D.3	E36 AMG					U.1	83P		U.2	04000	U.3	74		
2	DAIMLER-BENZ (D)					O.1	-		O.2	-	S.1	005	S.2	-
5	PERSONENKRAFTWAGEN					15.1	225/45R17 91W							
	GESCHLOSSEN					15.2	225/45R17 91W							
V.9	-					15.3	-							
14	SCHADSTOFFARM E2					R	-			11	7			
P.3	BENZIN					K	-							
10	0001	143	0414	P.1	03606	6	-			17	E	16	FW486478	
22	ZU 15: A.AMG LM-RAD 7,5JX17H2 ET42 1244001302*ZU 15: A					21	-							
	.GEN. 205/60R15 91T M+S A.MERCEDES-BENZ RAD 7JX15H2 ET													
	41 A1244010902 WAHLW.A1244011302*M.AMG-MOTOR M104-3.6*													
	ACHSANTRIEB 3,0*AMG FAHRWERKSATZ (FEDERN UND ANGEF.STO													
	BDÄMPFER)*AMG-GESCHWINDIGKEITSMESSER ANZEIGEBEREICH 28													
	0KM/H*M.AMG SEITENSCHWELLER W124 TYP: 007124881, FRONT													
	SPOILER W124 TYP: 001124881													
	FORTSETZUNG S. BEIBLATT													

, (FORTSETZUNG AUF BEIBLATT)HECKSCHÜRZE W124 TYP:
001124882* BASISFAHRZEUG MERCEDES-BENZ E320T***DA
TUM ZUR EMISSIONSKLASSE: 30.05.1995*

Beiblatt zur Zulassungsbescheinigung Teil I

AA KY635

WDB1240921F312194

DAIMLER-BENZ (D)

Landratsamt

Ostalb-Kreis

Zulassungsbehörde

AALEN





Leading Edge Autosport

319 Westtown Rd Ste 1
West Chester, PA. 19382
Phone: 610-431-8459
Precision, Performance, Perfection

REPAIR ORDER #

005006

Org. Est. # 005445

REPAIR ORDER - RO

Scheduled : 11/22/2020 04:09 PM

Print Date : 11/30/2020

mario
Cell 631-
Cust ID : 1651
Last Service : No History

2001 Mercedes-Benz - e36 - gas

Lic # : 312194 - PA

VIN # : WDB124092 1F312194

MFG Date : 11/22/2020

Current Odom : 12491

Elapsed : 0

Labor Requested / Part Description	Part #	Qty	Parts List	Extended
rear brake feel like they are hanging up				
rear tires dry rot bad				
vibration in rear of vehicle				
Safety Check / Multi-Point Inspection				44.95
Brakes- F: 5 R: 4				
Tires- F: 9 R: 5				
SI Due- na				
replace both mirror boots				185.93
left boot	124-811-01	1.00	145.35	145.35
right boot	124-811-04	1.00	243.53	243.53
perform transmission service, change filter, gasket, and fluid				185.93
gasket	126-271-11	1.00	9.78	9.78
ATF Dextron 3	DexIII	6.00	4.25	25.50
trans filter	126-277-02	1.00	29.96	29.96
replace both headlight wiper blades				99.16
Wiper Blade	26CA	1.00	15.95	15.95
install right headlight rear cover				12.40
rear cover	cover	1.00	77.78	77.78
Lube Oil & Filter Change				24.95
5w40 Synthetic	5w40	8.00	7.55	60.40
oil filter	104-180-01	1.00	12.44	12.44
replace all 4 brake hoses and flush system				371.85
Brake Fluid - L	DOT4	3.00	12.99	38.97
Brake Hose-Rear	171 428 00 35	2.00	18.32	36.64
Brake Hose-Front	204 428 04 35	2.00	22.08	44.16
replace rear brake calipers, pads, and rotors				309.88
Brake Disc-Rear	210 423 05 12 64	2.00	63.32	126.64
Brake Pad Set-Rear w/ Shims	003 420 30 20 41	1.00	76.09	76.09
Brake Caliper-Rear Left Unloaded w/o Bracket	19-1861	1.00	94.63	94.63
Brake Caliper-Rear Right Unloaded w/o Bracket	19-1860	1.00	92.60	92.60
replace drive belt				86.77
Drive Belt	6PK-2475	1.00	49.42	49.42
Mount & Balance 4 Tires				145.00
pa tire tax	tire tax	4.00	1.00	4.00
kumho ecsta	225/45r17	4.00	99.95	399.80
replace air filter				37.19
air filter	air filter	1.00	57.38	57.38
replace valve cover gasket				557.78
valve cover gasket kit	gasket kit	1.00	89.38	89.38



Leading Edge Autosport

319 Westtown Rd Ste 1

West Chester, PA. 19382

Phone: 610-431-8459

Precision, Performance, Perfection

REPAIR ORDER #

005006

Org. Est. # 005445

REPAIR ORDER - RO

Scheduled : 11/22/2020 04:09 PM

Print Date : 11/30/2020

2001 Mercedes-Benz - e36 - gas

Lic # : 312194 - PA

VIN # : WDB124092 1F312194

MFG Date : 11/22/2020

Current Odom : 12491

Elapsed : 0

Last Service : No History

Labor Requested / Part Description

	Part #	Qty	Parts	List	Extended
replace rear pinion seal and nut					247.90
pinion washer	washer	1.00	8.68		8.68
pinion nut	pinion nut	1.00	12.24		12.24
Gear Oil GL5	75W90	2.00	19.95		39.90
rear pinion seal	pinion seal	1.00	44.88		44.88

Share Your Experience! Leave Us A Review On Facebook!

Parts: 1,836.10

Labor: 2,309.69

Tax: 248.75

Total: 4,394.54

Balance: 4,394.54

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. Unless otherwise explicitly stated, there is a minimum one (1) hour labor rate charge for any diagnostic work. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work must be performed in our shop & cannot exceed the original cost of repair. Any vehicle left on premises for any amount of time exceeding fourteen (14) days after work is completed will be subject to a \$75/ day storage fee. Any parts - new, used, or otherwise - left on premises for any amount of time exceeding thirty (30) days after work is completed will become property of Leading Edge Autosport LLC. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Authorized By _____ Date _____ Time _____

Auto Critic Inc.

1336 S Federal Hwy
Pompano Beach FL 33062
(954)786-7086
F(954)786-7084

Mario Biundo

1995 M-Benz E36 Wagon (Japan)
WDB1240921F312194

2/22/2021 – Vehicle Towed to Auto Critic : Current Mileage 12588

Customer states vehicle has no Reverse.

Start Vehicle to check for Reverse, Car Stalled During Test drive, would not stay running longer than 1-2 Mins, Was able to check that vehicle has No reverse. Pull car into building to drop transmission pan and inspect for metal shavings. Found pan filled with metal shavings.

2/24/2021- Vehicle Towed to transmission repair shop for transmission rebuild
When transmission rebuild was complete (4 weeks later, due to hard to get parts) tried to test drive car and the car would not run for longer than 1- 2 mins and would shut off.

3/24/2021- Vehicle towed back to Auto Critic Inc. Tried to drive car and car would not stay running. Start Diagnostic on why car wont stay running. Upon Inspection we found the Crankshaft Position Wiring compromised, it was broken and exposed. We Believe this compromised wire shorted a component in the Engine Control Unit. DIAGNOSTIC TOOK DAYS ! No information / Diagrams are available for this car.

4/5/2021- Remove Engine Control Unit and ASD Relay to send out for Inspection / Repair.

4/14/2021- Update – Waiting on special order parts from overseas for control unit repair.

4/27/2021- Picked up Engine Control Unit w/ OHM control Box to set Engine Control Unit. NO GUARANTEE ON REPAIR:: Vehicle started and we were able to drive vehicle for 2 Days and test transmission rebuild, vehicle now has reverse.


4/29/2021- Notified Customer to come and pick up vehicle and customer let us know he would pick up the car the following day (Friday 4/30/2021).

4/30/2021 – Customer did not show up:: Parked Vehicle in the building on Friday for the weekend. Upon returning to the shop on Monday (5/3/2021) Vehicle would no longer start, just cranks.

5/3/2021 – Notified Customer that the vehicle no longer runs.

Current Mileage 5/3/2021 :: 12603
Vehicle Drove 15 Miles Total

8/27/2021 – RELEASE OF RESPONSIBILITY – Auto Critic Inc is not responsible for the current operation of the vehicle but is more than willing to help try to get the car running.

x 

ITEM	QTY	PRICE	DESCRIPTION
LABOR	0.00	0.00	Customer Complaint : No Reverse - Shifting @ 5500 RPM- Holds Shift out
SUBLET WORK	1.00	2400.00	Sublet: TRANSMISSION REBUILD
KD	1.00	24.50	KICK DOWN SWITCH -wp
CONTROL UNIT	1.00	850.00	ENGINE CONTROL UNIT REBUILD * Special Order Parts overseas*
LABOR	0.00	0.00	Found Broken / Compromised Wire for Crank Sensor - Repair Wiring.
LABOR	0.60	84.00	Repair Short in ASD Relay
TOW	1.00	120.00	TOW to Transmission Shop

<i>QUESTIONS:</i> Call us We are always happy to answer any vehicle service questions you have. Please refer to the printed work order you received from us at the beginning of the job for contract terms, limitation of liabilities, and warranties/ guarantees pertaining to items and services listed in this work order summary.	Sublet	2400.00
	Supplies	15.00
	Disposal	1.00
	Parts	994.50
	Labor	84.00
	SubTotal	3494.50
	Salestax	76.55
	Coupons	0.00
	Deposits	0.00

AUTOMATIC TRANSMISSION REBUILD

Disassemble Transmission, discard all soft parts, clean all parts to be used in reassembly.

Replace Clutches, Bands, Seals, Gaskets, Bushings, Bearing and Internal Transmission Rings along with a new Transmission Filter.

Replace Solenoid, Planetary, & Torque Converter. Reassemble , modify and update as needed. Reassemble Rebuilt Transmission.