Leading Edge Autosport
319 Westtown Rd Ste 1
West Chester, PA. 19382
Phone: 610-431-8459
Precision, Performance, Perfection

INVOICE

INVOICE
5006
Org. Est. # 005445

Tax Resale # : 7124467

Work Completed : 01/11/2021

Date: 02/08/2021

biundo, mario

allentown, pa
Cell 631-377-8877

1995 Mercedes-Benz - e36 - 3.2l inline six
Lic # : 312194

Odometer In : 12491

VIN # : WDB124092 **1F312194**

Part Description / *Number*	Qty	Sale	Ext
left boot *124-811-01*	1.00	145.35	145.35
right boot *124-811-04*	1.00	243.53	243.53
gasket *126-271-11*	1.00	9.78	9.78
ATF Dextron 3 *DexIII*	6.00	4.25	25.50
trans filter *126-277-02*	1.00	29.96	29.96
Wiper Blade *26CA*	1.00	15.95	15.95
bulb *9003*	2.00	9.38	18.76
rear cover *cover*	2.00	77.78	155.56
5w40 Synthetic *5w40*	8.00	7.55	60.40
oil filter *104-180-01*	1.00	12.44	12.44
Brake Fluid - L *DOT4*	3.00	12.99	38.97
Brake Hose *171 428 00 35*	2.00	18.32	36.64
Brake Hose *204 428 04 35*	2.00	22.08	44.16
shipping calipers for rebuild *shipping*	1.00	25.00	25.00
Brake Pad Set w/ Shims *005 420 17 20-41*	1.00	56.98	56.98
Brake Disc *124 423 10 12*	2.00	87.08	174.16
Brake Pad Sensor *140 540 12 17*	2.00	4.94	9.88
Drive Belt *6PK-2475*	1.00	49.42	49.42
pa tire tax *tire tax*	4.00	1.00	4.00
kumho ecsta *225/45r17*	4.00	99.95	399.80
air filter *air filter*	1.00	57.38	57.38

Labor Description	Hours	Ext
rear brake feel like they are hanging up rear tires dry rot bad vibration in rear of vehicle		
Safety Check / Multi-Point Inspection Brakes- F: 5 R: 4 Tires- F: 9 R: 5 SI Due- na	0.39	44.95
replace both mirror boots	1.50	185.93
perform transmission service, change filter, gasket, and fluid	1.50	185.93
replace both headlight wiper blades	0.80	99.16
install right headlight rear cover, replace both headlight bulbs	1.00	123.95
Lube Oil & Filter Change	0.21	24.95
replace all 4 brake hoses and flush system	3.00	371.85
replace rear bake calipers, pads, and rotors	2.50	309.88
rebuild both rear calipers with shipping back		525.00
replace drive belt	0.70	86.77
Mount & Balance 4 Tires Dealer Rate	1.26	145.00
replace air filter	0.30	37.19
replace valve cover gasket	4.50	557.78
sand blast valve cover and center section when removed, prime, and repaint factory silver	1.50	185.93
replace rear pinion seal and nut	2.00	247.90
replace oil pressure switch	1.20	148.74
ALIGNMENT ***Break Tie Rods Loose For Alignment***		169.00

Copyright (c) 2021 Mitchell Repair Information Company, LLC invhrs 1.16.20dc

Leading Edge Autosport
319 Westtown Rd Ste 1
West Chester, PA. 19382
Phone: 610-431-8459
Precision, Performance, Perfection

INVOICE

INVOICE 5006
Org. Est. # 005445

Tax Resale # : 7124467

biundo, mario

Work Completed : 01/11/2021 **Date: 02/08/2021**

allentown, pa
Cell 631-377-8877

1995 Mercedes-Benz - e36 - 3.2l inline six
Lic # : 312194
Odometer In : 12491

VIN # : WDB124092 **1F312194**

Part Description / Number	Qty	Sale	Ext
valve cover gasket kit *gasket kit*	1.00	89.38	89.38
high temp primer, paint, and clear coat for valve cover *paint*	1.00	25.99	25.99
pinion washer *washer*	1.00	8.68	8.68
pinion nut *pinion nut*	1.00	12.24	12.24
Gear Oil GL5 *75W90*	2.00	19.95	39.90
rear pinion seal *pinion seal*	1.00	44.88	44.88
oil pressure switch *oil pressure*	1.00	129.19	129.19
invoice past due one month 20% fee added *failure to pay*	1.00	582.76	582.76

Labor Description	Hours	Ext

[Payments - Check - $2,500.00]

Labor:	2,755.91
Parts:	2,546.64
Sublet:	694.00
Sub:	5,996.55
Tax:	0.00
Total:	$5,996.55
Bal Due:	$3,496.55

Share Your Experience! Leave Us A Review On Facebook!

I hereby authorized the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work must be performed in our shop & cannot exceed the original cost of repair. Any vehicle left on premises for any amount of time exceeding fourteen (14) days after work is completed will be subject to a $75/ day storage fee. Any parts - new, used, or otherwise - left on premises for any amount of time exceeding thirty (30) days after work is completed will become property of Leading Edge Autosport LLC.
NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Share Your Experience! Leave Us A Review On Facebook!

Vehicle Received: 11/22/2020

Signature _____ Date _____

Customer Number : 1651

Visit us on the web: www.Leadingedgeautosport.com

Email Address: ***Leadingedgeautosport@gmail.com***

Copyright (c) 2021 Mitchell Repair Information Company, LLC invhrs 1.16.20dc

Europäische Gemeinschaft
Bundesrepublik Deutschland

D

Zulassungsbescheinigung Teil II

(Fahrzeugbrief)

Свидетелството за регистрация - Част II / Permiso de circulación. Parte II / Osvědčení o registraci - Část II / Registreringsattest. Del II / Registreerimistunnistus. Osa II / Άδεια κυκλοφορίας/Πιστοποιητικό Εγγραφής. Μέρος II / Registration certificate. Part II / Certificat d'immatriculation. Partie II / Prometna dozvola II / Carta di circolazione. Parte II / Reģistrācijas apliecība. II. daļa / Registracijos liudijimas. II dalis / Forgalmi engedély. II. Rész / Certifikat tal' Registrazzjoni. It-II Parti / Kentekenbewijs. Deel II / Dowód Rejestracyjny. Część II / Certificado de matrícula. Parte II / Certificat de înmatriculare Partea II / Osvedčenie o evidencii. Časť II / Prometno dovoljenje. Del II / Rekisterointitodistus. Osa II / Registreringsbevis. Del II

Diese Bescheinigung nicht im Fahrzeug aufbewahren!

A	Amtliches Kennzeichen	AA KY635					
B	Datum der Erstzulassung des Fahrzeugs	30.05.1995	(1)	Anzahl der Vorhalter	–	(1)	Anzahl der Vorhalter
C.3.1 C.6.1	Name oder Firmenname	[redacted]					
C.3.2 C.6.2	Vorname(n)						
C.3.3 C.6.3	Anschrift zum Zeitpunkt der Ausstellung der Bescheinigung	[redacted]					
C.4c							
I	Datum	07.09.2020				I Datum	

Der Inhaber der Zulassungsbescheinigung wird nicht als Eigentümer des Fahrzeugs ausgewiesen.



LANDRATSAMT
OSTALBKREIS
KFZ-ZULASSUNGSBEHÖRDE
AALEN

Nur zur Nutzung des Sicherheitscodes im internetbasierten Zulassungsverfahren freilegen. Dokument nur unbeschädigt gültig.

F W 4 8 6 4 7 8

(Nummer der Zulassungsbescheinigung)

(Fahrzeug-Identifizierungsnummer als Barcode)

D.1	Marke	MERCEDES-BENZ					
D.2	Typ	124 T					
	Variante	–					
	Version	–					
D.3	Handelsbezeichnung(en)	E36 AMG					
(2)	Hersteller-Kurzbezeichnung	DAIMLER-BENZ (D)					
(2.1)	Code zu (2)	0708	(2.2)	Code zu D.2 weit. Prüfziffer	000 00000-		
E	Fahrzeug-Identifizierungsnummer	WDB1240921F312194			(3)	Prüfziffer zur Fahrzeug-Identifizierungsnr.	6
J	Fahrzeugklasse	01	(4)	Art des Aufbaus	0200		
(5)	Bezeichnung der Fahrzeugklasse und des Aufbaus	PERSONENKRAFTWAGEN GESCHLOSSEN					
R	Farbe des Fahrzeugs				(11)	Code zu R	7
P.1	Hubraum in cm³	03606	P.2 P.4	Zulassungsleistung in kW Nenn-Dauerleistung in kW	0200/05750		
P.3	Kraftstoffart oder Energiequelle	BENZIN			(10)	Code zu P.3	0001
K	Nummer der EG Typgenehmigung oder ABE	–	(6)	Datum der Erteilung	–		
(17)	Messwert zur Bestätigung	E					
(25)	Zusätzliche Vermerke der Zulassungsbehörde						

(23) Raum für interne Vermerke des Herstellers

(24) Diese Bescheinigung wurde für das nebenstehend beschriebene Fahrzeug ausgegeben durch Zulassungsbehörde bzw. Genehmigungsinhaber)

LANDRATSAMT
OSTALBKREIS
KFZ-ZULASSUNGSBEHÖRDE

Datum: 07.09.20

Unterschrift: Eberhard

BISH. ZULASSUNGSBESCH. TEIL II / BISH. FAHRZEUGBRIEF
U ENTWERTET UND ZURÜCKGEGEBEN NR.: FW486573

Zulassungsbescheinigung Teil I

(Fahrzeugschein)

Nr. AA-K-0-251/20-00089

Europäische Gemeinschaft (D) Bundesrepublik Deutschland

Свидетелство за регистрация - Част I / Permiso de circulación. Parte I / Osvědčení o registraci – Část I /Registreringsattest. Del I / Registreerimistunnistus. Osa I / Νέα κοινοτοποίηση Πιστοποιητικό Εγγραφής Μέρος I / Registration certificate. Part I / Certificat d'immatriculation. Partie I / Prometna dozvola I / Carta di circolazione. Parte I / Reģistrācijas apliecība. daļa / Registracijos liudijimas. I dalis / Forgalmi engedély. I. Rész / Certifikat ta' Registrazzjoni. I-I Part. / Kentekenbewijs. Deel I / Dowód Rejestracyjny. część I / Certificado de matrícula. Parte I / Certificat de înmatriculare Partea I / Osvedčenie o evidencii. Časť I / Prometno dovoljenje. Del I / Rekisteröintitodistus. Osa I / Registreringsbeviset. Del I

Amtliches Kennzeichen:

AA KY635

.1.1 Name oder Firmenname

[redacted]

.1.2 Vorname(n)

.1.3 Anschrift

[redacted]

Nächste HU (Monat und Jahr): 09.2022 | Datum: 07.09.2020

4c Der Inhaber der Zulassungsbescheinigung wird nicht als Eigentümer des Fahrzeugs ausgewiesen.

B	30.05.1995	2.1	0708	2.2	00000000-	L	02	9	01
J	01	4	0200						
E	WDB1240921F312194	3	6						
D.1	MERCEDES-BENZ								
D.2	124 T - -								
D.3	E36 AMG								
2	DAIMLER-BENZ (D)								
5	PERSONENKRAFTWAGEN GESCHLOSSEN								
V.9	-								
14	SCHADSTOFFARM E2								
P.3	BENZIN								
10	0001	14.2	0414	P.1	03606				
22	ZU 15: A.AMG LM-RAD 7,5JX17H2 ET42 1244001302*ZU 15: A .GEN. 205/60R15 91T M+S A.MERCEDES-BENZ RAD 7JX15H2 ET 41 A1244010902 WAHLW.A1244011302*M.AMG-MOTOR M104-3.6* ACHSANTRIEB 3,0*AMG FAHRWERKSATZ (FEDERN UND ANGEP.STO ßDÄMPFER)*AMG-GESCHWINDIGKEITSMESSER ANZEIGEBEREICH 28 0KM/H*M.AMG SEITENSCHWELLER W124 TYP: 007124881, FRONT SPOILER W124 TYP: 001124881 FORTSETZUNG S. BEIBLATT								

L	02	9	01	P.2 P.4	0200/05750	T	236		
18	04765 --			19	1740--				
20	1428 - -			G	001690--				
12	-	13	-			Q	-		
V.7	-	F.1	002200			F.2	002200		
7.1	01000	7.2	01200			7.3	-		
8.1	01000	8.2	01200			8.3	-		
U.1	83P	U.2	04000			U.3	74		
0.1	-	0.2	-			S.1	005	S.2	-
15.1	225/45R17 91W								
15.2	225/45R17 91W								
15.3	-								
R						11	7		
K	-								
6	-			17	E	16	FW486478		
21	-								

,(FORTSETZUNG AUF BEIBLATT)HECKSCHÜRZE W124 TYP: 001124882* BASISFAHRZEUG MERCEDES-BENZ E320T***DATUM ZUR EMISSIONSKLASSE: 30.05.1995*

Beiblatt zur Zulassungsbescheinigung Teil I

AA KY635

WDB1240921F312194

DAIMLER-BENZ (D)

Landratsamt
Ostalbkreis
Zulassungsbehörde
AALEN

RIECO-Vordr. V24

Leading Edge Autosport
319 Westtown Rd Ste 1
West Chester, PA. 19382
Phone: 610-431-8459
Precision, Performance, Perfection

REPAIR ORDER #
005006
Org. Est. # 005445

REPAIR ORDER - RO

Print Date : 11/30/2020

Scheduled : 11/22/2020 04:09 PM

[redacted]
Cell 631-[redacted]
Cust ID : 1651
Last Service : No History

2001 Mercedes-Benz - e36 - gas
Lic # : 312194 - PA

VIN # : WDB124092 **1F312194**
MFG Date : 11/22/2020
Current Odom : 12491

[redacted]
Elapsed : 0

Labor Requested / Part Description	Part #	Qty	Parts List	Extended
rear brake feel like they are hanging up				
rear tires dry rot bad				
vibration in rear of vehicle				
Safety Check / Multi-Point Inspection				*44.95*
Brakes- F: 5 R: 4				
Tires- F: 9 R: 5				
SI Due- na				
.				
replace both mirror boots				*185.93*
left boot	124-811-01	1.00	145.35	145.35
right boot	124-811-04	1.00	243.53	243.53
perform transmission service, change filter, gasket, and fluid				*185.93*
gasket	126-271-11	1.00	9.78	9.78
ATF Dextron 3	DexIII	6.00	4.25	25.50
trans filter	126-277-02	1.00	29.96	29.96
replace both headlight wiper blades				*99.16*
Wiper Blade	26CA	1.00	15.95	15.95
install right headlight rear cover				*12.40*
rear cover	cover	1.00	77.78	77.78
Lube Oil & Filter Change				*24.95*
5w40 Synthetic	5w40	8.00	7.55	60.40
oil filter	104-180-01	1.00	12.44	12.44
replace all 4 brake hoses and flush system				*371.85*
Brake Fluid - L	DOT4	3.00	12.99	38.97
Brake Hose-Rear	171 428 00 35	2.00	18.32	36.64
Brake Hose-Front	204 428 04 35	2.00	22.08	44.16
replace rear bake calipers, pads, and rotors				*309.88*
Brake Disc-Rear	210 423 05 12 64	2.00	63.32	126.64
Brake Pad Set-Rear w/ Shims	003 420 30 20 41	1.00	76.09	76.09
Brake Caliper-Rear Left Unloaded w/o Bracket	19-1861	1.00	94.63	94.63
Brake Caliper-Rear Right Unloaded w/o Bracket	19-1860	1.00	92.60	92.60
replace drive belt				*86.77*
Drive Belt	6PK-2475	1.00	49.42	49.42
Mount & Balance 4 Tires				*145.00*
pa tire tax	tire tax	4.00	1.00	4.00
kumho ecsta	225/45r17	4.00	99.95	399.80
replace air filter				*37.19*
air filter	air filter	1.00	57.38	57.38
replace valve cover gasket				*557.78*
valve cover gasket kit	gasket kit	1.00	89.38	89.38

Copyright (c) 2020 Mitchell Repair Information Company, LLC ropartdetail2 dj 7.2.18

Company, LLC ropartdetail2 dj 7.2.18

Leading Edge Autosport
319 Westtown Rd Ste 1
West Chester, PA. 19382
Phone: 610-431-8459
Precision, Performance, Perfection

REPAIR ORDER #
005006
Org. Est. # 005445

REPAIR ORDER - RO

[redacted]

Scheduled : 11/22/2020 04:09 PM

Print Date : 11/30/2020

2001 Mercedes-Benz - e36 - gas
Lic # : 312194 - PA

Last Service : No History

VIN # : WDB124092 **1F312194**
MFG Date : 11/22/2020
Current Odom : 12491

Elapsed : 0

Labor Requested / Part Description	Part #	Qty	Parts List	Extended
replace rear pinion seal and nut				*247.90*
pinion washer	washer	1.00	8.68	8.68
pinion nut	pinion nut	1.00	12.24	12.24
Gear Oil GL5	75W90	2.00	19.95	39.90
rear pinion seal	pinion seal	1.00	44.88	44.88

Share Your Experience! Leave Us A Review On Facebook!

Parts: 1,836.10
Labor: 2,309.69

Tax: 248.75

Total: 4,394.54
Balance: 4,394.54

hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate
ne vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. Unless otherwise explicitly stated, there is a
inimum one (1) hour labor rate charge for any diagnostic work. An express mechanic's lien is hereby acknowledged on above car or truck to secure the
mount of repairs thereto. Warranty work must be performed in our shop & cannot exceed the original cost of repair. Any vehicle left on premises for any
mount of time exceeding fourteen (14) days after work is completed will be subject to a $75/ day storage fee. Any parts - new, used, or otherwise - left
n premises for any amount of time exceeding thirty (30) days after work is completed will become property of Leading Edge Autosport LLC .
IOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

uthorized By _____ Date _____ Time _____

Copyright (c) 2020 Mitchell Repair Information Company, LLC ropartdetail2 dj 7.2.18

分解整備記録簿写
1・2年点検整備記録簿写

1年 ■　2年 ■+□

点検良好	レ	交換	×	調整	A	清掃	C
分解	○	修理	△	締付	T	給油(水)	L

使用者の氏名又は名称　　様

住　所

自動車登録番号又は車両番号

車台番号

◆点検及び整備の概要等

エンジン・ルーム点検

■パワー・ステアリング
- ベルトの緩み、損傷
- ★取付けの緩み
- オイル漏れ
- オイルの量



■点火装置
- ☆スパーク・プラグの状態
- 点火時期
- ディストリビュータのキャップの状態



■バッテリ、電気配線
- ターミナル部の緩み、腐食
- 電気配線の接続部の緩み
- 損傷



■原動機
- 排気ガスの色
- CO、HCの濃度
- ☆エア・クリーナ・エレメントの汚れ、詰まり、損傷
- オイルの漏れ



■冷却装置
- ファン・ベルトの緩み、損傷
- 冷却水の漏れ

■燃料装置
- 燃料漏れ



■公害発散防止装置等
- メターリング・バルブの状態
- ブローバイ・ガス還元装置の配管の損傷
- 燃料蒸発ガス排出抑止装置の配管等の損傷
- 燃料蒸発ガス排出抑止装置のチェック・バルブの機能
- チョーク・キャニスタの詰まり、損傷
- 触媒等の排出ガス減少装置の取付けの緩み、損傷
- 二次空気供給装置の機能
- 排気ガス再循環装置の機能
- 減速時排気ガス減少装置の機能
- 一酸化炭素等発散防止装置の配管の損傷、取付状態

室内点検

■ハンドル
- 操作具合
- 遊び、緩み、がた

■ブレーキ・ペダル
- 遊び
- 踏み込んだ時の床板とのすき間
- ブレーキの効き具合



室内点検

■パーキング・ブレーキ・レバー(ペダル)
- 引きしろ(踏みしろ)
- パーキング・ブレーキの効き具合



■クラッチ・ペダル
- 遊び
- 切れた時の床板とのすき間



足廻り点検

■かじ取り車輪
- ★ホイール・アライメント

■ショック・アブソーバ
- 損傷、オイルの漏れ

■サスペンション
- 取付け部、連結部の緩み、がた
- 各部の損傷

■ホイール
- ☆タイヤの空気圧
- ☆タイヤの亀裂、損傷
- ☆タイヤの溝の深さ、異状摩耗
- スペアタイヤの空気圧
- ☆ボルト、ナットの緩み
- ★フロント・ホイール・ベアリングのがた
- ★リア・ホイール・ベアリングのがた

■ブレーキ・ディスク、ドラム、シュー
- ☆ディスクとパッドとのすき間
- ☆パッドの摩耗
- ディスクの摩耗、損傷
- ☆ドラムとライニングとのすき間
- ☆シューの摺動部分、ライニングの摩耗
- ドラムの摩耗、損傷



■ブレーキのマスタ・シリンダ、ホイール・シリンダ、ディスク・キャリパ
- マスタ・シリンダの液漏れ
- ホイール・シリンダの液漏れ
- ディスク・キャリパの液漏れ
- マスタ・シリンダの機能、摩耗、損傷
- ホイール・シリンダの機能、摩耗、損傷
- ディスク・キャリパの機能、摩耗、損傷



下廻り点検

■ステアリング・ギヤ・ボックス
- ★取付けの緩み

■ステアリングのロッド、アーム類
- ★緩み、がた、損傷
- ボール・ジョイントのダスト・ブーツの亀裂、損傷

■トランスミッション、トランスファ
- ☆オイルの漏れ
- ☆オイルの量




■プロペラ・シャフト、ドライブ・シャフト
- ☆連結部の緩み
- ドライブ・シャフトのユニバーサル・ジョイント部ダスト・ブーツの亀裂、損傷



■デファレンシャル
- ★オイルの漏れ
- ★オイルの量



■ブレーキ・ホース、パイプ
- 液漏れ、損傷、取付状態



■エグゾースト・パイプ、マフラ
- ☆取付けの緩み、損傷、腐食
- ☆遮熱板の取付けの緩み、損傷、腐食
- マフラの機能



外廻り点検

■フレーム、ボデー
- 緩み、損傷

その他必要となった点検・整備の内容

日常点検（依頼の有・無）

レ	ブレーキ液の量
レ	バッテリ液の量
レ	冷却水の量
レ	エンジン・オイルの量
レ	エンジンのかかり具合、異音
レ	低速、加速の状態
レ	ヘッドライト、ストップランプ、ウインカ、ランプ等の点灯、汚れ、損傷
レ	ウインド・ウォッシャ液の量、噴射状態
レ	ワイパの拭き取り状態

交換部品等	数量
エンジン・オイル	7 ℓ
オイル・フィルタ	1 個
LLC(ロング・ライフ・クーラント)	ℓ
ブレーキ・フルード	ℓ
ファンベルト	1
ブレーキパッド	1
ワイパーブレード	1
冷却材	1
ウォッシャー液	1
燃料漏れ	1
フューエルホース	1

注　この整備記録簿は、自動車検査証に記載されている生涯記録簿として活用して下さい。

お客様へ(メンテナンスに関するアドバイス)

タイヤの残溝	前輪	左・右	mm	点検の年月日	年　月　日
	後輪	左・右	mm	整備完了日	年　月　日
ライニング(パッド)の残厚	前輪	左・右	mm	整備主任者	
	後輪	左・右	mm		
総走行距離			km		

CO　　%　HC　　ppm

注：タイヤの残溝、ライニング等の残厚は最摩耗箇所の数値です。
☆印は1年間の走行距離が5,000km以下、★印は2年間の走行距離が10,000km以下の場合で、前回の当該点検を行うべき時期に点検した場合は省略できる項目です。
☆スパーク・プラグの状態（白金プラグ、イリジウム・プラグは点検省略可能です。）

富山ヤナセ株式会社高岡営業所
高岡市瑞穂町2番8号
TEL(0766)28－0880

富第2626号
普(小、乗)、小4
小3、小2、軽

保証書(有・無)　(不許複製)

富山県自動車整備振興会

タイヤの残溝	前輪	左・右	mm	点検の年月日	H22 年　月　日
	後輪	左・右 6.0	mm	整備完了日	H22 年　月　日
ライニング(パッド)の残厚	前輪	左・右 新品	mm	整備主任者	渡辺
	後輪	左・右 新品	mm		
総走行距離		231,214	km		

CO　　%　HC　　ppm

注：タイヤの残溝、ライニング等の残厚は最摩耗箇所の数値です。
☆印は1年間の走行距離が5,000km以下、★印は2年間の走行距離が10,000km以下の場合で、前回の当該点検を行うべき時期に点検した場合は省略できる項目です。
☆スパーク・プラグの状態（白金プラグ、イリジウム・プラグは点検省略可能です。）

富山ヤナセ株式会社高岡営業所
高岡市瑞穂町2番8号
TEL(0766)28-0880

富第2626号
普(小、乗)、小4
小3、小2、軽

保証書(有・無)　(不許複製)

社団法人 富山県自動車整備振興会