



STEVE'S EUROPEAN AUTOMOTIVE

Service
Invoice
90428

GVVDJ2AG509430

Created Time	11/10/25 4:19 PM	Year	1980
Invoiced	07/15/2026	Make	MG
Advisor	George W	Model	B
Division	SV	Lic.#	
PO#		ProdDate	
Checked By		Color	Black
Page#	1 of 13	Miles In	81,845
		Miles Out	81,855

Job Description

Perform initial electrical testing and repair some items:

Line Total 940.50

Customer States:

There is a severe battery drain. I bought a brand-new battery and installed it, the very next day it would not crank. I got it going with a jump, and when I drove it to Steve's I disconnected the battery. I think the alternator has gone bad and I have a new alternator sitting on the passenger's seat floor.

Dash lights do not work.

Small center interior illumination light does not work. I have it sitting connected by one wire, and a replacement bulb sitting on the center console.

Low beam headlights do not work (high beams do).

Fan for heat / defog does not work.

Turnsignals don't cancel when turning back to straight.

Perform extensive testing, inspection & analysis on the symptom(s). This process requires involved, in depth testing that is required in order to attempt to resolve the problem.

Technician results and recommendations:

Initial visual inspection found wire connector block on the alternator had loose wires. Cleaned block and reinstalled wire connectors. Verified alternator is not charging the battery.

Further inspection found ignition switch is staying on.

Also discovered ignition coil over heated.

Replaced ignition relay.

4920 Pontiac Lake Rd. Waterford, MI 48328 Tel: 248.674.2770 Fax Number: 248.674.2778

service@steveseuropeanauto.com www.steveseuropeanauto.com State Registration: F134733

Customer understands that all warranties & disclaimers are referenced in the text of the Service Invoice.

Repairs properly completed & checked by: _____

Repairs performed by: _____ Cert # _____

APR



Invoice Total

Supplies	\$98.39
Discount	(\$590.81)
Subtotal	\$3,310.09
Tax	\$32.26
Total	\$3,342.35



STEVE'S EUROPEAN AUTOMOTIVE

Service
Invoice
85146

any ss 2	Created Time Invoiced Advisor Division PO# Checked By Page#	08/29/24 12:55 PM 09/10/24 George W SV 1 of 5	Year Make Model Lic.# ProdDate Color Miles In Miles Out	1980 MG B Black 79,317 79,319
GVVDJ2AG509430				

Job Description

Vehicle does not start - perform preliminary inspection and attempt to get the engine running:

Line Total 209.00

Customer states: The engine doesn't start.

Push vehicle into the shop and perform visual inspection of the engine. Perform preliminary assessment of the battery and advise if charging or testing is recommended. Test ignition system for spark and advise if testing is required. Verify that there is fuel in the system. Advise on the next recommended course of testing.

Technician results and recommendations:

Engine is vapor locking. **Performed fuel pressure test. Fuel pressure is 3.5 PSI with a resting pressure of 3 psi. This is normal. Recommend fabricating and installing an aluminum heat shield under carburetor. Approximately 2.5 hours**

The vehicle arrived running poorly or not running at all:

****Note:** This vehicle did not run when it arrived or it was in a very poor running condition. We have no recent service history for the vehicle. Many things cannot be assessed when the vehicle is not in running condition. We need to first get it running, and then see what additional items may be recommended. The possibility exists that the engine has suffered one or more critical component/system failures which may not be evident until our initial repairs are completed. Our client understands and agrees that we are to be paid for the services we performed during the evaluation.

Fabricate and install carburetor heat shield:

Line Total 522.50

4920 Pontiac Lake Rd. Waterford, MI 48328 Tel: 248.674.2770 Fax Number: 248.674.2778

service@steveseuropeanauto.com www.steveseuropeanauto.com State Registration: F134733

Customer understands that all warranties & disclaimers are referenced in the text of the Service Invoice.

Repairs properly completed & checked by:

Repairs performed by: _____ Cert # _____



Invoice Total	
Supplies	\$58.52
Subtotal	\$790.02
Tax	\$0.00
Total	\$790.02



STEVE'S EUROPEAN AUTOMOTIVE

Service
Invoice
84236

GVVVDJ2AG509430

Created Time	06/24/24	Year	1980
Invoiced	8:01 AM	Make	MG
Advisor	08/28/2024	Model	B
Division	George W	Lic.#	
PO#	SV	ProdDate	
Checked By		Color	Black
Page#	1 of 18	Miles In	79,319
		Miles Out	79,328

Job Description

Perform comprehensive vehicle inspection (PPI - Digital Vehicle Inspection):

Line Total 350.00

Customer states:

I just bought this car two weeks ago. I have no service history. I know for sure the cabin blower doesn't work.

While I was driving on the highway, the engine quit running, and doesn't re-start.

I would like to get the car reliable.

Technician Recommendations:

Note to technician: inform Service Advisor if a compression test is recommended for this vehicle.

Research vehicle history through VIN number links if possible. Research open campaigns, service bulletins and recalls for vehicle.

Torque lug bolts/nuts to ____ foot pounds/NM.

Note to customer: a complete vehicle inspection should only be used as an aid. This inspection does not mean that there are no other problems, but only what we noticed or what appeared at the time of the inspection. Certain items on this inspection may need further testing and analysis to determine the extent of the issues before a more accurate estimate can be given. It's impossible for this inspection to determine if unexpected future problems are going to occur with vehicle.

4920 Pontiac Lake Rd. Waterford, MI 48328 Tel: 248.674.2770 Fax Number: 248.674.2778

service@steveseuropeanauto.com www.steveseuropeanauto.com State Registration: F134733

Customer understands that all warranties & disclaimers are referenced in the text of the Service Invoice.

Repairs properly completed & checked by: _____

Repairs performed by: _____ Cert # _____



Invoice Total	
Supplies	\$98.39
Subtotal	\$6,446.72
Tax	\$122.16
Total	\$6,568.88

WHITE'S AUTO GLASS & TRIM

16705 ECORSE RD., ALLEN PARK, MI 48101

PHONE: (734) 783-1460

E-Mail: white19677@msn.com

INVOICE

No. 274227

DATE 10-15-25
SALESPERSON

SOLD TO:

SHIP TO:

RO #	YEAR	VEHICLE	VIN #	INSTALLER
	1980	MG		
QUANTITY	DESCRIPTION		UNIT PRICE	TOTAL
	Replace Windshield		\$ 250.00	
	Replace convertible Top			
	Paid card			
	Total		1650.00	
	Tom Calvary			



STEVE'S EUROPEAN AUTOMOTIVE

Service
Estimate
119430

7/20 +

GVDJ2AG509430

Created Time Promised Advisor Division PO# Page#	06/27/24 4:21 PM George W SV 8 of 8	Year Make Model Lic.# ProdDate Color On Site	1980 MG B Black
---	---	--	--------------------------

Job Description

looseness or abnormal wear. Inspect and grease universal joints if required.
Road test vehicle.

Part Number	Description	QTY
112608	U Joint	2

Replace front shocks:

Attempt to remove shock hardware. This operation may include, cutting seized shock bolts from attaching points on the vehicle. Remove front shocks from vehicle. Inspect the condition of shock stops, dust cups, rubber bushings and mounting hardware. Replace as needed. Install per manufacturer's procedure.

Install replacement front shocks.

Torque lugs bolts to ___ foot pounds/NM (if required).

Road test vehicle to confirm proper operation

Part Number	Description	QTY
71095	SHOCK ABSORBER	2

Test and attempt to determine the cause of inoperative turn signals, hazard lights, left license light, left front marker light:

Customer States: The ___ lights do not work.

Inspect fuse condition for the effected inoperative circuit. Test for power and ground in the circuit. Inspect all the bulbs. Perform preliminary testing & analysis on symptom. Perform testing & analysis to determine a possible cause of the symptom (or symptoms). Additional labor beyond the preliminary testing may be required to resolve the problem.

Technician results and recommendations:

Date	Services Due
08/26/2024	OIL LEAK RE-INSPECTION
12/24/2024	SCHEDULED MAINTENANCE*

4920 Pontiac Lake Rd. Waterford, MI 48328 Tel: 248.674.2770 Fax Number: 248.674.2778

service@steveseuropeanauto.com www.steveseuropeanauto.com State Registration: F134733

This estimate is based on our inspection & does not cover any additional parts or labor which may be required after repairs have been started. Occasionally, worn or damaged parts are discovered which may NOT be evident on the first inspection. Due to this, the above prices are not guaranteed & part prices subject to change. Valid for 30 days.

Signature: _____ Date: _____



Estimate Total	
Supplies	\$98.39
Subtotal	\$6,661.19
Tax	\$148.01
Total	\$6,809.20

WINDSHIELD
TOP

CARB

ALTERNATOR
NEW BATTERY
SHOCKS

STRUTS

BLINKER SWITCH

TOTAL REAR BRAKES

SUN VISOR ATTACHMENT

OIL CHANGE

RADIATOR FIXED

SPARK PLUG WIRES

HEAD LIGHT WIRING REPLACE

TRANSMISSION LEAK REPAIR

GEAR OIL LEAK FIXED

REAR TRANSMISSION MOUNTS

U-JOINTS