

Estimate: \$1,700.00 Added Cost: \$4,300.00
Phone: 310-457-0266 Contacted By: shane Date/Time: 5/25/2005 12:50 PM
L OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. X
Original Estimate: \$1,700.00
Pay Type: TOTAL Labor 700.00
Amount \$: TOTAL Parts 3966.85
Employee: TOTAL Sublet Labor 300.00
SUBTOTAL 4966.85
TAX 307.43
** TOTAL DUE ** \$5,274.28

Signature: X
Independent Specialist in
Honda & Acura Automobiles

IMPORTANT INFORMATION ON REVERSE SIDE

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. X
Original Estimate: \$74.50
Qty: FLUID TOTAL Labor 235.00
5 Engine oil (qts.) Mobil One 32.65 TOTAL Parts 145.69
3 Transmission Oil/Manual Qts. 19.14 TOTAL Fluids 51.79
TOTAL Hazardous Waste 3.00
SUBTOTAL 435.48
TAX 15.30
** TOTAL DUE ** \$450.78

SIGNATURE ACKNOWLEDGES RECEIPT OF VEHICLE: X

R.A.R. #A114000
EPA #CAL-00126391

CREDIT CARDS
ACCEPTED
WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

www.autowaveinc.com

Independent Specialist in
Honda & Acura Automobiles

READ IMPORTANT INFORMATION ON REVERSE SIDE

Remove and reinstall valve covers to adjust valves. HAZARDOUS WASTE 0.50 17
REPLACE BOOST GAUGE

**** Continued on Next Page ****

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. X
Original Estimate: \$74.50
Pay Type: TOTAL Labor
Amount \$: TOTAL Parts
Employee: TOTAL Sublet Labor
TOTAL Misc. Shop Supply
TOTAL Other
SUBTOTAL
TAX
** TOTAL DUE **

SIGNATURE ACKNOWLEDGES RECEIPT OF VEHICLE: X

R.A.R. #A114000
EPA #CAL-00126391

CREDIT CARDS
ACCEPTED
WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

READ IMPORTANT INFORMATION ON REVERSE SIDE

Independent Sp
Honda & Acura A

INVOICE

Blueprint JDM LLC
2380 N Ogden, Suite 108
Mesa, AZ 85215

Info@blueprintjdm.com
+1 (480) 400-4730

BLUEPRINT
JDM

Bill to

Invoice details

Invoice no.: 1027
Invoice date: 01/22/2026
Due date: 01/22/2026

Service Tech: Jeff

Car Information: 1996 NSX-T

Product or service	Description	Qty	Rate	Amount
Labor	Diagnose misfire and rough running condition. Technician's notes: Found spark plugs fouled due to aftermarket piggy back fuel system. Found 2 Ignition coils bad and 1 coil intermittent.	1	\$180.00	\$180.00
MISC	NGK Iridium spark plugs (BKR7EIX-11)	6	\$11.99	\$71.94
Honda Parts	Ignition coil (FRONT)	3	\$461.20	\$1,383.60
Honda Parts	Ignition coil rear	3	\$295.42	\$886.26
Labor	Remove and replace spark plugs and ignition coils.	1	\$180.00	\$180.00
Honda Parts	Oil filter	1	\$20.72	\$20.72
Honda Parts	Oil drain plug washer	1	\$0.75	\$0.75
Fluids	Castrol GTX 10w-30 Engine oil (Quart)	6	\$8.00	\$48.00
Labor	Oil Change	0.5	\$180.00	\$90.00
Fluids	Supercharger oil	1	\$8.00	\$8.00
Labor	Remove and replace supercharger oil	0.25	\$180.00	\$45.00

ACURA 181 WEST
24458 CALABASAS ROAD
CALABASAS, CA 91382
(818) 222-5555
184214481996
TERMINAL #01

AMEX
CARD # 372018963045886 8481
DATE: 03/19/01 TIME: 17:28:04

SALE \$127.14
AUTH #1: 587323 REF #1: 1481886

ITEM DESC: 132631

I AGREE TO PAY ABOVE TOTAL AMOUNT
ACCORDING TO CARD ISSUER AGREEMENT

THANK YOU
PLEASE COME AGAIN
HAVE A NICE DAY

PAID
MAR 19 2001
By: Amy

FOR YOUR CONVENIENCE
SERVICE DEPT. HOURS:

MONDAY THRU FRIDAY:
6:30 AM to 6:00 PM

SATURDAY
7:00 AM to 4:00 PM

CLOSED SUNDAYS

THIS FORM IS AN ITEMIZED LIST OF REPAIRS
AND IS PART OF A REPAIR ORDER. IT IS NOT
A SALE INVOICE OR RECEIPT OF SALE. THIS
REPAIR ORDER CONTINUATION IS SUBJECT
TO ALL THE CONDITIONS OF THE ORIGINAL
REPAIR ORDER.

CUSTOMER SIGNATURE

CUSTOMER COPY

BAR# AF153988 EPA# CAD983603747

EPA #CAL-00126391

WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

READ IMPORTANT INFORMATION ON REVERSE SIDE

Ho

APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. X

Original Estimate: \$74.50

Pay Type:	TOTAL Labor	235.00
32.65 Amount \$:	TOTAL Parts	145.69
19.14 Employee:	TOTAL Fluids	51.79
	TOTAL Hazardous Waste	3.00
	SUBTOTAL	435.48
	TAX	15.30
	** TOTAL DUE **	\$450.78

VEHICLE: X

www.autowaveinc.com

Independent Specialist in
Honda & Acura Automobiles

IMPORTANT INFORMATION ON REVERSE SIDE

REMOVE AND REINSTALL VALVE COVERS TO ADJUST VALVES. Install new gaskets. Road test.

REPLACE BOOST GAUGE

0.50 11 40.00

**** Continued on Next Page ****

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. X

Original Estimate: \$2,500.00

Pay Type:	TOTAL Labor	2559.00
Amount \$:	TOTAL Parts	3418.64
Employee:	TOTAL Sublet Labor	862.00
	TOTAL Misc. Shop Supplies	7.90
	TOTAL Other	13.86
	SUBTOTAL	6861.40
	TAX	265.56
	** TOTAL DUE **	\$7,126.96

SIGNATURE ACKNOWLEDGES RECEIPT OF VEHICLE: X

CREDIT CARDS
ACCEPTED

INDEPENDENT SPECIALIST IN
HONDA & ACURA AUTOMOBILES

READ IMPORTANT INFORMATION ON REVERSE SIDE

Blueprint

Service Tech: Jeff
Car Information: 1996 NSX-T

Description	Qty	Rate	Amount
Diagnose misfire and rough running condition. Technician's notes: Found spark plugs fouled due to aftermarket piggy back fuel system. Found 2 Ignition coils bad and 1 coil intermittent.	1	\$180.00	\$180.00
VGK Iridium spark plugs BKR7EIX-11)	6	\$11.99	\$71.94
Ignition coil (FRONT)	3	\$461.20	\$1,383.60
Ignition coil rear	3	\$295.42	\$886.26
Remove and replace spark plugs and ignition coils.	1	\$180.00	\$180.00
Oil filter	1	\$20.72	\$20.72
Oil drain plug washer	1	\$0.75	\$0.75
Castrol GTX 10w-30 Engine oil (Quart)	6	\$8.00	\$48.00
Oil Change	0.5	\$180.00	\$90.00
Supercharger oil	1	\$8.00	\$8.00
Remove and replace supercharger oil	0.25	\$180.00	\$45.00

ACURA 101 WEST
24450 CALABASAS ROAD
CALABASAS, CA 91302
(818) 222-3555
184214481994
TERMINAL #81

132631

INVOICE

PAGE 1

SERVICE ADVISOR: 55 ANTHONY PICADO

VIN	LICENSE	MILEAGE IN / OUT	TAG
JH4NA118XTT000277	476395/476395	T599	

PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
0.00	19MAR01	0.00	CASH	19MAR2001

OPTIONS: DLR:251361 ENG:3.0_Liter

LIST	NET	TOTAL
ELS) (NSX MODELS)	9.00	9.00
OIL (4MM)	14.55	9.19
	0.48	0.48
	2.99	5.28
9.00 OTHER:	2.00	2.00
TOTAL LINE A:		25.95
BILSTEIN R-2000 SH W/ BILSTEIN R-2000	75.04	75.04
0	24.95	24.95
5.04 OTHER:	24.95	99.99
TOTAL LINE B:		99.99

I AGREE TO PAY ABOVE TOTAL AMOUNT
ACCORDING TO CARD ISSUER AGREEMENT

PLEASE COME AGAIN
HAVE A NICE DAY

THANK YOU FOR CHOOSING ACURA 101 WEST. YOU
MAY RECEIVE A SERVICE SATISFACTION SURVEY
FROM AMERICAN HONDA. WE WOULD APPRECIATE A
RATING OF EXCELLENT. IF FOR ANY REASON YOU
CAN NOT PLEASE CONTACT OUR SERVICE MANAGER
MAXX FOWLER. WE WANT TO MAKE SURE THAT YOUR
RELATIONSHIP WITH US IS LONG TERM !!!!!

DESCRIPTION	TOTALS
LABOR AMOUNT	84.04
PARTS AMOUNT	14.95
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	24.95
HAZARDOUS WASTE CHARGES	2.00
TOTAL CHARGES	125.94
LESS THIS AMOUNT	0.00
SALES TAX	1.20
PLEASE PAY THIS AMOUNT	127.14

FOR YOUR CONVENIENCE
SERVICE DEPT. HOURS:
MONDAY THRU FRIDAY:
6:30 AM to 6:00 PM
SATURDAY
7:00 AM to 4:00 PM
CLOSED SUNDAYS

CUSTOMER SIGNATURE

CUSTOMER COPY

BAR# AF153988 EPA# CAD983603747

Honda & Acura Automobiles

READ IMPORTANT INFORMATION ON REVERSE SIDE

AutoWave

17122 Gothard Street • Huntington Beach, CA

*** ESTIMATE # 9271 ***

Yr/Make/Model 1996 ACURA NSX
Service Writer SHANE

QTY Material (Part #)

1	94109-14000
1	15400-PL2-004
4	12513-PR7-A00
1	NPN
6	12343-PR7-A00
2	12341-PR7-A01
1	RM
1	19200-PR7-A03
1	14400-PR7-A01
1	14510-PR7-A01
1	38920-PR7-A01
1	16010-SD4-202
2	19300-004-000

PROBLEMS NOTES / LABOR CH

BELTS/WATER PUMP (REPLACE)
Replace timing, air conditioner, alter
timing belt tensioner. Replace front c
Inspect related components. Road tes

CHECK PINGING
Incorrect pulley (too large) at superch
wrong injectors. Wrong fpu.

INSTALL HIGH BOOST KIT
Includes replacing injectors, pulley, fu
engine control. Repair wiring at map.

INSTALL RM RACING MUFFLER

REPLACE REAR CAMSHAFT PLU
Includes adjusting valves and replace

LUBE, OIL AND FILTER / NSX
Drain engine oil. Install new engine
Adjust tire pressure as necessary. Ch
test.

REPLACE FUEL FILTER

CHECK ENGINE LIGHT ON
Codes 45 and 46 fuel supply codes R
This part may have damage due to w

CHECK OIL LEAK
Breather at supercharger pulley venti

***** Labor Continued on Next Page *****

* Comments:

Qts Oil Trans Oil Gear Fluids Grease \$
Fuel \$ Sublet \$ Do you want old parts? Yes No

Revised Amt: Time: Date: Direct: Phone: Per
Revised Amt: Time: Date: Direct: Phone: Per
Revised Amt: Time: Date: Direct: Phone: Per

Date: 05-08-2002 Time: 01:59 PM

AUTHORIZATI

A.R. #1418250
EPA #CAL-000125391

CREDIT CARDS
ACCEPTED

INDEPENDENT SPECIALIST IN
HONDA & ACURA AUTOMOBILES

READ IMPORTANT INFORMATION ON REVERSE SIDE

SUBTOTAL 265.56
TAX
** TOTAL DUE ** \$7,126.96

Independent Specialist in
Honda & Acura Automobiles

ON REVERSE SIDE

3 2 6 3 1

VOICE*

PAGE 1

ICE ADVISOR: 55 ANTHONY PICADO

VIN	LICENSE	MILEAGE IN / OUT	TAG
18XTT000277		476395/476395	T599
PO NO.	RATE	PAYMENT	INV. DATE
	0.00	CASH	19MAR2001

251361 ENG:3.0_Liter

LIST	NET	TOTAL
	9.00	9.00
14.55	9.19	9.19
0.48	0.48	0.48
2.99	0.88	5.28
	2.00	2.00
2.00	TOTAL LINE A:	25.95

DO
N R-2000

	75.04	75.04
	24.95	24.95
24.95	TOTAL LINE B:	99.99

FOR CHOOSING ACURA 101 WEST. YOU
VE A SERVICE SATISFACTION SURVEY
ICAN HONDA. WE WOULD APPRECIATE A
EXCELLENT. IF FOR ANY REASON YOU
LEASE CONTACT OUR SERVICE MANAGER
ER. WE WANT TO MAKE SURE THAT YOUR
HIP WITH US IS LONG TERM !!!!!

DESCRIPTION	TOTALS
LABOR AMOUNT	84.04
PARTS AMOUNT	14.95
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	24.95
HAZARDOUS WASTE CHARGES	2.00
TOTAL CHARGES	125.94
LESS THIS AMOUNT	0.00
SALES TAX	1.20
PLEASE PAY THIS AMOUNT	127.14

A# CAD983603747

Honda & Acura Automobiles

ON REVERSE SIDE



AUTO WAVE INC.

17122 Gothard Street • Huntington Beach, CA 92647 • (714) 841-2433

**** ESTIMATE # 9271 ****



Yr/Make/Model 1996 ACURA NSX
Service Writer SHANE

Cone No.

License No. HEPCFRE
CURRENT Mileage 64827
PREVIOUS Mileage 011
Chassis JH4NA118XTT000277
Engine
Prod Date 11/95 Color BLACK

QTY Material (Part #)

1 94109-14000
1 15400-PL2-004
4 12513-PR7-A00
1 NPN
6 12543-PR7-A00
2 12341-PR7-A01
1 RM
1 19200-PR7-A03
1 14400-PR7-A01
1 14510-PR7-A01
1 38920-PR7-A01
1 16010-SD4-202
2 19300-004-000

PROBLEMS NOTES / LABOR CHARGED

BELTS/WATER PUMP (REPLACE) / NSX
Replace timing, air conditioner, alternator belts. Replace water pump. Replace
timing belt tensioner. Replace front camshaft seals (4). front crankshaft seal.
Inspect related components. Road test.

CHECK PINGING
Incorrect pulley (too large) at supercharger creating too much boost. Possible
wrong injectors. Wrong fpru.

INSTALL HIGH BOOST KIT
Includes replacing injectors, pulley, fuel pressure regulator. Re install emc at
engine control. Repair wiring at map sensor harness.

INSTALL RM RACING MUFFLER

REPLACE REAR CAMSHAFT PLUGS
Includes adjusting valves and replacing valve cover gaskets

LUBE, OIL AND FILTER / NSX
Drain engine oil. Install new engine oil & filter. Replace drain plug gasket.
Adjust tire pressure as necessary. Check and fill fluid levels as necessary. Road
test.

REPLACE FUEL FILTER

CHECK ENGINE LIGHT ON
Codes 45 and 46. fuel supply codes Remove ad reinstall emc at ecu and adjust.
This part may have damage due to water

CHECK OIL LEAK
Breather at supercharger pulley venting small amount of oil.

* Comments:

**** Labor Continued on Next Page ****

Qts Oil _____ Trans Oil _____ Gear Fluids _____ Grease \$ _____ Other \$ _____
Fuel \$ _____ Sublet \$ _____ Do you want old parts? Yes _____ No _____ ORIGINAL ESTIMATE: \$5250.00

Revised Amt: Time: _____ Date: _____ Direct _____ Phone _____ Person _____ Initials \$ _____
Revised Amt: Time: _____ Date: _____ Direct _____ Phone _____ Person _____ Initials \$ _____
Revised Amt: Time: _____ Date: _____ Direct _____ Phone _____ Person _____ Initials \$ _____

Date 05-08-2002 Time 01:59 PM

AUTHORIZATION: X

A.R. #A118250
A.KAL-000126391

CREDIT CARDS
ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

READ IMPORTANT INFORMATION ON REVERSE SIDE

Independent Specialist in
Honda & Acura Automobiles

AUTO
reet • Huntington

**** R.O. #19962 of

Sale

T
IEW ROAD
265

Inv # 000002 Appr Code: 567149
02/06/05 11:15:50

LABOR C

es. Replace valve cover gaskets.
includes replacement of thermosta
em. Inspect air conditioner system
at drive belts. Road test.

& air filter was not necessary.
D
BANK ONE SENSOR ONE
SENSOR WIRE HARNESS

SERVICE AIR FILTER
REPLACE BLOWER BELT AND SERVICE BLOWER
REMOVE AND REINSTALL DRIVERS DOOR
To lube window runs

DESCRIPTION SUBLET LAI
FRONT END ALIGNMENT

QTY.	PART NUMBER	DESCRIPTION	PART
3	08798-9031	FLUID/MANUAL TRANS.	
1	15400-PL2-004	FILTER/OIL	
2	94109-14000	DRAIN WASHER/OIL PAN	

**** Continued

Recommendations: Front brake pads are at 5.0mm. Rear brake pad

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN I

Qty.	FLUID	Pay T
5.5	Engine oil (qts.) Mobil One	42.57
3	Transmission oil/manual/qts.	22.41

SIGNATURE ACKNOWLEDGES RECEIPT OF VEHICLE: X

B.A.R. #A118250
EPA #CAL-000126391

CREDIT CARDS
ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

READ IMPORTANT INF

AUTOWAVE INC.

Huntington Beach, CA 92647 • (714) 841-2433

*** ESTIMATE # 9271 ***

License No. HEPCFRE
CURRENT Mileage 64827
PREVIOUS Mileage 011
Chassis JH4NA118XTT000277
Engine
Prod Date 11/95 Color BLACK

Cone No.

PROBLEMS NOTES / LABOR CHARGED

ELTS/WATER PUMP (REPLACE) / NSX
Replace timing, air conditioner, alternator belts. Replace water pump. Replace timing belt tensioner. Replace front camshaft seals (4), front crankshaft seal, inspect related components. Road test.

HECK PINGING

Correct pulley (too large) at supercharger creating too much boost. Possible long injectors. Wrong fpru.

STALL HIGH BOOST KIT

Includes replacing injectors, pulley, fuel pressure regulator. Re install emc at engine control. Repair wiring at map sensor harness.

STALL RM RACING MUFFLER

PLACE REAR CAMSHAFT PLUGS

Includes adjusting valves and replacing valve cover gaskets

WBE, OIL AND FILTER / NSX*

Install new engine oil & filter. Replace drain plug gasket. Adjust tire pressure as necessary. Check and fill fluid levels as necessary. Road

LACE FUEL FILTER

CK ENGINE LIGHT ON

Codes 45 and 46 fuel supply codes. Remove and reinstall emc at ecu and adjust. Part may have damage due to water.

CK OIL LEAK

Leak at supercharger pulley venting small amount of oil.

Work Continued on Next Page ****

Grease \$ _____ Other \$ _____
Old parts? Yes _____ No _____
ORIGINAL ESTIMATE: \$5250.00

Phone _____ Person _____ Initials _____ \$ _____
Phone _____ Person _____ Initials _____ \$ _____
Phone _____ Person _____ Initials _____ \$ _____

AUTHORIZATION:

Independent Specialist in
Honda & Acura Automobiles

INFORMATION ON REVERSE SIDE

AUTOWAVE INC.

Huntington Beach, CA 92647 • (714) 841-2433

*** R.O. #19962 of Estimate #21511 *** #IH69757

Page 1

Sale

AMEX
XXXXXXXXXX7004
Entry Method: Swiped
Approved: Online Batch#: 000525
02/06/09 11:15:50

Inv #: 000002 Appr Code: 567149
Total \$ 2,348.21

Customer Copy

Vehicle: 1996 ACURA NSX
License: HEPCFRE
Current Mileage: 93946 - In: 93942
V.I.N.: JH4NA118XTT000277
Engine:
Prod. Date: 11/95
Color: BLACK
Next Service: 4/30/2009, Mileage: 97696

LABOR COMPLETED

TECH.	TOTAL
11	\$40.00

es. Replace valve cover gaskets. Change engine oil and filter. Service transmission. includes replacement of thermostat & radiator cap). Adjust and inspect brakes. Inspect em. Inspect air conditioner system. Change brake fluid. Service anti-lock brake at drive belts. Road test.

& air filter was not necessary.

D
BANK ONE SENSOR ONE
SENSOR WIRE HARNESS

11	0.00
11	105.00
11	157.50
11	0.00
11	0.00
11	157.50
11	210.00

SERVICE AIR FILTER
REPLACE BLOWER BELT AND SERVICE BLOWER
REMOVE AND REINSTALL DRIVERS DOOR
To lube window runs

SUBLET LABOR CHARGED

DESCRIPTION
FRONT END ALIGNMENT

DAVE'S FRAME & ALIGNMENT

TOTAL
60.00

PARTS ISSUED

QTY.	PART NUMBER	DESCRIPTION	EACH	TOTAL
3	08798-9031	FLUID/MANUAL TRANS.	7.47	22.41
1	15400-PL2-004	FILTER/OIL	15.95	15.95
2	94109-14000	DRAIN WASHER/OIL PAN	0.34	0.68

*** Continued on Next Page ***

Recommendations: Front brake pads are at 5.0mm. Rear brake pads are at 4.0mm. Both are okay. Customer advised.

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. X

Original Estimate: \$105.00

Qty.	FLUID	Pay Type:	TOTAL Labor
5.5	Engine oil (qts.) Mobil One	Amount \$:	1470.00
3	Transmission oil/manual qts.	Employee:	687.70
			TOTAL Sublet Labor
			60.00
			TOTAL Fluids
			64.98
			TOTAL Misc. Shop Supplies
			3.90
			TOTAL Hazardous Waste
			3.00
			SUBTOTAL
			2289.58
			TAX
			58.63
			** TOTAL DUE **
			\$2,348.21

SIGNATURE ACKNOWLEDGES RECEIPT OF VEHICLE: X

B.A.R. #A149250
EPA #CAL-000126391

CREDIT CARDS
ACCEPTED
WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

www.autowaveinc.com

Independent Specialist in
Honda & Acura Automobiles

READ IMPORTANT INFORMATION ON REVERSE SIDE



AUTOWAVE INC.

17122 Gothard Street • Huntington Beach, CA 92647 • (714) 841-2433

**** R.O. #14667 of Estimate #15306 ****

7/11/2005

Page 1

Customer: [REDACTED]
Address: [REDACTED]
Home Phone: [REDACTED]
Work Phone: [REDACTED]
Cellular Phone: [REDACTED]
Service Writer: SHANE

Vehicle: 1996 ACURA NSX
License: HEPCFRE
Current Mileage: 79810
V.I.N.: JH4NA118XTT000277
Engine: 11/95
Prod. Date: BLACK
Color: BLACK
Next Service: 8/24/2005, Mileage: 83310

LABOR COMPLETED

DESCRIPTION	HOURS BILLED	TECH.	TOTAL
REMOVE, TEAR-DOWN & REINSTALL TRANSMISSION To recondition.	10.00	11	700.00
REPLACE CLUTCH Clutch kit includes pressure plate, dual clutch discs and flywheel. Throw-out bearing was also replaced.	0.00	11	0.00

SUBLET LABOR CHARGED

DESCRIPTION	SUPPLIER	TOTAL
FRONT AND REAR END ALIGNMENT	EMI RACING	300.00

PARTS ISSUED

QTY.	PART NUMBER	DESCRIPTION	EACH	TOTAL
1	23220-PR8-J00	COUNTERSHAFT NSX TYPE R	352.98	352.98
1	23210-PR8-020	MAINSHAFT NSX TYPE R	352.98	352.98
1	23431-PR8-010	GEAR C/SHAFT 2ND NSX TYPE R	115.52	115.52
1	23441-PR8-020	GEAR MAINSHAFT 4TH NSX TYPE R	106.27	106.27
1	23451-PR8-010	GEAR MAIN SHAFT 5TH NSX TYPE R	106.27	106.27
1	23471-PR8-000	GEAR C/SHAFT 3RD NSX TYPE R	86.58	86.58
1	23481-PR8-000	GEAR C/SHAFT 4TH NSX TYPE R	123.11	123.11
1	41233-PR8-J00	GEAR/FINAL DRIVE	531.33	531.33
1	41581-PR8-J00	STOPPER PLATE NSX TYPE R	65.58	65.58
1	41696-PR8-000	SPRING PLATE NSX TYPE R	12.72	12.72
1	21173-PR8-J00	SHAFT OIL PUMP NSX TYPE R	103.10	103.10
1	22200-PR7-305	CLUTCH KIT	1433.82	1433.82
1	22810-PR8-003	BEARING/THROW-OUT	156.35	156.35
1	23646-PR8-020	SYNCR0 SET	195.50	195.50

**** Continued on Next Page ****

Revised Estimate: \$6,000.00 Original Estimate: \$1,700.00 Added Cost: \$4,300.00
Contact: [REDACTED] : shane Date/Time: 5/25/2005 12:50 PM
Reason: replace transmission bearings

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. X

Original Estimate: \$1,700.00

Pay Type:	TOTAL Labor	700.00
Amount \$:	TOTAL Parts	3966.85
Employee:	TOTAL Sublet Labor	300.00
	SUBTOTAL	4966.85
	TAX	307.43
	** TOTAL DUE **	\$5,274.28

SIGNATURE ACKNOWLEDGES RECEIPT OF VEHICLE: X

B.A.R. #AJ149250
EPA #CAL-000126391

CREDIT CARDS
ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

READ IMPORTANT INFORMATION ON REVERSE SIDE

Independent Specialist in
Honda & Acura Automobiles

AUTOWAVE INC.
17122 Gothard Street
HUNTINGTON BEACH, CA 92647
Tel: (714) 841-2433
Fax: (714) 841-2433
WWW.AUTOWAVEINC.COM

AUTOWAVE INC.

17122 Gothard Street • Huntington Beach, CA 92647 • (714) 841-2433

**** R.O. #17784 of Estimate #19070 ****

Sale

AMEI: [REDACTED]
XXXXXXXXXX7004
Entry Method: Suiped
Approved: Online Batch#: 000140
08/02/07 13:47:22

Vehicle: [REDACTED]
License: [REDACTED]
Current Mileage: [REDACTED]
V.I.N.: [REDACTED]
Engine: [REDACTED]
Prod. Date: [REDACTED]
Color: [REDACTED]
Next Service: [REDACTED]

LABOR COMPLETED

Inv #: 000000 Appr Code: 547141
Total: \$ 450.70

BIL ONE
w oil filter and Mobil One engine oil. Replace drain plug washer and fill fluid levels as necessary. Road test.
LL OUT-PASSENGER SIDE

QUAL
n. Replace drain plug washer. Inspect clutch components.

PARTS ISSUED

QTY.	PART NUMBER	DESCRIPTION
1	15400-PL2-004	FILTER/OIL
1	94109-14000	DRAIN WASHER/OIL PAN
4	91512-SM4-003	CLIP/INNER FENDER/NSX
1	NPN	HOBBS SWITCH
1	NPN	BRACKET
1	16010-SLO-505	FILTER/FUEL

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. X

Qty.	FLUID	Pay Type:
5	Engine oil (qts.) Mobil One	Amount \$:
3	Transmission Oil/Manual/Qts.	Employee:

SIGNATURE ACKNOWLEDGES RECEIPT OF VEHICLE: X

B.A.R. #AJ149250
EPA #CAL-000126391

CREDIT CARDS
ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

READ IMPORTANT INFORMATION ON REVERSE SIDE

www.autowaveinc.com

AVE INC.

92647 • (714) 841-2433

1996 ACURA NSX
HEPCFRE
79810
JH4NA118XTT000277
11/95
BLACK
8/24/2005, Mileage: 83310

HOURS BILLED	TECH.	TOTAL
10.00	11	700.00
0.00	11	0.00

SupPLIER
EMI RACING

EACH	TOTAL
352.98	352.98
352.98	352.98
115.52	115.52
106.27	106.27
106.27	106.27
86.58	86.58
123.11	123.11
531.33	531.33
65.58	65.58
12.72	12.72
103.10	103.10
1433.82	1433.82
156.35	156.35
195.50	195.50

Added Cost: \$4,300.00
By: shane Date/Time: 5/25/2005 12:50 PM

ORIGINAL ESTIMATED PRICE: X
Original Estimate: \$1,700.00

TOTAL Labor	700.00
TOTAL Parts	3966.85
TOTAL Sublet Labor	300.00
SUBTOTAL	4966.85
TAX	307.43
** TOTAL DUE **	\$5,274.28

Independent Specialist in
Honda & Acura Automobiles

AUTO WAVE INC.

reet • Huntington Beach, CA 92647 • (714) 841-2433

AUTO WAVE INC.
17122 GOTHARD
HUNTINGTON BEACH, CA 92647
Merchant ID: 00000000566554
Term ID: 00007213
5645037282

**** R.O. #17784 of Estimate #19070 ****

Sale
AMEX
XXXXXXXXXXXX7004
Entry Method: Swiped
Appr'd: Online Batch#: 000142
00/03/07 13:47:22

Inv #: 000003 Appr Code: 547141
Total: \$ 450.78

Customer Copy

Vehicle: 1996 ACURA NSX
License: HEPCFRE
Current Mileage: 89590 - In: 89587
V.I.N.: JH4NA118XTT000277
Engine: 11/95
Prod. Date: BLACK
Color: BLACK
Next Service: 11/3/2007, Mileage: 93090

LABOR COMPLETED

TECH.	TOTAL
11	16.50
11	0.00
11	38.00
11	38.00
11	47.50
11	47.50
11	47.50

PARTS ISSUED

QTY.	PART NUMBER	DESCRIPTION	EACH	TOTAL
1	15400-PL2-004	FILTER OIL	15.95	15.95
1	94109-14000	DRAIN WASHER/OIL PAN	0.30	0.30
4	91512-SM4-003	CLIP INNER FENDER/NSX	1.38	5.52
1	NPN	HOBBS SWITCH	60.00	60.00
1	NPN	BRACKET	24.50	24.50
1	16010-SLO-505	FILTER/FUEL	39.42	39.42

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE: X
Original Estimate: \$74.50

QTY.	FLUID	Pay Type:	TOTAL Labor	235.00
5	Engine oil (qts.) Mobil One	Amount \$:	TOTAL Parts	145.69
3	Transmission Oil/Manual/Qts.	Employee:	TOTAL Fluids	51.79
			TOTAL Hazardous Waste	3.00
			SUBTOTAL	435.48
			TAX	15.30
			** TOTAL DUE **	\$450.78

SIGNATURE ACKNOWLEDGES RECEIPT OF VEHICLE: X

CREDIT CARDS
ACCEPTED

www.autowaveinc.com

Independent Specialist in
Honda & Acura Automobiles

S.A.R. #A149250
EPA #CAL-000126391

WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

READ IMPORTANT INFORMATION ON REVERSE SIDE

AUTO WAVE INC.

17122 Gothard Street • Huntington Beach, CA 92647 • (714) 841-2433

**** R.O. #14230 of Estimate #14720 ****

4/1/2005

Customer:
Address:

Home Phone:
Work Phone:
Cellular Phone:
Service Writer: SHANE

Vehicle: 1996 ACURA NSX
License: HEPCFRE
Current Mileage: 78325
V.I.N.: JH4NA118XTT000277
Engine: 11/95
Prod. Date: BLACK
Color: BLACK
Next Service: 4/25/2005, Mileage: 81

LABOR COMPLETED

DESCRIPTION	HOURS BILLED
CLUTCH REPLACEMENT - NSX	8.00
Remove and reinstall transmission to install clutch assembly. Assembly includes single disc clutch, segment, billet flywheel, pressure plate and throw-out bearing.	0.00
NOTE: Freight charges listed under "other".	0.00
CHECK FRONT SUSPENSION - TOO LOW	2.00
Adjust.	
SEND REAR BUMPER TO LANZINI FOR PAINTING	1.00
Includes remove rear bumper, disassemble, reassemble, reinstall.	
CONSTANT VELOCITY DRIVE BOOT KIT/ LEFT	1.00
Includes remove and reinstall axle to replace inner and outer axle boots, grease, clips, bands and axle nut.	
test.	0.30
CONSTANT VELOCITY DRIVE BOOT KIT/RIGHT	2.50
Includes remove and reinstall axle to replace inner and outer axle boots, grease, clips, bands and axle nut.	
test.	0.30
REPLACE TRANSMISSION MAIN SHAFT SEAL	Fixed
CLUTCH MASTER CYLINDER (REPLACE) NSX	
Remove and replace cylinder. Refill brake fluid, bleed system and road test.	
LUBE, OIL AND FILTER / NSX / MOBIL ONE	4.00
Drain engine oil. Install new engine oil & filter. Replace drain plug gasket. Adjust tire pressure as necessary. Check and fill fluid levels as necessary. Road test.	
VALVE ADJUSTMENT / NSX	0.50
Remove and reinstall valve covers to adjust valves. Install new gaskets. Road test.	
REPLACE BOOST GAUGE	

**** Continued on Next Page ****

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE

Pay Type:	TOTAL Labor
Amount \$:	TOTAL Parts
Employee:	TOTAL Sublet Labor
	TOTAL Fluids
	TOTAL Hazardous Waste
	SUBTOTAL
	TAX
	** TOTAL DUE **

SIGNATURE ACKNOWLEDGES RECEIPT OF VEHICLE: X

S.A.R. #A149250
EPA #CAL-000126391

CREDIT CARDS
ACCEPTED

WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

READ IMPORTANT INFORMATION ON REVERSE SIDE

Indep
Honda

ACURA 181 WEST
24458 CALABRASO ROAD
CALABRASO, CA 91382
(618) 222-5555
194214481996
TERMINAL #61

1 3 2 6 3 1

INVOICE

PAGE 1

SERVICE ADVISOR:
VIN

TO WAVE INC.

Huntington Beach, CA 92647 • (714) 841-2433

O. #17784 of Estimate #19070 ****

Page 1

Vehicle: 1996 ACURA NSX
License: HEPCFRE
Current Mileage: 89590 - In: 89587
V.I.N.: JH4NA118XTT000277
Engine:
Prod. Date: 11/95
Color: BLACK
Next Service: 11/3/2007, Mileage: 93090

LABOR COMPLETED

	TECH.	TOTAL
Oil One engine oil. Replace drain plug washer. Adjust tire	11	16.50
els as necessary. Road test.	11	0.00
NGER SIDE	11	38.00
	11	38.00
lug washer. Inspect clutch components. Road test.	11	47.50
	11	47.50
	11	47.50

PARTS ISSUED

	EACH	TOTAL
ON	15.95	15.95
	0.30	0.30
HER/OIL PAN	1.38	5.52
FENDER/NSX	60.00	60.00
CH	24.50	24.50
	39.42	39.42

VAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. X

Original Estimate: \$74.50

Pay Type:	TOTAL Labor	235.00
Amount \$:	TOTAL Parts	145.69
Employee:	TOTAL Fluids	51.79
	TOTAL Hazardous Waste	3.00
	SUBTOTAL	435.48
	TAX	15.30
	** TOTAL DUE **	\$450.78

VEHICLE: X

Independent Specialist in
Honda & Acura Automobiles

www.autowaveinc.com

IMPORTANT INFORMATION ON REVERSE SIDE



AUTO WAVE INC.

17122 Gothard Street • Huntington Beach, CA 92647 • (714) 841-2433

**** R.O. #14230 of Estimate #14720 ****

Page 1

4/1/2005

Customer:
Address:

Home Phone:
Work Phone:
Cellular Phone:
Service Writer: SHANE

Vehicle: 1996 ACURA NSX
License: HEPCFRE
Current Mileage: 78325
V.I.N.: JH4NA118XTT000277
Engine:
Prod. Date: 11/95
Color: BLACK
Next Service: 4/25/2005, Mileage: 81825

LABOR COMPLETED

DESCRIPTION

CLUTCH REPLACEMENT - NSX
Remove and reinstall transmission to install clutch assembly. Assembly includes single disc clutch, segmented
billet flywheel, pressure plate and throw-out bearing.

NOTE: Freight charges listed under "other".

CHECK FRONT SUSPENSION - TOO LOW
Adjust.

SEND REAR BUMPER TO LANZINI FOR PAINTING
Includes remove rear bumper, disassemble, reassemble, reinstall.

CONSTANT VELOCITY DRIVE BOOT KIT/ LEFT
Includes remove and reinstall axle to replace inner and outer axle boots, grease, clips, bands and axle nut. Road
test.

CONSTANT VELOCITY DRIVE BOOT KIT/RIGHT
Includes remove and reinstall axle to replace inner and outer axle boots, grease, clips, bands and axle nut. Road
test.

REPLACE TRANSMISSION MAIN SHAFT SEAL
CLUTCH MASTER CYLINDER (REPLACE) NSX
Remove and replace cylinder. Refill brake fluid, bleed system and road test.

LUBE, OIL AND FILTER / NSX / MOBIL ONE
Drain engine oil. Install new engine oil & filter. Replace drain plug gasket. Adjust tire pressure as necessary.
Check and fill fluid levels as necessary. Road test.

VALVE ADJUSTMENT / NSX
Remove and reinstall valve covers to adjust valves. Install new gaskets. Road test.

REPLACE BOOST GAUGE

**** Continued on Next Page ****

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE. X

Pay Type:
Amount \$:
Employee:

TOTAL Labor	2559.00
TOTAL Parts	3418.64
TOTAL Sublet Labor	862.00
TOTAL Misc. Shop Supplies	7.90
TOTAL Other	13.86
SUBTOTAL	6861.40
TAX	265.56
** TOTAL DUE **	\$7,126.96

SIGNATURE ACKNOWLEDGES RECEIPT OF VEHICLE: X

Independent Specialist in
Honda & Acura Automobiles

B.A.R. #AJ149250
EPA #CAL-000126391

CREDIT CARDS
ACCEPTED

WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

READ IMPORTANT INFORMATION ON REVERSE SIDE



24650 Calabasas Rd., Calabasas, CA 91302
(818) 222-5555

INVOICE

PAGE 1

55 ANTHONY PICADO



17122 G

Customer
Address
City/State/Zip