1994 Ford Bronco XLT 4X4 Restoration

1. Alternator
2. Fuel Filter
3. Front Door Lock Switch
4. ABS Relay
5. Steering Gear Box Assembly
6. Front Wheel Speed Sensor
7. Spark Plugs and Wires
8. Shocks and Struts
9. Heater Core
10. Water Pump
11. Thermostat
12. Radiator
13. Top and Bottom Hoses
14. Air Bag Clock Spring
15. Repaint Body
16. Trim Shop – Seats, Carpet Head Liner Arm Rest
17. Door Panels
18. Air Vent Window Locks
19. Drag Link, Tie Rods and Bushings
20. Heater Hoses
21. Catalytic Converter
22. Muffler
23. Radio with back up camera
24. Intake Gasket
25. Serpentine Belt
26. Front Bumper Front Grill Headlights
27. Turn Signal Arm Assembly
28. Side View Mirrors
29. Side Step Bars
30. XLT Badges

31. Tail Lights
32. Vacuum Line Evaporator Canister
33. Ignition Switch
34. Reverse Light Switch Harness
35. Driver Seat Power Control
36. Exterior Door Handles
37. Battery
38. Rear Seat Belts
39. Starter
40. ABS Control Module and Pump
41. Rear Window Switch
42. Brake Fluid Level Sensor
43. Engine Assembly 5.0
44. Transmission Assembly
45. Rear Differential Assembly + FRONT Diff.
46. Exhaust Manifolds
47. TRANSFER CASE

Your vehicle was equipped with the following features:

- Tachometer
- Front License Plate Bracket
- Touch Drive Electric Shift 4X4
- Floor Console
- P235/70R15XL Outline White Letter All-Season Tires
- Swing-Away Spare Tire Carrier
- Speed Control/Tilt Steering Wheel
- Bright Power Mirrors
- Luxury Group
- Air Conditioner
- Electric Rear Window Defroster
- AM/FM/Cassette/Clock Stereo Radio
- Light Group
- 15" Deep Dish Forged Aluminum Wheels
- XLT Package
- Oxford White Fiberglass Roof
- Power Door Locks/Windows
- Privacy Glass
- Convenience Group

Your vehicle was actually produced on November 1, 1993 — seven days ahead of schedule.

Kevin Martz

For Mustang, Thunderbird, Cougar, Falcon, Fairlane, Lincoln, Torino, and other Ford Products from 1949-2017

1374315 PRODUCTION NUMBER

Crossroads Automotive
3210 Georgia 34
Newnan, GA 30265
(770) 254-1514
crossroads@msauto.com
https://mainstreetauto.com/

Invoice for RO #274103
Service Advisor: Roger Keener
Posted Da[redacted]
Vehicle: 1994 Ford Bronco [redacted]

[redacted]

1994 Ford Bronco Eddie Bauer 5.0L 8Cyl GAS
Naturally Aspirated
VIN: 1FMEU15N5RLA30106
License: N/A
Color: N/A
Odometer In: 217375 / Out: 217375

RO # 274103
Time-In: 05/12/26 at 08:00 AM EDT
Save Parts: No

Client Concerns

OIL LEAKS PASSENGER SIDE-

TWO DIFFERENT TIMES NO START. HAD TO PULL SHIFTER TO NETURAL

FROM A DEAD STOP WHEN TRYING TO ACCELERATE IT DOES SEEM TO HESITATE

1 CHECK AND ADVISE - AT ONE POINT CUSTOMER SAW SOME OIL LEAKING ON THE GARAGE - NO LONGER SEEING OIL LEAK - BUT - PLEASE RECHECK EVERYTHING FOR AN FLUID LEAKS

Tech: J Graham

Labor:	CHECK AND ADVISE			$0.00
✓ Approved on 05/12/26 at 08:09 AM EDT		0		0

2 - STILL HAVING STARTING PROBLEMS IN PARK OCCASIONALLY

Part:	Duralast Neutral Safety Switch	1	$125.21	$125.21
✓ Approved on 05/12/26 at 08:09 AM EDT		Subtotal $125.21 + est. Tax $10.02		$135.23

3 - CHECK AND ADVISE - SLIGHT HESITATION WHEN TAKING OFF FROM A STOP - HAS HAD TPS REPLACE BACK IN OCTOBER

Tech: J Graham

Labor:	CHECK AND ADVISE		$0.00
✓ Approved on 05/12/26 at 08:09 AM EDT		0	0

4 SEE REAR BRAKE LIGHT BAR UNDER REAR TRUNK DOOR - WIRE IS BROKEN - CUSTOMER STATED IT WASNT LIKE THAT WHEN HE - DROPPED IT OFF ORIGINALLY

✓ Approved on 05/12/26 at 08:09 AM EDT	0	0

5 - Remove & Replace Engine Assembly - Long Block

Tech: J Graham

lote: The original engine was purchased through AutoZone. Due to the length of time we had the vehicle and the circumstances the customer was facing, we made the decision replace the engine with a Jasper engine to make the situation right.

e customer was originally quoted approximately $12,000 by Binion, and that quote was intended to include a Jasper engine. However, without the customer's knowledge, an oZone engine was installed instead. Unfortunately, we experienced multiple issues with that engine and were ultimately unable to get it to seal properly, resulting in a istent oil leak.

iscounts applied to this ticket represent the additional cost we incurred to upgrade the vehicle to a Jasper engine and honor the customer's original expectations. We were ble to obtain labor reimbursement from AutoZone, which helped offset a portion of the expense associated with the repair.

Remove & Replace Engine Assembly - Long Block With Air Conditioning			$2,620.64
jasper reman engine	1	$4,804.80	$4,804.80
jasper full kit 10	1	$631.26	$631.26
Oil Kendall Synth Blend 5w30 Bulk - KENDALL,GT-1 HP,5W30,BULK,GF-7	6	$6.99	$41.94
Duralast Belt Tensioner	1	$152.54	$152.54
core			$600.00
ved on 05/26/26 at 07:56 AM EDT	Subtotal $8,851.18 + est. Tax $450.44		$9,301.62

Shop Supplies $50.00

...and other Ford Products from 1949-2017

JASPER ENGINES & TRANSMISSIONS
100% Associate Owned

JASPER® Limited Nationwide Warranty

JASPER® warrants components against defects in our workmanship and material in accordance with the schedules and limitations outlined below. Repairs or replacement will be made at the JASPER factory within a reasonable time after notice and upon receipt of the goods deemed to be defective per the schedules and limitations of our written warranty. ***A warranty case number must be assigned and repair instructions provided prior to repair or replacement of goods.***

	Time or Mileage, whichever occurs first.	
GASOLINE ENGINES:		
Completes for Cars and Trucks	3 Years or 100,000 Miles	Parts + Labor ~†
Industrial/Non-Automotive	6 Months	Parts
Turbochargers	1 Year, Unlimited Mileage	Parts + Labor ✦
Cylinder Heads	1 Year, Unlimited Mileage	Parts
PERFORMANCE ENGINES:		
Class I, Cars and Trucks - Completes	3 Years or 100,000 Miles	Parts + Labor ~†◊
Panther Crate - Completes	3 Years or 100,000 Miles	Parts + Labor ◊
Class II, Cars and Trucks - Completes (Except Racing and Abuse)	6 Months or 8,000 Miles	Parts + Labor ~◊
	1 Year or 16,000 Miles	Parts
Class III	Including Racing Applications	No Warranty ◊
MARINE STOCK NUMBERS:		
Complete Engines	2 Years, Unlimited Hours	Parts + Labor*
Class II Performance Marine	6 Months, Unlimited Hours	Parts + Labor*
Sterndrives	1 Year, Unlimited Hours	Parts
Outboard Lower Units	2 Years, Unlimited Hours	Parts + Labor*
	2 Years, Unlimited Hours	Parts + Labor
DIESEL ENGINES:		
Completes**		
Vehicles 33,000 lbs. or less & School Buses/Shuttle Buses	1 Year, Unlimited Mileage	Parts + Labor ~●□
Vehicles 33,001 lbs. or more & Transit Buses/Motorcoaches	6 Months, Unlimited Mileage	Parts + Labor●
Industrial/Non-Automotive	6 Months, Unlimited Hours	Parts + Labor●
Ford/International 6.0L/6.4L/6.7L/7.3L D.I.		
Cummins ISB Front Gear Applications, and Duramax 6.6L		
Running Completes**	2 Years, Unlimited Mileage	Parts + Labor
Vehicles 33,000 lbs. or less & School Buses/Shuttle Buses		
Vehicles 33,001 lbs. or more & Transit Buses/Motorcoaches	2 Years, Unlimited Mileage	Parts + Labor ~●▲
Industrial Non-Automotive	1 Year, Unlimited Mileage	Parts + Labor●
Diesel Air & Fuel Components	1 Year, Unlimited Hours	Parts + Labor●
Fuel Pumps	1 Year, Unlimited Mileage	Parts + Labor ✦▲
Turbochargers	1 Year, Unlimited Mileage	Parts + Labor ✦▲
Injectors	1 Year, Unlimited Mileage	Parts + Labor ✦▲
Cylinder Heads	1 Year, Unlimited Mileage	Parts
Exhaust Aftertreatment Components	1 Year, Unlimited Mileage	Parts
Actuators	1 Year, Unlimited Mileage	Parts
TRANSMISSIONS/TRANSFER CASES:		
Cars and Trucks	3 Years or 100,000 Miles	Parts + Labor †
Allison Transmissions	2 Years	Parts + Labor
Allison Transmissions for School Bus	3 Years	Parts + Labor
Allison Transmissions for Chevy/GMC (1 Ton and below)	3 Years or 100,000 Miles	Parts + Labor †
Industrial/Non-Automotive	6 Months	Parts
Torque Converters	3 Years or 100,000 Miles	Parts
ERFORMANCE TRANSMISSIONS:		
Class I, Cars and Trucks	3 Years or 100,000 Miles	Parts + Labor †
Class II, Cars and Trucks (Except Racing and Abuse)	6 Months or 8,000 Miles	Parts + Labor
	1 Year or 16,000 Miles	Parts
FERENTIALS:		
Cars and Trucks	3 Years or 100,000 Miles	Parts + Labor †
Industrial/Non-Automotive	6 Months	Parts
Actuators	3 Years or 100,000 Miles	Parts + Labor †

Crossroads Automotive
3210 Georgia 34
Newnan, GA 30265
(770) 254-1514
crossroads@msauto.com
https://mainstreetauto.com/

Invoice for RO #275566

Service Advisor: Roger Keener
Posted Date: 08/18[redacted]
Client[redacted]
Vehicle: 1994 Ford Bronco XLT

[redacted]

1994 Ford Bronco XLT 5.0L 8Cyl GAS
Naturally Aspirated
VIN: 1FMEU15N5RLA30106
License: N/A
Color: N/A
Odometer In: 218752 / Out: 218752

RO # 275566
Time-In: 08/13/26 at 08:08 AM EDT
Save Parts: No

Client Concerns

check tailgate not opening

check shuttering on light acceleration

1 - check tailgate not opening
Tech: J Graham

Labor:	labor			$319.98
Parts:	tailgate latch assembley	1	$138.00	$138.00
	Dorman - HELP Door Lock Rod Clip	1	$13.70	$13.70

✓ Approved on 08/13/26 at 08:11 AM EDT — Subtotal $471.68 + est. Tax $12.14 — **$483.82**

2 - DIAG - ENGINE- check shuttering on light acceleration
Tech: J Graham

Labor:	ENGINE DIAGNOSTICS		$145.00
Discount:	Warranty Labor Discount		-$145.00

✓ Approved on 08/13/26 at 08:11 AM EDT — 0 — **0**

3 - DIAG - ENGINE- idle will jump up and down, especially with ac on
Tech: J Graham

Labor:	ENGINE DIAGNOSTICS		$145.00
Discount:	Warranty Labor Discount		-$145.00

✓ Approved on 08/13/26 at 08:11 AM EDT — 0 — **0**

4 - Remove & Replace Idle Speed Control Motor
Tech: J Graham

Labor:	Remove & Replace Idle Speed Control Motor			$199.99
Part:	Duralast Idle Air Control Valve	1	$122.94	$122.94

✓ Approved on 08/14/26 at 03:06 PM EDT — Subtotal $322.93 + est. Tax $9.84 — **$332.77**

Fees

Shop Supplies		$50.00
Merchant Processing Fee		$22.78
	Subtotal	**$72.78**

otherwise stated, Repairs come with a 24 Month / 24,000 Mile Warranty.In the event of a problem this store must be allowed to inspect vehicle before any repairs are made.
e of tampering will void any and all warranty.
ts made using a credit card are subject to a surcharge of 3%. This fee covers the increasing costs associated with credit card processing. To avoid this fee, you may pay
ck or cash.
g an appointment, you consent to receive text messages regarding your vehicle's service. Message & data rates may apply. You may unsubscribe at any time by replying

CROSSROADS Automotive

Crossroads Automotive
3210 Georgia 34
Newnan, GA 30265
(770) 254-1514
crossroads@msauto.com
https://mainstreetauto.com/

Invoice for RO #274103

Service Advisor: Roger Keener
Date Created: 05/12
Client: [redacted]
Vehicle: 1994 Ford Bronco Eddie Bauer

[redacted]

1994 Ford Bronco Eddie Bauer 5.0L 8Cyl GAS
Naturally Aspirated
VIN: 1FMEU15N5RLA30106
License: N/A
Color: N/A
Odometer In: 217375 / Out: 217375

RO # 274103
Time-In: 05/12/26 at 08:00 AM EDT
Save Parts: No

Client concerns:

- OIL LEAKS PASSENGER SIDE-
- TWO DIFFERENT TIMES NO START. HAD TO PULL SHIFTER TO NETURAL
- FROM A DEAD STOP WHEN TRYING TO ACCELERATE IT DOES SEEM TO HESITATE

1 CHECK AND ADVISE - AT ONE POINT CUSTOMER SAW SOME OIL LEAKING ON THE GARAGE - NO LONGER SEEING OIL LEAK - BUT PLEASE - RECHECK EVERYTHING FOR AN FLUID LEAKS
Tech: J Graham

Labor:	CHECK AND ADVISE			$0.00
✓ Approved on 05/12/26 at 08:09 AM EDT		0		0

2 - STILL HAVING STARTING PROBLEMS IN PARK OCCASIONALLY

Part:	Duralast Neutral Safety Switch	1	$125.21	$125.21
✓ Approved on 05/12/26 at 08:09 AM EDT		Subtotal $125.21 + est. Tax $10.02		$135.23

3 - CHECK AND ADVISE - SLIGHT HESITATION WHEN TAKING OFF FROM A STOP - HAS HAD TPS REPLACE BACK IN OCTOBER
Tech: J Graham

Labor:	CHECK AND ADVISE			$0.00
✓ Approved on 05/12/26 at 08:09 AM EDT		0		0

4 SEE REAR BRAKE LIGHT BAR UNDER REAR TRUNK DOOR - WIRE IS BROKEN - CUSTOMER STATED IT WASNT LIKE THAT WHEN HE - DROPPED IT OFF ORIGINALLY

✓ Approved on 05/12/26 at 08:09 AM EDT		0		0

5 - Remove & Replace Engine Assembly - Long Block
Tech: J Graham

Labor:	Remove & Replace Engine Assembly - Long Block With Air Conditioning			$2,620.64
Parts:	jasper reman engine	1	$4,804.80	$4,804.80
	jasper full kit 10	1	$631.26	$631.26
	Oil Kendall Synth Blend 5w30 Bulk - KENDALL,GT-1 HP,5W30,BULK,GF-7	6	$6.99	$41.94
	Duralast Belt Tensioner	1	$152.54	$152.54
Fee:	core			$600.00
✓ Approved on 05/26/26 at 07:56 AM EDT		Subtotal $8,851.18 + est. Tax $450.44		$9,301.62

RO Fees

Fees:	Shop Supplies	$50.00
	Merchant Processing Fee	$251.29

Crossroads Automotive
3210 Georgia 34
Newnan, GA 30265
(770) 254-1514
crossroads@msauto.com
https://mainstreetauto.com/

Invoice for RO #274751

Service Advisor: Christopher Glisson
Posted Date: 07/07/[redacted]
Client [redacted]
Vehicle: 1994 Ford [redacted]

[redacted]

1994 Ford Bronco [redacted] 5.0L 8Cyl GAS
Naturally Aspirated
VIN: 1FMEU15N5RLA30106
License: N/A
Color: N/A
Odometer In: 217795 / Out: 217795

RO # 274751
Time-In: 06/23/26 at 08:11 AM EDT
Save Parts: No

Client Concerns
Slight ticking noise when engine is started
Very Sluggish under Load
ENGINE HAS STOPPED AT TRAFFIC LIGHT TWICE
USES EXCESS GAS AND CAN SMELL GAS WHEN RUNNING

1 - Free Diagnostic-ENGINE

Tech: J Graham
Note: warranty from ro274103

Labor:	Diagnostic Labor			$0.00
Part:	EBAY BRACKET ASSEMBLY	1	$530.69	$530.69
Discount:	Part Discount			-$530.69
✓ Approved on 06/23/26 at 08:12 AM EDT		0		0

2 - *72.99 Standard Synthetic Blend Oil Change w/o Rotate (GOOD)

Tech: J Graham
Note: Welcome to Crossroads Automotive,

We are truly grateful for the opportunity to serve you and care for your vehicle. Our goal is to provide not only high-quality service, but also a transparent and trustworthy experience every step of the way.

As part of our commitment to transparency, every visit includes a complimentary multi-point vehicle inspection. During this process, our technicians capture photos and videos so you can see exactly what we see. This allows you to make informed decisions about your vehicle with confidence and peace of mind.

If you ever have questions or would like further explanation, our team is always here to help. Thank you again for choosing Crossroads Automotive—we look forward to keeping you safely on the road.

Sincerely,
The Crossroads Automotive Team

Labor:	Remove & Replace Engine Oil & Filter			$31.50
Parts:	Service Champ Oil Filter - Oil Filter	1	$7.49	$7.49
	Oil Kendall Synth Blend 5w30 Bulk - KENDALL,GT-1 HP,5W30,BULK,GF-7	6.02	$6.99	$42.08
	Dorman - Autograde Wheel Lug Nut	4	$8.00	$32.00
Discount:	Customer Satisfaction			-$113.07
✓ Approved on 06/23/26 at 12:51 PM EDT		0		0

ss otherwise stated, Repairs come with a 24 Month / 24,000 Mile Warranty.In the event of a problem this store must be allowed to inspect vehicle before any repairs are made.
nce of tampering will void any and all warranty.
ents made using a credit card are subject to a surcharge of 3%. This fee covers the increasing costs associated with credit card processing. To avoid this fee, you may pay heck or cash.
king an appointment, you consent to receive text messages regarding your vehicle's service. Message & data rates may apply. You may unsubscribe at any time by replying

CROSSROADS Automotive

Crossroads Automotive
3210 Georgia 34
Newnan, GA 30265
(770) 254-1514
crossroads@msauto.com
https://mainstreetauto.com/

Invoice for RO #271144

Service Advisor: Roger Keener
Posted Date: 11/14
Clien[redacted]
Vehicle: 1994 Ford Bronco XLT

[redacted]

1994 Ford Bronco XLT 5.0L 8Cyl GAS Naturally Aspirated VIN: 1FMEU15N5RLA30106 License: N/A Color: Green Odometer In: 216672 / Out: 216672	RO # 271144 Time-In: 10/31/25 at 09:48 AM EDT Save Parts: No

1 - CHECK GRINDING NOISE FROM TRANSMISSION OR TRANSFER CASE. NOISE HAPPENED A DAY AFTER ENGINE, TRANSMISSION AND REAR DIFFERENTIAL.

✓ Approved on 10/31/25 at 10:12 AM EDT — 0 — **0**

2 - Remove & Replace Transfer Case Assembly
Tech: J Graham

Labor:	Remove & Replace Transfer Case Assembly			$387.48
Part:	Zumbrota Drivetrain Transfer Case	1	$1,986.32	$1,986.32

✓ Approved on 11/13/25 at 09:31 AM EST — *Subtotal $2,373.80 + est. Tax $139.04* — **$2,512.84**

RO Fees

Fee:	*Shop Supplies*	$50.00
	Subtotal	**$50.00**

Unless otherwise stated, Repairs come with a 24 Month / 24,000 Mile Warranty.In the event of a problem this store must be allowed to inspect vehicle before any repairs are made. Evidence of tampering will void any and all warranty.

Payments made using a credit card are subject to a surcharge of 3%. This fee covers the increasing costs associated with credit card processing. To avoid this fee, you may pay with check or cash.

By booking an appointment, you consent to receive text messages regarding your vehicle's service. Message & data rates may apply. You may unsubscribe at any time by replying "STOP".

Total Repair Order & Signature:

Total Labor:	$387.48
Total Parts:	$1,986.32
Total Fees:	$50.00
Subtotal:	**$2,423.80**
Taxes:	$139.04
Grand Total:	**$2,562.84**
BALANCE DUE:	**$0.00**

X _____

✔ PAID

Completed Transactions

11/14/25	JEROME SIMPSON	$2,562.84	Credit Card Payment	Mastercard**** 7385	Mastercard

678-794-5848

CROSSROADS Automotive

Crossroads Automotive
3210 Georgia 34
Newnan, GA 30265
(770) 254-1514
crossroads@msauto.com
https://mainstreetauto.com/

Invoice for RO #271256

Service Advisor: Roger Keener
Date Created: 11/0[redacted]
Clie[redacted]
Vehicle: 1994 Ford Bronco XLT

[redacted]

1994 Ford Bronco XLT 5.0L 8Cyl GAS
Naturally Aspirated
VIN: 1FMEU15N5RLA30106
License: N/A
Color: N/A
Odometer In: 216680 / Out: 216680

RO # 271256
Time-In: 11/06/25 at 10:43 AM EST
Save Parts: No

1 - Remove Replace front Differential Carrier

Tech: J Graham

Note: FORD PN# F2AZ4635D

Labor:	Remove & Replace Differential Carrier. DOES NOT include alignment.			$736.20
Part:	K&W differential additive	1	$45.57	$45.57

✓ Approved on 11/14/25 at 10:15 AM EST — Subtotal $781.77 + est. Tax $3.19 — **$784.96**

2 - Standard Alignment

Tech: J Graham

Labor:	Standard Alignment Labor	$119.99

✓ Approved on 11/14/25 at 10:15 AM EST — **$119.99**

3 - Standard Synthetic Blend Oil Change without Rotate (GOOD)

Tech: J Graham

Labor:	LOF Labor			$25.02
Parts:	Service Champ Oil Filter - Oil Filter	1	$8.97	$8.97
	KEN HP SB 5W30 SYNTH BLEND - 5W30 SYNTH BLEND	6	$5.50	$33.00
Fee:	Hazardous waste Disposal Fee			$3.00

✓ Approved on 02/07/26 at 01:41 PM EST — Subtotal $69.99 + est. Tax $2.94 — **$72.93**

4 - driveline service- ro 22339

Sublet:	front differential rebuild	$1,700.00

✓ Authorized on 11/14/25 at 10:15 AM EST — **$1,700.00**

ss otherwise stated, Repairs come with a 24 Month / 24,000 Mile Warranty.In the event of a problem this store must be allowed to inspect vehicle before any repairs ade. Evidence of tampering will void any and all warranty.

nts made using a credit card are subject to a surcharge of 3%. This fee covers the increasing costs associated with credit card processing. To avoid this fee, you y with check or cash.

ing an appointment, you consent to receive text messages regarding your vehicle's service. Message & data rates may apply. You may unsubscribe at any time by "STOP".

Binion Automotive
26 Spence Avenue
Newnan, GA 30263
(770) 253-4608
binion@msauto.com
ps://mainstreetauto.com/

Invoice for RO #2684230

Service Advisor: Jamel Johnson
Posted Date: 10/24/25 at 02:09 PM EDT
Clie[redacted]
Vehicle: 1994 Ford Bronco XLT

[redacted]

1994 Ford Bronco XLT 5.0L 8Cyl GAS Naturally Aspirated VIN: N/A License: N/A Color: N/A Odometer In: 216600 / Out: 216600	RO # 2684230 Time-In: 10/09/25 at 08:02 AM EDT Save Parts: No

- THROTTLE ISSUE
- BRAKE ISSUE
- TRANSMISSION HARD SHIFT IN FIRST/REVERSE
- Oil or Transmission Leak

1 - INSP- COMPLETE VEHICLE INSPECTION

✓ Approved on 10/09/25 at 08:03 AM EDT — 0 — 0

2 - Remove & Replace Disc Brake Caliper (Driver Front)

Tech: M Hill

Labor:	Remove & Replace Front Disc Brake Caliper (Each)			$37.50
	Remove & Replace Front Brake Line (Each)			$60.00
	Remove & Replace Front Brake Line (Each)			$60.00
	Bleed Brake Hydraulic System			$75.00
Parts:	BrakeBest Hardware & Hydraulics Brake Hydraulic Hose	1	$93.97	$93.97
	BrakeBest Hardware & Hydraulics Brake Hydraulic Hose	1	$90.55	$90.55
	BrakeBest Reman Caliper w/ Installation Hardware - LEFT FRONT	1	$113.90	$113.90
	Motorcraft Pads -- Standard Premium - Integrally Molded Disc Brake Pad Set	1	$112.24	$112.24
Discount:	Customer Satisfaction			-$114.00

✓ Approved on 10/09/25 at 09:52 AM EDT — Subtotal $529.16 + est. Tax $28.75 — **$557.91**

3 - (Warranty) Remove & Replace Engine Oil Pan Gasket

Tech: M Hill

Labor:	Remove & Replace Engine Oil Pan Gasket			$899.94
Parts:	MasterPro Ignition Throttle Position Sensor	1	$32.50	$32.50
	Fel-Pro Engine Oil Pan Gasket Set	1	$73.70	$73.70
scounts:	Warranty Labor Discount			-$899.94
	Part Discount			-$106.20

Approved on 10/09/25 at 09:52 AM EDT — 0 — **0**

Fees

Shop Supplies	$50.00
Subtotal	**$50.00**

herwise stated, Repairs come with a 24 Month / 24,000 Mile Warranty.In the event of a problem this store must be allowed to inspect vehicle before any repairs Evidence of tampering will void any and all warranty.

ade using a credit card are subject to a surcharge of 3%. This fee covers the increasing costs associated with credit card
check or cash.

INVOICE

Killer Mobile Audio LLC
301 Kelly Drive, Suite 4
Peachtree City, GA 30269

killermobileaudio@gmail.com
770-486-7407

FRITZ'S
Auto Sound & Security

[redacted]

Invoice details

Invoice no.: 7118
Invoice date: 09/26/2025

#	Product or service	Description	Qty	Rate	Amount
1.	BU-CAMINSTALL	Camera install	1	$175.00	$175.00
2.	RY-CM-MINy3/BL-01	RY-CM-MINy3/BL-01 RYDEEN BUNDLE MINY3/BLO1	1	$90.00	$90.00
3.	1HR-LBR	Hourly labor rate (knitch in wire for backup camera. replaced all wires)	1	$0.00	$0.00

Ways to pay

BANK

View and pay

Subtotal	$265.00
Sales tax	$6.30
Total	**$271.30**

Binion Automotive
26 Spence Avenue
Newnan, GA 30263
(770) 253-4608
binion@msauto.com
https://mainstreetauto.com/

Invoice for RO #2674947

Service Advisor: Matthew Henson
Posted Date: 08/2[redacted]
Clie[redacted]
Vehicle: 1994 Ford Bronco XLT

[redacted]

1994 Ford Bronco XLT 5.0L 8Cyl GAS
Naturally Aspirated
VIN: 1FMEU15N5RLA30106
License: N/A
Color: N/A
Odometer: INOP

RO # 2674947
PO # -
Time-In: 07/12/24 at 07:19 AM EDT
Save Parts: No

Client concerns:

- *SEE CUSTOMER LIST*

1 - Remove & Replace Volt Gauge
Tech: MHill

Labor:	*Remove & Replace Volt Gauge*			$372.50
Part:	*FORD VOLTMETER GAUGE*	1	$69.99	$69.99

✓ Approved on 08/21/25 at 08:12 AM EDT — *Subtotal $442.49 + est. Tax $4.90* — **$447.39**

2 - Remove & Replace Window Regulator Motor
Tech: MHill

Labor:	*Remove & Replace Window Regulator Motor (One Side)*			$223.50
Part:	*Dorman - OE Solutions Window Motor*	1	$99.99	$99.99

✓ Approved on 08/21/25 at 08:55 AM EDT — *Subtotal $323.49 + est. Tax $7.00* — **$330.49**

Unless otherwise stated, Repairs come with a 24 Month / 24,000 Mile Warranty.In the event of a problem this store must be allowed to inspect vehicle before any repairs are made. Evidence of tampering will void any and all warranty.

Payments made using a credit card are subject to a surcharge of 3%. This fee covers the increasing costs associated with credit card processing. To avoid this fee, you may pay with check or cash.

By booking an appointment, you consent to receive text messages regarding your vehicle's service. Message & data rates may apply. You may unsubscribe at any time by replying "STOP".

Binion Automotive
26 Spence Avenue
Newnan, GA 30263
(770) 253-4608
binion@msauto.com
https://mainstreetauto.com/

Invoice for RO #2678344

Service Advisor: Matthew Henson
Date Created: 12/20[redacted]
Client [redacted]
Vehicle: 1994 Ford Bronco Eddie Bauer

[redacted]

1994 Ford Bronco Eddie Bauer 5.8L 8Cyl GAS Naturally Aspirated
VIN: 1FMEU15H2RLA80052
License: N/A
Color: N/A
Odometer In: 212593 / Out: 212593

RO # 2678344
Time-In: 12/20/24 at 08:30 AM EST
Save Parts: No

1 - replace headlight knob

Part:	*Dorman - HELP Headlight Switch Knob*	1	$46.00	$46.00

✓ *Approved on 12/20/24 at 08:45 AM EST* — *Subtotal $46.00 + est. Tax $3.22* — **$49.22**

RO Fees

Fee:	*Shop Supplies*		$0.00
		Subtotal	**$0.00**

Unless otherwise stated, Repairs come with a 24 Month / 24,000 Mile Warranty.In the event of a problem this store must be allowed to inspect vehicle before any repairs are made. Evidence of tampering will void any and all warranty.

Payments made using a credit card are subject to a surcharge of 3%. This fee covers the increasing costs associated with credit card processing. To avoid this fee, you may pay with check or cash.

By booking an appointment, you consent to receive text messages regarding your vehicle's service. Message & data rates may apply. You may unsubscribe at any time by replying "STOP".

otal Repair Order & Signature:

Total Parts:	$46.00
Total Fees:	$0.00
Subtotal:	**$46.00**
Taxes:	$3.22
Grand Total:	**$49.22**
BALANCE DUE:	**$49.22**

Binion Automotive
26 Spence Avenue
Newnan, GA 30263
(770) 253-4608
binion@msauto.com
https://mainstreetauto.com/

Invoice for RO #2673359

Service Advisor: Jessica McCurdy
Posted Date: 04/30
Clien[redacted]
Vehicle: 1994 Ford Bronco XLT

[redacted]

1994 Ford Bronco XLT 5.0L 8Cyl GAS
Naturally Aspirated
VIN: N/A
License: N/A
Color: N/A
Odometer: INOP

RO #2673359
Time-In: 04/29/24 at 04:36 PM EDT
Save Parts: No

Client concerns:

- FRONT END, ALTERNATOR, CHECK ENGINE LIGHT & ABS LIGHT, DOOR LOCK SWITCH PASSENGER SIDE, PROGRAM KEY FOBS,

1 - Remove & Replace Alternator- CUSTOMER PART				TECH: M Hill
Labor:	Remove & Replace Altemator	1.00 hrs	$140.00	$140.00
✓ Approved on 04/30/24 at 08:46 AM EDT				**$140.00**

2 - Remove & Replace Fuel Filter				TECH: M Hill
Labor:	Remove & Replace Fuel Filter	0.50 hrs	$140.00	$70.00
Part:	MicroGard Fuel Filter	1	$19.99	$19.99
✓ Approved on 04/30/24 at 08:46 AM EDT		*Subtotal $89.99 + est. Tax $1.40*		**$91.39**

3 - REPAIR DOOR WIRE				TECH: M Hill
Labor:	REPAIR DOOR WIRE	0.50 hrs	$140.00	$70.00
✓ Approved on 04/30/24 at 10:21 AM EDT				**$70.00**

4 - ABS RELAY				TECH: M Hill
Part:	T Series ABS Relay	1	$19.99	$19.99
✓ Approved on 04/30/24 at 10:21 AM EDT		*Subtotal $19.99 + est. Tax $1.40*		**$21.39**

5 - Remove & Replace Steering Gear Box Assembly				TECH: M Hill
Labor:	Remove & Replace Steering Gear Box Assembly	2.50 hrs	$140.00	$350.00
Parts:	MasterPro Chassis Steering Pitman Arm	1	$99.99	$99.99
	TruGrade Steering Gear	1	$449.99	$449.99
✓ Approved on 04/30/24 at 10:56 AM EDT		*Subtotal $899.98 + est. Tax $38.50*		**$938.48**

6 - ALIGN- ALIGNMENT				TECH: P COLAIACOMO
Labor:	ALIGNMENT	1.00 hrs	$109.99	$109.99
✓ Approved on 04/30/24 at 10:56 AM EDT				**$109.99**

Warranty

- Remove & Replace Wheel Speed Sensor				TECH: M Hill
bor:	Remove & Replace Front Wheel Speed Sensor (One Side)	0.50 hrs	$140.00	$70.00 ✓
:	Standard Ignition ABS Wheel Speed Sensor	1	$149.99	$149.99 ✓
pproved on 04/30/24 at 10:56 AM EDT		*Subtotal $219.99 + est. Tax $10.50*		**$230.49**

BINION Automotive

Binion Automotive
26 Spence Avenue
Newnan, GA 30263
(770) 253-4608
binion@msauto.com
https://mainstreetauto.com/

Invoice for RO #2673271

Date Created: 04/2[redacted]
Clie[redacted]
Vehicle: 1994 Ford Bronco XLT

[redacted]

1994 Ford Bronco XLT 5.0L 8Cyl GAS
Naturally Aspirated
VIN: N/A
License: N/A
Color: N/A
Odometer: INOP

RO #2673271
Time-In: 04/24/24 at 08:48 AM EDT
Save Parts: No

1 - Remove & Replace Suspension Shock or Strut

TECH: M Hill

Labor:	Remove & Replace Front Suspension Shock or Strut (Both)	0.80 hrs	$140.00	$112.00
	Remove & Replace Rear Suspension Shock or Strut (Both)	0.60 hrs	$140.00	$84.00

✓ Approved on 04/26/24 at 08:00 AM EDT — **$196.00** ✓

2135.05

2 - Remove & Replace Heater Core

TECH: M Hill

Labor:	Remove & Replace Heater Core	2.20 hrs	$140.00	$308.00

✓ Approved on 04/26/24 at 08:55 AM EDT — **$308.00** ✓

3 - Remove & Replace Water Pump

TECH: M Hill

Labor:	Remove & Replace Water Pump	2.10 hrs	$140.00	$294.00
Part:	Gates Molded Coolant Hose	1	$39.99	$39.99

✓ Approved on 04/26/24 at 08:55 AM EDT — *Subtotal $333.99 + est. Tax $2.80* — **$336.79** ✓

4 - Remove & Replace Engine Coolant Thermostat

TECH: M Hill

Labor:	Remove & Replace Engine Coolant Thermostat	1.30 hrs	$140.00	$182.00

✓ Approved on 04/26/24 at 08:55 AM EDT — **$182.00** ✓

5 - FLUSH- COMPLETE COOLANT SYSTEM FLUSH

TECH: M Hill

Labor:	COMPLETE COOLANT SYSTEM FLUSH	1.00 hrs	$129.00	$129.00
Part:	VECTOR GREEN COOLANT - AF GREEN	2	$19.99	$39.98

✓ Approved on 04/26/24 at 08:55 AM EDT — *Subtotal $168.98 + est. Tax $2.80* — **$171.78**

6 - Remove & Replace Air Bag Clockspring

TECH: M Hill

Labor:	Remove & Replace Air Bag Clockspring	0.75 hrs	$140.00	$105.00
Part:	OE Air Bag Clockspring	1	$349.99	$349.99

✓ Approved on 04/26/24 at 08:57 AM EDT — *Subtotal $454.99 + est. Tax $24.50* — **$479.49** ✓

7 - Remove & Replace Radiator

TECH: M Hill

Labor:	Remove & Replace Radiator	1.00 hrs	$140.00	$140.00
Part:	Duralast Radiator	1	$299.99	$299.99

✓ Approved on 04/26/24 at 10:53 AM EDT — *Subtotal $439.99 + est. Tax $21.00* — **$460.99** ✓

Smokey's Garage
1885 Veterans Blvd
Sevierville, TN. 37862
Phone: 865-366-3455
THE BEST DAMN GARAGE IN TOWN

INVOICE
17027

INVOICE

Printed Date: 10/06/2025 **Work Completed: 10/06/2025**

[redacted]

1994 Ford - Bronco - 5L, V8 (302CI) VIN(N)
Lic # :
Odometer In : 216116
VIN # :

Part Description / Number	Qty	Sale	Ext
Brake Caliper *18-4390*	1.00	70.83	70.83
Brake Caliper <CORE> *18-4390*	1.00	0.00	n/c
Shop Supplies			9.83

Labor Description	Ext
DRIVING THROUGH GATLINBURG WHEN SOMEONE STOPED THEM AND SAID THE BRAKES WHERE SMOKING CUSTOMER NEVER SEEN THE SMOKE, ONLY THE FRONT WHEELS WERE REALLY WARM AND THERE IS MORE BRAKE DUST THAN NORMAL	
DIAGNOSTIC // DRIVING THROUGH GATLINBURG WHEN SOMEONE STOPED THEM AND SAID THE BRAKES WHERE SMOKING CUSTOMER NEVER SEEN THE SMOKE, ONLY THE FRONT WHEELS WERE REALLY WARM AND THERE IS MORE BRAKE DUST THAN NORMAL MID AUGUST HAD NEW PADS AND ROTORS PUT ON AS WELL AS NEW REAR SHOES	100.00
CALIPER - Remove & Replace - Front,One Side - [Includes: Bleed Brake System and replace Pads (if necessary).]	118.40
[Discount] 10.00% off labor	

RIGHT SIDE

Org. Estimate 304.25 *Revisions* 0.00 Current Estimate 304.25

Labor:	**218.40**
Parts:	**80.66**
Discount:	**-21.84**
SubTotal:	**277.22**
Tax:	**27.03**
Total:	**304.25**
Bal Due:	**$0.00**

[Payments - American Express - $304.25]

REVIEW US ON GOOGLE!

ehicle Received: 10/6/2025

Customer Number : 8557

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs hereto. Warranty work must be performed in our shop & cannot exceed the original cost of repair.
Warranty: From the date of delivery for a period of 12 months or 12,000 miles, whichever comes first.
We express our Implied Warranty on Tire Purchases.

rts returns are subject to manufactures/vendor return policy. Any qualifying refund will be returned to you upon Smokey's receiving the same from manufacture/vendor less ocking fees.
re will be a 15% restocking fee in addition to any manufacture/vendor restocking fee if applicable.

nature _____ Date _____

s on the web: https://

[redacted]

35 Bullsboro Dr., Newnan, Ga. 30263
Office 770 683 8765
Cell 404 542 3328

ESTIMATE #
INVOICE #

WORK ORDER: UPHOLSTERY

DATE 2/13/24
START WORK

CAR INFORMATION	MATERIAS
YEAR/MAKER: 94 Ford	COMPANY KEYSTON BROS.
MODEL: Bronco.	BOOK MARINE COLLECTION
COLOR: Blue/white.	CODE
VIN #:	AMOUNT Olympus Dove olv 120

208.000 Miles SEASCAPE 14 AQUA

ACTION TAKEN

SENT INVOICE DATE:	MATERIAL ORDERED DATE:	DUE DATE OF PROJECT:

ITEM	QUANTITY	AMOUNT
Two Front Seats	750-750	
Back Seat	950	
DHS Cover	350	
Headliner	1'100	
2 Sun visor	225	
2 Door panels Carpet	250	
Ar rest parts	100	
NEW FOAM	180	

SUBTOTAL	4'980 00
TAXES 7 % ✓	
CREDIT CARD 3% ✓	4981
TOTAL ✓	~~4981 00~~
DEPOSIT $2'500	2'481 00
BALANCE	
RECEIVE PAYMENT	

NO REFUNDS
All claims and return items must be accompanied by this receipt.

2/23/24

Cell 404 542 3328

ESTIMATE #
INVOICE #

WORK ORDER: UPHOLSTERY

CUSTOMER'S INFORMATION	DATE
[redacted]	3/11/24
	START WORK

CAR INFORMATION	MATERIAS
YEAR/MAKER: 94 Ford Bronco	COMPANY
MODEL:	BOOK
COLOR: Blue/White.	CODE
VIN #:	AMOUNT

ACTION TAKEN

SENT INVOICE DATE:	MATERIAL ORDERED DATE:	DUE DATE OF PROJEC

ITEM	QUANTITY	
1	New Carpet $ 801.	
1	New Pad. 800 Series	
-	Complete Carpet Black -	
Order 3/11/24	Front — To Trunk $ 387.81	
ACC 1800 633 2358.		

SUBTOTAL	$ 2,033
TAXES 7 %	
CREDIT CARD 3%	
TOTAL	
DEPOSIT	1000
BALANCE	1033
RECEIVE PAYMENT	

NO REFUNDS
All claims and return items must be accompanied by this receipt.

770-683-8765

SALE

Store: 0001
REF#: 00000002
Batch #: 042 RRN: 407116500078
03/11/24 12:37:31
Trans ID: 011153377521061
APPR CODE: 820309
AMEX Chip
**********3004 **/**

AMOUNT $1,000.00

APPROVED

X C J Simpson
SIMPSON/CHARLES J

AMERICAN EXPRESS
AID: A000000025010801
TVR: 00 00 00 80 00
TSI: E8 00

I AGREE TO PAY ABOVE TOTAL AMOUNT IN ACCORDANCE WITH CARD ISSUER'S AGREEMENT (MERCHANT AGREEMENT IF CREDIT VOUCHER)
KEEP COPY FOR YOUR RECORDS

THANK YOU!

MERCHANT COPY

WOLFMAN'S
Mufflers, Welding & Fabrication

2-D Bullsboro Drive • Newnan, Georgia 30263
770-683-4449

[redacted]

INSTALLING A NEW CATALYTIC CONVERTER DOES NOT GUARANTEE EMISSIONS TESTING APPROVAL.
70 - 100 MILES BREAK IN AT HIGHWAY SPEED BEFORE EMISSIONS RETEST.
MANUFACTURER WARRANTY VOID IF TUNE UP NOT PERFORMED AFTER CATALYTIC CONVERTER REPLACEMENT.

INSTRUCTIONS

QTY	PART	DESCRIPTION OF LABOR OR MATERIAL	AMOUNT
		install rear Cat	
		Combo	425.00
		PARTS	
		LABOR	
		TAX	14.87
		We appreciate your business!	

Sig [redacted]

TOTAL 439.87 ✓

1994 Ford Bronco
This item has been ordered:
1 from DC 12 ATLANTA
OESPECTRUM
1 MON 37036
DC or Hub Pickup
1994 Ford Bronco
This item has been ordered:
1 from DC 12 ATLANTA



E AND E AUTO FINISH

25 Barrington Bottoms Ct
Sharpsburg
30277-3642
13476345088
EANDEAUTOREFINISH@GMAIL.COM

1994 FORD BRANCO VIN:
1FMEU15N5RLA30106

INV0076

DATE
Nov 21, 2023

DUE
On Receipt

BALANCE DUE
USD $1,231.27

BILL TO

[redacted]

PARTS
$3831.27 (Total)
561.75 — Steering Wheel? X

DESCRIPTION	RATE	QTY	AMOUNT
PART - FRONT BUMPER CHROME	$339.99	1	$339.99
PART - FRONT GRILL	$68.49	1	$68.49
PART - HEADLIGHT ~~$61.49 EA.~~	$61.49	1	$61.49 ~~E~~
PART - FRONT TURN SIGNAL	$61.68	1	$61.68
PART FRONT LOWER - SIDE MARKERS	$31.12	1	$31.12
PART - SIDE VIEW MIRROR	$82.49	1	$82.49
PART - REAR TRUNK DOOR TRIM RESTORE AND POLISH	$50.00	1	$50.00

3269.52

1 from DC ... OESPECTRUM

1 MON 37037 OESPECTRUM
DC or Hub Pickup
1994 Ford Bronco
This item has been ordered:
1 from DC 12 ATLANTA

1 MON 37036 OESPECTRUM
DC or Hub Pickup
1994 Ford Bronco
This item has been ordered:
1 from DC 12 ATLANTA

1 MON 37037 OESPECTRUM

DESCRIPTION	RATE	QTY	AMOUNT
PART - SUN VISORS OEM P/N FA1Z-5804104-CJ NEW AVAIL 156.89 EACH TOTAL - 313.78 PLUS SHIPPING DICONTINUED PART - SPECIAL ORDER	$0.00	1	$0.00
PART - BRANCO XLT BADGES (FENDER) DISCONTINUED NEW AVAILABLE - 29.74 EACH ESTIMATED DELIVERY DATE DECEMBER	$29.74	2	$59.48
PART - SIDE STEPS POLISH CHROME - SIDE STEP	$243.99	1	$243.99
SHIPPING ESTIMIATED SHIPPING COST	$194.31	1	$194.31
LABOR ESTIMIATED 6 HRS LABOR	$75.00	6	$450.00
PART - STEERING WHEEL $561.75 NEW STEERING WHEEL USED AVAIL - $299.99 + SHIPPING DICONTINUED PART - SPECIAL ORDER (NEW)	$561.75	1	$561.75
DETAILING - INTERIOR DETAILING CARPETS, SEATS STEAM/SHAMPOO COMPLETE INTERIOR	$450.00	1	$450.00
PART - BULB 9007	$99.99	1	$99.99
LABOR - TRIM PAINT DOOR AND DASH FLAT BLACK	$150.00	1	$150.00
CASH DEPOSIT - $2600 22NOV2023	$0.00	1	$0.00
PART- TAIL LIGHT RT - $21.49 LT - $47.98 SHIPPING $10.55	$58.53	1	$58.53

DC or Hub Pickup
1994 Ford Bronco
This item has been ordered:
1 from DC 12 ATLANTA
1 MON 37036 OESPECTRUM
DC or Hub Pickup
1994 Ford Bronco
This item has been ordered:
1 from DC 12 ATLANTA

DESCRIPTION	RATE	QTY	AMOUNT
PART - HEADLIGHT CHROME TRIM TRIM 58.49 SHIPPING $10.51	$69.00	1	$69.00
LABOR - SPARKPLUG / WIRING / TIMING SPARK PLUG & WIRING INSTALL - $150 2 SEIZED SPARK PLUG REMOVAL - $75 COMPRESSION CHECK & BOROSCOPE - 100 TIMING - $75	$400.00	1	$400.00
PAID - CHECK - $ 1072.57 21DEC2023	$0.00	1	$0.00
PART - BULBS 3157 BACKUP LIGHTS FRONT TURN SIGNALS PARKING LIGHTS REAR SIDE MARKER REAR TURN SIGNAL	$3.39	10	$33.90
PART - BULBS 3156 BRAKE LIGHTS	$8.09	2	$16.18
PART - BULBS 194 FRONT SIDE MARKER LICENSE PLATE	$1.29	4	$5.16
PART - TRUNK LIGHT & UNDER HOOD	$1.29	2	$2.58
PART - HEADLIGHT LOCK CLIPS	$4.99	3	$14.97
PARTS - ENGINE OIL (BEFORE SEAL INSTALL)	$22.48	1	$22.48
PARTS - RADIATOR FLUID	$10.28	2	$20.56
ARTS - HARDWARE BOLTS/TABS	$32.49	1	$32.49

SUMMIT RACING EQUIPMENT

Packing List

Customer	Order	Date
25949234	6540184	02/20/2024

1-800-230-3030
SummitRacing.com
2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

Calling Customer Service?
Please have your
Order number ready.

Sold To:

Ship To:

[redacted]

Shipment ID:	04006540184-2402-P001

If all items from your order are not included in this shipment, they will be shipping separately. Please check SummitRacing.com for your order details and tracking info.

Part Number	Part Description	Shipping Qty.	Serial Number
PQP-VHR-2110-80	VENT WINDOW HANDLE	1	-

Return or Exchange a Product:

E&E AUTO REFINISH

E AND E AUTO FINISH

25 Barrington Bottoms Ct
Sharpsburg
30277-3642
13476345088
EANDEAUTOREFINISH@GMAIL.COM

1994 FORD BRANCO VIN:
1FMEU15N5RLA30106

PD IN FULL

INV0076

DATE
Nov 21, 2023

DUE
On Receipt

BALANCE DUE
USD $1,849.78

PAYMENTS
1072.57 check 12/21
3600.00 CASH 11/22
~~1200.00 CASH~~
1442.70 CASH 1/17/24
6115.27

PAID CASH 2/1/24

TOTAL owed 1/31/24
3097.83

BILL TO

[redacted]

DESCRIPTION	RATE	QTY	AMOUNT
PART - FRONT BUMPER CHROME	$339.99	1	$339.99
PART - FRONT GRILL	$68.49	1	$68.49
PART - HEADLIGHT	$61.49	1	$61.49
PART - FRONT TURN SIGNAL	$61.68	1	$61.68
PART FRONT LOWER - SIDE MARKERS	$31.12	1	$31.12
PART - SIDE VIEW MIRROR	$82.49	1	$82.49
PART - REAR TRUNK DOOR TRIM RESTORE AND POLISH	$50.00	1	$50.00

4449.78

DESCRIPTION	RATE	QTY	AMOUNT
PART - SUN VISORS OEM P/N FA1Z-5804104-CJ NEW AVAIL 156.89 EACH TOTAL - 313.78 PLUS SHIPPING DICONTINUED PART - SPECIAL ORDER	$0.00	1	$0.00
PART - BRANCO XLT BADGES (FENDER) DISCONTINUED NEW AVAILABLE - 29.74 EACH ESTIMATED DELIVERY DATE DECEMBER	$29.74	2	$59.48
PART - SIDE STEPS POLISH CHROME - SIDE STEP	$243.99	1	$243.99
SHIPPING ESTIMIATED SHIPPING COST	$194.31	1	$194.31
LABOR ESTIMIATED 6 HRS LABOR FOR BODY PANELS REPLACEMENT ON INVOICE. TRIMS, MIRROR, FRONT BUMPER, HEADLIGHTS, SIDE MAKERS, TURN SIGNAL, REAR BUMPER & SIDE STEPS	$75.00	6	$450.00
PART - STEERING WHEEL $561.75 NEW STEERING WHEEL USED AVAIL - $299.99 + SHIPPING DICONTINUED PART - SPECIAL ORDER (NEW)	$0.00	1	$0.00
DETAILING - INTERIOR DETAILING CARPETS, SEATS STEAM/SHAMPOO COMPLETE INTERIOR	$450.00	1	$450.00
PART - BULB 9007	$99.99	1	$99.99
LABOR - TRIM PAINT DOOR AND DASH FLAT BLACK	$150.00	1	$150.00
CASH DEPOSIT - $2600 22NOV2023	$0.00	1	$0.00
PART- TAIL LIGHT RT - $21.49 LT - $47.98 SHIPPING $10.55	$58.53	1	$58.53

DESCRIPTION	RATE	QTY	AMOUNT
PART - HEADLIGHT CHROME TRIM TRIM 58.49 SHIPPING $10.51	$69.00	1	$69.00
LABOR - SPARKPLUG / WIRING / TIMING SPARK PLUG & WIRING INSTALL - $150 2 SEIZED SPARK PLUG REMOVAL - $75 COMPRESSION CHECK & BOROSCOPE - 100 TIMING - $75	$400.00	1	$400.00
PART - BULBS 3157 BACKUP LIGHTS FRONT TURN SIGNALS PARKING LIGHTS REAR SIDE MARKER REAR TURN SIGNAL	$3.39	10	$33.90
PART - BULBS 3156 BRAKE LIGHTS	$8.09	2	$16.18
PART - BULBS 194 FRONT SIDE MARKER LICENSE PLATE	$1.29	4	$5.16
PART - TRUNK LIGHT & UNDER HOOD	$1.29	2	$2.58
PART - HEADLIGHT LOCK CLIPS	$4.99	3	$14.97
PARTS - ENGINE OIL (BEFORE SEAL INSTALL)	$22.48	1	$22.48
PARTS - RADIATOR FLUID SERVIED RADIATOR SYSTEM WHEN RECIEVED - RADIATOR WAS EMPTY AND SERVICED AFTER THERMOSTAT REPLACEMENT.	$10.28	3.5	$35.98 (15.42)
PARTS - HARDWARE BOLTS/TABS	$32.49	1	$32.49
PART - OIL PAN SEAL	$38.24	1	$38.24
LABOR	$75.00	1	$75.00
PART - ENGINE OIL & FILTER	$60.00	1	$60.00

DESCRIPTION	RATE	QTY	AMOUNT
PART- FLUID TOP OFF TRANSMISSION AND DIFF. FLUID TOP OFF.	$60.00	1	$60.00
PART - VACUUME LINE - EVAP CANISTER	$40.00	1	$40.00
PARTS - VACUUM LINE HEATER	$30.00	1	$30.00
LABOR - TROUBLESHOOT SEAT BUTTON LUMBAR SUPPORT SWITCH	$75.00	1	$75.00*
LABOR - STEERING LINK ADJUSTMENT FINE TUNE AND ADJUST FRONT STEERING AND SUSPENSION	$75.00	1	$75.00*
LABOR - IGNITION CYCLINER	$60.00	1	$60.00
LABOR - TROUBLESHOOT RADIATOR LEAK TROUBLESHOOTING RADIATOR LEAK, PRESSURE TEST SYSTEM - VERFIED NO LEAK PRESENT. DISCUSSED WITH CUSTOMER ABOUT ENGINE PRESPERATION WHILE STATIC. NO LEAKS NOTED WITH ENGINE RUNNING AND COOLING SYSTEM AT NORMAL TEMPERATURE. WILL REPLACE THERMOSTAT DUE TO BEING STUCK OPEN	$75.00	2	$150.00*
PART - THERMOSTAT & GASKET	$32.49	1	$32.49
LABOR - TROUBLESHOOT ABS ISOLATED CAUSE OF ABS LIGHT - FOUND METAL SHAVINGS AROUND WHEELS SPEED SENSORS. CLEANED AND CLEARED ALL DEBRIS. ABS SYSTEM CHECKS GOOD NO ABS LIGHT.	$75.00	1	$75.00*
LABOR - TROUBLESHOOT REVERSE LIGHT REVERSE LIGHT - PERFORMED WIRING CHECK. WIRE DAMAGE AT MULTIPLE LOCATION AND REVERSE SWITCH ON TRANSMISSION DAMAGED. REPLACED WIRING HARNESS AND SWITCH.	$75.00	1.5	$112.50*
PART - REVERSE LIGHT SWITCH & HARNESS	$62.99	1	$62.99
ABOR - TROUBLESHOOT WINDOW MOTORS EMOVED DOOR PANELS AND FOUND BAD GROUND CONNECTIONS - EANED GROUND POINTS. BOTH WINDOWS OPERATE NORMAL.	$75.00	0.5	$37.50*

	RATE	QTY	AMOUNT
LABOR - PAINT WIPER BLADES PAINT BOTH WIPERBLADES BLACK & CLEAR COAT	$75.00	1	$75.00
LABOR - PAINT - REAR BUMPER STEP PAINT AND LABOR - BLACK PAINT AND CLEAR COAT INCLUDED.	$100.00	1	$100.00

* Indicates non-taxable line item

Payment Info

Scan this code to pay online

SUBTOTAL	$4,193.02
TAX (7%)	$256.76
TOTAL	$4,449.78
PAID	-$2,600.00 Nov 22, 2023
BALANCE DUE	USD $1,849.78

4.5% TRANSACTION FEES WILL BE ADDED FOR ALL ONLINE PAYMENT TRANSACTION INCLUDING CHECKS. IF PAID BY OTHER METHODS PLEASE DISREGARD FEES

E AND E AUTO FINISH
25 Barrington Bottoms Ct
Sharpsburg
30277-3642
13476345088
EANDEAUTOREFINISH@GMAIL.COM

1994 FORD BRANCO VIN:
1FMEU15N5RLA30106
INV0075

DATE
Nov 21, 2023

DUE
On Receipt

BALANCE DUE
USD $1,120.62

1/31/24

BILL TO

[redacted]

Total Paint Cost
was $3563.62

DESCRIPTION	RATE	QTY	AMOUNT
PAINT - PRIMER/SEALER	$325.00	1	$325.00
PAINT - BASE COAT PAINT CODE: PL Medium Calypso Green Metallic	$477.99	1	$477.99
PAINT - CLEAR COAT	$245.00	1.5	$367.50
LABOR - PAINT	$1,800.00	1	$1,800.00
LABOR - BODY WORK / RUST REMOVAL DRIVER FENDER DENT RIVER DOOR DENT UST - REAR FENDER UST - TRUNK DOOR	$300.00	1	$300.00
SC. SHOP SUPPLIES	$60.00	1	$60.00

DESCRIPTION	RATE	QTY	AMOUNT
3600 CASH 11-22			
CASH PAYMENT $1000 22NOV2023 1072.67 Check 12-21	$0.00	1	$0.00
✓ CASH PAYMENT $1443 17JAN2024	$0.00	1	$0.00

Payment Info

Scan this code to pay online

SUBTOTAL	$3,330.49
TAX (7%)	$233.13
TOTAL	$3,563.62
PAID	-$2,443.00 Jan 18, 2024
BALANCE DUE	USD $1,120.62

4.5% TRANSACTION FEES WILL BE ADDED FOR ALL ONLINE PAYMENT TRANSACTION INCLUDING CHECKS. IF PAID BY OTHER METHODS PLEASE DISREGARD FEES*

E AND E AUTO FINISH

25 Barrington Bottoms Ct
Sharpsburg
30277-3642
13476345088
EANDEAUTOREFINISH@GMAIL.COM

1994 FORD BRANCO VIN: 1FMEU15N5RLA30106

INV0075

DATE
Nov 21, 2023

DUE
On Receipt

BALANCE DUE
USD $2,563.62

Paint
12-19-23

BILL TO
[redacted]

DESCRIPTION	RATE	QTY	AMOUNT
PAINT - PRIMER/SEALER	$325.00	1	$325.00
PAINT - BASE COAT PAINT CODE: PL Medium Calypso Green Metallic	$477.99	1	$477.99
PAINT - CLEAR COAT	$245.00	1.5	$367.50
LABOR - PAINT	$1,800.00	1	$1,800.00
LABOR - BODY WORK / RUST REMOVAL DRIVER FENDER DENT DRIVER DOOR DENT RUST - REAR FENDER RUST - TRUNK DOOR	$300.00	1	$300.00
MISC. SHOP SUPPLIES	$60.00	1	$60.00
CASH PAYMENT $1000 22NOV2023	$0.00	1	$0.00

Payment Info

Scan this code to pay online

QR code linking to online payment will appear here

SUBTOTAL	$3,330.49
TAX (7%)	$233.13
TOTAL	$3,563.62
PAID	-$1,000.00 Nov 22, 2023
BALANCE DUE	USD $2,563.62

RETAIL INVOICE

SUMMIT RACING EQUIPMENT

1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
20 King Mill Road • McDonough, GA 30253 • 770-288-3200
2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

1-800-230-3030 • 1-330-630-3030 • www.SummitRacing.com

GUARANTEED LOWEST PRICES!

Invoice	Customer	Sales Rep.	Cashier	Tax Exempt	Date	Time
6540184	25949234	KYLE	SHAMIER F.		02/20/24	17:48

[redacted]

D E P O S I T

Qty.	Part Number	Part Description		Unit Price	Balance Due
1	PQP-VHR-2110-80	VENT WINDOW HANDLE	SHP4	10.99	10.99
1	PQP-VHL-2110-80	VENT WINDOW HANDLE	D/S	10.99	10.99

INVOICE INCLUDES ITEMS SHIPPING FROM MANUFACTURER.

Subtotal	21.98
Tax	1.54
Total	23.52

xxxxxxxxxxxxA 5017 23.52

Customer Signature: _____



FRITZ AUTO SOUND & SECUR

FOLLOW

301 KELLY DRIVE
PEACHTREE CITY, GA 30269
+1 770-486-7407

Subtotal	**$995.60**
Total Taxes	$0.00

Total $ 995 60

PAYMENT ID: TX7WPFP3T3C5J
Cashier: Employee

Hide Details

Card: VISA CREDIT 0905
February 22, 2024, 4:05 PM
Method: EMV
Auth ID: 06691D
Reference ID: 405300516146
Authorizing Network: VISA
AID: A0000000031010
CVM: SIGNATURE

DATE	VISA CREDIT
February 22, 2024 4:05 pm	VISA 0905

Killer Mobile Audio LLC
301 Kelly Drive Ste.
Peachtree City, GA 30276

killermobileaudio@gmail.com
770-486-7407

FRITZ'S
Auto Sound & Security

[redacted]

#	Product or service	SKU	Qty	Rate	Amount
	MET-95-5701 Ford F Series Truck		1	$40.00	$40.00
	KEN-DMX809S Kenwood DMX809S Excelon DDIN XM/Maestro with wireless Carplay/AndroidAuto		1	$450.00	$450.00
	DDINSTALL Double Din Install		1	$200.00	$200.00
	RY-CM-MINy3 Rydeen Universal Mini Camera		1	$65.00	$65.00
	RY-BL01 Rydeen MINy Camera License Bracket		1	$25.00	$25.00
	BU-CAMINSTALL Camera install		1	$175.00	$175.00

Subtotal	$955.00
Sales tax	$40.60
Total	**$995.60**

E AND E AUTO REFINISH
25 BARRINGTON BOTTOMS CT
SHARPSBURG, GA 30277-3642
(347) 634-5088
EANDEAUTOREFINISH@GMAIL.COM

1994 FORD BRANCO VIN: 1FMEU15N5RLA3010
INV0147

DATE
Jan 26, 2025

DUE
On Receipt

BALANCE DUE
USD $448.28

BILL TO

[redacted]

DESCRIPTION	RATE	QTY	AMOUNT
PART - STARTER NEW STARTER	$179.99	1	$179.99
LABOR - STARTER INSTALLATION REMOVED BROKEN TERMINAL STUDS	$225.00	1	$225.00*
PART - STARTER SOLONOID	$35.99	1	$35.99
LABOR - STARTER SOLENOID INS	$45.00	1	$45.00*
LABOR - TROUBLESHOOT	$50.00	1	$50.00*

* Indicates non-taxable line item

SUBTOTAL	$535.98
DISCOUNT	-$100.00
TAX (7%)	$12.30
TOTAL	$448.28

BINION Automotive

Binion Automotive
26 Spence Avenue
Newnan, GA 30263
(770) 253-4608
binion@mnsauto.com
https://mainstreetauto.com/

Invoice for RO #2678024

Service Advisor: Matthew Henson
Date Created: 12/03/24 at 12:46 PM EST
Client: JEROME SIMPSON
Vehicle: 1994 Ford Bronco Eddie Bauer

[redacted]

1994 Ford Bronco Eddie Bauer 5.8L 8Cyl GAS Naturally Aspirated
VIN: 1FMEU15H2RLA80052
License: N/A
Color: N/A
Odometer In: 212475 / Out: 212475

RO # 2678024
Time-In: 12/03/24 at 12:46 PM EST
Save Parts: No

1 - REPLACE REAR WINDOW SWITCH

Tech: M Hill

				$50.00
Labor:	REPLACE REAR WINDOW SWITCH	1	$39.99	$39.99
Part:	OE REAR WINDOW SWITCH			

✓ Approved on 12/03/24 at 12:47 PM EST — *Subtotal $89.99 + est. Tax $2.80* — **$92.79**

2 - Standard Synthetic Blend Oil Change

Tech: J Hayes

				$23.00
Labor:	LOF Labor	6	$5.49	$32.94
Parts:	KENDALL 5W20 SYNTHETIC BLEND MOTOR OIL - 5W20 SYNTH BLEND	1	$5.99	$5.99
	MIGHTY OIL FILTER - OIL FILTER			$3.00
Fee:	Hazardous waste Disposal Fee			-$1.83
Discounts:	Package Price Adjustment on Labor			-$3.11
	Package Price Adjustment on Parts			

✓ Approved on 12/03/24 at 01:41 PM EST — *Subtotal $59.99 + est. Tax $2.51* — **$62.50**

3 - TIRE- TIRE ROTATION

Tech: J Hayes

Labor:	TIRE ROTATION			$25.00

✓ Approved on 12/03/24 at 01:41 PM EST — **$25.00**

4 - Remove & Replace ABS Control Module

Tech: M Hill

Labor:	Remove & Replace ABS Control Module			$100.00
Parts:	FORD ABS CONTROL PUMP	1	$349.99	$349.99 ✓
	FORD ABS CONTROL MODULE	1	$749.99	$749.99 ✓

✓ Approved on 12/03/24 at 01:51 PM EST — *Subtotal $1,199.98 + est. Tax $77.00* — **$1,276.98**

5 - Remove & Replace Brake Fluid Level Sensor

Tech: M Hill

Labor:	Remove & Replace Brake Fluid Level Sensor			$75.00
Part:	FORD LEVEL SENSOR	1	$159.99	$159.99

✓ Approved on 12/03/24 at 03:23 PM EST — *Subtotal $234.99 + est. Tax $11.20* — **$246.19** ✓

RO Fees

Fee:	Shop Supplies		$38.22
		Subtotal	**$38.22**