X-Cell Automotive
8800 Whitmore Lake Rd
Brighton, MI. 48116
Phone - 810-231-9474

Junk - 12-14

INVOICE
2461
Org. Est. # 004012
F140136

INVOICE

Print Date : 06/12/2014

[redacted]

1970 CHEVROLET - C 10
350 V8
Lic # :
Unit # :
Vin # :
Hat # :

Odometer In : 36523

Part Description / Number	Qty	Sale	Extended
ANTI FREEZE			
CEM RUAB53	2.00	20.00	40.00
10W30 MOTOR OIL			
PMP 53129	1.00	20.00	20.00
Oil Filter			
51061	1.00	8.50	8.50

Labor Description	Hours	Extended
Lube, oil, and filter Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Preform basic safety inspection. Road test vehicle.	1.00	80.00
CHECK CARB FOR PROPER OPERATION	0.50	40.00
LUBE SPEEDOMETER CABLE	0.50	40.00
RENEW RADIATOR WITH A NEW UNIT SUPPLED BY CUSTOMER	2.00	160.00

9751

[Technicians : Please Select, Technician; BROWN, CHARLES M201890]

Org. Estimate $392.61 Revisions $0.00 Current Estimate $ 392.61 Additional Cost Revised Estimate

Labor:	**320.00**
Parts:	**68.50**
Sublet:	**0.00**
Sub:	**388.50**
Tax:	**4.11**
Total:	**392.61**
Bal Due:	**$392.61**

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....

BOB'S TIRES & AUTO
8535 W GRAND RIVER
BRIGHTON, MI 48116
(810) 229-7005

TERMINAL ID.: 8788520052897

[redacted]

APPROVED

TOTAL $1330.19

JOSEPH CARNEY

THANK YOU

CUSTOMER COPY

Carney (5)

BOB'S TIRE AND AUTO SERVICE, INC

8535 W GRAND RIVER AVE
BRIGHTON, MI. 48116
Phone: 810-229-7005 Fax: 810-229-8711
ALL LUG NUTS MUST BE RE-TORQUED

INVOICE
94093
Org. Est. # 122180

Print Date: 06/17/2015

1970 CHEVY - C10 -
Lic # : - MI

VIN # :

Odometer In : 0
Odometer Out : 38118

	Qty	Sale	Ext	Labor Description	Extended
	2.00	49.90	99.80	INSTALL BRAKE MASTER CYLINDER, REAR WHEEL CYLINDERS, CLEAN AND ADJUST REAR BRAKES, TURN REAR DRUMS.	120.00
				LABOR	
	2.00	43.90	87.80	BLEED BRAKE SYSTEM	37.50
				LABOR	
D	2.00	29.90	59.80	BUILD AND INSTALL BRAKE LINE FROM UNOIN ON LEFT FRAME RAIL TO REAR MAIN BRAKE LINE ON RIGHT FRAME RAIL.	75.00
	1.00	67.90	67.90	LABOR	
	1.00	10.50	10.50	INSTALL EXHAUST MANIFOLD FLANGE GASKETS	97.50
				LABOR	
	1.00	9.95	9.95	INSTALL FRONT COIL SPRINGS AND LOWER BALL JOINTS	262.50
				LABOR	
EXHAUST GASKET *G17B-S*	1.00	5.95	5.95	INSTALL OUTER TIE RODS	50.00
				LABOR	
RF UPPER CONTROL ARM SHAFT KIT *K6098*	1.00	59.90	59.90	INSTALL RF UPPER CONTROL ARM SHAFT KIT	75.00
				LABOR	
FRONT COIL SPRINGS *RC6082*	1.00	119.90	119.90	ALIGNMENT	59.90
				LABOR	

Org. Estimate 1,330.19 Revisions 0.00 Current Estimate 1,330.19

Labor:	777.40
Parts:	521.50
Sub:	1,298.90
Tax:	31.29
Total:	1,330.19
Bal Due:	$1,330.19

pd AMEX

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. If wheels removed, lug nuts must be checked for tightness after 50 miles of use

Signature _____ Date _____ Time _____

Written By: BOB'S TIRE & AUTO - Technicians : COX , BEN M231024

Copyright (c) 2015 Mitchell Repair Information Company, LLC invhrs 2.1515d

[redacted]

DATE_____ MAKE OF CAR C10 70
LICENSE_____ COLOR_____

QUANTITY	DESCRIPTION	PARTS	LABOR
2	Lower balljoints K6023	79.80	150.00
2	Outer tie rods ES350L	53.80	50.00
1	R.F. upper ctrl. arm shaft kit K6098	59.90	75.00
1	Alignment		59.90
2	Rear wheel cyls. W13387,88		
1	C+A rear brks, turn drums	59.80	75.00
1	Master cyl. 10-1329	87.90	45.00
1	Shop	10.50	
1	Bleed brake system		37.50
		846.10 + tax	
	Main brake line going to rear		
	touching Exhaust on R.S.		

SALES TAX_____
ESTIMATE TOTAL_____

TO KEEP YOUR FINAL BILL DOWN, SOME PARTS MAY BE RETURNED TO THE MANUFACTURER, BUT ALL PARTS WILL BE NEW UNLESS OTHERWISE SPECIFIED.

PLEASE PROCEED WITH REPAIRS ON ABOVE ITEMS, BUT CALL ME IF ANY ADDITIONAL SERVICE
IS RECOMMENDED.
CHECK ONE:_____I DO WANT OLD PARTS RETURNED.
_____I DO NOT WANT OLD PARTS RETURNED.

SIGNATURE_____

BOB'S TIRE AND AUTO SERVICE, INC
8535 W GRAND RIVER AVE
BRIGHTON, MI. 48116
Phone: 810-229-7005 Fax: 810-229-8711
ALL LUG NUTS MUST BE RE-TORQUED

Carney

INVOICE (4)

101628

Org. Est. # 129717

INVOICE

[redacted]

Printed: 05/27/2016

1970 CHEVY - C10 -
Lic # : - MI

VIN # :

Odometer In : 0
Odometer Out : 39364

Number	Qty	Sale	Ext
FRONT SWAY BAR KIT *342501*	1.00	215.95	215.95
REAR SWAY BAR KIT *342503*	1.00	179.95	179.95
REAR SHOCKS *37040*	2.00	49.90	99.80
REAR SUSPESION TRACK BAR *341240*	1.00	59.95	59.95
REAR AXLE SHAFTS *14071751*	2.00	149.90	299.80
REAR AXLE BEARINGS *R1559-TV*	2.00	15.95	31.90
REAR AXLE SEALS *8835S*	2.00	9.95	19.90
80W90 GEAR LUBE *80W90*	1.00	18.95	18.95
SHOP MATERIAL *SHOP*	1.00	10.50	10.50
SHIPPING CHARGES *SHIP*	1.00	113.00	113.00

Labor Description	Ext
INSTALL FRONT SWAY BAR KIT LABOR	75.00
INSTALL REAR SWAY BAR KIT, FABRICATE MOUNT POINTS TO MOUNT SWAY BAR BUSHINGS TO REAR ARMS LABOR	150.00
INSTALL REAR SHOCKS LABOR	45.00
INSTALL REAR TRACK BAR LABOR	45.00
INSTALL REAR AXLE SHAFTS, AXLE BEARINGS, AXLE SEALS, CLEAN AND ADJUST REAR BRAKES, AND TURN DRUMS LABOR	187.50

Org. Estimate 1,608.40 Revisions 0.00 Current Estimate 1,608.40

pd AMEX

Labor:	502.50
Parts:	1,049.70
SubTotal:	1,552.20
Tax:	56.20
Total:	1,608.40
Bal Due:	$1,608.40

[Payments -]
Vehicle Received 5/27/2016

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. If wheels removed, lug nuts must be checked for tightness after 50 miles of use. All repairs and parts listed were furnished in compliance with Michigan auto repair act (p.a. 300).

x_____
company authrized represenitive

Signature_____ Date_____ Time_____

Written By: BOB'S TIRE & AUTO - Technicians PETRY, DANN M256547

Copyright (c) 2016 Mitchell Repair Information Company, LLC invhrs 3.1.16d

Red Line Performance LLC
3629 Westphal
Howell, MI 48843
(517) 304-0067
redlineperformancellc@comcast.net

Invoice

Bill To	Make/Model/VIN/Miles	Date	Invoice #
[redacted]	1970 Pick-up 350 cu.in. VIN: CE24OZ173532 MILES: 43,274	3/9/2017	864
		MI State Registration# F161737 Federal ID# 90-0493960 Mechanic Certification # MI65670	

Description	Quantity	Rate	Amount
CUSTOMER REQUEST: -recondition cylinder head -check oil leaks and advise -check into distributor cost -smoke out of exhaust during start up			
CAUSE: engine is near end of service life, oil pump pick-up plugged with plastic from old timing gears, low oil volume			
CORRECTION: Install remanufactured cylinder heads, install remanufactured short block, build engine, paint all components, replace all peripheral parts, replace heater core, replace battery, tune engine, set total and base timing, adjust carburetor	37	70.00	2,590.00
PARTS:			
rebuilt cylinder heads sublet	1	825.00	825.00T
short block reman engine	1	1,500.00	1,500.00T
gasket valve cover FEL-1628	1	39.87	39.87T
SBC head bolts ARP 134-3601	1	89.39	89.39T
exhaust manifold RNB 674-199	1	79.78	79.78T
exhaust manifold RNB 674-201	1	98.78	98.78T
carb base gasket	1	9.18	9.18T
gasket intake w/block off FEL 1256	1	28.44	28.44T
MSD distributor (ready to run) MSD-8360	1	330.00	330.00T
MSD coil blaster 2 MSD 8202	1	49.91	49.91T
MSD streetfire wires MSD 5553	1	51.77	51.77T
fuel filter kit (stone) HOLY-162-500	1	14.45	14.45T
heater core 399067	1	36.99	36.99T
Elite V-belt GDY 15535	1	14.56	14.56T

All repairs completed properly. ***Jerry Veilleux-MI65670***

The only warranties applying to the part(s) are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties either express or implied including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income or any other incidental damages. All parts new or original equipment unless otherwise specified. You are entitled by law to the return of all parts replaced, except those which are too heavy or large, and those required to be sent back to the manufacturer or distributor because of warranty work or an exchange agreement. You are entitled to inspect the parts which cannot be returned to you.

Subtotal	
Sales Tax (6.0%)	
Total	
Payments/Credits	
Balance Due	

A Plus Auto Repair & Transmission

4355 South Old US 23
Brighton, MI 48114
810 229-7878
F-135792
WWW.APLUSTRANSMISSION.COM

Invoice #:0052885
Original Estimate #:

[redacted]

1970 Chevrolet C+k 10 20 30 p/u
350
VIN : C E240Z173532
Mileage 46799
Trans : 700R4
License : FMY285
CLR : 7/26/2017
4WD : 3:29 pm

Service Advisor : ROB

Category Summary	Parts	Labor	Job Total
CUSTOMER CONCERNS	$0.00	$0.00	$0.00
AUTO MINOR	$47.07	$47.50	$94.57
AUTO REBUILD	$1,089.34	$712.50	$1,801.84
AUTO REBUILD R&R	$205.43	$-7.50	$197.93
COMMENTS	$0.00	$0.00	$0.00
DIFFERENTIAL SERVICE	$12.33	$95.00	$107.33
UBLET/OUTSIDE SERVICE	$0.00	$180.00	$180.00
WARRANTY	$0.00	$0.00	$0.00

Technician	Service Description				Parts	Labor	Job Total
DF	Customer Concerns:BUILD TRANS TO CHANGE OVER 350 TO 700R4 ***Findings:					0.00	
DF	Customer Concerns:WANTS 700 R4 INSTALLED TALKED TO ROB CHUCK BROWN IS GOING TO PICK UP OLD PARTS. CELL 810 923 9990 ***Findings:					0.00	
DF	Remove and Replace Transmission 2WD/4WD. Fill With Proper Fluid. Road test and Make Any Necessary Adjustments.				205.43	427.50	632.93
	GEAR SPEEDO DRIVE 15T GREY 700R4	15.30	1	15.30			
	SPD HSG 350/C 700R4 DRIVEN GEAR	50.17	1	50.17			
	GEAR,400 SPD-O DRIVEN (40T)	16.16	1	16.16			
	FILLER TUBE, & DIP STICK UNIV (TECK	28.63	1	28.63			
	DETENT CABLE, OE STYLE, 200C 4R, 7	32.86	1	32.86			
	FLUID ATF SYNTHETIC	4.86	12	58.32			
	BOLT, GM TORQUE CONV. METRIC WASHE	1.33	3	3.99			
PA	REBUILD TRANSMISSION 700R4 (4L60) REPLACE ALL NECESSARY PARTS				1089.34	712.50	1801.84
	VB KIT, 700-R4, HYDR LU	120.88	1	120.88			
	GEAR,700-R4 GOVERNOR GEAR KIT 1982-	8.00	1	8.00			
	CVR,250/350/C/700R4,GOV, 82-91	77.42	1	77.42			
	BAND,4L60E 2-4 HI ENERGY 95-UP	21.76	1	21.76			
	SHELL,700R4/4L60E, REAC, 82-UPTHE B	101.03	1	101.03			
	700 TORQUE CONVERTER	221.71	1	221.71			
	M.L/S, 700R4 L87-93 CORK	186.40	1	186.40			
	FILTER, 700R4 82-93	10.62	1	10.62			
	BUSH KIT,700-R4/4L60E L1984-UPW/TEF	46.25	1	46.25			
	SPRAG,700R4/4L60/4L60E FWD CLU(29 E	64.70	1	64.70			
	ROLL CL,700/4L60/65E,LOW,87-UPWIDE	42.28	1	42.28			
	CTR SUPP, 700R4/4L60E, 86-96 WIDE	23.02	1	23.02			
	OUTPUT SFT, 700-R4, 2WD, 82-9118 1/	39.89	1	39.89			
	EXT HSG, 700-R4/4L60E, 82-95 NO MO	79.42	1	79.42			
	PISTON KIT,700-R4 CORVETTE SHIFT PE	45.96	1	45.96			
DF	CUSTOMIZE SHIFTER BRACKET FOR TRANS INSTALL BRACKET FOR CARB TV CABLE				47.07	47.50	94.57
	THROTTLE LEVER STUD	20.21	1	20.21			
	THROTTLE BRACKET	26.86	1	26.86			
SUB	R&R 3 U-JOINTS, SHORTEN AND BALANCE THE DRIVE SHAFT. (CUT,PRESS,STRAIGHTEN,WELD,BALANCE.)					180.00	180.00
PA	REBUILD TRANSMISSION 700R4 (4L60) REPLACE ALL NECESSARY PARTS				0.00	0.00	
	CORE TRANSMISSION	0.00	1	0.00			
	OHK, 700-R4 82-93 CORK COMBO	0.00	1	0.00			
	STEEL, 4L60E 3-4 .106" L93-UP	0.00	1	0.00			
	BUSHING, 700-R4/4L60E PUMP BODY	0.00	1	0.00			
	BUSHING, 700R4 CASE TO OUTPUT	0.00	1	0.00			
	TV BOOST VALVE KIT, .500" BORE DIA	0.00	1	0.00			
	GASKET, 700/4L60E PAN CORK	0.00	4	0.00			
	GAS	0.00	1	0.00			
DF	Remove and Replace Transmission 2WD/4WD. Fill With Proper Fluid. Road test and Make Any Necessary Adjustments.					0.00	
DF	Rear Differential Service (Remove Cover and Change Fluid) 3.73 NO POS				12.33	95.00	107.33
	FLUID 80W-90	4.93	2.5	12.33			
DF	DRILLED CROSS MEMBER TO MOVE BACK					95.00	95.00
SA RV	WARRANTY: 1 YEAR OR 12,000 MILES, Whichever occurs first, unless otherwise specified. Any warranty work must be performed at our facility, or through one of our nationwide authorized repair facilities. If an out of town breakdown should occur, you must first call us prior to authorizing any repairs, or claim will be denied.					0.00	
SA RV	TECHNICIAN NOTES:CARB IS DUMPING GAS AT TIME. RUNS TO RICH. MUST BE FIXED ASAP.					0.00	
SA	LABOR & PARTS DISCOUNT					-530.00	-530.00

3629 Westphal
Howell, MI 48843
(517) 304-0067
redlineperformancellc@comcast.net

Invoice

PAID 10-28-2017

Bill To

[redacted]

Make/Model/VIN/Miles	Date	Invoice #
1970 Pic[illegible]350 cu.in. VIN [illegible]24OZ173532 MILES:	10/28/2017	939

MI State Registration# F161737
Federal ID# 90-0493960
Mechanic Certification # MI65670

Description	Quantity	Rate	Amount
CUSTOMER REQUEST: -install new carburetor -wire tachometer and install			
SERVICES PROVIDED: -replace carburetor and make necessary adjustments (carburetor provided by customer) -fabricate throttle linkage -wire choke -fabricate fuel line from filter to pump	5	70.00	350.00
-install tachometer provided by customer, including all wiring	1	70.00	70.00
PARTS: throttle linkage RED3629		44.90	44.90T
throttle linkage bushing 64920	1	7.41	7.41
aeroquip fuel line RED5479		75.47	75.47T
shop supplies and hazardous waste removal		18.87	18.87T

All repairs completed properly. ***Jerry Veilleux-MI65670***

The only warranties applying to the part(s) are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties either express or implied including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income or any other incidental damages. All parts new or original equipment unless otherwise specified. You are entitled by law to the return of all parts replaced, except those which are too heavy or large, and those required to be sent back to the manufacturer or distributor because of warranty work or an exchange agreement. You are entitled to inspect the parts which cannot be returned to you.

Subtotal	$566.65
Sales Tax (6.0%)	$8.35
Total	$575.00
Payments/Credits	$-575.00
Balance Due	**$0.00**

...stphal
Howell, MI 48843
(517) 304-0067
redlineperformancellc@comcast.net

Invoice

PAID 05/18/2017

Bill To		Date	Invoice #
[redacted]	...Miles ...70 Pick... ...50 cu.in. VIN ...24OZ173532 MILES:	5/19/2017	888

MI State Registration# F161737
Federal ID# 90-0493960
Mechanic Certification # MI65670

Description	Quantity	Rate	Amount
CUSTOMER COMPLAINT: -replace choke with electric choke (install electric choke conversion) -check for oil leaks			
CAUSE: Diagnose oil leak to oil port above oil filter in engine block. Engine remanufacturer did not seal the plug with pipe thread sealant. No charge to customer.			
CORRECTION: diagnose oil leak and replace plug in block with new plug. Apply pipe thread sealant.		0.00	0.00
no charge install electric choke conversion, adjust as necessary	0.4	70.025	28.01
PARTS: divorced choke electric conversion CU1444	1	41.91	41.91T
expedited shipping (over night)		47.57	47.57

All repairs completed properly. ***Jerry Veilleux-MI65670***

The only warranties applying to the part(s) are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties either express or implied including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income or any other incidental damages. All parts new or original equipment unless otherwise specified. You are entitled by law to the return of all parts replaced, except those which are too heavy or large, and those required to be sent back to the manufacturer or distributor because of warranty work or an exchange agreement. You are entitled to inspect the parts which cannot be returned to you.

Subtotal	$117.49
Sales Tax (6.0%)	$2.51
Total	$120.00
Payments/Credits	$-120.00
Balance Due	**$0.00**

Howell, MI 48843
(517) 304-0067
redlineperformancellc@comcast.net

Invoice

Bill To

[redacted]

Make/Model/Year/Miles
1970 Pick-up 350 cu.in.
VIN: CE24OZ173532
MILES: 50,889 showing

Date	Invoice #
9/19/2018	1025

MI State Registration# F161737
Federal ID# 90-0493960
Mechanic Certification # MI65670

Description	Quantity	Rate	Amount
CUSTOMER REQUEST:			
-replace steering gear			
-rebuild steering coupler			
-remove horn contact and button, reindex steering wheel			
LABOR			
R&I power steering gear, replace with remanufactured gear box	4	70.00	280.00
R&I steering coupler and rebuild with new aftermarket coupler	1.5	70.00	105.00
remove steering wheel and horn contact, reindex wheel, loctite and retorque fastener and reconnect horn	0.5	70.00	35.00
PARTS:			
gearbox, power 7501	1	231.99	231.99T
steering coupler rebuild kit OER-C2553	1	21.99	21.99T
shipping and handling		7.99	7.99T
shop supplies and hazardous waste removal		11.00	11.00T

All repairs completed properly. ***Jerry Veilleux-MI65670***

The only warranties applying to the part(s) are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties either express or implied including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income or any other incidental damages. All parts new or original equipment unless otherwise specified. You are entitled by law to the return of all parts replaced, except those which are too heavy or large, and those required to be sent back to the manufacturer or distributor because of warranty work or an exchange agreement. You are entitled to inspect the parts which cannot be returned to you.

Subtotal	$692.97
Sales Tax (6.0%)	$16.38
Total	$709.35
Payments/Credits	-$709.35
Balance Due	**$0.00**

Red Line Performance LLC

Invoice

3629 Westphal
Howell, MI 48843
(517) 304-0067
redlineperformancellc@comcast.net

Bill To	Make/Model/VIN/Miles	Date	Invoice #
[redacted]	1970 Pick-up 350 cu.in. VIN: CE24OZ173532 MILES: 51,537 showing	5/9/2019	1078
		MI State Registration# F161737 Federal ID# 90-0493960 Mechanic Certification # MI65670	

Description	Quantity	Rate	Amount
CUSTOMER COMPLAINT:			
-warranty return-steering is still tight at times; no assist			
(note: steering gear had been replaced, reference invoice #1025 on 9/19/2018)			
-check for oil leak			
CAUSE:			
-determined replacement steering gear to be defective			
-steering column bearings require cleaning and repacking			
-determined speedometer cable housing leaking and requires resealing			
-tierod sleeve clamps were incorrectly indexed during alignment, RH and LH sides interfering with sway bar			
LABOR:			
diagnostics	0.5	70.00	35.00
R&R steering column, remove shaft, clean and regrease bearings, replace horn contact and upper shaft spring, clean and inspect	3.6	70.00	252.00
R&R steering gear and replace with new gear	4	70.00	280.00
warranty R&R steering gear and replace with new gear		-280.00	-280.00
sublet alignment	1	120.00	120.00T
PARTS:			
steering column horn contact and upper retention spring RED5819 (includes shipping)	1	25.00	25.00T
steering gear box 7501	1	644.99	644.99T
warranty steering gear box 7501		-644.99	-644.99T
shop supplies		20.00	20.00T

PAID
MAY - 2019

All repairs completed properly. *Jerry Veilleux-MI65670*

The only warranties applying to the part(s) are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties either express or implied including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income or any other incidental damages. All parts new or original equipment unless otherwise specified. You are entitled by law to the return of all parts replaced, except those which are too heavy or large, and those required to be sent back to the manufacturer or distributor because of warranty work or an exchange agreement. You are entitled to inspect the parts which cannot be returned to you.

Subtotal	$452.00
Sales Tax (6.0%)	$9.90
Total	$461.90
Payments/Credits	$0.00
Balance Due	**$461.90**

9979 Weber
810 229-2746

Invoice

Date	Invoice #
7/23/2019	8050

Bill To

[redacted]

PAID
07/24/2019

Claim #

Description	Amount
Chevy Pick Up	
Parts	283.02T
Labor	150.00
Repair Spring in Front Seat. Install Seat Belts	
Sales Tax	16.98
	449.00

Total $450.00

COMPONENTS INC.

7070 Metcalf Rd. - Louisburg, KS 66053
Voice: (913) 837-4368
Fax: (913) 837-5721

Invoice

Invoice Date:	Invoice Number:
Aug 21, 2020	60737
	Page: 1

Sold To:
Retail Customer

[redacted]

Customer ID	Customer PO	Payment Terms
Retail		Prepaid
Sales Rep ID	Shipping Method	Ship Date / Due Date
		8/21/20

Quantity	Item	Description	Unit Price	Extension
-1.00	**113R**	**A.C. Compressor Bracket**	**98.50**	-98.50

Subtotal	-98.50
Sales Tax	
Freight	
Total Invoice Amoun	-98.50
Payment Received	-98.50
TOTAL	0.00

Check No: **Redline Perf.**

All returns must have an RGA number and a copy of this reciept.

Please pay from this invoice, no statement will be sent.

Installation Instructions

Important information about your new a/c system.

Please read the following directions prior to installing this a/c system.

IN-DASH A/C AND HEAT SYSTEMS
ID-260, 265, 270, 280

NACP

Nostalgic AC Parts

"Keeping Your Classics Cool"

♦ Contact us by email or phone if you need any assistance or information regarding this a/c system.

888-977-8889

SALES@NACKITS.COM

X TEMP SENSOR (GAUGE)

Red Line Performance LLC

Invoice

3629 Westphal
Howell, MI 48843
(517) 304-0067
redlineperformancellc@comcast.net

Bill To	Make/Model/VIN/Miles	Date	Invoice #
[redacted]	1970 Pick-up 350 cu.in. VIN: CE24OZ173532 MILES: 55,449 showing	5/21/2020	1157
		MI State Registration# F161737 Federal ID# 90-0493960 Mechanic Certification # MI65670	

Description	Quantity	Rate	Amount
CUSTOMER REQUEST: -install A/C system (aftermarket kit) remove all OEM equipment necessary for new system -engine not running good; check and advise			
SERVICE PROVIDED: diagnose drivability issue, replace spark plugs, and distributor cap	2.5	70.00	175.00
PARTS: distributor cap SMP DR-450 distributor rotor SMP DR-318 spark plugs ACD R43	1 1 8	15.75 7.28 2.2775	15.75T 7.28T 18.22T
pulley-back ordered	1	250.00	250.00T

PAID
MAY - 2020

All repairs completed properly. ***Jerry Veilleux-MI65670***

The only warranties applying to the part(s) are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties either express or implied including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income or any other incidental damages. All parts new or original equipment unless otherwise specified. You are entitled by law to the return of all parts replaced, except those which are too heavy or large, and those required to be sent back to the manufacturer or distributor because of warranty work or an exchange agreement. You are entitled to inspect the parts which cannot be returned to you.

Subtotal	$466.25
Sales Tax (6.0%)	$17.48
Total	$483.73
Payments/Credits	$0.00
Balance Due	**$483.73**

Red Line Performance LLC

3629 Westphal
Howell, MI 48843
(517) 304-0067
redlineperformancellc@comcast.net

Invoice

Bill To	Make/Model/VIN/Miles	Date	Invoice #
[redacted]	1970 Pick-up 350 cu.in. VIN: CE24OZ173532 MILES: 57,756showing	7/1/2021	1235
		MI State Registration# F161737 Federal ID# 90-0493960 Mechanic Certification # MI65670	

Description	Quantity	Rate	Amount
CUSTOMER REQUEST: install aftermarket cruise control system supplied by customer			
SERVICES: -install cruise control system; Dakota Digital CRS-2000 -wire in system and test	10	70.00	700.00
PARTS: Dakota Cruise CRS-2000- supplied by customer			
shop supplies		47.17	47.17T

Paid 7-1-2021

All repairs completed properly. ***Jerry Veilleux-MI65670***

The only warranties applying to the part(s) are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties either express or implied including any implied warranties of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income or any other incidental damages. All parts new or original equipment unless otherwise specified. You are entitled by law to the return of all parts replaced, except those which are too heavy or large, and those required to be sent back to the manufacturer or distributor because of warranty work or an exchange agreement. You are entitled to inspect the parts which cannot be returned to you.

Subtotal	$747.17
Sales Tax (6.0%)	$2.83
Total	$750.00
Payments/Credits	$0.00
Balance Due	**$750.00**

In

Se

8/17/2

Invoice

A Plus Transmission
4355 S Old US Hwy 23
Brighton, MI 48114
810-206-0901
Facility # F171385

[redacted]

Plate MI FMY285
Description 1970 Chet C+K 10 20 30 P/U 350
VIN CE240Z173532
Odometer 61,264

Invoice Date 8/17/2023 10:48 AM
Appointment 8/7/2023 7:00 AM
Promised 8/7/2023 5:00 PM

Customer Complaint
Complaint:

APP SET 7-5

BANG AND GRIND ON A START UP. NOT UP SHIFTING PROPERLY AFTER THAT.

NEEDS TO BE KEPT IN SIDE

MO SET APPT

Findings:

Labor 0.3 Hour $0.00 *

Sub $0.00

Inspection

GreatWater Garages Courtesy Inspection
Visual inspection of 30+ components which includes Filters, Fluids, Bulbs, Belts, Wipers & Tires.

Labor 0.2 Hour $0.00 *

Sub $0.00

Service

Automatic Transmission Assembly, Remove & Install
Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor 6 Hour $796.62 *

POWER HOT FLUSH TRANSMISSION COOLING SYSTEM 1 Hours $132.77 *

Most repairs are covered by our GreatWater 360 Auto Care 3-Year/36,000 Mile Warranty. Please ask for details.

We appreciate your business!
Scan the QR code to leave us a review!