			BAD COMPANY INC		
		8009	B Hankins Industrial Park Rd		
			Toano VA 23168		
Van-	2011		757-250-3900	STATUS: WAITING	
Year	Make/Model	Detail		VIN	NAME OF THE OWNER, OWNER, OWNER, OWNER, OWNER, OWNER,
1973 Chevrolet C30		manual, 350 SBC, 4 speed		CCY333B133998	
Vame		Date	Drop off (met, drive & drop, tow)	Phone	
Address*	是是1000 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	4/3/2024	towed in	TEL STREET	The base
Audress"			· 公司的基本的基本的基本的基本的基本的基本的基本的基本的基本的基本的基本的基本的基本的	E-Mail	I (State)
			performance exceptions, additives, re-	- 6K D	

Intake: original parts, sat up, running, pre-existing noises or performance exceptions, additives, recent maintenance, history of repairs

## Shop Notes: Customer description of problem, or request for work, BCI recommendations SHOP RATE: \$200/hr, CUSTOMER SUPPLIED PARTS: \$250/hr

Customer requests: The truck squeals then abruptly stops when I brake! BCI recommends: Bring her in and we will take a look to see what we can do to get her back on the road! We expect you to have her towed in this Friday 4/5/24. We ordered in your brake parts ahead of time from Advance so that we can get you processed quickly! UPDATE 4/4/24: I see that forums report this is a tricky year for brake parts, of course. Heads up--it might be a minor struggle in spite of all our preparations. UPDATE 5/22/24: We removed the right front wheel and bled the brakes to see if that was the cause of the truck pulling to the left and saw that everything looked new. We were able to get the rear to lock up and checked the rear brake components. A lot of the brake components will need replaced because there is a lot of build up and caked with fluid. The passenger side hardline was rust pitted so it was replaced. The wheel seal was leaking all over everything so we cleaned all the components that were affected. We are checking the radiator because it is leaking.

20.0812	Description of Materials or Work		Cost	
30,0218	Billing	Parts	\$246.5	
	Deposit is 100% of parts and 50% of labor.	Labor	\$2,100.0	
3500.00	We will provide bi-weekly progress and in the second secon	S&H/Fees	\$150.0	
00 12 12	We will provide bi-weekly progress and include billing for completed Change orders are billed separately and are prepaid at 100%.  Storage is available, by arrangement is	labor		
	Storage is available, by arrangement if was prepaid at 100%.	L AVOIGN	BETT CANDED	
CA ACL CT	Storage is available, by arrangement, if you need to pause your project  Credit card convenience: +3.5%			
NOTE:	Customer supplied parts: inappropriate, incomplete or poor quality will be rejected and replaced at the owner's expense without	estimate		
TA THE	是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个	or notes	SISTANCES	
\$2.543.7 33000	*extracting broken or damaged bolts incurs a charge of \$200.00 each		- VOATIME.	
	Labor, Installation, Modifications and Fabrications*	Installation, Modifications and Entricetion		
Licha de la composition della	diagnose brakes		\$2,100.00	
credit	deposit against unknown brake repairs	O Francis Co	included	
30 90 3962	test drive	\$500.00		
THE RELIEF	remove right front wheel: everything looks new	We only by	included	
updated	Dieed brakes (front)		include	
	r/r rear drum brakes and components		include	
	1// passenger side hardline	Jan Bin y	\$1,000.0	
	r/r driver side hardline	THE REAL PROPERTY OF THE PERSON NAMED IN COLUMN TWO IN COL	\$300.0	
	clean and reinstall hardware that isn't replaced to		\$200.0	
leaks found	clean and reinstall hardware that isn't replaceable (e-brake components, e r/r radiator-might be the	tc)	\$200.0	
	r/r radiatormight be the expansion tenter.	Buston Too	\$200.0	
	r/r radiatormight be the expansion tank; keep an eye on any drips/leaks	\$400.00	\$200.0	
	repacked bearings while they were oversed	with a first	\$200.0	
	refill a little fuel	No. of the last of	include	
		<b>Maria</b>	include	

	Handon's Industrial Park Po	86008	Kell Francisco		
	Tours VA 23188	N. Carlos			400
	Parts and Supplies		E WERE		\$246.52
MINIST E	calipers			ALC: UN	not needed
updated 4/1	17/24 carquest rotor (x2)	Usy light age	TOTAL PROPERTY	\$300.00	returned
updated 4/1	18/24 Wearever drum kit	de la company		BUT WAS	\$18.00
updated 4/1	\$50.00	returned			
	Duralast brake shoes				\$78.52
may:0	hoses (just one, the rear center hose)	98	TES AS THE	N. Oyo	\$32.00
	replaced brake lines at the axle with custom lines	S			included
	master cylinder (is there warranty?)				not needed
	booster				not needed
pdated 4/18	3/24 Carquest wheel cylinder (x2)			GODENE T	\$42.00
	ABS system??	160 \$200/m, C	SHOP RA		no system
aw bus mis	brake fluid	sals then com	e trank sang	AT .aleeur	\$12.00
eith ni	Duralast axle seals (one side was leaking into th	e drum)	BED DW TECH	Feel of the	\$32.00
pageage	gear oil	e stron saiste	down be	ibio ewi	none
DE UD-E	radiator	igger ammol	edi aga isa	GENERALE.	not necessary
HUE PROTEIN	tube nuts	GENCISED HOLE	8)16(27)19	3121 3112 31111	
D92001 C	5 gal of 93	SEUR VISIT ES	V DERN IT SEE	UI STAFF	\$7.00
3/63	J yai Ui 93	ALE ON THE OT	ESCENT IS	UT WEST	\$25.00
and the same of the			de la	10 10	
with the hales	Shipping and Handling	odl keyela	0 20W F C	hattel spec	\$0.00
	none	richardo are al	A/o homen	enany fari	i elmanonomia T
3552 6011	Fees and Misc				\$150.00
A STATE OF THE PARTY OF THE PAR				2 2 4 3 4 4 4	\$150.00
Sed No. 5	Shop Fee, per 30 days or part thereof			THE PARTY OF	\$150.00
9000	a postage of the second	of parts and	200 r ci 1	entient	
	Payments Payments	oro yisteaw-is	provide b	law sve	\$500.00
4/4/2024	deposit by debit card \$500.00 (@\$517.50)	ansilo.	\$500.00		
	a legge of lack salled of base not it inferned	ARTH VEGSIO	SILVE	081131831	\$300.00
posed time	e span for completion of work:	Total Partell a	SO/F	0.000	20 100 50
tomer's de		Total Parts/La	The second secon		\$2,496.52
tome, 5 de	φ300.00	EPA/Waste	Disposal		\$0.00
varranty on pro	oducts sold hereby are those made by the manufacturer. BAD	Storage		N. A. C. Land	\$0.00
PANY INC her	by expressly disclaims all warranties, either expressed or	Tax Calc	Subtotal	COMMENT.	\$2,496.52
d, including in	aplied warranty of merchantability or fitness for a particular	\$246.52	7.00%	Contract Try	
se, and neithe	r assumes nor authorizes any other person to assume liability ne sale of any product. Acknowledged: (initial)	THE RESIDENCE OF THE PARTY OF T	E. STATE OF THE REAL PROPERTY AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO IN COLUMN	810	\$17.20
nection with th	Total Estim	ате	The second second	\$2,513.7	
(initial) De	sturm all austamanda marti (f	Deposit		MOS SAL	\$500.0
The state of the s	eturn all customer's parts (for customer's process)	Total Due		ONORUS	\$2,013.7
E READ CAR	REFULLY, initial one of the statements below: I understand	AUTHORIZATIO	N OF WORK:	l authorize ti	he work stated
der state law,	I am entitled to a written estimate if my final bill will exceed	above, including procurement of materials. BAD COMPANY			
		INC may operate my vehicle for testing, inspection or delivery, at my risk. An express mechanic's lien is			
I reques	at a written estimate	acknowledged to secure the cost of work and materials. BAL COMPANY INC assumes no responsibility for loss or damage by theft or fire to vehicles placed with us for storage, sale, repair or road testing. No guaranteed refunds for parts, labor shipping or fees.			
	t a written esumate				
I do not	request a written estimate as long as the repair costs				
exceed \$_	This amount will not be exceeded without				
oroval.					
ing to the ric	bt Cook	Date:	Hall Theth		
ing to the rig	ht, Customer acknowledges and agrees that in the breach of this agreement, Bad Company Inc shall be	Ve Blanchine	STATE OF THE STATE OF	IS HIGHWAY	
Customer's	breach of this agreement. Bad Company Inc shall be	for designation	2 2000		
to recover re	asonable attannant, bud company inc shall be	THE RESERVE OF THE PARTY OF THE	THE RESERVE OF THE PARTY OF THE		
to recover re	Customer ale	A TOTAL STATE OF THE STATE OF T			
to recover re	easonable attorney's fees, court costs, and any other Customer also acknowledges and agrees that any past pear interest at 12% per annum.	Customer's	bin u		

在1965年,29月日前,0月2日日本中国的公司的,1965年,1965年