

GMC S-15 w/ Factory Gypsy Package

New tires 2 years ago w/ Approx 1,000 miles on them

ATC Rebuilt

Tonneau Cover

Truck Cover

Power Windows + Locks

Stall Converter

MSD Ignition

Turbo 350 Trans

"Built" Hi-Po 350 V8 w/new Edelbrock Carb

Custom B+M Shifter on Floor

PS + Power Front Disc Brakes

3:11 open? rear end

20 Gallon Fuel Tank

Tilt Wheel

Factory Sport Suspension

Perfect Paint / No chips or scratches

Rust-Free

Bucket Seats and Console / Added gauges

Lowered Suspension

Performance Cam

New Battery

Very Quick + Extremely Quick



S&P Automotive Specialists
 6150 Georgia 21 South
 Rincon, GA 31326
 (912) 826-5303
 victor@spauto.net
 SPAutoRincon.com

Invoice #2671

Created: 10/7/2024 04:31 PM EDT
 Invoiced: 10/25/2024 02:16 PM EDT
 Payment Term: On Receipt
 Service Writer: Vicki Haney

1984 GMC S15 Base
 VIN: 1GTCS14B0E2527332
 Mileage In: 1
 Mileage Out: 2

DIAGNOSTIC			
HARD TO SHIFT			
Description	HRS	Subtotal	
1 DIAGNOSTIC	0.86	\$120.00	
EPA (2%): \$2.40 Shop Supplies (3%): \$3.60 Tax (8%): \$0.29			Total: \$126.29

SHIFTER ASSEMBLY				
Description	Price	QTY	HRS	Subtotal
1 SHIFTER ASSEMBLY	\$1,095.95	1		\$1,095.95
2 SHIFTER ASSEMBLY			3	\$420.00
3 SHIFTER BOOT	\$139.95	1		\$139.95
EPA (2%): \$8.40 Shop Supplies (3%): \$12.60 Tax (8%): \$99.88				Total: \$1,776.78

Thank you for choosing S&P! The work is complete and your payment is due upon pickup of the vehicle, or by mobile payment. Mechanics liens may be placed on vehicles until repairs are paid for in full. Storage fees, of \$35/day, will begin on 3rd day after repairs are complete. Please contact us promptly if you have any questions about anything we did.

All labor warranties are 90 days from completion of repair, and 1 year on parts, unless otherwise stated on invoice.

No warranty, of any kind, on customer provided parts.

Customer must contact us for any warranty repairs BEFORE any other actions are taken, or warranty will be null & void. We do have nationwide coverage.

Parts	\$1,235.90
Labor	\$540.00
Subtotal	\$1,775.90
Shop Supplies	\$16.20
EPA	\$10.80
Tax	\$100.17
Grand Total	\$1,903.07
Paid To Date	(\$0.00)

REMAINING BALANCE \$1,903.07

Signature _____

Authorizations		
In Person by RICHARD GLISSON	+ DIAGNOSTIC	\$1,903.07
10/23/2024 at 9:01 AM EDT	+ SHIFTER ASSEMBLY	



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
8/14/2023	JF6324

Name / Address

Vehicle Info
1984 GMC S15 1GTCS14B0E2527332 off white

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Repair Labor	Modified the throttle linkage for idle bump. Relocated throttle return spring. Moved the spring bracket. Mounted the idle bump bracket and bump installed. Wired in the idle bump. Ran vehicle to warm up and performed calibration of idle bump.	1.8	132.00	237.60
Parts	ATK Bracket HLY-20-92	1	130.00	130.00T
Parts	ATK Carburetor Throttle Solenoid	1	12.75	12.75T
Shipping	Shipping	1	11.99	11.99
Repair Labor	Windshield wiper diagnostic. Motor did not have a ground when switch was on. Made a ground. Found switch not sending signal on low. Intermittent wiper reestat was adjusted to get low to work. Removed steering wheel to inspect wiper switch in steering column. Switch is bad. Ordered parts. Installed new wiper switch. Reinstalled the steering wheel and all removed. Installed new turn signal stalk. Wipers now function as designed.	3.2	132.00	422.40
Parts	OR Turn signal switch ACDelco 19244660 list \$88.12	1	49.66	49.66T
Parts	OR Wiper Switch DS809 list \$288.12	1	115.99	115.99T

Subtotal	\$5,792.75
Sales Tax (7.0%)	\$124.51
Total	\$5,917.26
Payments/Credits	\$0.00
Balance Due	\$5,917.26



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
8/14/2023	JF6324

Name / Address

Pickup Co
I
S

Vehicle Info

1984 GMC S15
1GTCS14B0E2527332
off white

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Parts	OR Hayden Fan Control 3653 list \$33.88	1	18.13	18.13T
Parts	ATK Electric fan Assembly 19122	1	18.13	18.13T
Shipping	Shipping	2	94.50	189.00T
	WRAP HEADERS	1	41.99	41.99
Repair Labor	Wrapped the headers while off during headgasket replacement.	1	0.00	0.00
Parts	AZ Exhaust Wrap 10108 list \$85.62	1	49.49	49.49T
Parts	OR Header Wrap 010107 list \$66.08	1	38.99	38.99T
Repair Labor	TEST DRIVE AND POWER VALVE REPLACEMENT Test drove the truck to make sure the truck would maintain temperature. It does maintain temperature. Slight hesitation. Need to replace the power valve. Power Valve Installation and Tuning. Replaced the power valve to be more suited to the amount of vacuum the engine produces. The power valve has to be a little less than half of the measured vacuum. Vacuum was around 10, installed a 4.5 power valve.	1	132.00	132.00
Parts	AZ Holley 12-45 Power Valve	1	15.34	15.34T
Parts	OR Holley Carb Gasket set 37-119	1	41.99	41.99T
	THRATTLE BUMP INSTALLATION			
			Subtotal	
			Sales Tax (7.0%)	
			Total	
			Payments/Credits	
			Balance Due	



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
8/14/2023	JF6324

JFrazzar
Sports Car Serv

3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Name / Address
Richard G. Lison
161 Junco Way
Savannah, GA 31419-8800

Name / Address
Richard G. Lison 161 Junco Way Savannah, GA 31419-8800

Vehicle Info
1984 GMC S15 1GTCS14B0E2527332 off white

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Repair Labor	Inspected the climate control panel to correct the vent selector malfunction. The panel works on vacuum and cable actuation. It appears that there is a broken vacuum bell. The tip of the bell that hooks to the door is broken. Removed the after market gauge cluster down. Removed the floor vents and unhooked the spring on the door. Recharged the AC system. Install the vacuum canister and check valve. Test drove the truck. HVAC controls function as designed. Heater vent is permanently closed due to broken parts.	3.4	132.00	448.80
Parts	OR Vacuum Tank 47076	1	22.04	22.04T
Parts	OR Vacuum Check Valve 47149	1	9.38	9.38T
	HARD PULL THERMOSTATIC FAN SWITCH AND FAN UPGRADE TO LARGER CFM TO KEEP TRUCK COOL			
Repair Labor	Thermostatic fan switch install. Looked at the wiring diagram and located the best spot for the thermostatic fan switch. Removed knee bolster trim and disconnected the fan switch. Connected the wires to complete the circuit. Installed thermo switch at the radiator and found ground.	1.5	132.00	198.00

Subtotal	Subtotal
Sales Tax (7.0%)	Sales Tax (7.0%)
Total	Total
Payments/Credits	Payments/Credits
Balance Due	Balance Due

Item	OR HVAC Fan Control
Parts	ATX Electric fan Assen
Parts	Shipping
Parts	WRAP HEADERS
Parts	Wrapped the headers with AZ Exhaust Wrap 101081
Parts	Replacement
Parts	OR Header Wrap 0101071

Rate	Total
LAN	Tech 2

Date	Invoice #
8/14/2023	JF6324

Invoice



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
8/14/2023	JF6324

Name / Address

Vehicle Info
1984 GMC S15
1GTCS14B0E2527332
off white

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Parts	OR AC Condensor 7-4167 list \$227.10	1	193.34	193.34T
Parts	OR Fan Assembly Hayden 3670 list \$108.46	1	89.10	89.10T
Parts	OR Quick mount 210 list \$18.63	1	16.98	16.98T
Parts	AZ AC Hose Assembly 34815 list \$119.15	1	94.87	94.87T
Parts	AZ AC Clutch Switch MT0207 list \$25.34	1	21.93	21.93T
Parts	OR A/C kit MUK10174 list \$81.34	1	65.23	65.23T
Parts	OR AC compressor connector S588 list \$57.61	1	40.71	40.71T
Parts	OR R134A Adaptor kit list \$28.80	1	21.99	21.99T
Parts	OR Weather strip 01042 - Seal between Radiator and Support and Condensor	2	12.99	25.98T
Parts	OR AC hose splicer - Reducer - to drop hose size from -8 to -6 to fit oe part of system 17406 list \$15.24	1	6.34	6.34T
Parts	AC fitting -6	1	8.57	8.57T
Parts	AC fitting -8	1	10.66	10.66T
6 AC Barrier	Galaxy 5/16 AC Barrier Hose 8mm Size 6	1.5	10.66	15.99T
8 AC Barrier	Galaxy 13/32 AC Barrier Hose 10 mm Size8	1.5	11.88	17.82T
ANTIFREEZE	Green Antifreeze per Gallon	2	24.99	49.98T
Freon	Freon per Pound	2.2	26.99	59.38T
UNDERDASH HVAC BOX OPERATION				

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
8/14/2023	JF6324

Name / Address

Vehicle Info
1984 GMC S15 1GTCS14B0E2527332 off white

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Parts	and researched the wiring diagram for the AC compressor power. Layed out and designed the wiring for the system. Installed the AC compressor control relay. Installed compressor clutch power supply connector. Ran wire back to the power supply. Ran power supply for condenser fan and ran the ground as well. Installed R134A ports and pulled vacuum on the system. Filled cooling system with coolant. Charged AC system with 2.2 lbs of refrigerant and tested system. The system blows cold air. Idle adjustments had to be made to make up for the AC compressor. The truck is built with an aggressive cam which is not suited for AC. At idle the truck will have a lopey idle but that is how the truck was built. The idle has been adjusted as high as is acceptable. AC blows cold. Trimmed the hood latch/core support member to clear the condenser fan. Painted the support member. Reinstalled the grille and light assembly. Test drove the truck. AC blows cold through the panel and the foot vents. HVAC controls will have to be looked at if AC is wanted only at the panel vents. AZ AC Compressor R4 58948 list \$360.05	1	288.99	288.99T

Subtotal	288.99
Sales Tax (7.0%)	20.23
Total	309.22
Payments/Credits	
Balance Due	309.22

JFrazar
Sports Car Services
3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Name / Address
Richard Gillson
161 Junco Way
Savannah, GA 31419-8800

Item	OR AC Condenser
Parts	OR Fan Assembly
Parts	OR Quick me ASS
Parts	AZ AC Hoseh Sy
Parts	AZ AC Clt MUK
Parts	OR A.C. Compress



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
8/14/2023	JF6324

Name / Address

Vehicle Info

1984 GMC S15
1GTCS14B0E2527332
off white

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Repair Labor	AC planning. Inspected the truck and determined an R4 compressor is the compressor to go with. Condenser and dryer are required. Line assembly is required and we will have to fabricate one line. Orifice tube and clutch switch will be required also. The radiator will have to be moved back to accommodate the new condenser.	0.5	132.00	66.00
Repair Labor	AIR CONDITIONING INSTALLATION Removed ac delete pulley and installed the new AC compressor. Test fit beautifully. Ready to proceed. Removed grill. Drained the coolant and removed the radiator. Test fitted the new condenser. Finished the fitment of the condenser and mounted it with hardware. Flushed evaporator with denatured alcohol. Installed the accumulator. Mounted and routed the AC compressor lines. Installed the orifice tube. Mounted condenser fan. Relocated and mounted the transmission cooler. Installed insulation on core support to protect the condenser. Fabricated a radiator spacer and mounted the radiator in its position. Fabricated an AC line that reduces down to fit the condenser. Connected wiring to AC pressure switch. With assistance from another technician Inspected	16.2	132.00	2,138.40

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due

ech	Tech 2
RAN	
Rate	Total
132.00	181.80
39.76	39.76T
18.39	18.39T
132.00	132.00

Date	Invoice #
8/14/2023	JF6324



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

JFrazzar Sports Car Serv
3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Name / Address
Richard GLisson
161 Junco Way
Savannah, GA 31419-8800

Date	Invoice #
8/14/2023	JF6324

Name / Address

Vehicle Info
1984 GMC S15 1GTCS14B0E2527332 off white

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Repair Labor	Tailgate latch diagnostic. With persuasion we were able to get the tail gate to open. The handle mechanism was not actuating the rods that go to the latches. Disassembled and determined that the handle assembly requires replacement. Part is ordered. Painted the tail gate handle. Two coats of satin black. Installed tail gate handle and adjusted the fitment. Tailgate opens every time.	1.4	132.00	184.80
Parts	AZ Tailgate Handle GM 77075 list \$40.43	1	39.76	39.76T
Parts	AZ Satin Black Spray Paint UP4901	1	18.39	18.39T
Repair Labor	STEERING COLUMN MODIFICATION Inspected steering column for key malfunction. The original gear selector collar was rotating down and engaging the ignition lock. This prevented the key from rotating to the off position. Rotated the collar up and ignition functions as designed. Removed steering column trim to inspect linkages and wiring in column. Secured the former gear selector collar in the proper position without interfering with any other systems in the column. Reinstalled the trim. Ignition functions as designed. AIR CONDITIONING INSPECTION AND DESIGN	1	132.00	132.00

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due

3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
8/14/2023	JF6324

Name / Address

[Redacted]

Vehicle Info

1984 GMC S15
IGTCS14B0E2527332
off white

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Cust Issue	Mileage in 34250 1. Install AC 2. Make sure steering column shift is secured 3. Tailgate handle malfunction 4. Check wiper function Compressor - R4 With Serp part # 58948 4s new Accumulator 33198 - Full Kit 10557SK Orifice Tube - 38904 Suction and discharge Line - 55863 Condenser OE 91 S10 7-4167 36674 Clutch Switch And Tailgate handle - All parts ordered TAILGATE DIAGNOSTIC AND REPAIR	1	0.00	0.00

	Subtotal
	Sales Tax (7.0%)
	Total
	Payments/Credits
	Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
2/23/2023	JF5903

Name / Address

Vehicle Info
1984 GMC S15 1GTCS14B0E2527332 off white

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
10W40	Total Classic 10W-40 Performance Engine Oil	5	8.50	42.50T
Shop Supplies	Shop Supplies	1	35.00	35.00
	LOCK CYLINDER AND POWER LOCK REPLACEMENT			
Repair Labor	Removed steering wheel to install new lock cylinder. Removed clock spring and blinker switch. Installed new ignition cylinder with key and reinstalled all removed. Replaced door lock cylinders in both doors. Pulled driver side door panel to inspect and diagnose the power lock malfunction. Was able to get it to lock. Working on getting it to unlock. One broken wire going to the switch. Needs two switches. Comanded the actuator to lock and unlock with test probe. Actuataor functions as designed. Once switches and wire are repaired system should function. Repaired damaged wire for power locks. Researched power lock switches and ordered proper switches. The switches did not come in the truck from GMC. They came out of a later model truck. Installed new switches and put door panels back on. Power locks function as designed.	5.9	132.00	778.80
Parts	AZ Power lock switch 901-004 list \$12.38	2	8.83	17.66T

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
11/12/2024	JF7920

Name / Address

Vehicle Info
1984 GMC S15 1GTCS14B0E2527332 off white

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Cust Issue	Mileage in 34389 1. belt squeal when ac on Compressor ordered 2. door pull on drivers door arm rest. Secure if possible Done	1	0.00	0.00
Repair Labor	3. drivers turn signal is malfunctioning BELT SQUEAL WITH AC ON DIAGNOSTIC Belt squeal. Inspected the belt drive with AC engaged. Everything is spinning appropriately except the AC compressor. With the engine off tried to spin the compressor by hand. It will not spin. AC Compressor is required. Evacuated the AC system. Removed and replaced the compressor. Recharged the system. Tested function. AC blow cold and no belt squeal.	4	0.00	0.00
Parts	AZ 4 Seasons AC Compressor 58948 list \$399.67 warranty	1	0.00	0.00T
Parts	Continental Serpentine belt 6PK-2370 DOOR PULL REPAIR	1	0.00	0.00T

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
11/12/2024	JF7920

Name / Address

Vehicle Info
1984 GMC S15 1GTCS14B0E2527332 off white

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Repair Labor	Removed the door panel and inspected door pull. Plastic base is cracked and coming apart. The proper repair would be replacement. Brian was able to reinstall and secure. Door pull is much better now. If it gets loose again, the arm rest will require replacement.	1	158.00	158.00
Shop Supplies	Shop Supplies TURN SIGNAL REPAIR	1	5.00	5.00
Repair Labor	Turn signal diag. Tested turn signal and found drivers rear not functioning. Removed and replaced bulb. Signal functions as designed.	0.3	158.00	47.40
Parts	Bulb	1	1.99	1.99
	COMPLETE TICKET			

Subtotal	\$212.39
Sales Tax (7.0%)	\$0.14
Total	\$212.53
Payments/Credits	\$0.00
Balance Due	\$212.53

Jirazar Sports Car Services

3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
9/24/2024	JF7797

Name / Address

Vehicle Info
1984 GMC S15 1GTCS14B0E2527332 off white

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Cust Issue	Mileage in 34284			
Repair Labor	1. Fluid leak. Transmission fluid TRANSMISSION LEAK DIAGNOSTIC AND REPAIR Brought truck in. Removed grille to gain access to transmission cooler. Inspected transmission cooler hose. Reconnected and secured. Filled trans with fluid and ran to make sure there aren't any leaks. None at this time. Belt is making noise. Belt is needed.	1	0.00	0.00
Parts	Transmission fluid quart BELT REPLACEMENT	4	12.99	51.96T
Repair Labor	Removed the bad serpentine belt. Had cleaned all of the pulleys due to rubber residue clogging them. Replaced the serpentine belt. Test drove. Vehicle shifted as designed and belt noise is gone.	0.8	146.00	116.80
Parts	OR Gates Micro V-Belt K060952 list \$101.68 VEHICLE WASH	1	47.15	47.15T
Sublet	Washed the exterior of the truck to get any teansmission fluid off of it.	1	50.00	50.00
	COMPLETE TICKET			
Subtotal				\$411.91
Sales Tax (7.0%)				\$6.94
Total				\$418.85
Payments/Credits				\$0.00
Balance Due				\$418.85

ce

#

.00

.00

.60T

.60

16

76

00

.76



Invoice

Date	Invoice #
4/3/2024	JF7257

Sale

Vehicle Info
1984 GMC S15 1GTCS14B0E2527332 off white

419-8800

P.O. No.	Tech	Tech 2
	John Jr.	

Description	Qty	Rate	Total
Speedo - Diag done - Needs cable SPEEDO	1	0.00	0.00
Inspected the car for the speedometer function. Ordered part. Installed the speedo cable.	2	146.00	292.00
AZ Speedometer Cable CA-3001	1	16.60	16.60
TOOK BACK TO WAREHOUSE - LISTED FORSALE			

Subtotal	\$308.60
Sales Tax (7.0%)	\$1.16
Total	\$309.76
Payments/Credits	\$0.00
Balance Due	\$309.76