









Independent Porsche Service and Repair  
Excellence since 1974

TRE AUTOMOTIVE - www.tremotorsports.com  
15854 Strathern St, Van Nuys, Ca 91406

Page 4

Invoice No. (818)909-9220  
250702003

Closed/Paid: 09/22/15 03:30 pm

Job15 Remove and reinstall driver seat Labor: 0.20 hrs @ \$125.00/hr = \$25.00

001 Fastening hardware-N 1.0 @ 5.00 =\$ 5.00 5.00  
Job Subtotal: \$30.00

Job16 seat repair Sublet: \$115.00  
Drive seat. Disassemble back for access. Remove stripped nut from inner frame and weld on new received nut. Reassemble

Payments to TRE Automotive


Status: Closed Work Order

Payments: \$12,862.74

1 07/13/15 10000.00 AMEX 176171  
2 09/22/15 2862.74 Cash db

Cost Summary

Labor 5862.50  
Parts 6384.85  
Sublet 1375.00  
Haz Waste 2.00  
Discount 586.25  
credit back -750.00  
Tax 574.64  
Total \$12862.74  
Payments 12862.74  
Bal Due 0.00



Thank you for choosing TRE Automotive

<p><b>ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE</b></p> <p>BAR # ARD00228518</p> <p>EPA # CAD982050866</p> <p>I acknowledge notice and oral approval of an increase in the original estimated price. X</p>		<p>CALIFORNIA</p> <p><b>ASC</b></p>	<p><b>ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE</b> <input type="checkbox"/> SAVE <input type="checkbox"/> DISCARD</p> <p><small>By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle here in described on streets, highways or elsewhere for the purpose of testing and/or inspection, if automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse at this/these pages (connected with this vehicle), I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains with the Repair Garage.</small></p> <p>CUST. SIG. X _____</p> <p>CUSTOMER ACKNOWLEDGEMENT</p>
---	--	-------------------------------------	--

READ IMPORTANT INFORMATION ON REVERSE SIDE



**TRE AUTOMOTIVE** - www.tremotorsports.com  
 15854 Strathern St, Van Nuys, Ca 91406

**Independent Porsche Service and Repair**  
 Excellence since 1974

Invoice No. **(818)909-9220**  
 250427007

Closed/Paid: 05/13/15 02:00 pm

**Job14 Paint wiper arms**  
 PLUGS FOR DOOR rear bumper-S

1.0 @ 15.00 =\$ 15.00 21.95  
**Job Subtotal: \$46.95**

**Recommendations:** Tires are old and beyond age service limit

Payments to TRE Automotive  
 Status: Closed Work Order

Payments: \$3,659.34  
 1 05/13/15 3659.34 AMEX 179877

Cost Summary	
Labor	1862.50
Parts	1364.07
Sublet	309.00
Haz Waste	1.00
Tax	122.77
<b>Total</b>	<b>\$3659.34</b>
Payments	3659.34
Bal Due	0.00

Thank you for choosing TRE Automotive



**ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE**  SAVE  DISCARD

BAR # ARD00228518 DEBIT CALIFORNIA

EPA # CAD982050866

I acknowledge notice and oral approval of an increase in the original estimated price. X

**ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE**

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle here in described on streets, highways or elsewhere for the purpose of testing and/or inspection, if automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse as true and correct. I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains with the Repair Garage.

CUST. SIG. X

CUSTOMER ACKNOWLEDGEMENT

**READ IMPORTANT INFORMATION ON REVERSE SIDE**



Independent Porsche Service and Repair  
Excellence since 1974

TRE AUTOMOTIVE - www.tremotorsports.com  
15854 Strathern St, Van Nuys, Ca 91406

Page 1

Invoice No. (818)909-9220  
250702003

78 Porsche 911 Silver  
ODO in:177818 out:177818  
Lic: 7KVE209/CA H6Cyl 3.0  
Vin: 9118201381  
Eq: AC FI  
Last in 7/31/2015

Closed/Printed: 08/23/15 03:30 pm

1 07/06/15 11:12am 1915.51  
Steven in person.

Engine repairs: The motor was popping like a bad exhaust leak  
Trace problem to broken head studs. Disassemble motor and estimate repairs

2 years/ unlimited mile warranty parts and labor all tasks that TRE performed

**Job01 Engine repairs**

Labor: 50.00 hrs@\$100.00/hr=\$5,000.00

Remove engine and gearbox from car. Disassemble to long block and inspect.  
multiple broken head studs ( a common problem with the type Porsche used on several  
models) . Remove pistons and and cylinders for access to head studs.  
Includes 8 hours labor to remove all head studs (broken or not) from the block.7/6/15

Install new head studs, reinstall pistons and cylinder, install heads, replacement  
camshafts, valve train hardware as listed. Replace injection holders and seals,  
install air pop off valve, install new clutch (worn and rusty). Install other new  
seals as listed while top end of motor is apart.

I-T3070	Intake valve 3.0-3.2-N	4.0 @	24.95 =\$	99.80
930 105 419 50	Exhaust valve 3.3-N	3.0 @	39.95 =\$	119.85
930 100 907 03	Head Set- 3.0-N	1.0 @	249.95 =\$	249.95
000 043 010 00	Loctite 574-N	1.0 @	44.98 =\$	44.98
FL-500	Metal/Plastic Cleaner-N	6.0 @	8.95 =\$	53.70
901 105 342 04	Rocker shaft-N	12.0 @	23.25 =\$	279.00
930 105 043 XX	Rocker arm REBUILT-R	12.0 @	65.00 =\$	780.00
VG 3036	Valve guide-N	12.0 @	5.95 =\$	71.40
001	Fastening hardware-N	20.0 @	5.00 =\$	100.00
911 105 222 05	Chain rail-Brown-N	1.0 @	8.95 =\$	8.95
911 105 222 06	Chain rail-Black-N	5.0 @	9.95 =\$	49.75
901 107 351 01	Oil return tube- solid-N	4.0 @	19.95 =\$	79.80
964 REGROUND	camshafts-S	1.0 @	650.00 =\$	650.00
FL-100	Brad Penn 20-50-N	11.0 @	7.35 =\$	80.85
999 034 005 00	Valve adjustment nut-N	12.0 @	1.99 =\$	23.88
901 105 370 02	Valve adjustment screw-N	12.0 @	29.95 =\$	359.40
930 107 347 03	Cam line-left Carrera-N	1.0 @	49.95 =\$	49.95
930 107 348 11	Cam line-right Carrera-N	1.0 @	59.95 =\$	59.95
911 613 571 01	Red Oil Switch-N	1.0 @	12.95 =\$	12.95

----->----->----->---Continued on the next page--->----->----->

**ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE** CALIFORNIA **ASC** **ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE**  SAVE  DISCARD

BAR # ARD00228518 DEBIT

EPA # CAD982050866

I acknowledge notice and oral approval of an increase in the original estimated price. X

CUST. SICK. X

CUSTOMER ACKNOWLEDGEMENT

**READ IMPORTANT INFORMATION ON REVERSE SIDE**





TRE AUTOMOTIVE - www.tremotorsports.com  
 15854 Strathern St, Van Nuys, Ca 91406

Invoice No. (818)909-9220  
 250707006

Payments to TRE Automotive  
 Status: Closed Work Order

Payments: \$7,463.83  
 1 07/28/15 4000.00 Cash db  
 2 08/26/15 2700.00 Cash db  
 3 09/22/15 763.83 Cash db

Independent Porsche Service and Repair  
 Independent Porsche Service and Repair  
 Excellence since 1974

Page 2

Closed/Paid: 09/22/15 03:24 pm

Cost Summary	
Labor	1000.00
Parts	6131.39
Sublet	400.00
Haz Waste	1.00
Discount	620.39
Tax	551.83
Total	\$7463.83
Payments	7463.83
Bal Due	0.00

Thank you for choosing TRE Automotive



ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

BAR # ARD00228518

EPA # CAD982050866

DEBIT



ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE  SAVE  DISCARD

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employee permission to operate the vehicle here in described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse at this/hese pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge/guarantee of this estimate customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains with the Repair Garage.

CUST. SIG. X

CUSTOMER ACKNOWLEDGEMENT

I acknowledge notice and oral approval of an increase in the original estimated price. X

READ IMPORTANT INFORMATION ON REVERSE SIDE





TRE AUTOMOTIVE - www.tremotorsports.com  
15854 Strathern St, Van Nuys, Ca 91406

Independent Porsche Service and Repair  
Excellence since 1974

Page 2

Invoice No. (818)909-9220  
250722005

Closed/Paid: 09/22/15 03:22 pm

**Job02 Suspension upgrade 911 rear**

B46 975	Bilstien sport rear-N	2.0 @	189.95 = \$	379.90
901 331 059 00	Trailing arm bushing-N	4.0 @	44.34 = \$	177.36
TREJ02	Rear tow hook-red-N	2.0 @	0.00 = \$	0.00
<b>Job Subtotal:</b>				<b>\$2,658.64</b>

Sublet: \$250.00

**Job03 4 wheel alignment**

Labor: 2.00 hrs@\$100.00/hr=\$200.00

**Job04 Corner balance**

Job Subtotal: \$200.00

**Job05 hoses**

Labor: 0.00 hrs@\$125.00/hr=\$0.00

parts only- replaced at time that gas tank was out and while engine was out

911 201 515 00	Connector hose-N	1.0 @	34.60 = \$	34.60
HS-109	Fuel line 9mm-N	1.0 @	3.95 = \$	3.95
911 611 209 00	Battery bracket-N	1.0 @	9.39 = \$	9.39
443 819 373 D	Heater hose-N	1.0 @	23.15 = \$	23.15
911 211 274 00	Heater hose-Small diam.-N	1.0 @	17.95 = \$	17.95
911 211 275 01	Reducer-N	2.0 @	35.41 = \$	70.82
<b>Job Subtotal:</b>				<b>\$159.86</b>

**Job06 Paint gas tank**

Labor: 0.50 hrs@\$125.00/hr=\$62.50

Clean gas tank , prep exterior and paint

001	paint/brushes-N	4.0 @	5.00 = \$	20.00	20.00
<b>Job Subtotal:</b>				<b>\$82.50</b>	

**Job07 Strip rear window tint**

Labor: 1.00 hrs @ \$125.00/hr= N/C

Note- back glass had large amount of adhesive on it, and glass was scratched at upper edge. Remove adhesive and tint

**Payments to TRE Automotive**

Status: Closed Work Order

Payments: \$6,473.43

1	09/04/15	2100.00	Cash	db
2	09/22/15	4373.43	Cash	db

**Cost Summary**

Labor	2462.50
Parts	3954.98
Sublet	250.00
Discount	550.00
Tax	355.95
<b>Total</b>	<b>\$6473.43</b>
Payments	6473.43
Bal Due	0.00

Thank you for choosing TRE Automotive

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE  SAVE  DISCARD

BAR # ARD00228518 DEBIT

EPA # CAD982050866

I acknowledge notice and oral approval of an increase in the original estimated price. X

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE  SAVE  DISCARD

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employee permission to operate the vehicle here in described on streets, highways or elsewhere for the purpose of testing and/or inspection, if automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse at this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge that this estimate customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains with the Repair Garage.

CUST. SIG. X \_\_\_\_\_

CUSTOMER ACKNOWLEDGEMENT

READ IMPORTANT INFORMATION ON REVERSE SIDE



TRE AUTOMOTIVE - www.tremotorsports.com  
 15854 Strathern St, Van Nuys, Ca 91406  
 (818)909-9220

Independent Porsche Service and Repair  
 Excellence since 1974

Page 1

Invoice No. 250722005


78 Porsche 911 Silver  
 ODO in:177818 out:177818  
 Lic: 7KVZ209/CA H6Cyl 3.0  
 Vin: 9118201381  
 Eq: AC FI  
 Last in 7/31/2015

Closed/Paid: 08/22/15 03:22 pm  
 Quotes  
 1 07/27/15 05:45pm 6536.04  
 Steven in person.

ESTIMATE 7/22/15 SUSPENSION UPGRADE

Job01 Suspension upgrade 911 front Labor: 12.00 hrs@\$100.00/hr=\$1,200.00  
 Change out torsion bars, front control arm bushings, install adjustable sway bar kit.  
 install new shock inserts

R36 5001	Bilstein insert/Bilsti-N	2.0 @	189.95 = \$	379.90
FSBA22	911 Front Swaybar Kit-N	1.0 @	475.00 = \$	475.00
903187	U-tab kit-N	1.0 @	26.98 = \$	26.98
MS-WR	Welding rod-N	1.0 @	5.00 = \$	5.00
MS-GAS	Argon gas-N	1.0 @	5.00 = \$	5.00
99-3014-340	Front a-arm bushings-N	1.0 @	99.95 = \$	99.95
911 341 049 01	Ball joint-N	2.0 @	99.95 = \$	199.90
911 341 119 06	Ball joint pin-N	2.0 @	24.69 = \$	49.38
901 341 426 00	Ball joint washer-N	2.0 @	8.64 = \$	17.28
901 341 425 00	Ball joint nut-N	2.0 @	17.51 = \$	35.02
SB8082S	Strut bar kit-N	2.0 @	275.00 = \$	275.00
900 038 002 01	Strut lock plate-N	1.0 @	2.91 = \$	5.82
TREB621	21MM hollow torsions-N	1.0 @	320.00 = \$	320.00
901 341 475 00	Torsion bar seal-N	2.0 @	6.15 = \$	12.30
SBRFADP1	nut plate adapter-S	1.0 @	30.00 = \$	30.00
930 TIE ROD	Update kit-S	1.0 @	179.95 = \$	179.95
				<b>Job Subtotal: \$3,316.48</b>



Job02 Suspension upgrade 911 rear Labor: 10.00 hrs@\$100.00/hr=\$1,000.00  
 Remove rear spring plates, torch off original rubber bushes, clean plates, inspect,  
 paint and reassemble with new parts as listed. Remove original rear bar mount, trim  
 as needed. Install wevo rear bar mounts, prep, and paint.. Install adjustable drop  
 links and adjustable rear sway bar

TREB729	29MM rear torsion bars-N	1.0 @	370.00 = \$	370.00
MS-EX	Epoxy cup-N	1.0 @	3.95 = \$	3.95
911 501 983 00W	Swaybar mount-WEVO-N	2.0 @	94.25 = \$	188.50
FL-800	Spray Paint-N	1.0 @	6.95 = \$	6.95
MS-WR	Welding rod-N	1.0 @	5.00 = \$	5.00
909976	Neatrix Rear Bushings-N	1.0 @	51.98 = \$	51.98
RSBA22	911 Rear Swaybar Kit-N	1.0 @	475.00 = \$	475.00

-----Continued on the next page----->>>

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

BAR # ARD00228518 DEBIT

EPA # CAD982050866

I acknowledge notice and oral approval of an increase in the original estimated price. X

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE  SAVE  DISCARD

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle here in described on a receipt, highway or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this form page (connected with this vehicle). I authorize service to be performed, including submit work, and acknowledge that the customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains with the Repair Garage.

CUSTOMER ACKNOWLEDGEMENT

CUST. SIG. X

READ IMPORTANT INFORMATION ON REVERSE SIDE

READ IMPORTANT INFORMATION ON REVERSE SIDE



TRE AUTOMOTIVE - www.tremotorsports.com  
15854 Strathern St, Van Nuys, Ca 91406

Invoice No. (818)909-9220  
250731004

Independent Porsche Service and Repair  
Excellence since 1974

Page 1

78 Porsche 911 Silver  
ODO in:177818 out:177818  
Lic: 7KVZ209/CA H6Cyl 3.0  
Vin: 9118201381  
Eq: AC FI  
Last in 7/31/2015

Closed/Paid: 09/20/19 11:55 am  
**Quotes**  
1 09/20/19 09:30am 375.63  
Steven in person.

Additional work

Job01 Install oil cooler fan and duct labor: 2.00 hrs @ \$125.00/hr = \$250.00  
with switch and relay// special discount price

911 613 113 00	Mirror switch L/R-N	1.0 @	12.99 = \$	12.99	
6" BLOWER	fan-S	1.0 @	65.00 = \$	65.00	
0 332 209 150	GP Relay-black-N	1.0 @	17.95 = \$	17.95	
001	Fastening hardware-N	2.0 @	5.00 = \$	10.00	
999 659 011 50	Rubber elect. cap-N	1.0 @	9.32 = \$	9.32	115.26
<b>Job Subtotal:</b>					<b>\$365.26</b>

Recommendations: \*Lube, Oil and Filter\* \*Tune-Up\* Front - 15/14 32  
PSI  
Rear - 46/14 36PSI

Payments to TRE Automotive  
Status: Closed Work Order

Payments: \$0.01  
1 09/20/19 0.01 Cash comp/pd cls out

Cost Summary

Labor	250.00
Parts	115.26
Discount	375.62
Tax	10.37
Total	\$0.01
Payments	0.01
Bal Due	0.00

Thank you for choosing TRE Automotive

<p>ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE</p> <p>BAR # ARD00228518 EPA # CAD982050866</p> <p>DEBIT   </p>		<p>CALIFORNIA </p> <p>ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE <input type="checkbox"/> SAVE <input type="checkbox"/> DISCARD</p> <p><small>By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle here in described on sheets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this site and the reverse at this time pages (connected with this sheet), I authorize service to be performed, including related work, and acknowledge that I, the estimate customer, have hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains with the Repair Garage.</small></p> <p>CUST. SIG. X _____</p> <p style="text-align: right;">CUSTOMER ACKNOWLEDGEMENT</p>
---	--	---

READ IMPORTANT INFORMATION ON REVERSE SIDE



TRE AUTOMOTIVE - www.tremotorsports.com  
15854 Strathern St, Van Nuys, Ca 91406

Invoice No. (818)909-9220  
251012003

78 Porsche 911 Silver  
ODO in:178551 out:178551  
Lic: 7KVZ209/CA H6Cyl 3.0  
Vin: 9118201381  
Eq: AC FI  
Last in 7/31/2015

Independent Porsche Service and Repair  
Excellence since 1974

Page 1

Closed/Revised: 11/10/15 01:50 pm  
1 10/12/15 11:54am 0.00  
Steven in person.

\*Please make sure it gets covered daily\*  
Give it a good once over, Make sure it is road ready for Targa Baja Event

- 1.) throttle sticks intermittently when hot  
cis adjust? throttle interface? or distributor?
- 2.) license plate light is out on one side
- 3.) tach illumination bulb is out on one of them
- 4.) race belt set and harness bar: purchase and install
- 5.) passengerside headlight ring is loose

Job01 Replace acc. pedal bushings Labor: 1.50 hrs@\$125.00/hr=\$187.50

901 423 253 00	Pedal bushing-Small-N	2.0 @	4.99 = \$	9.98	9.98
					Job Subtotal: \$197.48

Job02 Lic. plate light

911 631 620 04	Lic. Plate Light-N	1.0 @	21.65 = \$	21.65	21.65
					Job Subtotal: \$21.65

Job03 Repair tach illumination

Supply supplementary ground to tach light circuit.				Labor: 1.00 hrs@\$125.00/hr=\$125.00	Job Subtotal: \$125.00
--	--	--	--	--------------------------------------	------------------------

Job04 Install belts and guide

PC100 PRO CAM	5 point harness-S	2.0 @	245.00 = \$	490.00	
BK STAINLESS	guide bar-S	1.0 @	355.00 = \$	355.00	
SA01 HANRESS MOU	seat belt-S	2.0 @	54.20 = \$	108.40	
SA03 DOOR HARNES	mounts-S	2.0 @	53.20 = \$	106.40	
964 201 507 00	Washer reservoir cap-N	1.0 @	0.00 = \$	0.00	1059.80
					Job Subtotal: \$1,434.80

----->-----Continued on the next page----->----->----->----->

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

BAR # ARD00228518 DEBIT

EPA # CAD982050866

I acknowledge notice and oral approval of an increase in the original estimated price. X

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE  SAVE  DISCARD

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle here is described on screen, highway or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of these pages furnished with this work. I authorize service to be performed, including labor and material, including subject work, and acknowledge receipt of this estimate. Customer is hereby notified that the work properly is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains with the repair garage.

CUSTOMER ACKNOWLEDGEMENT  
CUST. SK. X

READ IMPORTANT INFORMATION ON REVERSE SIDE



**TRE AUTOMOTIVE** - [www.tremotorsports.com](http://www.tremotorsports.com)  
 15854 Strathern St, Van Nuys, Ca 91406  
 (818)909-9220

Invoice No. 251012003

Payments to TRE Automotive  
 Status: Closed Work Order

Payments: \$1,877.16  
 1 11/02/15 1877.16 Check 35842

Independent Porsche Service and Repair  
 Excellence since 1974

Page 2

Closed/Paid: 11/02/15 01:50 pm

Cost Summary	
Labor	687.50
Parts	1091.43
Tax	98.23
<b>Total</b>	<b>\$1877.16</b>
Payments	1877.16
Bal Due	0.00

Thank you for choosing TRE Automotive



ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

BAR # ARD00228518

EPA # CAD982050866

DEBIT



ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE  SAVE  DISCARD

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employee permission to operate the vehicle here in described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this form pages (connected with this vehicle). I authorize service to be performed, including sublet work and acknowledge receipt of this estimate customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains with the Repair Garage.

CUST. SIG. X

CUSTOMER ACKNOWLEDGEMENT

I acknowledge notice and oral approval of an increase in the original estimated price. X

READ IMPORTANT INFORMATION ON REVERSE SIDE





Independent Porsche Service and Repair  
Excellence since 1974

TRE AUTOMOTIVE - www.tremotorsports.com  
15854 Strathern St, Van Nuys, Ca 91406

Page 2

Invoice No. (818)909-9220  
251109007

Closed/Paid: 12/16/15 02:29 pm

**Job06 Wevo shifter installation**

shifter set up. Lubricate and adjust. Reassemble and road test

WEVO 915 C	915 shifter classic-N	1.0 @	595.00 =\$	595.00	595.00
					<b>Job Subtotal: \$970.00</b>

**Job07 Additional parts fuel injection Labor: 0.00 hrs@\$125.00/hr=\$0.00**

BOTH items had failed. Continuing to drive the car with the failed parts would have caused engine damage due to improper fuel mixture. We spent 8 hours or our time diagnosing, verifying that these parts were indeed faulty. Then installing the parts and making the needed adjustments This is a ONE time concession to you for the labor at no charge and a big discount on the parts

0 438 170 031	Accumulator- 81-83-N	1.0 @	249.95 =\$	249.95	
LF CIS F REBUILT	warm up regulator-S	1.0 @	350.00 =\$	350.00	599.95
					<b>Job Subtotal: \$599.95</b>


**Job08 Adjust window- passenger side Labor: 3.00 hrs @ \$125.00/hr= N/C**

**Job09 Wing net noise addressed Labor: 1.00 hrs@\$125.00/hr=\$125.00**

**Job Subtotal: \$125.00**

Payments to TRE Automotive  
Status: Closed Work Order

Payments: \$3,500.00  
1 12/16/15 3500.00 Check 35982



**Cost Summary**

Labor	1125.00
Parts	2173.85
Sublet	585.00
Discount	614.50
shipping	35.00
Tax	195.65
<b>Total</b>	<b>\$3500.00</b>
Payments	3500.00
Bal Due	0.00

Thank you for choosing TRE Automotive

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE  SAVE  DISCARD

BAR # ARD00228518

DEBIT



I acknowledge notice and oral approval of an increase in the original estimated price. X

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle here in described on streets, highways or elsewhere for the purpose of testing and/or inspection, if automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains with the Repair Garage.

CUST. SIG. X

CUSTOMER ACKNOWLEDGEMENT

READ IMPORTANT INFORMATION ON REVERSE SIDE