



Delta V Motorsports

1510 Webster Street
 Richmond, VA 23220
 (804) 355-4440
 service@deltavmotorsports.com
 https://deltavmotorsports.com

Invoice for RO #118491

Service Advisor: Glenn Burton
 Posted Date: 12/06/23 at 03:40 PM EST
 Client: Taylor Pace
 Vehicle: 1972 Volkswagen Transporter 211

	1972 Volkswagen Transporter 211 1.6L 4Cyl GAS AF Naturally Aspirated VIN: BH256195 License: N/A Color: N/A Odometer In: 791 / Out: 791	RO #118491 Time-In: 11/28/23 at 02:04 PM EST Save Parts: No
--	---	---

1 - Speedo is inop		TECH: W Booth
Labor:	Replace speedo cable and dust cap	\$274.43
Parts:	soc dust cap	1 \$20.56
	cof speedo cable	1 \$52.97
✓ Approved on 11/28/23 at 02:43 PM EST		Subtotal \$347.96 + est. Tax \$4.41 \$352.37

2 - Wipers were on, heard a sound and wipers stopped, fuel guage is inop, turn signals are blinking irradic		TECH: W Booth
Labor:	replaced 2 fuses and everything seems to be working correctly now.	\$91.48
Part:	LTL Fuse - Ceramic 8 AMP 5-pc Card - 8 Amp.	2 \$3.08
✓ Approved on 11/28/23 at 02:43 PM EST		Subtotal \$94.56 + est. Tax \$0.18 \$94.74

3 - spare tire is on vehicle, flat tire needs to be checked and fixed/replaced		TECH: W Booth
Labor:	removed inner tube from tire (tom valve stem) and replaced with valve stem and mounted and balanced-checked air in all 5 tires	\$92.48
✓ Approved on 11/28/23 at 02:43 PM EST		\$92.48

4 - check ragtop to see if it is connected to track correctly near front of vehicle.		TECH: W Booth
Labor:	adjusted bow for center section, may work, if not it will need to be replaced or sublet to interior shop	\$91.48
✓ Approved on 11/28/23 at 02:43 PM EST		\$91.48

5 - alternator light is not working		TECH: W Booth
Labor:	replace altemator	\$548.85
Parts:	bos altemator	1 \$360.79
	VW alt tin (3 piece)	1 \$28.79
	rpm alt pulley	1 \$66.34
✓ Approved on 12/06/23 at 03:39 PM EST		Subtotal \$1,042.26 + est. Tax \$27.36 \$1,069.62

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Warranty on parts and labor is **2 years or 24,000 miles**, whichever comes first.

Warranty **exclusions** including but not limited to:
 High performance or competitive driving, Customer Supplied Parts, performance parts, Tuned/modified vehicles, declined work in relation to repairs within same system (ie oil/coolant leaks)

Vintage vehicles: We try our best to provide the absolute highest quality replacement parts for vintage vehicles. Any failure of a new or used part for a vintage repair will not be covered under warranty unless it is an install error. _____



Delta V Motorsports
 1510 Webster Street
 Richmond, VA 23220
 (804) 355-4440
 service@deltavmotorsports.com
 https://deltavmotorsports.com

Invoice for RO #118262

Service Advisor: Glenn Burton
 Posted Date: 10/25/23 at 03:52 PM EDT
 Client: Taylor Pace

Vehicle: 1972 Volkswagen Transporter 211

T P	1972 Volkswagen Transporter 211 1.6L 4Cyl GAS AF Naturally Aspirated VIN: BH256195 License: N/A Color: N/A Odometer: INOP	RO #118262 Time-In: 10/02/23 at 02:13 PM EDT Save Parts: No
--------	--	---

Client concerns:

- Driver door will not open from outside
- Accelerator pedal is loose and sticking
- Rag top is off track, Check and advise
- Sliding driver window opens while driving. Check and advise

1 - Accelerator pedal is loose and acting up, check levers/pivots etc as it may not be assembled right or it's bent		TECH: K Roach	
			\$131.21
Labor:	check linkage at pedal-install pedal kit	1	\$49.22
Part:	mtmfg accel kit		
✓ Approved on 10/02/23 at 03:59 PM EDT		Subtotal \$180.43 + est. Tax \$2.95	\$183.38

2 - Rag top is off track, check and advise		TECH: K Roach	
			\$174.95
Labor:	Clean and re-grease rails and realign		
✓ Approved on 10/02/23 at 03:59 PM EDT			\$174.95

3 - drivers door won't open from outside		TECH: K Roach	
			\$87.48
Labor:	check linkage for door handle		\$349.90
	R&R Door handle	1	\$195.22
Part:	mtmfg Driver Exterior door handle		
✓ Approved on 10/02/23 at 03:59 PM EDT		Subtotal \$632.60 + est. Tax \$11.71	\$644.31

4 - can sliding window on drivers door be adjusted so that it doesnt open on its own when driving		TECH: K Roach	
			\$0.00
Labor:	check to see if window can be tightened up.	0	0
✓ Approved on 10/02/23 at 03:59 PM EDT			

5 - Front Brake pulls aggressively and uneven, Recommend to Inspect front braking system		TECH: K Roach	
Note: Found multiple issue with left front wheel. Both left front wheel cylinders are leaking Brake Fluid causing deterioration of brake shoes. This is causing the brake shoes to "Melt" and deteriorate rapidly. Recommend to R&R Front brakes and wheel cylinders.			
	determined that the lower left wheel cylinder is leaking, top also looks wet. Pads are wearing funny.		\$874.75
Labor:	Bleed brakes after the fact.	2	\$29.18
Parts:	nak wheel seal	2	\$236.04
	fte wheel cylinder	2	\$226.22
	fte wheel cylinder	1	\$78.42
	dynamic brake shoes		
✓ Approved on 10/16/23 at 10:56 AM EDT		Subtotal \$1,444.61 + est. Tax \$34.19	\$1,478.80

6 - After front brakes were replaced, found master cylinder leaking at boot (internal leak)		TECH: K Roach	
			\$150.00
Labor:	replace master cylinder and re-bleed	1	\$280.00
Part:	luk master cyl		
✓ Approved on 10/24/23 at 10:40 AM EDT		Subtotal \$430.00 + est. Tax \$16.80	\$446.80



Delta V Motorsports

1510 Webster Street
 Richmond, VA 23220
 (804) 355-4440
 service@deltavmotorsports.com
 https://deltavmotorsports.com

Invoice for RO #117987

Service Advisor: Glenn Burton
 Posted Date: 09/08/23 at 11:04 AM EDT

Client: Taylor Pace

Vehicle: 1972 Volkswagen Transporter 211

1972 Volkswagen Transporter 211 1.6L 4Cyl
 GAS AF Naturally Aspirated
 VIN: BH256195
 License: N/A
 Color: N/A
 Odometer In: 374 / Out: 374

RO #117987
 Time-In: 08/03/23 at 11:35 AM EDT
 Save Parts: No

1 - Rear is sagging on the drivers side.		TECH: W Booth	
✓ Approved on 08/03/23 at 11:43 AM EDT	0	0	

2 - DeltaV MPI		TECH: W Booth	
<p>Note: On first inspection, found there are no provisions for heat/defrost. Vehicle is missing tubes, routing for cables, heater boxes etc. Not sure if it would be possible to get heat/def which is a requirement for VA state safety inspection. The vehicle is sagging severely on the drivers side. Unsure if it was done incorrectly, if there is an issue previously overlooked or some other issue. For quoting purposes we propose new components and have attempted to elevate labor to make sure we cover worst case scenario (hopefully). Transmission is leaking badly at nose cone seal and gasket -see line for transmission. Overall, body in great shape (visibly, did not check with paint gauge for filler etc) Seems to run well, although unsure of configuration-never had a Brazilian bus in shop.</p>			
Labor:	multi-point inspection	0	\$0.00
✓ Approved on 08/03/23 at 11:43 AM EDT		0	

3 - transmission is leaking		TECH: W Booth	
<p>Note: Transmission is leaking badly from nose cone bushing/seal and gasket between main case and nosecone section.</p>			
Labor:	-TIME IS EST--replace seals-R&R transmission and replace external seals		\$2,799.20
Parts:	wed BUSHING(BRONZE)	1	\$24.34
	wed bushing	1	\$11.23
	pelican gasket	1	\$16.64
	FEB Gear Oil SAE 75W GL-4 1-Liter	4	\$104.08
	VW BLACK SEALANT	1	\$41.50
	crc grease	2	\$22.30
	bd gasket	2	\$24.58
	ww nut	1	\$26.25
	ww snap ring	2	\$8.44
	ww plug	2	\$52.50
✓ Approved on 08/23/23 at 08:58 AM EDT			Subtotal \$3,181.06 + est. Tax \$19.91
			\$3,200.97

4 - rebuild/reinstall/replace rear torsion		TECH: W Booth	
<p>Note: Left side is sagging very badly. Unsure until disassembly if torsion bar is damaged or simply installed incorrectly. Of the 4 bolts that are installed on the torsion bar to gear reduction boxes, a bolt popped out when we lifted vehicle for inspection of the shifter (new complaint) and we found bolt broken off in reduction box with either drill bit or extractor broken off in bolt where an attempt was made to remove the bolt at some point. All 4 bolts were marked with yellow paint as we might do to ensure bolt was torqued to spec. Especially after seeing this, we have to proceed with caution not knowing how any previous work was performed. We consider this vehicle unsafe at this time and if driven (customer advised against it), assume no liability in this issue. Proper repair would include disassembly of torque box to try and gain access to broken bolts and check all threads for that component. Machine shop may need to get involved.</p>			
Labor:	-TIME IS EST--R&R torsion bars and install new springs left and right-Included if doing the transmission at same time.		\$1,749.50
	Due to additional work, brake lines had to come off and system needed to be refilled and bled		\$174.95
Parts:	pel bushing	4	\$63.88
	WW TORSION BAR, Mid 1955-1967 BUS, WW	2	\$475.08
	crp seal kit	2	\$62.40
✓ Approved on 08/23/23 at 08:58 AM EDT			Subtotal \$2,525.81 + est. Tax \$36.08
			\$2,561.89

working correctly-4th is not a smooth shift or functional		TECH: W Booth
Checked and found shifter linkage bent. Straightened out lever/linkage and reinstalled. Bushing appears to be in useable shape. Road tested (short trip, see torsion line notes) to confirm shifter finds all 4 forward gears and reverse.		\$174.95
✓ Approved on 08/23/23 at 08:58 AM EDT		\$174.95

6 - top off trans fluid		TECH: W Booth
Labor:	Checked fluid level and topped off	\$43.74
✓ Approved on 08/23/23 at 08:58 AM EDT		\$43.74

7 - additional items found during R&R of engine		TECH: W Booth
Labor:	Distributor was loose and bracket could not be tightened down, replaced with used bracket	\$87.48
	Plug wires were not correct for cap and coil, swapped cap and coil wire with used replacements	\$174.95
	Drain plate was leaking, resealed and replaced oil	\$87.48
Parts:	LMO Motor Oil Classic 20W-50 HD 5L	1 \$85.69
	REI Oil Sump Gasket Set	1 \$11.83
✓ Approved on 09/08/23 at 09:18 AM EDT		Subtotal \$447.43 + est. Tax \$5.85 \$453.28

8 - repair left side inside reduction box bolt holes from previous damage		
Sublet:	drilled and installed threaded inserts	\$350.00
✓ Authorized on 09/08/23 at 09:18 AM EDT		Subtotal \$350.00 + est. Tax \$21.00 \$371.00

9 - machine work		
Sublet:	machine work to fix broken bolts in left side reduction	\$350.00
✓ Authorized on 09/08/23 at 09:18 AM EDT		Subtotal \$350.00 + est. Tax \$21.00 \$371.00

10 - shipping		
Sublet:	shipping	\$85.57
✓ Authorized on 09/08/23 at 09:18 AM EDT		Subtotal \$85.57 + est. Tax \$5.13 \$90.70

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Warranty on parts and labor is 2 years or 24,000 miles, whichever comes first.

Warranty **exclusions** including but not limited to:
 High performance or competitive driving, Customer Supplied Parts, performance parts, Tuned/modified vehicles, declined work in relation to repairs within same system (ie oil/coolant leaks)

Vintage vehicles: We try our best to provide the absolute highest quality replacement parts for vintage vehicles. Any failure of a new or used part for a vintage repair will not be covered under warranty unless it is an install error. _____



Delta V RVA
 1510 Webster Street
 Richmond, VA 23220
 (804) 355-4440
 service@deltavmotorsports.com
 https://deltavrva.com

Invoice for RO #119216

Service Advisor: Glenn Burton
 Posted Date: 06/20/24 at 11:39 AM EDT
 Client: Taylor Pace

Vehicle: 1972 Volkswagen Transporter 211

	1972 Volkswagen Transporter 211 1.6L 4Cyl GAS AF Naturally Aspirated VIN: BH256195 License: N/A Color: N/A Odometer In: 1281 / Out: 1281	RO #119216 Time-In: 05/16/24 at 11:43 AM EDT Save Parts: No
--	---	---

1 - Right front tire keeps loosing air, removed inner tube last visit	TECH: W Booth
Labor: R&R tire-sublet install inner tube	\$46.99
✓ Approved on 05/16/24 at 01:54 PM EDT	\$46.99

2 - brake lights are not working	TECH: W Booth
Labor: reattached wire	\$28.19
✓ Approved on 05/16/24 at 01:54 PM EDT	\$28.19

3 - replace all fluids	TECH: W Booth
Labor: all fluids have been replaced.	\$0.00
✓ Approved on 05/16/24 at 01:54 PM EDT	0 0

4 - parking brake is inop	TECH: W Booth
Labor: Modify spreader bar to make ebrakes work. Could not locate any part numbers that were different than what was installed. Unsure if there is a different part in the system causing issue or not but the brakes are working as they should	\$563.82
✓ Approved on 05/16/24 at 01:54 PM EDT	\$563.82

5 - Bus is cutting off after long drive on the highway	TECH: W Booth
Labor: cannot duplicate-top speed of this bus is 55-60 mph. If it is being driven faster than that on highway, it may be heating up too much and tuming off.	\$0.00
✓ Approved on 05/16/24 at 01:54 PM EDT	0 0

6 - Check for oil leak, dripping on floor of garage.	TECH: W Booth
Labor: leaking mildly from oil pump, main seal slight leak-small leaks are typical even after rebuild recommend holding off on the leaks we see for the time and watching oil level.	\$0.00
✓ Approved on 05/16/24 at 01:54 PM EDT	0 0

7 - install vent window lock	TECH: W Booth
Labor: roll pin was missing from lock, replace roll pin and reinstall	\$93.97
Part: stock roll pin	1 \$3.85
✓ Approved on 06/20/24 at 09:24 AM EDT	Subtotal \$97.82 + est. Tax \$0.23
	\$98.05