



Zakira's Garage
4480 Lake Forest Drive
Ste 314
Blue Ash, OH 45242
(513) 272-2229
ap@zakiras.com
<http://www.zakiras.com>

RO #26047

Service Advisor: Paul Theobold

Posted Date: 03/05/26 at 03:26 PM EST

Client: Bill Stittason

Vehicle: 1963 Chevrolet Biscayne Base

1963 Chevrolet Biscayne Base 6.7L 8Cyl GAS Naturally Aspirated
VIN: N/A
License: BIS KWIK
Color: Gold
Odometer In: 49026 / Out: 49027

RO # 26047

Client concerns:

- Vehicle to be transported to our shop via enclosed trailer
- General inspection to get vehicle ready for future auction
- Customer's goal is to have vehicle starting and in good operational condition.
- Customer states there is a potential radiator leak. Please check and verify.
- Customer states there is a possible passenger side exhaust leak. Please check and verify.

Inspection Rating Key:

😊 Checked & Okay ⚠ Requires Attention Soon ✖ Requires Immediate Attention — Not Applicable

Pre-Purchase Inspection (2 hours)		TECH: Mike Kruetzkamp
😊 ⚠ ✖ — Exterior		
✅ ☐ ☐ ☐ ☐ Dents or Scratches	Finding:	
✅ ☐ ☐ ☐ ☐ Rust Findings	Finding:	
☐ ☐ ☐ ☐ Paint Measurements	Finding:	
☐ ☒ ☐ ☐ Windshield and Glass	Finding: Forward channel of driver rear quarter window has come loose and fallen into quarter panel.	
✅ ☐ ☐ ☐ ☐ Front Lights	Finding:	
☐ ☒ ☐ ☐ Rear Lights	Finding: Reverse lights inoperable Vehicle was further inspected to determine cause of inoperable reverse lights. Findings were that the bracket, switch, and wiring on the transmission to activate the reverse lights are missing. It is unknown if the components are missing due to removal in the past, or just due to reverse lights not being a standard option until prior to this vehicle in 1966	
☐ ☐ ☐ ☒ Other	Finding:	
😊 ⚠ ✖ — Interior		
☐ ☒ ☐ ☐ Damages	Finding: Windlace cord around drivers door is torn. Floor liner is dry rotted and falling apart.	
☐ ☒ ☐ ☐ Radio/Head Unit Control	Finding: Speaker makes a crackle noise when radio is first turned on, but no radio stations are received	
✅ ☐ ☐ ☐ ☐ A/C and Heat	Finding:	

☒ ☐ ☐ ☐ Instrument Cluster Including Warning Lights	Finding:
☒ ☐ ☐ ☐ Door locks and Windows	Finding:
☐ ☐ ☐ ☒ Sunroof (if Applicable)	Finding:
☒ ☐ ☐ ☐ Lights	Finding:
☒ ☐ ☐ ☐ Seat Adjustment	Finding:
☐ ☐ ☐ ☒ Other	Finding:
☐ ☐ ☒ ☐ Visible Leaks	
☐ ☒ ☐ ☐ Engine Oil	Finding: Engine has several oil leaks that appear to be very light leaks over a long period of time. Such leaks appear to be from: fuel pump mounting surface, timing cover, and valve covers. Leaks will be cleaned to determine actual severity of them.
  	
☐ ☐ ☒ ☐ Transmission Fluid	Finding: Transmission has two large leaks at the rear on the tail shaft seal, and where the speedometer cable connects to the transmission. The center of the transmission has a coat of oil that will be cleaned to determine actual severity.
  	
☐ ☐ ☒ ☐ Coolant	Finding: Radiator has leaks at the bottom of the cooling cores. Intake manifold has coolant crystals from signs of previous leak below the thermostat. This area will be cleaned to determine if leak still exists.
  	

☐ ☐ ☐ ☒ Power Steering (if Applicable)	Finding:
☐ ☒ ☐ ☐ Differential/Transfer Case 	Finding: Differential has light leaks that appear to be from the pinion and the center section mating surface. Differential will be cleaned to determine actual severity.
☒ ☐ ☐ ☐ Hoses	Finding:
☐ ☒ ☐ ☐ Exhaust	Finding: No exhaust leak was found. Exhaust has a rattling sound from both mufflers most like due to rust or loose baffles in the mufflers.
☐ ☐ ☐ ☒ Other Leaks	Finding:
☐ ☐ ☒ ☐ Brakes and Tires	
☒ ☐ ☐ ☐ Driver Front Brakes	Finding:
☒ ☐ ☐ ☐ Passenger Front Brakes	Finding:
☐ ☐ ☒ ☐ Driver Rear Brakes   	Finding: Wheel cylinder is bad and severely leaking brake fluid. Drum, shoes, and hardware are all in good shape
☐ ☐ ☒ ☐ Passenger Rear Brakes 	Finding: Wheel cylinder has dried brake fluid residue behind dust boots and should be replaced. Drum, shoes, and hardware are all in good shape.

☐ ☒ ☐ ☐ Driver Front Tires	Finding: All tires have DOT codes indicating over 25 years of age. Tread is good, but there is signs of light dry rot on insides of tires
	
☐ ☒ ☐ ☐ Passenger Front Tires	Finding:
	
☐ ☒ ☐ ☐ Driver Rear Tires	Finding:
☐ ☒ ☐ ☐ Passenger Rear Tires	Finding:
☒ ☐ ☐ ☐ Brake Lines	Finding:
☐ ☐ ☒ ☐ Brake Fluid	Finding: Master cylinder fluid is very bad. Master cylinder needs replaced and entire brake system flushed
	
☐ ☐ ☐ ☒ Other	Finding:
☐ ☐ ☒ ☐ Driveability	
☒ ☐ ☐ ☐ Test Drive Findings	Finding:
☐ ☐ ☒ ☐ Suspension	
☒ ☐ ☐ ☐ Front Shocks/Struts	Finding:
☒ ☐ ☐ ☐ Rear Shocks/Struts	Finding:
☐ ☐ ☐ ☒ Front Axle	Finding:

☒ ☐ ☐ ☐ Rear Axle	Finding:
☒ ☐ ☐ ☐ Sway Bar Links	Finding:
☒ ☐ ☐ ☐ Control Arms	Finding:
☒ ☐ ☐ ☐ Tie rods	Finding:
☒ ☐ ☐ ☐ Wheel Bearings	Finding:
☐ ☐ ☒ ☐ Other	Finding: Carrier bearing on driveshaft is bad causing driveshaft to rattle on acceleration
	