

Hot Rod Hanks Customs Inc
 Hank Bogan
 20211 Jordan River Road
 Umatilla, FL 32784
 Shop 352-771-2238
 Fax 352-669-7450
 HotRodHank10@aol.com
 Registration: MV103045

Hot Rod Hanks Customs Inc.

"For All Your Auto Restoration Needs"

INVOICE

DATE:

TIME:

CUSTOMER INFORMATION			
NAME	[REDACTED]	YEAR/MAKE/MODEL	1957 Chevy Custom
ADDRESS	[REDACTED]	TAG	
CITY	[REDACTED]	VIN	
PHONE	[REDACTED]	Customer Complaint/Problem	From 01/28/26 to 02/02/26
FAX	[REDACTED]	MILEAGE IN	
		MILEAGE OUT	
		PROMISE DATE	02/03/26
		SAVE OLD PARTS (CORE MAY APPLY)	YES
			NO

****THIS CHARGE REPRESENTS COSTS AND PROFITS TO THE MOTOR VEHICLE REPAIR FACILITY FOR MISCELLANEOUS SHOP SUPPLIES OR WASTE DISPOSAL OF FLORIDA.**
*****FS403.718 MANDATES A \$1.00 FEE FOR EACH NEW TIRE SOLD IN THE STATE OF FLORIDA.**
******FS403.7185 MANDATES A \$1.50 FEE FOR EACH NEW OR REMANUFACTURED BATTERY SOLD IN THE STATE OF FLORIDA.**

ESTIMATE GOOD FOR 30 DAYS. NOT RESPONSIBLE FOR DAMAGE CAUSED BY THEFT, FIRE, OR ACTS OF NATURE. I HEREBY AUTHORIZE THE ABOVE REPAIRS, INCLUDING SUBLET WORK, ALONG WITH THE NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE MY VEHICLE FOR THE PURPOSE OF THE TESTING, INSPECTING, AND DELIVERY AT MY RISK. IF I CANCEL REPAIRS PRIOR TO THEIR COMPLETION FOR ANY REASON, A TEARDOWN AND REASSEMBLY FEE OF \$ _____ WILL BE APPLIED.

QTY	DESCRIPTION	PART NUMBER	DATE		AMOUNT
			PRICE	LABOR	
1	Remove old sway bar end links, and bar bushings, install all new including end link studs, spacers, upgraded from 5/16" studs to 3/8" studs.	Napa 106 oil filter			18.29
2	Tested sending unit in tank, was slow to only 2.2 ohms. Drain fuel from tank approx. 10 gallons, remove sending unit, to bench test, found several cracks in float, installed new float, re adjust float level, install unit, hook up fuel lines, gauge signal wire, put fuel in, sending unit reading properly.	6 gts 20w-50 VR1 racing oil			77.80
3	Remove leaking speed sensor from transmission, soaked heat insulation, find a rigged end cap, threaded a new proper cap with internal rubber seal, reinstall, add new heat insulation on wires, secure to transmission, pull side and check fluid level, and good.	QA1 DS6 coil over shocks, top studs			580.05
4	Remove oil filter, drain oil, install new filter, oil.	1OUT sending unit tank float			9.49
5	Remove both leaking rear coil over shocks, and disassemble, rebuild with new shocks, spanner nuts, stem adapters, set pre load to original ride height, reinstall, rear wheels back on, and torqued all 4 wheels to 80 ft lbs	1 ft vel heat sleeve			12.49
		speed sensor retaining cap			3.49
		Total parts			701.61
		Total labor	115.00 per hr	18 hrs	2,070.00

A STORAGE FEE OF \$ _____ PER DAY MAY BE APPLIED TO VEHICLES WHICH ARE NOT CLAIMED WITHIN 3 WORKING DAYS NOTIFICATION OF COMPLETION.

**SHOP SUPPLIES	
**FEES	
SUBTOTAL	2,771.61
TAX(7%)	194.01
TOTAL	2,965.62
INTENDED METHOD OF PAYMENT	

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN: I UNDERSTAND THAT, UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE IF MY FINAL BILL WILL EXCEED \$100.
 _____ I REQUEST A WRITTEN ESTIMATE.