




 **ENTHUSIAST AUTO GROUP**

BMW SALES, SERVICE & RESTORATION

www.EABMW.com

INFORMATION - HISTORY - SERVICE RECORDS - RECEIPTS



Enthusiast Auto Group, LLC
Service Invoice 10923

Enthusiast Auto Group, LLC
17000 Highway 101
Crestwood, CA 95224
415-255-1200

DATE: 12/17/87
TIME: 10:00 AM
MILEAGE: 10,000

Customer Name: [REDACTED]
Address: [REDACTED]
City: [REDACTED]
State: [REDACTED]
Zip: [REDACTED]

Vehicle Description: [REDACTED]

Work Done:
- Oil, filter and fluid change
- Wash and wax
- Tire rotation
- Brake inspection
- Air filter change
- Spark plug inspection
- Fluid level check
- Battery test
- Safety inspection
- Wash and wax
- Tire rotation
- Brake inspection
- Air filter change
- Spark plug inspection
- Fluid level check
- Battery test
- Safety inspection

Final EAG Dealer's Presentation
Full tank of Shell 85 motor oil
Personalized service tags included on passenger seat
EAG welcome package included in passenger seat

Enthusiast Auto Group, LLC
17000 Highway 101
Crestwood, CA 95224
415-255-1200

DATE: 12/17/87
TIME: 10:00 AM
MILEAGE: 10,000

Customer Name: [REDACTED]
Address: [REDACTED]
City: [REDACTED]
State: [REDACTED]
Zip: [REDACTED]

Vehicle Description: [REDACTED]

Work Done:
- Oil, filter and fluid change
- Wash and wax
- Tire rotation
- Brake inspection
- Air filter change
- Spark plug inspection
- Fluid level check
- Battery test
- Safety inspection
- Wash and wax
- Tire rotation
- Brake inspection
- Air filter change
- Spark plug inspection
- Fluid level check
- Battery test
- Safety inspection

Enthusiast Auto Group, LLC
17000 Highway 101
Crestwood, CA 95224
415-255-1200

DATE: 12/17/87
TIME: 10:00 AM
MILEAGE: 10,000

Customer Name: [REDACTED]
Address: [REDACTED]
City: [REDACTED]
State: [REDACTED]
Zip: [REDACTED]

Vehicle Description: [REDACTED]

Work Done:
- Oil, filter and fluid change
- Wash and wax
- Tire rotation
- Brake inspection
- Air filter change
- Spark plug inspection
- Fluid level check
- Battery test
- Safety inspection
- Wash and wax
- Tire rotation
- Brake inspection
- Air filter change
- Spark plug inspection
- Fluid level check
- Battery test
- Safety inspection

CERTIFICATE OF ORIGIN FOR A VEHICLE

5106

DATE: DEC. 17, 1987 INVOICE NO. 24291

VEHICLE IDENTIFICATION NO. WBSTC9300J2791654 YEAR 1988 MAKE BMW

BODY TYPE 4DRSDN SHIPPING WEIGHT 3420

H.P. (S.A.E.) 256 G.V.W.R. 4390 NO. CYLS. 6 SERIES OR MODEL M5

I, the undersigned authorized representative of the company, firm or corporation named below, hereby certify that the new vehicle described above is the property of the said company, firm or corporation and is transferred on the above date and under the invoice Number indicated to the following distributor or dealer.

NAME OF DISTRIBUTOR, DEALER, ETC.
NIELLO BMW
2020 FULTON AVENUE
SACRAMENTO, CALIFORNIA 95825

It is further certified that this was the first transfer of such new motor vehicle in ordinary trade and commerce.

BMW OF NORTH AMERICA, INC.

BY: *Charles T. [Signature]*
(SIGNATURE OF AUTHORIZED REPRESENTATIVE)
MONTVALE, NEW JERSEY 07645
CITY - STATE

000604637

ODOMETER DISCLOSURE STATEMENT

Federal law (and State law, if applicable) requires that you state the mileage upon transfer of ownership. Failure to complete or providing a false statement may result in fines and/or imprisonment.

I, GRAND PRIX MOTORS, INC state that the odometer now reads 1079 (no tenths) miles and to the best of my knowledge that it reflects the actual mileage of the vehicle described below, unless one of the following statements is checked.

- (1) I hereby certify that to the best of my knowledge the odometer reading reflects the amount of mileage in excess of its mechanical limits.
 (2) I hereby certify that the odometer reading is NOT the actual mileage.
WARNING — ODOMETER DISCREPANCY.

MAKE BMW BODY TYPE 4 DOOR
 MODEL M5
 VEHICLE IDENTIFICATION NUMBER WBSDC9300J2791654
 YEAR 1988
 TRANSFEROR'S NAME GRAND PRIX MOTORS, INC
 TRANSFEROR'S ADDRESS [REDACTED]
 TRANSFEROR'S NAME [REDACTED]
 DATE OF STATEMENT 08/22/91
 TRANSFEREE'S NAME [REDACTED]
 TRANSFEREE'S ADDRESS [REDACTED]
 CITY CHICAGO, ILL (STATE) ILL (ZIP CODE) 60610
 TRANSFEREE'S NAME [REDACTED]

FORM NB-65-SCP (3-89) 2 PART
 NB-65-SCP (3-89) 3 PART
 NORCOK OKLAHOMA CITY, OK • KINGS MTN, N.C. • LAS VEGAS, NV • CHICAGO, IL

STAPLE HERE

Type or print in BLACK INK

TITLE AND REGISTRATION APPLICATION



Arizona Department of Transportation
 Motor Vehicle Division

When validated, this is your registration and must be carried in your vehicle at all times.

Check the type of application:

- Title and Registration Title only Registration only Duplicate Dismantle Salvage

48-0905 R06/97
 Plate Number 138BNX Tab Number T000000 Vehicle ID Number WBSDC9300J2791654 Make BMW Body Style 4DR Year 1988
 Mh / Yr First Reg. FEB1988 Model M5 List Price 046500 GVW/GCW 000000 Fuel G Odometer Reading * 0009193 Actual B C Mobile Hm L/W

1 Name [REDACTED]
 2 [REDACTED]
 3 Mailing Address TUCSON AZ 85750 REGISTRATION EXPIRES LAST DAY OF JAN 1999
 4 City / State / Zip Code

Residence Address Of Owner Or Lessee (If Different From Mailing) _____ City / State / Zip Code _____
 Lienholder Name: NONE Amount: _____ Date: _____
 Lienholder Name: _____ Amount: _____ Date: _____
 Lienholder Name: _____ Amount: _____ Date: _____
 Mailing Address: _____
 Mobile Home Manufacturer _____ Mobile Home Physical Location _____

The vehicle was acquired: New Used Date Acquired _____
 Acquired from: Name _____ City / State _____
 Yes No Is the vehicle specially constructed or reconstructed?
 Yes No Will the vehicle be rented without a driver?
 I do not want my name and address released for commercial mailing lists.
 Service Options * _____

I certify that the information above is true and correct, and that the vehicle is free from liens, except those indicated above. I acknowledge that the odometer reading above is qualified by the seller and that it is not the responsibility of the Motor Vehicle Division to determine the accuracy of the odometer statement. I understand that vehicles registered for use in, or used to commute into, the Phoenix or Tucson metropolitan areas may be subject to emission testing.
ALL Owners Must Sign Here

I do hereby state that we hold this property as joint tenants and furthermore empower and authorize each other as attorney in fact to assign the certificate of title by his or her signature above and thereby transfer, sell, mortgage or otherwise encumber the vehicle in the same manner as though all joint owners had acted and signed.
Owners With "OR" Legal Status Must Also Sign Here

Batch / Date / County / Branch 0320 01291998 0043 01 Cat / Status REGULAR Canceled Plate Number / State / Agent [] [] 2
 New Title Number 1129980290010 New Film Reference Number 80290J2010 Type OTHER
 Prior Title Number R0544013 State IL Prior Film Reference Number ORIGINAL MVD Organization Number _____

FEES	
VL	213.74
REG	37.25
CRF	
WCT	
MCF	
EIF	
ADF	1.00
SPL	
TRN	
LOP	
UTX	
DOR	
SNO	
PST	
PEN	
TTL	4.00
TOTAL	233.46

* See Reverse Side
 CUSTOMER

Vehicle Inspection Report



**Arizona Department of Environmental Quality
Vehicle Inspection Program**

1763070

- This test was conducted in accordance with the Federal Short Test Procedure in 207B. If your vehicle failed, it may be covered by the manufacturer's warranty (see supplemental brochure for more information).
- Vehicle registrations expire on the last day of the registration month. You will not have to pay a late registration fee provided: Your vehicle failed the first test prior to registration expiration, is repaired, retested and passed, and the registration renewal is postmarked within 30 days of the first test.
- The Arizona Vehicle Emissions Inspection Program is administered by the Arizona Department of Environmental Quality. Inspection services provided, under contract, by Gordon-Duffy, Inc.

THE FINAL RESULT OF THIS INSPECTION IS:

COMPLIANCE BASIC

LICENSE PLATE	VEHICLE IDENTIFICATION NUMBER	MODEL YEAR/MAKE	STYLE	ODOMETER	FUEL	CYL	STD CLASS
DS JAN	WBSDC9300J2791654	88 BMW	SD	009	G	06	4
STATION/LANE	INSPECTOR(S)	DATE	TIME	TEST TYPE	INSPECTION NUMBER	REPRINT	FEE
PO1 4	4185 4147	01/29/98	14:21	INITIAL	P014A138	NO	\$8.05

EQUIPMENT OR PRESSURE & PURGE INSPECTION RESULTS

SYSTEM	RESULT	SYSTEM	RESULT
AIR SYSTEM	N/A	GAS CAP TEST	PASS
CATALYTIC CONVERTER	PASS		

EMISSIONS INSPECTION RESULTS

LOADED TEST POLLUTANT	LOADED READING	LOADED STANDARD	LOADED RESULT	IDLE READING	IDLE STANDARD	IDLE RESULT
HYDROCARBONS (HC) IN PPM	5	220	PASS	3	220	PASS
CARBON MONOXIDE (CO) IN %	0.00	1.20	PASS	0.00	1.20	PASS

THIS IS AN INITIAL INSPECTION OF THIS VEHICLE. THIS VEHICLE HAS PASSED THE EQUIPMENT INSPECTION AND THE EMISSIONS TEST. CONGRATULATIONS! THANK YOU FOR HELPING CLEAN OUR AIR. USE THE TEAR-OUT SECTION BELOW FOR REGISTERING YOUR VEHICLE. KEEP THE UPPER PORTION OF THIS VIA UNTIL YOU RECEIVE YOUR NEW REGISTRATION. IT IS YOUR PROOF OF COMPLIANCE WITH VIP REQUIREMENTS!

TEAR HERE

PO Box 2100
Phoenix AZ 85001

This is only a notice that the vehicle has been sold. To transfer Certificate of Title and give it to the new owner.

Buyer / Lessor Name
Buyer / Lessor Address
Date Sold Seller / Lessee Signature



Questions? Call: 800-264-7748

The Arizona Department of Environmental Quality shall preserve, protect and enhance the environment and public health and shall be a leader in the development of public policy to maintain and improve the quality of Arizona's air, land and water resources.

JAN 1998



OIL REPORT

LAB NUMBER: M08519 UNIT ID: 2791694
REPORT DATE: 3/9/2020 CLIENT ID: 55232
CODE: 201/10 PAYMENT: Bulk CC

MAKE/MODEL: BMW 3.5L (S38B35) OIL TYPE & GRADE: Gasoline Engine Oil
FUEL TYPE: Gasoline (Unleaded) OIL USE INTERVAL: Miles
ADDITIONAL INFO: 1988 M5

CLIENT: ENTHUSIAST AUTO GROUP PHONE: [REDACTED]
11608 READING RD FAX: [REDACTED]
SHARONVILLE, OH 45241 ALT PHONE:
EMAIL: trevor@eabmw.com

COMMENTS: TREVOR: Sitting doesn't generally do much harm to the oil-sharing components since modern engines are pretty well sealed up due to emissions requirements. The metals are certainly low enough to show no obvious mechanical problems at this point. Universal averages show typical wear levels for this type of engine after about 2,900 miles on the oil. The viscosity is in the 20W/50 range and the trace of fuel is harmless. The air and oil filters kept silicon and insolubles low. Check back in 2,000-3000 miles as long as the engine is running well.

MIHR on Oil	MIHR on Unit	Sample Date	UNIVERSAL AVERAGES
	9.460	2/27/2020	
Make Up Oil Added	0 qts		
ELEMENTS IN PARTS PER MILLION	UNIVERSAL AVERAGES	UNIVERSAL AVERAGES	UNIVERSAL AVERAGES
ALUMINUM	1	1	4
CHROMIUM	0	0	1
IRON	6	6	11
COPPER	4	4	5
LEAD	4	4	5
TIN	1	1	1
MOLYBDENUM	0	0	93
NICKEL	0	0	0
MANGANESE	0	0	0
SILVER	1	1	1
TITANIUM	0	0	0
POTASSIUM	0	0	3
BORON	16	16	2
SILICON	4	4	78
SODIUM	193	193	5
CALCIUM	931	931	29
MAGNESIUM	262	262	2120
PHOSPHORUS	875	875	222
ZINC	988	988	975
BARIUM	0	0	1134

Values Should Be*

PROPERTIES	VALUES	VALUES SHOULD BE*
SUS Viscosity @ 210°F	90.4	
cSt Viscosity @ 100°C	18.08	
Flashpoint in °F	375	>375
Fuel %	TR	<2.0
Antifreeze %	0.0	0.0
Water %	0.0	0.0
Insolubles %	0.1	<0.6
TBN		
TAN		
ISO Code		

* THIS COLUMN APPLIES ONLY TO THE CURRENT SAMPLE

416 E. PETTIT AVE. FORT WAYNE, IN 46806 (260) 744-2380 www.blackstone-labs.com

©COPYRIGHT BLACKSTONE LABORATORIES 2020

LIABILITY LIMITED TO COST OF ANALYSIS

FOR VALUE RECEIVED, I THE UNDERSIGNED, TRANSFER THE VEHICLE DESCRIBED ON THE FACE OF THIS CERTIFICATE TO

NAME OF PURCHASER(S) Grand Prix Motors Inc.
 ADDRESS 4035 East 22nd Street Tucson, Arizona 95711

AND CERTIFY TO THE BEST OF MY KNOWLEDGE, INFORMATION AND BELIEF UNDER PENALTY OF LAW THAT THE VEHICLE IS NEW AND HAS NOT BEEN REGISTERED IN THIS OR ANY STATE AND AT THE TIME OF DELIVERY THE VEHICLE WAS SUBJECT TO THE FOLLOWING SECURITY INTERESTS AND NONE OTHER AND WARRANT TITLE TO THE VEHICLE.

FEDERAL REGULATIONS REQUIRE YOU TO STATE THE ODOMETER MILEAGE UPON TRANSFER OF OWNERSHIP

I certify to the best of my knowledge that the odometer reading is 1079 and reflects the actual mileage of the vehicle unless one of the following statements is checked 1. The amount of mileage stated is in excess of \$9,999 or 2. The odometer reading is not the actual mileage

AMOUNT OF LIEN NONE DATE OF LIEN _____ KIND OF LIEN _____ IN FAVOR OF _____

LEASER'S NAME _____ BY _____ AUTHORIZED SIGNATURE OF DEALER _____ TITLE OR POSITION _____
 DEALER'S NAME Grand Prix Motors Inc. DEALER'S LICENSE NO. _____ BY _____ AUTHORIZED SIGNATURE OF DEALER _____ TITLE OR POSITION _____
 State of Arizona Being duly sworn upon oath and subscribed and sworn to before me on this _____ day of _____ 1993 My Commission Expires Dec. 26, 1993
 County of Pima My Commission Expires Dec. 26, 1993

USE NOTARIZATION ONLY IF REQUIRED BY TITLING JURISDICTION

FOR VALUE RECEIVED, I THE UNDERSIGNED, TRANSFER THE VEHICLE DESCRIBED ON THE FACE OF THIS CERTIFICATE TO

NAME OF PURCHASER(S) FRANK MIMMS
 ADDRESS 177 EDGEWOOD, HIGHLAND PARK, IL 60035

AND CERTIFY TO THE BEST OF MY KNOWLEDGE, INFORMATION AND BELIEF UNDER PENALTY OF LAW THAT THE VEHICLE IS NEW AND HAS NOT BEEN REGISTERED IN THIS OR ANY STATE AND AT THE TIME OF DELIVERY THE VEHICLE WAS SUBJECT TO THE FOLLOWING SECURITY INTERESTS AND NONE OTHER AND WARRANT TITLE TO THE VEHICLE.

FEDERAL REGULATIONS REQUIRE YOU TO STATE THE ODOMETER MILEAGE UPON TRANSFER OF OWNERSHIP

I certify to the best of my knowledge that the odometer reading is 1079 and reflects the actual mileage of the vehicle unless one of the following statements is checked 1. The amount of mileage stated is in excess of \$9,999 or 2. The odometer reading is not the actual mileage

AMOUNT OF LIEN NONE DATE OF LIEN _____ KIND OF LIEN _____ IN FAVOR OF _____

LEASER'S NAME _____ BY _____ AUTHORIZED SIGNATURE OF DEALER _____ TITLE OR POSITION _____
 DEALER'S NAME GRAND PRIX MOTORS, INC. DEALER'S LICENSE NO. _____ BY _____ AUTHORIZED SIGNATURE OF DEALER _____ TITLE OR POSITION _____
 State of ARIZONA Being duly sworn upon oath and subscribed and sworn to before me on this _____ day of _____ 1993 My Commission Expires Dec. 26, 1993
 County of PIMA My Commission Expires Dec. 26, 1993

USE NOTARIZATION ONLY IF REQUIRED BY TITLING JURISDICTION

FOR VALUE RECEIVED, I THE UNDERSIGNED, TRANSFER THE VEHICLE DESCRIBED ON THE FACE OF THIS CERTIFICATE TO

NAME OF PURCHASER(S) _____
 ADDRESS _____

AND CERTIFY TO THE BEST OF MY KNOWLEDGE, INFORMATION AND BELIEF UNDER PENALTY OF LAW THAT THE VEHICLE IS NEW AND HAS NOT BEEN REGISTERED IN THIS OR ANY STATE AND AT THE TIME OF DELIVERY THE VEHICLE WAS SUBJECT TO THE FOLLOWING SECURITY INTERESTS AND NONE OTHER AND WARRANT TITLE TO THE VEHICLE.


FEDERAL REGULATIONS REQUIRE YOU TO STATE THE ODOMETER MILEAGE UPON TRANSFER OF OWNERSHIP

I certify to the best of my knowledge that the odometer reading is _____ and reflects the actual mileage of the vehicle unless one of the following statements is checked 1. The amount of mileage stated is in excess of \$9,999 or 2. The odometer reading is not the actual mileage


AMOUNT OF LIEN _____ DATE OF LIEN _____ KIND OF LIEN _____ IN FAVOR OF _____

LEASER'S NAME _____ BY _____ AUTHORIZED SIGNATURE OF DEALER _____ TITLE OR POSITION _____
 DEALER'S NAME _____ DEALER'S LICENSE NO. _____ BY _____ AUTHORIZED SIGNATURE OF DEALER _____ TITLE OR POSITION _____
 State of _____ Being duly sworn upon oath and subscribed and sworn to before me on this _____ day of _____ 1993 My Commission Expires _____
 County of _____ My Commission Expires _____


USE NOTARIZATION ONLY IF REQUIRED BY TITLING JURISDICTION



Stillwell Grand Prix Motors, Inc.



4836 East 22nd Street
Tucson, Arizona 85711
(602) 748-1333
Facsimile
(602) 790-8349



RETAIL BUYERS ORDER

DATE 09/22/91 DATE REQ. _____

CUSTOMER NUMBER _____ FROM SOURCE _____
 CUSTOMER NAME _____
 ADDRESS _____
 ZIP CODE: 1847 EDGEWOOD HIGHLAND PARK, ILL 60035 OCCUPATION _____
 PHONE NUMBER _____
 EMPLOYER _____
 I/we offer to purchase from company on the terms and conditions specified on the face & on the reverse hereof through the agency of GRAND PRIX MOTORS, INC., 4836 E. 22nd St., TUCSON (Dealer) the vehicle & options described hereunder ("Vehicle") and from Dealer the accessories listed hereunder ("Accessories").

MODEL: M5 B5 COLOUR BODY: SCHWARTZ
 TYPE: 4 DOOR ROOF: _____ GVW _____ LB _____
 ENGINE: WBSDC9300J2791654 TRANSMISSION: 5 SPEED MANUAL TRIM: NATUR
 FILL IN GW FOR COMMERCIAL VEHICLES ONLY

TERMS OF SETTLEMENT		<input type="checkbox"/> SOLD UNIT STOCK NO.	<input type="checkbox"/> SALESMAN'S NUMBER	OFFICE USE
MAKE OR TRADE-IN:	BASIC SALE PRICE:		30390.00	
MODEL:	FACTORY FITTED OPTIONS:			
COLOUR:				
ENGINE NO.:				
<input type="checkbox"/> STOCK NO.	<input type="checkbox"/> CASH VALUE			
<input type="checkbox"/> REG. D. NO.	<input type="checkbox"/> A			
<input type="checkbox"/> MILEAGE				
TRADE-IN ALLOWANCE	HANDLING FEES:			
LESS PAYOUT TO:	SUB TOTAL		70700.00	70700.00
A/C NUMBER:	ACCESSORIES TO BE PURCHASED FROM DEALER:			
EQUITY IN TRADE	4 Seat Vents.			
CUSTOMER NUMBER	2 Sheep Skins			
DEPOSIT # 41281	3 Floor Mats			
REC. NO.:	4 Car Cover MS + SESS. including			
C.O.D. # 41302	TOTAL ACCESSORIES		3200.00	3200.00
CASH TOTAL	SUB TOTAL		34990.00	
FINANCE COMPANY:	TAX		2127.00	
TYPE TERM MTHS.	DOCUMENTARY FEE		80.00	
COMP. INS. CCJ	LICENSE TRANSFER			
FINANCE TOTAL	TITLE REGISTRATION			
SUB TOTAL	TOTAL		38297.00	
	NET OPTION TRANSFERS:			
	COMPANY CLAIM:			
	S/FEES:			
	TOTAL (17 + 19 + 23 + 25 + 27)			

Enthusiast Auto Group, LLC

Service Invoice 16952

Name	EAG E28, EAG E28	Company	Address 2	Created	03/02/20	Year	1988
Address	11608 Reading Rd			Invoiced	9:18 AM	Make	BMW
	Cincinnati, Oh 45241	Hat#		Advisor	01/16/24	Model	M5
Home	513.554.1269	V.I.N. #	2791654	Division	Service	Lic#	
Work		DOM		PO#	AR	Fleet#	Black
Fax				Checked By		Body	Miles In
				Page#	1 of 10	Miles Out	9,481

Job Description	Line Total
Comprehensive Enthusiast Auto Group Inspection	620.00
Labor	620.00
Parts	0.00
Sublets	0.00

All recommended work has been completed by EAG

Vehicle Notes:

Garage-Find of the Decade! This 1988 BMW M5 has been stored in a climate controlled garage in Tucson, Arizona since new with it's original and only owner since new. It was decommissioned from driving use in the mid-1990's with supporting documentation when the owner relocated to Europe. This M5 has not been started since, nor was the vehicle accessed while the owner was abroad for well over two decades. EAG recommends a comprehensive recommissioning and full baseline reset.

Full Vehicle Scan Results:

-No warnings are currently present

Measurement Results:

Front brakes 13mm life remaining
 Rear brakes 10mm life remaining
 Front tires are original to vehicle - Recommend new wheels and tires with preservation of originals
 Rear tires are original to vehicle - Recommend new wheels and tires with preservation of originals

Technician's Findings:

- Recommend EAG 10 year E28 M5 S38 inspection service
- Recommend S38 valve adjustment service
- Distributor seals are starting to seep - Recommend replacement
- Engine accessory drive belts are starting to crack - Recommend replacement
- Engine water pump is starting to seep - Recommend proactive water pump and thermostat replacement
- Drive shaft flex disk is showing signs of age - Recommend replacement with proactive shift selector seal replacement
- Fuel pump is inop - Recommend replacement

YOU MUST INITIAL AND SIGN BEFORE WORK WILL BE PERFORMED. In accordance with Ohio law we are required to provide an estimate for repairs over \$25.00.
 I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above to secure the amount of repairs thereto. EAG will not be held responsible for loss or damage to vehicle what so ever. ENTHUSIAST AUTO GROUP, LLC 11608 READING RD CINCINNATI OH 45241 513-554-1269

Invoice Total	
Labor	\$12,041.80
Parts	\$11,951.04
Sublets	\$85.00
Supplies	\$25.00
Subtotal	\$24,082.84
Tax	\$1,878.46
Total	\$25,961.30

Enthusiast Auto Group, LLC

Service Invoice 16952

Name	EAG E28, EAG E28	Company		Created	03/02/20	Year	1988
Address	11608 Reading Rd	Address 2		Time	9:18 AM	Make	BMW
	Cincinnati, OH 45241			Invoiced	01/16/24	Model	M5
Home	513.554.1269	Hint		Advisor	AR	Lot#	
Work		V/I/N #	2791654	PO#		Fleet#	
Fax		DOM		Checked By		Body	Black
				Pages	2 of 10	Miles In	9,461
						Miles Out	9,461

Job Description

- Power steering cooler hose is starting to seep - Recommend replacement
- Front strut bump stops are starting to deteriorate - Recommend replacement
- Front thrust rod bushings are starting to crack - Recommend replacement
- Rear pitman arm boots are starting to split - Recommend replacement
- Recommend brake caliper rebuild on all four corners
- Vehicle battery is outdated - Recommend replacement

EAG Preparation For Engine Start

Line Total	290.00
Labor	290.00
Parts	0.00
Sublets	0.00

1. Visual Inspection:

- Check for any signs of fluid leaks or loose connections
- Ensure all belts and hoses are properly connected and in good condition.

2. Fuel System:

- Drain current fuel and inspect entire fuel system
- Fill fuel tank with 5 gallons of Shell 93 octane fuel
- Prime the fuel system
- Ensure the fuel pump is functioning properly

3. Lubrication:

- Drain and refill engine oil and check level to ensure it is at the recommended reading.
- Remove valve cover gasket and inspect camshafts and all valvetrain components
- Check and adjust valve lash
- Ensure proper lubrication in cam carrier and valvetrain
- Borescope all engine cylinders to ensure no abnormalities
- Verify that the oil filter is properly installed and tightened.

4. Cooling System:

- Drain and flush cooling system and refill with new Genuine BMW coolant
- Ensure all radiator hoses and connections are secure and leak-free.
- Verify that the radiator fan is functioning properly.

YOU MUST INITIAL AND SIGN BEFORE WORK WILL BE PERFORMED. In accordance with Ohio law we are required to provide an estimate for repairs over \$25.00.

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above to secure the amount of repairs thereto. EAG will not be held responsible for loss or damage to vehicle what so ever. ENTHUSIAST AUTO GROUP, LLC 11608 READING RD CINCINNATI OH 45241 513-554-1269

Invoice Total	
Labor	\$12,041.80
Parts	\$11,951.04
Sublets	\$65.00
Supplies	\$25.00
Subtotal	\$24,082.84
Tax	\$1,878.46
Total	\$25,961.30

Enthusiast Auto Group, LLC

Service Invoice 16952

Name	EAG E28, EAG E28	Company		Created	03/02/20	Year	1988
Address	11608 Reading Rd	Address 2		Time	9:18 AM	Make	BMW
	Cincinnati, OH 45241			Invoiced	01/16/24	Model	M5
Home	513.554.1269	Hint		Advisor	AR	Lot#	
Work		V/I/N #	2791654	PO#		Fleet#	
Fax		DOM		Checked By		Body	Black
				Pages	3 of 10	Miles In	9,461
						Miles Out	9,461

Job Description

5. Ignition System:

- Ensure the ignition switch is in the off position.
- Check that all ignition components, such as spark plugs and wires, are properly installed and connected. Replace spark plugs with new OEM spark plugs

6. Pre-Start Preparation:

- Disable the ignition system by disconnecting the coil wire or disabling the fuel pump.
- Crank engine by hand to ensure all parts are moving freely and seamlessly
- Crank engine over mechanically to prime all systems

7. Start-Up Procedure:

- Turn the ignition key to the start position while simultaneously monitoring the engine
- Observe the oil pressure gauge or warning light to ensure oil pressure is established.
- Listen for any unusual noises or vibrations.

8. Initial Operation:

- Allow the engine to warm up gradually, avoiding high RPMs or heavy loads.
- Monitor the engine temperature gauge to ensure it stays within the normal operating range.
- Check for any fluid leaks, unusual smells, or warning lights.

9. Post-Startup Inspection:

- Recheck all fluid levels (oil, coolant, etc.) after the engine has run for a few minutes.
- Inspect the engine compartment for any signs of leaks, loose connections, or abnormal conditions.

YOU MUST INITIAL AND SIGN BEFORE WORK WILL BE PERFORMED. In accordance with Ohio law we are required to provide an estimate for repairs over \$25.00.

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above to secure the amount of repairs thereto. EAG will not be held responsible for loss or damage to vehicle what so ever. ENTHUSIAST AUTO GROUP, LLC 11608 READING RD CINCINNATI OH 45241 513-554-1269

Invoice Total	
Labor	\$12,041.80
Parts	\$11,951.04
Sublets	\$65.00
Supplies	\$25.00
Subtotal	\$24,082.84
Tax	\$1,878.46
Total	\$25,961.30

Enthusiast Auto Group, LLC

Service Invoice 16952

Name	EAG E28, EAG E28	Company Address 2	Created Time	03/02/20	Year	1988
Address	11606 Reading Rd		Invoice Time	9:18 AM	Model	BMW M5
	Cincinnati, OH 45241		Service Division	01/16/24	Lot#	
Home Work Fax	513.554.1269	Half# V.I.N.# DOM	PO#	AR	Fleet#	
		2781654	Checked By		Body	Black
			Page#	4 of 10	Miles In	9,461
					Miles Out	9,461

Job Description

Comprehensive 10-Year E28 M5 S38 Inspection	Line Total	812.82
	Labor	400.00
	Parts	412.82
	Sublets	0.00

- Engine Oil and Filter Change
- Check Wiper Blades / Inserts
- Check Level and Condition of All Fluids
- Check and Set Tire Pressures
- Replace Engine Air Filter
- Replace Fuel Filter
- Replace Spark Plugs
- Cooling System Flush
- Brake System Fluid Flush
- Power Steering Fluid Flush
- Transmission Fluid Flush
- Differential Fluid Flush

Part Number	Description	QTY	Each	Total
07 15 9 863 355	Crush Seal 22x27 AL	2	0.77	1.54
11 42 9 863 138	Oil Filter DMX1	1	17.47	17.47
12 12 9 861 802*	Spark Plug RSCD 7409	6	11.53	69.18
13 32 1 270 038	Fuel Filter E30 KLR	1	64.31	64.31
13 72 1 307 134	Air Filter E28	1	66.14	66.14
7W140	Synthetic Gear Oil -XJ	2	16.95	33.90
AMS 19W40	Synthetic Oil	7	11.76	82.25
ATF - FLUID	Power Steering Fluid	1	4.11	4.11
BRAKE FLUID	Brake Fluid	1	12.00	12.00
COOLANT	BMW Coolant	1	24.98	24.98
MTL REFLINE OIL	MTL Oil	2	18.47	36.94

S38 Valve Adjust Service	Line Total	416.77
	Labor	310.00
	Parts	106.77
	Sublets	0.00

- Remove valve cover and adjust all valves as needed
- Replace surrounding gasket and spark plug tube gaskets
- Replace rear cam cover gasket
- Degrease any effected area
- Replace any hardware needed during the service

Part Number	Description	QTY	Each	Total
11 12 1 202 729	Camset Oil Head Rear	1	2.21	2.21
11 12 1 312 172	VC Gasket S38	1	63.31	63.31
11 12 1 312 173	Spark Plug Seals 014/038	3	13.75	41.25

Replace Distributor Seals	Line Total	297.76
	Labor	248.00
	Parts	49.76
	Sublets	0.00

- Replace distributor shaft seal
- Replace distributor cam O-rings
- Replace any hardware needed during service
- Degrease affected area

Part Number	Description	QTY	Each	Total
11 14 1 271 415	Camshaft Seal	1	36.35	36.35
12 11 1 262 267	Cam O-Ring 014 S38	2	6.79	13.40

YOU MUST INITIAL AND SIGN BEFORE WORK WILL BE PERFORMED. In accordance with Ohio law we are required to provide an estimate for repairs over \$25.00.

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above to secure the amount of repairs thereto. EAG will not be held responsible for loss or damage to vehicle what so ever. ENTHUSIAST AUTO GROUP, LLC 11606 READING RD CINCINNATI OH 45241 513-554-1269

Invoice Total	
Labor	\$12,041.80
Parts	\$11,951.04
Sublets	\$65.00
Supplies	\$25.00
Subtotal	\$24,082.84
Tax	\$1,878.46
Total	\$25,961.30

Enthusiast Auto Group, LLC

Service Invoice 16952

Name	EAG E28, EAG E28	Company Address 2	Created Time	03/02/20	Year	1988
Address	11606 Reading Rd		Invoice Time	9:18 AM	Model	BMW M5
	Cincinnati, OH 45241		Service Division	01/16/24	Lot#	
Home Work Fax	513.554.1269	Half# V.I.N.# DOM	PO#	AR	Fleet#	
		2791654	Checked By		Body	Black
			Page#	5 of 10	Miles In	9,481
					Miles Out	9,451

Job Description

Replace Engine Drive Belts	Line Total	179.85
	Labor	125.00
	Parts	54.85
	Sublets	0.00

- Replace crankshaft drive belt
- Replace alternator drive belt
- Replace A/C compressor drive belt

Part Number	Description	QTY	Each	Total
11 22 1 708 788	Alternator Belt 13x1540	1	20.47	20.47
32 42 1 708 750	Fan Belt 10x368	1	20.96	20.96
64 62 1 711 056	AC belt	1	13.90	13.90

Replace Cooling System Waterpump	Line Total	591.98
	Labor	248.00
	Parts	343.98
	Sublets	0.00

- Replace engine water pump
- Replace any gaskets needed during services
- Replace any hardware needed during services

Note:

- Coolant flush performed during 10 year inspection service

Part Number	Description	QTY	Each	Total
07 11 9 906 322	Thermostat O-Ring	1	2.41	2.41
11 51 1 265 654	Water Pump Gasket	1	3.22	3.22
11 51 1 312 539	Water Pump	1	303.16	303.16
11 53 1 306 828	Thermostat Hose	1	9.39	9.39
11 53 1 306 829	7-Hose	1	26.80	26.80

Replace Driveshaft Flex Disc and Selector Seal	Line Total	654.47
	Labor	465.00
	Parts	189.47
	Sublets	0.00

- Replace rubber driveshaft flex disc
- Replace transmission shift shaft selector seal
- Replace hardware needed during service
- Degrease effected area

Part Number	Description	QTY	Each	Total
23 12 1 282 394	Selector Seal	1	22.92	22.92
26 11 7 511 454	Driveshaft Flex Disk	1	166.55	166.55

Rejuvenate Fuel System	Line Total	3014.66
	Labor	558.00
	Parts	2456.66
	Sublets	0.00

- Replace fuel tank
- Replace fuel pump assemblies
- Replace fuel sending unit
- Replace any hardware and gaskets needed during services

Part Number	Description	QTY	Each	Total
13 53 1 722 040	Fuel Press Regulator	1	136.85	136.85

YOU MUST INITIAL AND SIGN BEFORE WORK WILL BE PERFORMED. In accordance with Ohio law we are required to provide an estimate for repairs over \$25.00.

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above to secure the amount of repairs thereto. EAG will not be held responsible for loss or damage to vehicle what so ever. ENTHUSIAST AUTO GROUP, LLC 11606 READING RD CINCINNATI OH 45241 513-554-1269

Invoice Total	
Labor	\$12,041.80
Parts	\$11,951.04
Sublets	\$65.00
Supplies	\$25.00
Subtotal	\$24,082.84
Tax	\$1,878.46
Total	\$25,961.30

Enthusiast Auto Group, LLC

Service Invoice 16952

Name	EAG E28, EAG E28	Company	03/02/20	Year	1988
Address	11606 Reading Rd	Address 2	9:18 AM	Make	BMW
	Cincinnati, OH 45241		01/16/24	Model	M5
Home	513.554.1269	City	Service	License	
Work		State	AR	Fleet#	
Fax		Zip	2791654	Body	Black
			Checked By	Miles In	9,461
			Page#	Miles Out	9,461

Job Description

Part Number	Description	QTY	Each	Total
13 53 1 726 960	Hose	1	974.54	974.54
16 11 1 176 519	Metal Fuel Tank	1	35.96	35.96
16 11 9 780 564	Filter Cap	1	7.83	7.83
16 12 1 116 966	Fuel Pump O-Ring	1	261.84	261.84
16 12 1 153 050	Fuel level sender	1	441.08	441.08
16 14 1 176 232	Fuel Pump E30 M3	1	540.34	540.34
16 14 1 178 425	Fuel Pump	1	16.00	16.00
44K FUEL INJECTION	EFI Cleaner	2	32.00	64.00

Replace Power Steering Cooler Hose	Line Total	197.96
	Labor	148.80
	Parts	49.16
	Sublets	0.00

- Replace power steering cooler line
- Replace all hose clamps needed during service
- Replace all sealing crush washers needed during service
- Refill hydraulic system

Part Number	Description	QTY	Each	Total
32 41 1 093 597	Crush Ring 10X22, Alum	2	1.89	3.78
32 41 1 131 524	PS Hose Line	1	45.38	45.38

Replace Both Front Strut Bump Stops	Line Total	438.08
	Labor	372.00
	Parts	66.08
	Sublets	0.00

- Replace front strut bump stops
- Replace any hardware needed during service

Part Number	Description	QTY	Each	Total
31 33 1 124 449	Bump Stop	2	24.50	49.00
31 33 1 134 314	Dust Cover	2	8.54	17.08

Replace Front Thrust Arms	Line Total	746.12
	Labor	223.20
	Parts	524.92
	Sublets	0.00

- Replace both front thrust arms
- Replace both front thrust arm bushings
- Replace any hardware needed during service
- Perform 4 wheel alignment

Part Number	Description	QTY	Each	Total
31 12 1 132 241	Thrust Arm	1	102.81	102.81
31 12 1 132 342	Thrust Arm	1	259.59	259.59
31 12 9 058 819	Thrust Rod Bushing Set	1	102.82	102.82

Replace Rear Pitman Arms	Line Total	400.76
	Labor	124.00
	Parts	276.76
	Sublets	0.00

- Replace both rear pitman arms
- Install new self-locking hardware

Part Number	Description	QTY	Each	Total
33 32 1 123 585	Rear Subframe Pitman	2	136.38	272.76

YOU MUST INITIAL AND SIGN BEFORE WORK WILL BE PERFORMED. In accordance with Ohio law we are required to provide an estimate for repairs over \$25.00.

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above to secure the amount of repairs thereto. EAG will not be held responsible for loss or damage to vehicle what so ever. ENTHUSIAST AUTO GROUP, LLC 11606 READING RD CINCINNATI OH 45241 513-554-1269

Invoice Total	
Labor	\$12,041.80
Parts	\$11,951.04
Sublets	\$65.00
Supplies	\$25.00
Subtotal	\$24,082.84
Tax	\$1,876.46
Total	\$25,961.30

Enthusiast Auto Group, LLC

Service Invoice 16952

Name	EAG E28, EAG E28	Company	03/02/20	Year	1988
Address	11606 Reading Rd	Address 2	9:18 AM	Make	BMW
	Cincinnati, OH 45241		01/16/24	Model	M5
Home	513.554.1269	City	Service	License	
Work		State	AR	Fleet#	
Fax		Zip	2791654	Body	Black
			Checked By	Miles In	9,461
			Page#	Miles Out	9,461

Job Description

Suspension Refresh	Line Total	3273.40
	Labor	1016.80
	Parts	2256.60
	Sublets	0.00

- Left rear shock is seeping hydraulic fluid
- Both front struts are not functioning correctly
- Recommend full suspension refresh including:

- Install new rear shock absorbers
- Install new pressure accumulators
- Install new hydraulic lines from shock absorbers
- Bleed system and confirm full function
- Replace both front strut inserts

Note:

- Alignment performed in conjunction with other suspension services

Part Number	Description	QTY	Each	Total
31 31 1 133 517	Front strut insert	2	240.40	480.80
31 32 1 117 376	Cover Ring	2	16.62	33.24
37 12 2 225 774	Left Shock Absorber	1	339.34	339.34
37 12 2 225 775	Right Shock Absorber	1	339.34	339.34
37 21 1 124 595	Pressure Accumulator	2	387.08	774.16
37 22 1 120 825	Left Pressure Hose	1	183.03	183.03
37 22 1 120 826	Right Pressure Hose	1	106.69	106.69

Perform Full (4) Wheel Caliper Rebuild

- Remove all (4) calipers and disassemble
- Replace all rubber seals and hardware
- Replace all rear rubber brake lines
- Replace brake master cylinder

Part Number	Description	QTY	Each	Total
34 11 1 137 038	Caliper Bushing Kit	2	43.07	86.14
34 11 1 158 692	Caliper Kit	2	37.87	75.74
34 21 1 155 270	Master Cylinder	1	450.48	450.48
34 32 1 159 878	Rear Brake Hose	2	48.50	97.00
34 32 1 159 881	Brake Hose Rear	2	49.81	99.62
801 351 529 10	Caliper Half Seals	8	4.62	36.96

Install Four New Genuine BMW Wheels

- Install four new Genuine BMW wheels
- Install four new Genuine BMW center caps

Part Number	Description	QTY	Each	Total
56 11 2 225 518	BMW Wheel	4	481.37	1925.48

YOU MUST INITIAL AND SIGN BEFORE WORK WILL BE PERFORMED. In accordance with Ohio law we are required to provide an estimate for repairs over \$25.00.

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above to secure the amount of repairs thereto. EAG will not be held responsible for loss or damage to vehicle what so ever. ENTHUSIAST AUTO GROUP, LLC 11606 READING RD CINCINNATI OH 45241 513-554-1269

Invoice Total	
Labor	\$12,041.80
Parts	\$11,951.04
Sublets	\$65.00
Supplies	\$25.00
Subtotal	\$24,082.84
Tax	\$1,878.46
Total	\$25,961.30

Enthusiast Auto Group, LLC

Service Invoice 16952

Name	EAG E28, EAG E28	Company	03/02/20	Year	1988
Address	11608 Reading Rd	Address 2	9:18 AM	Make	BMW
Home	Cincinnati, OH 45241	Hat#	01/16/24	Model	M5
Work	613.554.1269	V.I.N. #	Service	Leit	
Fax		DOM	AR	Fleet#	
			PO#	Body	Black
			Checked By	Miles In	9,461
			Page#	Miles Out	9,461

Job Description					
38 13 2 225 378	Hub Cap Cover	4	120.83	482.52	

Mount And Road-Force Balance Four New Michelin Pilot Exalto P#2 Tires					
	Line Total			876.16	
	Labor			100.00	
	Parts			776.16	
	Sublets			0.00	

- Mount and road force balance new Michelin tires on all four corners
- Replace any hardware needed during service
- Test drive to ensure smooth and quiet ride quality

Tire Sizing:

Front and Rear: 225/50/16

Part Number	Description	QTY	Each	Total
225/50/16EXALTO	Michelin Pilot Exalto	4	193.79	775.16

Replace Vehicle Battery					
	Line Total			261.95	
	Labor			62.00	
	Parts			199.95	
	Sublets			0.00	

Part Number	Description	QTY	Each	Total
MTP H8	Battery	1	199.95	199.95

EAG Extra Mile Services					
	Line Total			1886.37	
	Labor			992.00	
	Parts			894.37	
	Sublets			0.00	

- Brake and clutch pedal pads have minor cosmetic blemish - Recommend replacement
- Cigarette lighter has minor cosmetic blemish - Recommend replacement
- Interior seat belt buckles are faded - Recommend replacement
- Front seat back //M badges are faded - Recommend replacement
- Exterior C pillar "sail panel" clips are damaged - Recommend replacement
- Front bumper turn signal lenses have minor cosmetic blemish - Recommend replacement
- Mid exhaust hangers are starting to seep - Recommend replacement
- Mirror adjustment switch is inop - Repair
- Drivers side headrest is inop - Recommend repair
- Radio antenna is inop - Recommend repair
- Radio volume knob has static when adjusting volume - Recommend cleaning and lubrication
- Door latch bump stops are missing - Recommend replacement
- Front fender liners are cracked - Recommend replacement

YOU MUST INITIAL AND SIGN BEFORE WORK WILL BE PERFORMED. In accordance with Ohio law we are required to provide an estimate for repairs over \$25.00.

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing inspection or delivery at my risk. An express mechanics lien is acknowledged on above to secure the amount of repairs thereto. EAG will not be held responsible for loss or damage to vehicle what so ever. ENTHUSIAST AUTO GROUP, LLC 11608 READING RD CINCINNATI OH 45241 613-554-1269

Invoice Total	
Labor	\$12,041.80
Parts	\$11,951.04
Sublets	\$65.00
Supplies	\$25.00
Subtotal	\$24,082.84
Tax	\$1,878.46
Total	\$25,961.30

Enthusiast Auto Group, LLC

Service Invoice 16952

Name	EAG E28, EAG E28	Company	03/02/20	Year	1988
Address	11608 Reading Rd	Address 2	9:18 AM	Make	BMW
Home	Cincinnati, OH 45241	Hat#	01/16/24	Model	M5
Work	613.554.1269	V.I.N. #	Service	Leit	
Fax		DOM	AR	Fleet#	
			PO#	Body	Black
			Checked By	Miles In	9,461
			Page#	Miles Out	9,461

Job Description					
-Trunk cargo net is missing - Recommend replacement					

Part Number	Description	QTY	Each	Total
18 21 1 105 635	Muffler Hanger Rear	2	10.43	20.86
38 21 1 108 634	Rubber Pedal Pad	2	5.47	10.94
51 13 1 870 459	Insert	8	4.58	36.64
51 13 1 885 399	Clamp	2	0.58	1.16
51 14 1 892 899	Clips	2	2.28	4.52
51 21 1 809 735	Bump Stop	4	1.77	7.08
51 23 1 927 129	Hood Shock	2	56.17	112.34
51 71 1 874 901	Driver Fender Liner	1	85.01	85.01
51 71 1 874 602	Passenger Fender Liner	1	92.70	92.70
52 10 1 927 000	M seat badge	2	15.81	31.62
81 34 1 387 689	Lighter	1	38.98	38.98
83 13 1 386 611	Turn Signal Cover	2	27.25	54.50
72 11 1 941 553	Rear Seat Belt	1	99.40	99.40
72 11 1 945 981	E28 Buckle	1	102.28	102.28
72 11 1 945 992	E28 Buckle	1	102.28	102.28
72 80 1 951 991	Trunk Net	1	94.10	94.10

EAG Premier Multi-Step Paint Correction + Preservation With Arteshine Nanographene Coating					
	Line Total			4995.00	
	Labor			4995.00	
	Parts			0.00	
	Sublets			0.00	

Exterior Services:

- Thoroughly wash and decontaminate all exterior panels
- Perform multi-stage paint correction process to restore and enhance the paint finish
- Apply multiple layers of Arteshine Nanographene coating on all exterior surfaces including:
 - Glass
 - Paint
 - Trim
 - Wheels
- Allow at least 24 hours for the ceramic coating to cure and provide maximum durability and hydrophobic properties
- Restore and protect plastic trims and moldings
- Polish and restore headlights and taillights for improved clarity and appearance
- Treat and protect exterior rubber seals and gaskets
- Remove and touch up any paint chips or scratches

Supplemental Spa Services:

- Clean and degrease the engine compartment for a pristine appearance
- Clean and decontaminate exhaust tips for a polished look
- Clean and treat tires for a deep black finish and protection

YOU MUST INITIAL AND SIGN BEFORE WORK WILL BE PERFORMED. In accordance with Ohio law we are required to provide an estimate for repairs over \$25.00.

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing inspection or delivery at my risk. An express mechanics lien is acknowledged on above to secure the amount of repairs thereto. EAG will not be held responsible for loss or damage to vehicle what so ever. ENTHUSIAST AUTO GROUP, LLC 11608 READING RD CINCINNATI OH 45241 613-554-1269

Invoice Total	
Labor	\$12,041.80
Parts	\$11,951.04
Sublets	\$65.00
Supplies	\$25.00
Subtotal	\$24,082.84
Tax	\$1,878.46
Total	\$25,961.30

Enthusiast Auto Group, LLC

Name: EAG E28, EAG E28
 Address: 11608 Reading Rd
 Cincinnati, Oh 45241
 Home: 513.554.1269
 Work:
 Fax:
 Company Address 2:
 Hat# VIN # DOM: 2791654

Service Invoice 16952

Created: 03/02/20
 Time: 9:18 AM
 Invoiced: 01/16/24
 Advisor: Service
 Division: AR
 PCH:
 Checked By:
 Page#: 10 of 10
 Year: 1988
 Make: BMW
 Model: M5
 Lic:
 Plate#:
 Body: Black
 Miles In: 9,461
 Miles Out: 9,461

Job Description

against cracking
 - Perform a full interior detail including:
 - Vacuuming and shampooing carpets and floor mats
 - Cleaning and conditioning leather surfaces
 - Cleaning and treating all interior glass for streak-free clarity
 - Cleaning and conditioning vinyl or plastic surfaces
 - Dusting and wiping down all interior surfaces
 - Odor elimination and freshening of the interior cabin

Line Total: 65.00
 Labor: 0.00
 Parts: 0.00
 Sublets: 65.00

Final EAG Delivery Preparation

- Full tank of Shell 93 octane fuel
 - Personalized service folder included on passenger seat
 - EAG welcoming package included on passenger seat

YOU MUST INITIAL AND SIGN BEFORE WORK WILL BE PERFORMED. In accordance with Ohio law we are required to provide an estimate for repairs over \$25.00. I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above to secure the amount of repairs thereto. EAG will not be held responsible for loss or damage to vehicle what so ever. ENTHUSIAST AUTO GROUP, LLC 11608 READING RD CINCINNATI OH 45241 513-554-1269

Invoice Total	
Labor	\$12,041.80
Parts	\$11,951.04
Sublets	\$65.00
Supplies	\$25.00
Subtotal	\$24,082.84
Tax	\$1,879.45
Total	\$25,962.30

Enthusiast Auto Group, LLC

Name: EAG E28, EAG E28
 Address: 11608 Reading Rd
 Cincinnati, Oh 45241
 Home: 513.554.1269
 Work:
 Fax:
 Company Address 2:
 Hat# VIN # DOM: 2791654

Service Invoice 16952

Created: 03/02/20
 Time: 9:18 AM
 Invoiced: 01/17/2024
 Advisor: Service
 Division: AR
 PCH:
 Checked By:
 Page#: 1 of 10
 Year: 1988
 Make: BMW
 Model: M5
 Lic:
 Fleet#:
 Body: Black
 Miles In: 9,461
 Miles Out: 9,461

Job Description

Comprehensive Enthusiast Auto Group Inspection

Line Total: 620.00
 Labor: 620.00
 Parts: 0.00
 Sublets: 0.00

All recommended work has been completed by EAG

All time based fluid services were performed @ time of sale on 01/2024

Vehicle Notes:

Garage-Find of the Decade! This 1988 BMW M5 has been stored in a climate controlled garage in Tucson, Arizona since new with it's original and only owner since new. It was decommissioned from driving use in the mid-1990's with supporting documentation when the owner relocated to Europe. This M5 has not been started since, nor was the vehicle accessed while the owner was abroad for well over two decades. EAG recommends a comprehensive recommissioning and full baseline reset.

Full Vehicle Scan Results:

-No warnings are currently present

Measurement Results:

Front brakes 13mm life remaining
 Rear brakes 10mm life remaining
 Front tires are original to vehicle - Recommend new wheels and tires with preservation of originals
 Rear tires are original to vehicle - Recommend new wheels and tires with preservation of originals

Technician's Findings:

-Recommend EAG 10 year E28 M5 S38 inspection service
 -Recommend S38 valve adjustment service
 -Distributor seals are starting to seep - Recommend replacement
 -Engine accessory drive belts are starting to crack - Recommend replacement
 -Engine water pump is starting to seep - Recommend proactive water pump and thermostat replacement

YOU MUST INITIAL AND SIGN BEFORE WORK WILL BE PERFORMED. In accordance with Ohio law we are required to provide an estimate for repairs over \$25.00. I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above to secure the amount of repairs thereto. EAG will not be held responsible for loss or damage to vehicle what so ever. ENTHUSIAST AUTO GROUP, LLC 11608 READING RD CINCINNATI OH 45241 513-554-1269

Invoice Total	
Labor	\$12,041.80
Parts	\$11,951.04
Sublets	\$65.00
Supplies	\$35.00
Subtotal	\$24,092.84
Tax	\$1,879.24
Total	\$25,972.08

Enthusiast Auto Group, LLC Service Invoice 16952

Name: EAG E28, EAG E28
 Address: 11608 Reading Rd
 Cincinnati, Oh 45241
 513.554.1269

Enthusiast Auto Group, LLC

Service Invoice 16952

Name: EAG E28, EAG E28
 Address: 11608 Reading Rd
 Cincinnati, Oh 45241
 513.554.1269

Company Address 2
 Cincinnati, Oh 45241
 513.554.1269

Created: 03/02/20
 Time Invoiced: 9:18 AM
 Year: 1988
 Make: BMW
 Model: M5
 License: AR
 Plate: AR
 Body: Black
 Miles In: 9,461
 Miles Out: 9,461

Job Description

Line	Description	Total
1	Comprehensive 10-Year E28 M5 S38 Inspection	812.82
	- Engine Oil and Filter Change	400.00
	- Check Wiper Blades / Inserts	412.82
	- Check Level and Condition of All Fluids	
	- Check and Set Tire Pressures	
	- Replace Engine Air Filter	
	- Replace Fuel Filter	
	- Replace Spark Plugs	
	- Cooling System Flush	
	- Brake System Fluid Flush	
	- Power Steering Fluid Flush	
	- Transmission Fluid Flush	
	- Differential Fluid Flush	

Note:
 EAG 10 year services performed at time of sale 01/2024

Part Number	Description	QTY	Each	Total
07 119 063 355	Cash Seal 22x27 AL	2	0.77	1.54
11 42 9 063 138	Oil Filter OX41	1	17.47	17.47
12 29 9 061 802P	Spark Plug XSDC 7409	6	11.53	69.18
13 32 1 270 036	Fuel Filter E30 R1.9	1	64.31	64.31
13 72 1 307 134	Air Filter - E28	1	66.14	66.14
TW140	Synthetic Castor Oil - XJ	2	16.99	33.99
AMS 15W40	Synthetic Oil	7	11.75	82.25
ATF FLUID	Power Steering Fluid	1	4.11	4.11
BRAKE FLUID	Brake Fluid	1	12.00	12.00
COOLANT	BMW Coolant	1	24.98	24.98
MTL REFLINE OIL	MTL oil	2	18.47	36.94

S38 Valve Adjust Service

- Remove valve cover and adjust all valves as needed
- Replace surrounding gasket and spark plug tube gaskets
- Replace rear cam cover gasket
- Degrease any effected area
- Replace any hardware needed during the service

Part Number	Description	QTY	Each	Total
11 12 1 306 729	Gasket Cyl Head Rear	1	2.21	2.21
11 12 1 312 112	VO Gasket S38	1	63.31	63.31
11 12 1 312 173	Spark Plug Seals S14/S38	3	13.75	41.25


Replace Distributor Seals

- Replace distributor shaft seal
- Replace distributor cam O-rings
- Replace any hardware needed during service
- Degrease affected area

YOU MUST INITIAL AND SIGN BEFORE WORK WILL BE PERFORMED. In accordance with Ohio law we are required to provide an estimate for repairs over \$25.00.

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above to secure the amount of repairs thereto. EAG will not be held responsible for loss or damage to vehicle what so ever. ENTHUSIAST AUTO GROUP, LLC 11608 READING RD CINCINNATI OH 45241 513-554-1269

Invoice Total	
Labor	\$12,041.80
Parts	\$11,951.04
Sublets	\$65.00
Supplies	\$35.00
Subtotal	\$24,092.84
Tax	\$1,879.24
Total	\$25,972.08



#900 Scotts Valley Dr.
 Scotts Valley, CA 95066
 (831) 430 9940
 (831) 430 9941
www.canepa.com

Job# 7246
 Customer: [REDACTED]
 Vehicle 1988 BMW M5
 VIN: WBSDC933J2791654
 Color: Black
 Mileage in: 9,688
 Mileage out: 9,698
 Date project started: 10/15/24
 Date project finished: 10/1/25

Project Outline

Exterior Paint:

- Inspect exterior painted finish and develop paint repair plan.
- Mask car and prepare for paint repair.
- Color-sand all exterior painted surfaces; hood, roof, sunroof, trunk, right & left front fenders, (4) doors, quarter panels, and rear license plate panel.
- Buff and polish all exterior painted surfaces.
- Remove polish residue front jambs and seams.

Speaker Grilles:

- Remove original passenger's and driver's speaker grilles.
- Formulate paint color to match original speaker grille. Spray multiple test panels. Tint and adjust color as needed.
- Prep (2) customer supplied replacement speaker grilles for paint.
- Apply sealer on two grilles using a process that replicates the original grille's textured finish.
- Apply (4) coats of base color and (1) coat of matte clear.
- Install 2 speaker grilles.

Center Grille:

- Remove original center grille and determine why it is loose on the car. Found the mounting tabs are broken.
- Procure and install new center grille.

M5 Emblem:

- Remove original M5 emblem from front grille.
- Install customer supplied M5 emblem of front grille.

Job #/Customer/Vehicle: 7246 Jeff Walsh Black 1988 BMW M5

QTY	PARTS AND MATERIALS	PRICE
1	grille center: c511170 -body 51 I3 1	234
1	battery, 12volt-agm -electrical	47
6	mx49 h8	
2	qt 20w50 ecn	
1	gal distilled wa	
1	instrn oil fsh-	

canepa
 Jeff Walsh

7246 Jeff Walsh

unaffected rear
 air removed dents
 rt door, right

Job #/Customer/Vehicle: 7246 Jeff Walsh Black 1988 BMW M5

Parts and Materials

DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL PRICE
511170 - body	1	234.47	234.47
12 volt agmt - electrical	1	448.43	448.43
ecorsa oil - engine	1	1.09	1.09
ecorsa water	1	1.09	1.09

4900 SCOTT VALLEY DRIVE
SCOTT VALLEY, CA 95076
PHONE: (925) 885-1111
WWW.CANOPA.COM

650-759-0648

ORDER WRITTEN BY: Julie

DATE OPEN: 10/15/24

46702

1988 BMW M5

Black

Year, Make and Model

Window Seals and Trim:

- Evaluate windshield and rear window seals and trim.
- Sublet for removal of windshield and rear window.
- Clean windshield and rear window channels. Remove dirt and glue residue.
- Clean windshield and rear window glass. Remove glue residue.
- Polish paint in windshield and rear window channels.
- Clean windshield and rear window trim moldings.
- Sand and prep windshield and rear window trim moldings for paint.
- Apply (1) coat of epoxy primer on trim moldings.
- Apply (2) coats of black base followed by (1) coat of eggshell clear.
- Sublet for the installation of the windshield and rear window, using customer supplied new windshield rubber seals and refinished trim moldings.

Service:

- Perform inspection.
- Found battery voltage low. Charge battery. Perform load test. Battery failed load test. Remove original battery. Install new battery.
- Diagnose fluid leak. Pressure test cooling system and check for leaks. Found coolant leak at heater valve and brake fluid leak at master cylinder.
- Remove master cylinder. Install new master cylinder.
- Flush brake fluid from brake system. Refill brake system with ATE DOT 4 Low Viscosity brake fluid and bleed air from the system.
- Remove leaking heater valve. Install new heater valve.
- Drain oil. Remove oil filter. Install new oil filter. Refill oil system with 6 quarts of Evolve Ecorsa Motorsport 20W50 engine oil. Start and run engine to bring to operating temperature. Check and adjust engine oil level as needed.
- Flush fluid from hydraulic clutch system. Refill hydraulic clutch system with ATE DOT 4 Low Viscosity brake fluid and bleed air from the system.
- Check engine coolant protection level. Found protection level to be low.
- Clean corrosion from expansion reservoir and radiator cap.
- Refill cooling system with antifreeze and distilled water.
- Perform road test.

Exhaust System:

- Muffler and tail section is heavily corroded and beyond repair.
- Remove heatshields and exhaust tips.
- Remove muffler and tail section.
- Procure and install new genuine BMW muffler and tail section.
- Install heatshields and exhaust tips.



inpea

Key Dr.
A. 95066

Job# 7246
Customer: [redacted]
Vehicle: [redacted]
VIN: WBSSD
Color: Black
Mileage in: 9,688
Mileage out: 9,698
Date project started:
Date project finished:

Exterior Paint:

- Inspect exte
- Mask car ar
- Color-sand left front fer
- Buff and pc
- Remove pc

Speaker Grilles:

- Remove o
- Formulate panels. Ti
- Prep (2) c
- Apply see grille's t
- Apply (4
- Install 2

Center Grille:

- Remove
- Found th
- Procure

M5 Emblem:

- Remove
- Install c

nepa

Job#

Customer:

Vehicle

VIN:

Color:

Mileage in:

Mileage out:

Date project started:

Date project finished:

Job# 72012
Customer: [redacted]
Vehicle 1988 BMW
VIN: WBSDC9
Color: Black
Mileage in: 9,688
Mileage out: 9,698
Date project started: 10/1/88
Date project finished:

Exterior Paint:

- Inspect exterior
- Mask car and
- Color-sand all
- left front fender
- Buff and polish
- Remove polish

Speaker Grilles:

- Remove original
- Formulate primer
- panels. Tint
- Prep (2) custom
- Apply sealer
- grille's frame
- Apply (4
- Install 2

Center Grille:

- Remove original
- Found the
- Procure &

M5 Emblem:

- Remove original
- Install custom



Staples

Staples



7246
Customer: [redacted]
Vehicle: WBSDC
Color: Black
Age in: 9,688
Age out: 9,698
Date project started:
Date project finished:

Exterior Paint:

- Inspect exterior
- Mask car and
- Color-sand &
- left front fender
- Buff and po
- Remove po

Speaker Grilles:

- Remove or
- Formulate
- panels, Tire
- Prep (2) c
- Apply seal
- grille's trim
- Apply (4
- Install 2

Center Grille:

- Remove th
- Procure &

M5 Emblem:

- Remove
- Install cu





Staples

epa

7246
Jeff Wals
1988 BMW
WBSDC
Black
9,688
9,698
project started:
project finished:

For Paint:

- Inspect exterior
- Mask car and
- Color-sand &
- left front fender
- Buff and pol
- Remove po

Exhaust Grilles:

- Remove or
- Formulate
- panels. Tin
- Prep (2) cu
- Apply seal
- grille's top
- Apply (4
- Install 2

Center Grille:

- Remove th
- Found th
- Procure #

5 Emblem:

- Remove
- Install cu

2025/07/30

Staples



2025/05/22 13:59:10

sh
W/ M5
:933J27

10/15/2
: 10/1/2

rior pair
id prepa
all exter
nders, (4
lish all €
lish res

iginal p
paint cr
nt and a
custome
ler on t

SUS



Staples

anepa

Valley Dr.
W, CA, 95066
940
1941
28 (5/2011)

Job# 7246
Customer: Jeff Walsh
Vehicle: 1988 BMW
VIN: WBSDC9
Color: Black
Mileage in: 9,688
Mileage out: 9,698
Date project started: 11
Date project finished:

Exterior Paint:

- Inspect exteri
- Mask car and
- Color-sand all left front fend
- Buff and polis
- Remove polt

Speaker Grilles:

- Remove orig
- Formulate p
- panels. Tint
- Prep (2) cus
- Apply seale
- grille's tr
- Apply (4
- Install 2

Center Grille:

- Remove
- Found th
- Procure &

M5 Emblem:

- Remove c
- Install cus

2025/07/30



46
iff Walsh
88 BMW M5
VBSDC933J279
black
9,688
9,698
tarted: 10/15/24
inished: 10/1/25

nt:
ect exterior painte
car and prepare
r-sand all exterio
ont fenders, (4)
and polish all ex
ove polish resid

rilles:
move original pas
mulate paint col
els. Tint and adj
p (2) customer s
ply sealer on two
le's f
ply (4
stall 2

rille:
move
und th
ocure

tem:
remove
stall cus