

LMC TRUCK  
www.LMCTRUCK.com

LMC TRUCK

ORDER # W6416060  
DATE 09/03/24

ORDER #	DATE	CATALOG	VEHICLE	PAYMENT	METHOD OF PAYMENT OR CREDIT CARD	
1044 01 03	09/03/24	CC 87	CT C10 82	VISA	6700	
LOCATION	QTY	PART	DESCRIPTION	OS	PRICE	AMOUNT
A04 01 03	1	36-1842	TEMPERATURE GAUGE		34.85	34.85
A10 07 01	1	37-8389	COLORBOND-SURFACE CLEANER		13.85	13.85
B02 04 03	0	37-8387	COLORBOND-SURGLINTY		21.45	128.70

Phyema  
415 N N  
Lexington

Sales Receipt

1 NEW FLEET TIRE  
(\$36.97)

Date	Sale No.	Check No.	Pay Method	Project
07/10/24		21976		

Item	Description	Quantity	Rate	Amount
Check vehicle	check over front suspension - Found failed lower ball joints, some steering parts - Customer only wants lower ball joints replaced interior come light not working - Found wires have been cut and left stuffed in headliner. Unable to locate the other end. - Customer was explained someone has removed them. coolant temp gauge no working - Found coolant temp gauge has failed needs to be replaced to correct issue - customer said they would do this. running issue at idle / transmission lurching - appears to be related to carb needing to be checked over and adjusted. - customer didn't approve any thing to be done with carb. Found vehicle needs spark plug wires - Customer declined having them replaced.	1	120.00	120.00
(Suspension) Labor	Classic Alignment	2	89.99	179.98
	1982 Chevrolet C10 30sci	1	400.00	400.00
	Sales Tax	1	120.00	120.00
			7.00%	57.40

TRUCK PARTS  
Suzuki Parts  
repaired gauge  
a Bud Rep Co

24

1ST CHOICE AUTO  
403 OLD US HWY 52  
LEXINGTON, NC 27295  
336-300-7576

Sep 23, 2024 07:38 AM  
1982 Chevrolet Pickup C10  
5.0L Eng

TYPE	DESCRIPTION	PART #	QTY	PRICE	RATE	HOURS	LINE TOTAL
Labor	VALVE COVER GASKET - Remove & Replace (Includes: Camshaft Covers on Over Head Cam Engines) C10 V8 Gas 5.0L Eng Both				\$90.00	2.0	\$180.00
Labor	STEERING GEAR (COMPLETE) - Remove & Replace						\$15.00
Parts	GEAR BOX	AD277522		\$90.00		1.2	\$108.00
Parts	VALVE COVER GASKETS	ADV312669R	1.0	\$215.00			\$215.00
Labor	FIX LIGHT SPARE TIRE						\$30.00
Labor	ALIGNMENT						\$15.00
Parts	OIL SENDING UNIT	R/R5144	1.0	\$28.00		1.0	\$28.00
Parts	DIST CAP AND ROTOR	AD/CAE1055/DAA1001	1.0	\$35.00			\$35.00

Labor: \$450.00  
Parts: \$323.00  
Shop Supplies: \$16.15  
Hazardous Materials: \$0.00  
Labor Taxes: \$31.50  
Parts Taxes: \$23.74  
TOTAL: \$844.39

Customer Signature:

Calc 1190.92

060  
of 640  
NOTES  
THIS SHIPMENT COMPLETES THE ORDER  
PAYMENT CREDIT

Branch 117  
Teller 1089  
Amount \$16,100.00  
Fee Amt \$0.00

PAY TO THE ORDER OF

ONCE A

Auto Zone @ Trailer Hike \$206.50  
\$259.95 Rear Bumper (Smooth Prem) → 564.92  
\$99.95 Rear Bumper (Bench Kit)  
\$7.95 License Plate Hardware Kit  
\$59.95 Rear license panel (chrome)  
\$19.95 (2)pc Bumper Bolt Kit  
\$12.95 License plate lamp Assy w/standard bumper  
\$54.95 Wheel Arch molding KIT  
\$29.95 Bed CORNER MOLDING KIT  
\$29.95 Bed CORNER MOLDING RH  
\$1.95 Molding clip WITH nut - chrome  
\$2.95 Molding clip - Rear Postion  
\$3.95 Dome light (Buss - white) - 954  
Bulb - dome light (clear)  
\$12.95 Vinyl edge sealer Pen  
\$183.25 of April 5, 2023  
\$748.17 TOTAL


**LMC TRUCK**

15450 W. 108TH STREET, LENEXA KS 66219  
800-562-8782 ORDERS-CATALOG REQUESTS-STATUS  
913-541-0884 WORLDWIDE ORDERS  
913-589-0323 FAX ORDERS

www.LMCTRUCK.com



ORDER # **W6416060**  
DATE 09/03/24



PAGE 1

Ship To:

ORDER #	DATE	CATALOG	VEHICLE	PAYMENT	METHOD OF PYMENT OR CREDIT CARD
W6416060	09/02/24	CC B7	CT C10 82	VISA	**** * 6769

LOCATION	QTY	PART	DESCRIPTION	O/S	PRICE	AMOUNT
A04 01 03	1	36-1842	TEMPERATURE GAUGE		34.95	34.95
A10 07 01	1	37-8399	COLORBOND-SURFACE CLEANER		13.95	13.95
B02 04 03	6	37-8387	COLORBOND-BURGUNDY		21.45	128.70

**W6416060**

8

Regular - A04

Run# 13: 239 of 640



- BACKORD - BACKORDERED, WILL SHIP WHEN AVAILABLE.
- TOS - TEMPORARILY OUT OF STOCK, CANCELLED, REORDER IN 3-4 WEEKS.
- TBA - TO BE ANNOUNCED (AVAILABILITY), PART HAS BEEN CANCELLED FROM ORDER, CHECK AVAILABILITY AT A FUTURE DATE.
- NLA - NO LONGER AVAILABLE, STOCK DEPLETED OR NO MANUFACTURER.

NOTES:

**STD**

PARTS 177.60

SHIPPING 38.50

CORES


C.O.D.

STATE TAX 15.13  
SHIPMENT TOTAL 231.23

THIS SHIPMENT COMPLETES THE ORDER

PAYMENT CREDIT

1ST CHOICE AUTO  
4031 OLD US HWY 52  
LEXINGTON, NC 27295  
336-300-7576



Sep 23, 2024 07:38 AM

YMMS: 1982 Chevrolet Pickup C10

Engine: 5.0L Eng

License:

VIN:

Odometer:

TYPE	DESCRIPTION	PART #	QTY	PRICE	RATE	HOURS	LINE TOTAL
Labor	VALVE COVER GASKET - Remove & Replace - [Includes: Camshaft Covers on Over Head Cam Engines.] C10,V8,Gas,5.0L Eng Both	-	-	-	\$90.00	2.0	\$180.00
Labor	STEERING GEAR (COMPLETE) - Remove & Replace -	-	-	-	\$90.00	1.2	\$108.00
Parts	GEAR BOX	AD/277522	1.0	\$215.00	-	-	\$215.00
Parts	VALVE COVER GASKETS	AD/VS12869R	1.0	\$30.00	-	-	\$30.00
Parts	PAINT		1.0	\$15.00	-	-	\$15.00
Labor	FIX LIGHT. SPARE TIRE	-	-	-	\$90.00	0.8	\$72.00
Labor	ALIGNMENT	-	-	-	\$90.00	1.0	\$90.00
Parts	OIL SENDING UNIT	R/RS144	1.0	\$28.00	-	-	\$28.00
Parts	DIST CAP AND ROTOR	AD/CAE1055/DAA1001	1.0	\$35.00	-	-	\$35.00

Labor: \$450.00

Parts: \$323.00

Shop Supplies: \$16.15

Hazardous Materials: \$0.00

Labor Taxes: \$31.50

Parts Taxes: \$23.74

TOTAL: \$844.39

Customer Signature: \_\_\_\_\_


CASH \$790.00

THANK YOU FOR YOUR BUSINESS

Ponyne  
415 N N  
Lexingto


POPEY BROTHERS, AT FARMHOLD  
415 NORTH MAIN STREET  
LEXINGTON, KY 40502  
502-259-4633

# Sales Receipt




Date	Sale No.	Check No.	Pay Method	Project
07/10/24	21976			

Item	Description	Quantity	Rate	Amount
Check vehicle	check over front suspension : Found failed lower ball joints, some steering parts - Customer only wants lower ball joints replaced interior dome light not working - Found wires have been cut and left stuffed in headliner. Unable to locate the other end. - Customer was explained someone has removed them. coolant temp gauge no working- Found coolant temp gauge has failed needs to be replaced to correct issue - customer said they would do this. running issue at idle / transmission lurching - appears to be related to carb needing to be checked over and adjusted. - customer didn't approve any thing to be done with carb. Found vehicle needs spark plug wires - Customer declined having them replaced.	1	120.00	120.00T
-Suspension	Front lower ball joints - MOO	2	89.99	179.98T
Labor		1	400.00	400.00T
Classic		1	120.00	120.00T
Alignment				
	1982 Chevrolet C10 305ci			
	Sales Tax		7.00%	57.40
<b>Total</b>				<b>\$877.38</b>



704-639-9718, Mr. RICHARD  
 323 S. ARLINGTON ST.  
 SALISBURY, NC 28144  
 ST# 01552, DP# 008687, TR# 07456  
 # ITEMS SOLD 9  
 TC# 5466, 3964, 8721, 9726, 0359, 6



ROD BAL-LIFE 068113124592  
 4 AT 1 FOR 15.00 .60.00.X  
 TIRE MOUNT C.007874224335  
 4 AT 1 FOR 11.00 .44.00.X  
 TLE ITEMS COMPLETE 104.00  
 SUBTOTAL 2.97.R  
 APL SLDB 003022301014.F  
 DISCOUNT GIVEN 10.70  
 SUBTOTAL 96.27  
 TAX 1 7.000% 6.55  
 TAX 2 2.000% 0.05  
 TOTAL 102.87  
 VISA TEND 102.87  
 CHASE VISA \*\*\*\*\*6769.1.4  
 APPROVAL # 09081A  
 REF # 336500528903  
 TRANS.ID - 463365789955238  
 VALIDATION - .FTH2  
 PAYMENT SERVICE - .E  
 RID.A0000000031010  
 RAC.4EEBD92EDFAF9673  
 TERMINAL # SC010240  
 \*NO SIGNATURE REQUIRED  
 12/31/23 16:56:38  
 SERVICE FEE 0.00

6 NEW FIRESTONE TIRES  
 (\$1636.49)

Date: 12-31-2023  
 Keytag #: 07652



CPC #: 4005015529955030512

address stated on this work order pursuant to law.

VIN: -- Customer Arrival Time  
 License: -- 12-31-2023 09:45 AM  
 Odometer: -- Service Completed Time  
 12-31-2023 10:42 AM

Quantity	Price
4	\$44.00 (\$11.00 EACH)
4	\$60.00 (\$15.00 EACH)
Service Total (Excluding Tax & Govt. Fees): \$104.00	

Quantity	Price
1	PREPAID
1	PREPAID
1	PREPAID
1	PREPAID
Merchandise Total (Excluding Tax): \$0.00	
Total (Excluding Tax & Govt. Fees): \$104.00	

Item	Description	Status
Tires	COMPLETE-Tire 2	Balance tires
Tires	COMPLETE-Tire 3	Tire pressure check
Tires	COMPLETE-Tire 4	Tire pressure check
TPMS Service Pack	DECLINED-Tire 1	Tire pressure check
TPMS Service Pack	DECLINED-Tire 2	Tire pressure check
TPMS Service Pack	DECLINED-Tire 3	Dispose of old tires
TPMS Service Pack	DECLINED-Tire 4	Dispose of old tires
	COMPLETE-Tire 1	COMPLETE-Tire 2
	COMPLETE-Tire 2	COMPLETE-Tire 3
	COMPLETE-Tire 3	COMPLETE-Tire 4
	COMPLETE-Tire 4	COMPLETE-Tire 1
	COMPLETE-Tire 1	COMPLETE-Tire 2
	COMPLETE-Tire 2	COMPLETE-Tire 3
	COMPLETE-Tire 3	COMPLETE-Tire 4
	COMPLETE-Tire 4	COMPLETE-Tire 1

THANK YOU  
 Official tires. Survey must be taken within ONE week of today. Void where prohibited.

Scan new DOTs  
 1WB1LE310223  
 Scan new DOTs  
 1WB1LE310223  
 Scan new DOTs  
 1WB1LE310223  
 Mount Tires  
 COMPLETE-Tire 1

Damages Noted Before Service	Type of Damage	Additional Comments
None	--	--
Technician Names	Customer Comments	Technician Comments
Service Writer/Greeter: Danny R. Tire tech: Lucas R.	None	None

**Customer Service Agreement**  
 I authorize the stated service to be completed with the necessary materials. I give permission to operate the vehicle.  
**I understand:**  
 1. Walmart does not inspect tires to determine if they are safe or have been recalled. Tires are not examined for conditions that may affect safety (tread depth, cuts, punctures, cracking, bulges, or uneven tread wear).  
 2. Only the service(s) listed on the service order are performed.  
 3. During oil changes, Walmart only checks and adjusts tire air pressure.  
 4. Walmart does not check tire age or air pressure of the spare tire.  
 5. Customers should regularly confirm that their tires, including any spare, are properly inflated, have tread depth greater than 2/32" in all grooves, and have no cuts, punctures, cracking, bulges, or uneven tread wear.  
 6. Driving conditions will affect tire performance.

**Customer Notification and Disclaimer**  
 Walmart may conduct complimentary courtesy checks based on your selection of service packages. Courtesy checks vary by service package and could include the following: checking of tire pressure, light bulb testing, fluid refills (washer, transmission, and power steering), battery check, interior vacuuming and checking of the wiper blades.

HAVE YOUR LUG NUTS RETORQUED AFTER THE FIRST 50 MILES

SIDE MOLDING 255.63

\$438.88

AUTO ZONE \$206.50

"9-15-2023" LM TRUCK PARTS \$564.92

NEW FIRESTONE TIRES \$636.47

(WAL-MART)  
12/31/23 MOUNT TIRES & BALANCE \$102.87

Repaint Buff & Put on  
new molding \$2,800.00

TOTAL

6/3/2024 [REDACTED] PAINT TRUCK \$1,800.00 } \$4,600

6/3/2024 (NEW WIPER BLADES) Wal-mart \$14.78

6/10/2024 NEW FIRESTONE TIRE FOR (SPARE) \$151.06

6/14/2024 TAX, TAG, TITLE \$699.32

6/17/2024 NEW AIR FILTER (STP) \$13.90