




Eurotech German Car Service, Inc.

659 Nicolet Avenue
Winter Park, FL 32789
Registration Number: MV21947
407-647-4757
service@eurotechwinterpark.com

Invoice #7770

Page 1 of 25
10/09/2025 12:38 PM



1987 Porsche 911
WP0EB0916HS172402
Engine: 3.2L H6 (B) GAS FI
Plate: Y83WUK
Odometer In: 45698
Odometer Out: 45705

Advisor: Larry Childress
Technician: Miguel Busto

GRAND TOTAL: \$10,142.87

✓ PAID

SERVICES

1	Basic Pre-Purchase Inspection	SUBTOTAL: \$246.95
	LABOR	Labor: \$246.95
	Test Drive	Parts: \$0.00
	Interrogate Fault Memory (attach report)	Fees: \$0.00
	Multipoint Inspection	Sublet: \$0.00

2	Remove Door Panel & Inspect Linkage	SUBTOTAL: \$246.95
	LABOR	Labor: \$246.95
	Remove Door Panel & Inspect Linkage	Parts: \$0.00
		Fees: \$0.00
		Sublet: \$0.00

3	Preliminary Testing (Level 1) (Warning Light Issue)	SUBTOTAL: \$163.00
	LABOR	Labor: \$163.00
	Level 1: Preliminary Testing (The Foundation of Accurate Diagnostics)	Parts: \$0.00
		Fees: \$0.00
		Sublet: \$0.00

Before diving into advanced testing or replacing parts, we start with Level 1 Preliminary Testing—a structured, efficient process designed to gather essential information about your vehicle's condition.

This level is all about initial inspection and data gathering, helping us determine if the issue is something simple or if deeper testing is needed.

4	Remove Odometer & Repair	SUBTOTAL: \$533.00
	LABOR	Labor: \$163.00
	Remove Odometer & Repair	Parts: \$0.00
		Fees: \$0.00
		Sublet: \$370.00

SUBLETS		TOTAL
		\$350.00
ODO Repair		\$20.00

Shipping

5 CIS Drivability Testing (Porsche)

SUBTOTAL: \$498.78

LABOR

Labor: \$498.78
 Parts: \$0.00
 Fees: \$0.00
 Sublet: \$0.00

CIS Drivability Testing (Porsche)

6 R134a Air Conditioning Evacuation and Recharge

SUBTOTAL: \$342.42

LABOR

Labor: \$230.48
 Parts: \$111.94
 Fees: \$0.00
 Sublet: \$0.00

Evacuate and Recharge Freon

PARTS

QTY	EACH	TOTAL
1.5	\$20.57	\$30.86
1.0	\$3.50	\$3.50
2.0	\$38.79	\$77.58

R134 Refrigerant

DYE

Refrigerant Oil - PAG46

7 Remove & Replace Right Rear Side Marker Light

SUBTOTAL: \$85.01

LABOR

Labor: \$81.50
 Parts: \$3.51
 Fees: \$0.00
 Sublet: \$0.00

Remove & Replace Right Rear Side Marker Light

PARTS

QTY	EACH	TOTAL
1.0	\$3.51	\$3.51

Bulb 12V 25W - Pack of 1

8 Remove & Replace Left Tag Lamp

SUBTOTAL: \$108.17

LABOR

Labor: \$48.90
 Parts: \$59.27
 Fees: \$0.00
 Sublet: \$0.00

Remove & Replace Left Tag Lamp

PARTS

QTY	EACH	TOTAL
1.0	\$59.27	\$59.27

License Plate Light

9 Remove & Replace Crankshaft Sensors

SUBTOTAL: \$1,302.71

LABOR

Labor: \$581.91
 Parts: \$720.80
 Fees: \$0.00
 Sublet: \$0.00

Remove & Replace Crankshaft Sensors

PARTS

QTY	EACH	TOTAL
-----	------	-------

urotech German Car Service, Inc.

659 Nicolet Avenue
 Winter Park, FL 32789
 Registration Number: MV21947
 407-647-4757
 service@eurotechwinterpark.com

Invoice #7770

Page 3 of 25
 10/09/2025 12:38 PM

RPM Sensor	2.0	\$360.40	\$720.80
------------	-----	----------	----------

10 Remove & Replace Throttle Bell Crank Bushings

LABOR

Remove & Replace Throttle Bell Crank Bushings

SUBTOTAL: \$230.21

Labor: \$163.00
 Parts: \$67.21
 Fees: \$0.00
 Sublet: \$0.00

PARTS

	QTY	EACH	TOTAL
Throttle Cable Bushing	2.0	\$4.38	\$8.76
Gear Oil 75W-90 GL-5 1L	1.0	\$58.45	\$58.45

SUBTOTAL: \$67.21

11 Preliminary Testing (Level 1) (Brake System)

LABOR

Level 1: Preliminary Testing
 (The Foundation of Accurate Diagnostics)

Before diving into advanced testing or replacing parts, we start with Level 1 Preliminary Testing—a structured, efficient process designed to gather essential information about your vehicle's condition.

This level is all about initial inspection and data gathering, helping us determine if the issue is something simple or if deeper testing is needed.

SUBTOTAL: \$163.00

Labor: \$163.00
 Parts: \$0.00
 Fees: \$0.00
 Sublet: \$0.00

12 Replace 12v Battery

LABOR

Remove and replace 12v Battery

SUBTOTAL: \$401.08

Labor: \$81.50
 Parts: \$311.58
 Fees: \$8.00
 Sublet: \$0.00

PARTS

	QTY	EACH	TOTAL
AGM Battery H8	1.0	\$311.58	\$311.58

HAZMATS & FEES

	QTY	FEE	TOTAL
Lead Surcharge	1.0	\$6.50	\$6.50
Battery Disposal Fee	1.0	\$1.50	\$1.50

13 Replace Relay For Warning System

LABOR

Replace Relay For Warning System

SUBTOTAL: \$351.31

Labor: \$0.00
 Parts: \$331.31
 Fees: \$0.00
 Sublet: \$20.00

urotech German Car Service, Inc.

659 Nicolet Avenue
 Winter Park, FL 32789
 Registration Number: MV21947
 407-647-4757
 service@eurotechwinterpark.com

Invoice #7770

Page 4 of 25
 10/09/2025 12:38 PM

PARTS	QTY	EACH	TOTAL
Relay	1.0	\$331.31	\$331.31

SUBLETS	TOTAL
Shipping	\$20.00

14 Remove and Replace Left Rear Swaybar Mount. Old mount must be cut off and new one welded in place.

SUBTOTAL: \$679.93

LABOR
 Remove and Replace Left Rear Swaybar Mount. Old mount must be cut off and new one welded in place.

Labor: \$498.78
 Parts: \$181.15
 Fees: \$0.00
 Sublet: \$0.00

PARTS	QTY	EACH	TOTAL
Sway Bar Bracket	1.0	\$181.15	\$181.15

15 Brake Fluid Flush

SUBTOTAL: \$150.10

LABOR
 Perform brake fluid flush
 Extract old brake fluid from reservoir
 Fill with new fluid per manufacturer specifications
 Connect brake flush tool
 Flush fluid at each caliper
 Remove brake flush tool
 Check and correct brake fluid level

Labor: \$130.40
 Parts: \$19.70
 Fees: \$0.00
 Sublet: \$0.00

PARTS	QTY	EACH	TOTAL
Bulk Brake Cleaner	1.0	\$4.95	\$4.95
Dot 4 Brake Fluid	1.0	\$14.75	\$14.75

16 Remove and Replace All Brake Flex Hoses With Caliper Rebuild

SUBTOTAL: \$363.30

LABOR
 Remove and Replace All Brake Flex Hoses With Caliper Rebuild

Labor: \$163.00
 Parts: \$200.30
 Fees: \$0.00
 Sublet: \$0.00

PARTS	QTY	EACH	TOTAL
Brake Hose	2.0	\$49.62	\$99.24
Brake Hose	2.0	\$50.53	\$101.06

Eurotech German Car Service, Inc.
 559 Nicolet Avenue
 Winter Park, FL 32789
 Registration Number: MV21947
 407-647-4757
 service@eurotechwinterpark.com

Invoice #7770
 Page 5 of 25
 10/09/2025 12:38 PM

17 Install New Rear Brake Pads With Caliper Rebuild and Adjust Parking Brake

SUBTOTAL: \$862.89

LABOR

Install New Rear Brake Pads With Caliper Rebuild

Labor: \$665.04
 Parts: \$197.85
 Fees: \$0.00
 Sublet: \$0.00

PARTS

	QTY	EACH	TOTAL
Brake Pad Set w/ Shims	1.0	\$135.61	\$135.61
Brake Pad Sensor	2.0	\$31.12	\$62.24

18 Install New Front Brake Pads and Rotors With Caliper Rebuild. Hubs will need to be removed from the rotors and bearings readjusted when installed. Will inspect, clean, and repack bearings while they are out.

SUBTOTAL: \$1,272.14

LABOR

Install New Front Brake Pads and Rotors With Caliper Rebuild. Hubs will need to be removed from the rotors and bearings readjusted when installed. Will inspect, clean, and repack bearings while they are out.

Labor: \$498.78
 Parts: \$773.36
 Fees: \$0.00
 Sublet: \$0.00

PARTS

	QTY	EACH	TOTAL
Brake Disc	2.0	\$260.79	\$521.58
Bulk Brake Cleaner	1.0	\$4.95	\$4.95
Brake Pad Sensor	1.0	\$37.20	\$37.20
Brake Pad Set OE Formulated w/ Shims	1.0	\$172.43	\$172.43
Brake Pad Sensor	1.0	\$37.20	\$37.20

19 Remove and Rebuild Both Front Calipers.

SUBTOTAL: \$1,085.07

LABOR

Remove and Rebuild Both Front Calipers

Labor: \$665.04
 Parts: \$420.03
 Fees: \$0.00
 Sublet: \$0.00

PARTS

	QTY	EACH	TOTAL
Caliper Repair Kit	2.0	\$95.69	\$191.38
Caliper Repair Kit	2.0	\$102.00	\$204.00
Bulk Brake Cleaner	2.0	\$4.95	\$9.90
Dot 4 Brake Fluid	1.0	\$14.75	\$14.75

20 Replace Passenger Door Lock Actuator Rod and Lube Linkage

SUBTOTAL: \$61.40

LABOR

Replace Passenger Door Lock Actuator Rod and Lube Linkage

Labor: \$48.90
 Parts: \$12.50
 Fees: \$0.00

German Car Service Inc.
 32789
 MV21947
 winterpark.com

QTY	EACH	TOTAL	
1.0	\$12.50	\$12.50	Sublet: \$0.00

Replace Passenger Door Lock Actuator

QTY	EACH	TOTAL	
1.0	\$218.37	\$218.37	

LABOR
 Replace Passenger Door Lock Actuator

PARTS
 Door Lock Actuator Motor (Front Left) //
 Door Lock Actuator Motor (Front Right)

SUBTOTAL: \$299.87
 Labor: \$81.50
 Parts: \$218.37
 Fees: \$0.00
 Sublet: \$0.00

Replace Wiper Blades

QTY	EACH	TOTAL	
2.0	\$19.34	\$38.68	

LABOR
 Replace Wiper Blades

PARTS
 Window Wiper Blade 13"

SUBTOTAL: \$38.68
 Labor: \$0.00
 Parts: \$38.68
 Fees: \$0.00
 Sublet: \$0.00

Service:

herein, "Eurotech" refers to Eurotech German Car Service Inc., its agents, employees, and other representatives. By signing this for repair, the parties enter into an agreement (the "Agreement").

TERMS. Labor charges are for ___ Flat Rate ___ Hourly ___ / ___
 c hourly rate for an estimate is \$163.00.

PARTS. (Please refer to RO Notes Section.)

WARRANTY. The parts and labor for any work provided by Eurotech are covered for 36 months, or 36,000 miles, whichever comes first, unless otherwise specified in writing. Maintenance items such as fluid changes, oil changes, wipers are excluded from warranty coverage. Used Parts are covered from warranty coverage. All warranty work must occur at the repair facility and cannot exceed the original cost of repair. In a situation where the vehicle cannot return to Eurotech at the time of failure, please contact our national warranty administrator at 1-866-541-9805.

SUPPLIES. ** This charge represents costs and profits to the repair facility for miscellaneous shop supplies or waste.

Florida mandates a \$1.00 fee for each new tire sold in the State of Florida. S. 403.7185 mandates a \$1.50 fee for each new or recycled battery sold in the State of Florida.

DISCLAIMER OF LIABILITY. Eurotech is not responsible for loss or damage to the vehicle or any personal items or articles left in the vehicle as a result of theft, natural disaster, accident, act of God or any other cause.

GRAND TOTAL: \$10,142.87

Total Labor: \$5,420.41
 Total Parts: \$3,667.56
 Total Fees: \$8.00
 Total Sublets: \$390.00
 Shop Supplies: \$37.85
 Sales Tax: \$619.05

PAID

10/13/2025 03:48 PM
 Paid by Credit Card via Terminal: \$10,142.87
 VENTURA DIEGO XXXX-XXXX-XXXX-1759
 Transaction ID: "0598WAZ1XDKM64TT"
 Authorization Code: "04307T"

Signed: 

533.00
 163.00
 : \$0.00
 : \$0.00
 370.00