



INVOICE



INVOICE NO.
 DATE April 18, 2026
 CUSTOMER ID 73 Alpha Spyder

VIN AR3041765

MILES 72132
 NH 4019123

4019123		PAYMENT TERMS	DUE DATE
invoices		Due upon receipt	
Hours	DESCRIPTION	UNIT PRICE	LINE TOTAL
20.00	transmission gets stuck in 5th gear R&R transmission, disassemble & found one interlock plug missing. Replaced interlock plug & readjust shift forks & reinstall transmission, bleed clutch & readjust shift lever. Replaced back up light switch (leaking) Replaced front & rear trans seals NOTE: plastic panels for console have broken tabs NOTE: had to remove motor mounts to reinstall transmission		\$ 2,000.00
4.00	8mm tab lock for forks	3.50	14.00
4.00	80/90 gear oil	16.00	64.00
1.00	npr gasket sealer	16.00	16.00
2.00	gallon Antifreeze	19.00	38.00
1.00	TP229 reverse switch	28.95	28.95
1.00	0S372 FRONT TRANS SEAL	12.95	12.95
1.00	0S604 REAR T28.95RANS SEAL	28.95	28.95
1.00	SHIPPING	23.50	23.50
15.00	noise & chunk in rear differential trace to excessive backlash (wear in ring & pinion) removed rear axle assembly & disassemble & swap parts from donor axle assembly, rebleed brakes with DOT 4 brake fluid reassemble assembly & road test	100.00	1,500.00
1.00	80/90 gear oil	16.00	16.00
15.00	car starts hard can not step on accelerator until ready test adjustments & found that correlation between thermostatic actuator & fuel injection pump too lean. Found thermostatic actuator out of spec & fuel injection pump out of spec. replaced injection pump & Thermostatic Actuator (customer supplied) reset engine specs & car now runs excellent	100.00	1,500.00
1.00	F1493 SPICA MICRO SWITCH	112.19	112.19
1.00	state inspection passed (sublet)	45.00	45.00
10.00	fuel does not shut off during decel trace to inoperative fuel cutoff switch in injection pump (all adjustments have been "tampered" with) reset to exact specs	100.00	1,000.00
1.50	Replaced directional switch R&R customer supplied directional switch & adjust Note : all wires were very loosely attached & supplied switch is very worn but works	100.00	150.00
1.00	replaced bulb for temperature gauge npr bulb	6.00	6.00
SUBTOTAL			\$ 6,555.54
SALES TAX			
TOTAL			\$ 6,555.54



28 Sumner Drive ♦ Dover, NH 03820
www.DupontServiceCenter.com
 (603) 742-8627

Inv. #: 0095380 Writer: CHRIS DUPONT
 Customer: [REDACTED]
 Address: [REDACTED]
 City: [REDACTED]
 CELL: [REDACTED]

Vehicle: 1973 Alfa Romeo 115
 License: 4019123 Date: 12/31/2020
 VIN: AR3041765 Page: Page 1 of 2
 Engine: PO #:
 Fleet/Unit#: Trans: STD
 Mileage: 70150

Tech	Labor Description	Labor	Parts	Subtotal
Qty	Part Number	Part Description		
ELE042				
70	Remove all components needed to access the turn signal switch assembly. Remove turn signal switch assembly. Found replacement turn signal switch assembly not working as designed. Removed components from the replacement turn signal switch and install into existing turn signal switch. Reinstall turn signal switch and clean up wiring. The turn signal works as designed at this time.	293.80	145.00	438.80
1.00	105	TURN SIGNAL SWITCH		145.00
SIN029				
70	Install Inspection Sticker.	0.00		
DIA006				
70	Install customer supplied rear fuel pump and filter at the tank. Repaired damaged wiring at the fuel tank pump. Found still have fuel pressure issue and the fuel pressure light did not go out. Tested for fuel pressure at the fuel injection pump. Found fuel pressure low. Tested for fuel pressure at the fuel pressure sensor. Spec is 7 PSI in and out of the main filter. Found we have 5 PSI in and out of the main filter. That is not enough to get the low fuel pressure light out. Inspected the main fuel filter at the engine. Found the filter looks old and possibly clogged. Replaced the fuel filter with a customer supplied fuel filter. Found we are still at 5 PSI. Tested replacement pump at the fuel tank. Found 5 PSI leaving the pump at the fuel tank. Removed the replacement pump and rewired in original pump. Retested the system and found over 7 PSI leaving the main fuel filter. Also found the low fuel pressure light goes out when it should. Roadtested the vehicle and the vehicle runs as designed. Please advise if the concern returns at this time.	598.00	1.77	599.77
1.00	FUSE	FUSE		1.77
COM016				
01	*****Client Supplied Parts***** Company policy prohibits the use of client supplied parts due to the multitude of problems involved. In the rare case that we utilize client supplied parts, the failure of that part or anything related, directly or indirectly, will not be covered. Our client supplied parts warranty specifically covers only the errors in labor operations performed by us, failures that occur as a result of improperly performed procedures, or failures of the parts that we supply. There will be no exceptions to warranty issues. Any additional operations necessary or loss of revenue caused by the use (or attempted use) of client supplied parts, will be charged to the client, and will typically be over and above the amount of any estimate. NO AAA discount will be applied to labor.	0.00		
Payments: VISA, \$1098.52, on 12/31/20 CardNo: [*****9898], AuthorizationNo: [622849]				



28 Sumner Drive ♦ Dover, NH 03820
www.DupontServiceCenter.com
 (603) 742-8627

Inv. #: 0095380 Writer: CHRIS DUPONT
 Customer: [REDACTED]
 Address: [REDACTED]
 City: [REDACTED]
 CELL: [REDACTED]

Vehicle: 1973 Alfa Romeo 115
 License: 4019123 Date: 12/31/2020
 VIN: AR3041765 Page: Page 2 of 2
 Engine: PO #:
 Fleet/Unit#: Trans: STD
 Mileage: 70150

Tech	Labor Description		Labor	Parts	Subtotal
	Qty	Part Number			
		Part Description			

OK Suggest Recommendation

OK Suggest Recommendation

Our work, parts and labor, is warranted for 24 months or 24,000 miles, whichever comes first. Dupont's Service Center, Inc. does not have any other warranty, either expressed or implied, including any warranty of merchantability of fitness for a particular purpose. Any warranties on parts and other accessories are those made by the manufacturer.



This warranty excludes the following:

- ♦ Any damage to a repair caused by negligence, abuse or road hazard
- ♦ Normal wear and tear of components, such as brake pads, tires and wiper blades
- ♦ We have a separate Road Hazard Warranty available for tires



Customer satisfaction is our number one priority. We are committed to providing quality products, competitive prices, professional service, and convenience. In our continuing efforts to provide the best customer service, our staff is eager to be of help, and readily available at 603-742-8627 or www.dupontservicecenter.com.

Signature X _____

Labor :	\$891.80
Parts :	\$146.77
Sublet :	\$0.00
Other Fees :	\$0.00
Supply Charges :	\$59.95
Subtotal :	\$1,098.52
Sales Tax :	\$0.00
Total :	\$1,098.52
Paid :	\$1,098.52
Due :	\$0.00

12/31/2020 01:00:32 PM Auth 622849 Ref 1311671678

\$ 1,098.52 [REDACTED] Agrees to Pay Total Amount
 VISA *****9898 According to Card Issuer Agreement

APPROVED

Signature X [REDACTED]



28 Sumner Drive
 Dover, NH 03820
 (603) 742-8627



WWW.DUPONTSERVICECENTER.COM



Customer	[REDACTED]	Vehicle : 1973 *ALF *SPIDER VELOCE	Inv. # : 0135362
Address	[REDACTED]	License : 4019123	Date : 8/27/2025
City	[REDACTED]	VIN : AR3041765	Page : Page 1 of 2
Phone 1	[REDACTED]	Engine : *4-1995 2.0L SOH	PO # :
Phone 2	[REDACTED]	Mileage : 74018	Advisor : HALEY COLLIN!

Tech	Description	Quan	Part Number	Part Description	Labor	Parts	Subtotal
79	Client authorized: labor to re-wire car for the alternator to work properly.						413.93
	*						
79	Client authorized: replace alternator assembly per diagnosis.						952.97
	*						
		1.00		NEW ALT REGULATOR		Declined	
		1.00		ALTERNATOR W REGULATOR			
		4.00		AUTOLITE RESISTOR			
79	Customer states: vehicle broke down on the way over for, started to die while driving and then stalled at stop light and will not turn over. Note to start: do not touch gas until engine catches and cranks or will flood *Found: check no start/insp vech battery dead jump to start, vech will run, test battery fail ,charge and retest battery did pass (note battery in service date is 10/21) check out put from alt 11.80 at idle and 12.20 at 2500 rpm no out put from alt ,check power to alt at b* ok 12.0 volt rec alternator and external voltage regulator						331.14
79	Complimentary Vehicle Check Over(SI) with State Inspection:						
	**						
79	** NH STATE INSPECTION ** Perform New Hampshire state safety inspection. Perform New Hampshire emissions inspection as required.						48.50
	*						
		1.00		NH INSP STICKER			
79	** RIGHT FRONT MARKER BULB, RENEW ** Remove components as require for access. Disconnect electrical connection. Remove and replace specified marker light bulb. Reconnect electrical connector. Reinstall previous removed components. Test bulb operation.						18.20
	*						
		1.00		BULB			
	10% Off AAA Discount: Thanks for being a loyal client of Dupont's service center and AAA (AAA discount can not be used towards the purchase of tires, batteries, tire and battery labor and detailing.)Cannot be combined with other offers.						-75.00
						

	Payments:						



State Of New Hampshire
 DEPARTMENT OF SAFETY
 DIVISION OF MOTOR VEHICLES
OFFICIAL VEHICLE INSPECTION REPORT



DATE: 08/12/2025	INSPECTION TYPE: SAFETY ONLY	OVERALL RESULT: PASSED SAFETY RESULT: PASSED
TIME: 04:32:25 PM	MECHANIC: 14142	
STATION ID: 00005200	NHOST UNIT: NH014449	
STATION NAME: DUPONTS SERVICE CENTER		
STICKER NUMBER: 2600746479		

VEHICLE INSPECTED

VIN: AR3041765		
MODEL YR: 1973	MODEL: SPIDER	ODOMETER: 74,000
MAKE: ALFA	FUEL: Gas & Non-Diesel	GVW: Light Duty (<8501 Lbs.)

SAFETY INSPECTION RESULTS -- PASSENGER VEHICLE

NO REJECTED OR CORRECTED SAFETY ITEMS FOR THIS VEHICLE

THANK YOU

New Hampshire vehicles are safer because potentially dangerous defects are found during our annual inspections.
 Tip - Properly inflated tires and regular maintenance can save you money, and keep your vehicle running longer and cleaner.

*** Concerns or questions regarding this state inspection, or the practices of inspection stations, may be referred to the ***
 New Hampshire Department of Motor Vehicles at dealerandinspection@dos.nh.gov or 603-223-8911.

MECHANIC NOTES AND MEASUREMENTS

NO NOTES

I do hereby certify that all information I have provided the department is accurate and complete. This report is signed under penalty of unsworn falsification pursuant to RSA 641:3.

 MECHANIC SIGNATURE

*** KEEP THIS COPY IN YOUR VEHICLE ***



Restoration & Performance Motorcars
 462 Monkton Road
 Vergennes, VT 05491
 (802) 877-2645

Invoice

Date	Invoice #
12/31/2024	216

Bill To
[REDACTED]

Customer Phone
[REDACTED]

Customer Alt. Phone

Yr/Make/Model	Serial Number:	Odometer Reading:	Project/Job	Terms	
1973 Alf Romeo Veloce Spider	AR3041765	73625			
Item	Qty	Description	List	Rate	Amount
Labor	5	Get car out and on lift to check over and make list. Pull air cleaner. Check oil in engine bay, line off oil separator and vacuum supply to separator off. Check won't hold idle. Drain coolant and pull radiator, shroud and fan to replace fan and shroud. Check Spica pump timing. Confirm pump timing. Check full throttle stop.		165.00	825.00
Labor	4	Set closed throttle stop and adjust short rod length. Test cold start and decel solenoid function. Install new vacuum line oil separator to idle manifold. Replace missing nut for all tensioner stud in water pump. Water pump casting broken. Order water pump. Remove Spica belt, crank pulley and water pump.		165.00	660.00
Labor	6	Drain block. Clean timing chest water pump sealing surface. Transfer tach drive to new water pump and install stud for alternator tension. Install water pump and crank pulley. Install Spica belt and check timing. Install cooling fan and alternator tensioner and fan belt. Glue up radiator weather strip. Make 2 bushings for radiator mounts. Install mounts.		165.00	990.00
Labor	5	Install coolant hoses upper, lower, bypass and heater. Pull valve cover and clean head. Clean valve cover and check for flatness. Back 2 hold down studs pretty mangled, 1 had been heli coiled. Chase threads in nuts and replace 1 stud with used from inventory. Glue up valve cover. Installed battery. Fill and bleed cooling system.		165.00	825.00
Parts	2	Feet 6M Braided Hose			
Parts	1	Fan Blade		6.58	13.16T
Parts	1	Fan Shroud		55.25	55.25T
Parts	1	Valve Cover Gasket		73.45	73.45T
Parts	2	Valve Cover Half-Moon Seal		38.35	38.35T
Parts	4	Valve Cover Nut Gasket		3.70	7.40T
Sublet Repairs/...	1	Inbound Shipping for Parts		1.20	4.80T
Sublet Repairs/...	1	Inbound Shipping Parts		27.50	27.50
Parts	1	Water Pump, 4-Cylinder		10.28	10.28
Parts	2	Gallon RTU Antifreeze		205.40	205.40T
		Sales Tax		18.59	37.18T
				6.00%	26.10
Total					\$3,798.87
Payments/Credits					\$0.00
Balance Due					\$3,798.87



Restoration & Performance Motorcars
 462 Monkton Road
 Vergennes, VT 05491
 (802) 877-2645

Invoice

Date	Invoice #
6/6/2025	462

Bill To
[REDACTED]

Customer Phone
[REDACTED]

Customer Alt. Phone

Yr/Make/Model	Serial Number:	Odometer Reading:	Project/Job	Terms	
1973 Alf Romeo Veloce Spider	AR3041765	73625			
Item	Qty	Description	List	Rate	Amount
Labor	4	Set closed throttle stop and adjust short rod length. Test cold start and deceleration solenoid function. Install new vacuum line oil separator to idle manifold. Replace missing nut for alt tensioner stud in water pump. Damages and casting broken. Order water pump. Remove Spica belt, crank pulley and water pump.		185.00	740.00
Labor	4	Get car out and run up to temp to set up Spica. Road test to check backfiring, good. Adjust TA reference gap with hot engine. Adjust long throttle rod. Run up to temp again and double check. Check ignition timing, distributor advance is erratic, need to pull distributor.		185.00	740.00
Labor	6	Pull distributor and replace one advance weight spring. Install distributor. Perform lube, oil and filter change and check dipstick accuracy. Brake reservoir leaking at grommets, order grommets. Clean brake fluid off of everything. Check out water leak into cabin. Pull cowl cover and wipers to investigate. Blow out drains and install wiring grommet. Found windshield seal is shrunken and dry and no glue. E-mail customer and order gasket. Run car again to set idle and sync throttle bodies. Throttles not closing fully. Need to address to get correct idle speed.		185.00	1,110.00
Labor	6	Pull throttle bodies to adjust plates so they close completely. Repair one stud on throttle body for fuel line clamp. Install throttle bodies. Double check full and closed throttle stops. Run up to temp and double check TA reference gap and readjust long actuator rod. Set fuel mixture. Check/set timing and lock distributor. Road tests. Install air box and cold air intake.		185.00	1,110.00
Labor	2	Pull interior trim and exterior chrome and cowl cover to remove windshield. Pull windshield, inspect and clean. Clean windshield frame.		185.00	370.00
Labor	1	Pull master cylinder reservoir to check for leaks. New grommets are incorrect. Clean nipples on reservoir and clean bungs in master. Reinstall grommets and reservoir, fill and check.		185.00	185.00
Labor	0.5	Install gasket on windshield and prep to install.		185.00	92.50
Labor	4	Install windshield. Install chrome trim surround and rear view mirror and visors. Install one threaded insert for mirror attachment. Install cowl cover and exterior chrome strip.		185.00	740.00
Labor	2	Clean up glue on windshield gasket and surround. Long road test.		185.00	370.00
Labor	1	Replace leaking master cylinder grommets. Drain brake fluid and clean out bung.		185.00	185.00
Labor	2	Replace grommets and install reservoir. fill with new fluid.			
Labor	0.5	Make a few more adjustments and fine tuning Spica. Road tests. Install air cleaner.		185.00	370.00
Gas, Oil & Grea...	7	Quart Brad Penn 20W50 Oil		185.00	92.50
Gas, Oil & Grea...	8.5	Gallons Non Ethanol Gas 5/30/2025		10.89	76.23T
Parts	1	Windshield Clips for Cowl		4.28	36.38T
				39.00	39.00T
Total					
Payments/Credits					
Balance Due					



Restoration & Performance Motorcars
462 Monkton Road
Vergennes, VT 05491
(802) 877-2645

Invoice

Date	Invoice #
6/6/2025	462

Bill To
[Redacted]

Customer Phone
[Redacted]

Customer Alt. Phone


Yr/Make/Model	Serial Number:	Odometer Reading:	Project/Job	Terms	
1973 Alf Romeo Veloce Spider	AR3041765	73625			
Item	Qty	Description	List	Rate	Amount
Parts	1	Oil Filter		23.00	23.00T
Parts	1	Windshield Gasket		145.60	145.60T
Parts	2	Brake Master Cylinder to Reservoir Grommet		13.00	26.00T
Parts	2	Feet 6mm Braided		3.65	7.30T
Parts	1	Caulking Cord		13.75	13.75T
Parts	1	Ultra Black RTV Silicone Gasket Maker, 9.5 oz.		32.55	32.55T
		Sales Tax		6.00%	23.99
Total					\$6,528.80
Payments/Credits					\$0.00
Balance Due					\$6,528.80

07/01/2015

Veloce Imports, Ltd
33 Londonderry Rd. Unit 14
Londonderry, NH 03053
603-434-7479

Invoice #3246

Foreign Car Service, Restorations



1973 ALFA ROMEO SPIDER GT
1962cc SPICA MECHANICAL FI
Tag:925MV8 Mileage 67,977
ID: AR3041765

Labor

R & R TRANSMISSION(4 SPEED) & OVERHAUL

Amount
\$1,201.20
\$1,201.20

Part No.

Parts

Quantity

Each

GB039/1	Top seal disc	1.00	\$16.32	\$16.32
GB046	Gear bushing	1.00	\$60.07	\$60.07
GB002/1	Synchronizer, OE molly	3.00	\$156.95	\$470.85
GB039	Top seal	1.00	\$14.94	\$14.94
				<u>\$562.18</u>

Service charges
SHOP SUPPLIES
SHIPPING

\$19.68
\$45.00
\$64.68



Subtotal \$1,828.06
Tax \$0.00
Total \$1,828.06

RO 3178
Diagnose and repair transmission noises, sudden lock up.
1, 2, 3 synchro rings damaged, 3rd gear main bushing damages.
polish bearing surfaces, replace required parts, set clearances.

An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto, until such time as cash payment has been made in full. It is understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control. Upon signing this repair order it is accepted as a complete and comprehensive description of the repair work done on this vehicle.

DATE _____


SIGNED _____

07/23/2015

Veloce Imports, Ltd
33 Londonderry Rd. Unit 14
Londonderry, NH 03053
603-434-7479

Invoice #3265

Foreign Car Service, Restorations



1973 ALFA ROMEO SPIDER GT
1962cc SPICA MECHANICAL FI
Tag: 925MV8
ID: AR3041765
Mileage 67,977

Labor
R&R Upper Caster Arm Bushing (Both)
Tune Injection Pump

Amount
\$400.40
\$136.50
\$536.90

Part No.
91031000

Parts
Caster Arm Bushing

Quantity Each
2.00 \$14.14
\$28.28
\$28.28

Service charges
SHOP SUPPLIES

\$3.10
\$3.10



Subtotal \$568.28
Tax \$0.00
Total \$568.28

RO3178

Install new caster arm bushings in the upper control arms. Fine tune injection pump.

An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto, until such time as cash payment has been made in full. It is understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control. Upon signing this repair order it is accepted as a complete and comprehensive description of the repair work done on this vehicle.

DATE _____

SIGNED _____

Alfa Restoration Costs 2017 - 2019			
Date	Amount	Receipt type	Description of Charges
1/1/2017	\$3,000.00	Invoice	Labor, Blasting deposit
1/26/2017	\$2,257.24	Invoice # 166	Fabricate frame jig, disassemble tub, remove doors, wiring, and plumbing
2/1/2017	\$3,070.00	Invoice # 181	Finish jig fitment, sand blasting deposit
3/13/2017	\$4,496.50	Invoice # 194	Rebuild / reseal engine
4/4/2017	\$2,821.87	Invoice # 207	Engine parts, fenders, body parts
4/20/2017	\$2,481.94	Invoice # 223	Body work - fenders, floors, rockers
6/1/2017	\$3,392.10	Invoice # 244	Labor deposit
6/7/2017	\$2,524.45	Invoice # 270	Body work - floors, tunnel, cross member
6/12/2017	\$5,916.64	Invoice # 270	Labor - body work
6/8/2017	\$2,154.50	Invoice # 271	Rebuild fuel injection pump
6/29/2017	\$5,000.00	Invoice # none	no detail [likely "labor deposit"]
7/7/2017	\$3,356.24	Invoice # 302	Body work - rockers, floors, wheel arch
7/28/2017	\$4,871.22	Invoice # 331	Body work - 1/4 panels, fender well
8/31/2017	\$5,031.72	Invoice # 355	Body work - trunk, fender, tire well
10/3/2017	\$5,000.00	Invoice # 384	Labor deposit
11/14/2017	\$2,000.00	Invoice # 412	Labor deposit
11/22/2017	\$3,000.00	Invoice # 419	Labor - blasting deposit
12/2/2017	\$269.76	Invoice # 385	Parts, bumper mount, tail valance
1/4/2018	\$3,000.00	Invoice # 385	Labor deposit (Inv. Amt: \$3269.76)
4/19/2018	\$3,000.00	Invoice # 504	Labor deposit, parts suspension
7/18/2018	\$3,968.82	Invoice # 603	Painting, finish body work, block out sanding and final paint prep, internal and underside paint work
9/14/2018	\$5,000.00	Visa	
9/21/2018	\$5,000.00	Visa	
10/5/2018	\$4,598.24	Invoice # 645	Labor deposit, assembly of chassis, wiring, and sub assemblies
12/28/2018	\$5,000.00	Invoice # 711	? No explanation [likely "labor deposit"]
12/28/2018	\$3,990.14	Invoice # 711	Parts - long list
2/7/2019	\$4,853.96	Visa	
2/15/2019	\$3,500.00	Visa	
2/22/2019	\$4,280.00	Visa	
3/8/2019	\$3,210.00	Visa	
3/27/2019	\$4,589.76	Visa	
3/30/2019	\$3,210.00	Visa	
Total charges	\$117,845.10		
VISA Charges without invoices	\$33,643.72		
Total "Labor Deposits" - no work done	\$36,500.00		



State Of New Hampshire

DEPARTMENT OF SAFETY
DIVISION OF MOTOR VEHICLES

OFFICIAL VEHICLE INSPECTION REPORT



DATE: 08/12/2025	INSPECTION TYPE: SAFETY ONLY	OVERALL RESULT: PASSED SAFETY RESULT: PASSED
TIME: 04:32:25 PM	MECHANIC: 14142	
STATION ID: 00005200	NHOST UNIT: NH014449	
STATION NAME: DUPONTS SERVICE CENTER		
STICKER NUMBER: 2600746479		

VEHICLE INSPECTED

VIN: AR3041765		
MODEL YR: 1973	MODEL: SPIDER	ODOMETER: 74,000
MAKE: ALFA	FUEL: Gas & Non-Diesel	GVW: Light Duty (<8501 Lbs.)

SAFETY INSPECTION RESULTS -- PASSENGER VEHICLE

NO REJECTED OR CORRECTED SAFETY ITEMS FOR THIS VEHICLE

THANK YOU

New Hampshire vehicles are safer because potentially dangerous defects are found during our annual inspections.
Tip - Properly inflated tires and regular maintenance can save you money, and keep your vehicle running longer and cleaner.

*** Concerns or questions regarding this state inspection, or the practices of inspection stations, may be referred to the ***
New Hampshire Department of Motor Vehicles at dealerandinspection@dos.nh.gov or 603-223-8911.

MECHANIC NOTES AND MEASUREMENTS

NO NOTES

I do hereby certify that all information I have provided the department is accurate and complete. This report is signed under penalty of unsworn falsification pursuant to RSA 641:3.


MECHANIC SIGNATURE

*** KEEP THIS COPY IN YOUR VEHICLE ***

State of New Hampshire

REGISTRATION CERTIFICATE 0904A0540213

Registration certificate not valid for title purposes. All resident taxes for which I am liable have been paid.

PLATE 4019123 TYPE PASS CD 8 VSN 1280374 GVW 2500
MAKE ALFA MODEL 115 BDY STL 2DSED CLR GRN
YEAR 1973 F G AXLES 2 LP NEW 25000 VIN AR3041765
PP# PP TYPE SP# SP TYPE

E
X
P
11/30/2026



N.H.S.D. - M.V.
OFFICIAL DIRECTOR
VALIDATION # 2287

RETAIN FOR TAX PURPOSES	
STATE FEES	
REGISTRATION	\$31.20
STATE PARK PLATE	\$0.00
TITLE	\$0.00
TOTAL FEES	\$31.20
MUNICIPAL FEES	
MOSMILLS 12 3	\$75.00
MOSMILLS 0 0	\$0.00
PERMIT FEE	\$75.00
AGENT	\$3.00
CLERK	\$2.00
LOCAL TITLE	\$0.00
TRANSFER	\$0.00
TRANSFER CREDIT	\$0.00
WASTE	\$3.00
TRANSPORTATION	\$5.00
TOTAL FEES	\$88.00
GRAND TOTAL FEES	\$ 119.20
MUNICIPAL COMMENT: Receipt: 790069;	
Pursuant to RSA 261:55, the Director must be notified in writing within 30 days when moving from the address printed on the registration certificate.	

O
W
N
E
R
S



RENEW REGISTRATION

23OCT2025 5034.0002 0904 8649 1 \$31.20



NOT VALID WITHOUT DIRECTOR'S SEAL

ATTENTION:

RSA 266:1 IV provides that newly registered vehicles and vehicles of which the ownership has been transferred must be inspected within 10 consecutive days of the registration date stamped on the registration certificate. If a new vehicle is purchased at retail from a licensed dealer the vehicle must be inspected no later than 20 days after the date of transfer.

LEGAL ADDRESS
9 BROWNING DR
DOVER NH
03820

For Commercial Motor Vehicles Only:
By signing this form, I certify knowledge of applicable federal and state motor carrier safety regulations and laws as adopted by the State of New Hampshire.

X

(THIS APPLICATION IS SIGNED AND ANY ADDITIONAL INFORMATION IS OFFERED UNDER PENALTY OF UNSWORN FALSIFICATION PURSUANT TO RSA 641:3)

RDMV 344 (REV 08/18)

OWNER'S COPY

AC ID NH 09 23

NEW HAMPSHIRE INSURANCE CARD

INSURANCE COMPANY: ESSENTIA INSURANCE COMPANY

NAMED INSURED:



EFFECTIVE:

09/26/2025

EXPIRATION:

09/26/2026

YEAR: 1973

MAKE: ALFA ROMEO

MODEL: 2000 SPIDER VELOCE

VEHICLE ID NUMBER: AR3041765

AC ID NH 09 23