

NEILS AUTOMOTIVE REPAIR

810 PLEASANT VALLEY ROAD
 DIAMOND SPRINGS, CA 95619
 (530)-626-3203
 WWW.NEILSAUTOMOTIVE.COM
 BAR# ARD297267
 EPA ID#CAL00231546

Customer		Acct: 12205		License 566662L3	VIN 1GCE514H45B117453	Year 2005
[REDACTED]		Make CHEVROLET		Model SSR		
		Engine 6.0L		Transmission M/T		
In	Mileage	Out	Fleet #	P.O. Number		
		98818				
Prod Date 10/04	CAT EO	CAT #	EFN#	FED/CA	Written By:	

Problem Statements

SMOG INSPECTION BIENNIAL

Recommended Services

Date	Mileage	Description

Labor Operations

Tech	Type	Description	Price
2	Lab	SET TIRE PRESSURE TO SPECS __30__ FRONT __30__ REAR AND PERFORM BIENNIAL SMOG INSPECTION	\$115.00
	Lab	YOU ARE NOT OBLIGATED TO HAVE THIS SHOP REPAIR YOUR CAR IF IT FAILS SMOG	\$0.00
	Lab	SMOG INSPECTION-PASSED	\$0.00
	Lab	THANK YOU FOR YOUR BUSINESS	\$0.00
Labor Total			\$115.00

Parts

Part Description	Status	Qty	Price Ea.	Total
STATE CERTIFICATE	N	1.00	\$8.25	\$8.25

TOTAL 244.66

BY L
 CHECK
 ADJUST
 ARE NE
 INSPECT

TOTAL

★ CODE N-NEW U-USED R-REBUILT M-OEM

QTY	PART NO. OR DESCRIPTION	SALE
	1 IN COOLANT REC TANK (SYRGE TANK)	8490
	1 P TANK CAP	1770
	1 P GAL. DEXCOOLANT	1980

Anderson Automotive

2972 Anderson Way
Placerville, CA 95667
(530) 622-0446

BAR - ARD00223021 / EPA CAL000255886

Date: 10-30-2023 28326

Time Received	OPERATION	LAB. CHG.
<input type="checkbox"/> A.M.	Lubrication <input type="checkbox"/>	
<input type="checkbox"/> P.M.	Change Oil <input type="checkbox"/>	
Written By	Change Oil Filter Cart <input type="checkbox"/>	
Cust. Order No.	Service Air Cleaner <input type="checkbox"/>	
Phone when ready	Change Trans. Oil <input type="checkbox"/>	
Yes <input type="checkbox"/> No <input type="checkbox"/>	Adjust Transmission <input type="checkbox"/>	
Hazardous Waste <input type="checkbox"/>	Pack Front Wheel Brgs. <input type="checkbox"/>	
Res. <input type="checkbox"/>	Rotate Tires <input type="checkbox"/>	
Adjust Brakes <input type="checkbox"/>	Retain Parts <input type="checkbox"/>	
Destroy Parts <input type="checkbox"/>		

Name: [REDACTED]
Address: [REDACTED]
Vin. No.: [REDACTED]

Year-Make-Model: 05 Chevrolet SSR License # 514223 (9794)

ESTIMATE AMT. [REDACTED]

ADD'L AUTH. AMT. [REDACTED]

REVISED ESTIMATE [REDACTED]

DATE: [REDACTED] APPROVED BY: [REDACTED]

TIME: [REDACTED] IN PERSON PHONE

I hereby authorize the repair work below to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on this car, truck or vehicle to secure the amount of repairs thereon. You will not be responsible for loss or damage to vehicle or articles left in vehicle in case of theft, accident or any other cause beyond your control.

Authorized By: J.B. Mast (SIGNATURE OR INITIALS)

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE

Qalt

INSPECT FOR LEAKS
FOUND CRACK IN SYRGE TANK
REPLACE TANK & CAP

HA 112

Tire pressure @ 34 PSI

MATERIALS AND SUPPLIES	
TOTAL PARTS	122.55

QTY.	SALE	BILLING	TEAR-DOWN ESTIMATE - PARTS AND LABOR
GALS. GAS		<input type="checkbox"/> CASH	ORIGINAL ESTIMATES
QTS. OIL		<input type="checkbox"/> CHARGE	AUTHORIZED BY
LBS. GREASE		<input type="checkbox"/> INTERNAL OK'D BY	DATE
TOTAL GAS OIL GREASE			TIME
			REVISED ESTIMATES
			REASON
			ADDITIONAL
			AUTHORIZED BY

Total Labor	112
Hazardous Waste Disposal	
Special Repairs	
Parts	122.55
Tires	
Gas, Oil & Grease	
Paint & Body	

BY LAW, YOU MAY CHOOSE ANOTHER LICENSED SMOG CHECK FACILITY TO PERFORM ANY NEEDED REPAIRS OR ADJUSTMENTS THAT THE SMOG CHECK TEST INDICATES WILL BE CHARGED FOR

★ CODE N-NEW U-USED R-REBUILT M-OEM

QTY	PART NO. OR DESCRIPTION	SALE
4 N	Std Dex III ATF	23.80
2 N	Rear Sway Bar link ends	86.95
		173.90
1 N	Brake Fluid	10.00
2 N	Degreaser	13.90
1 P	SERP BELT # 60938	61.75
1 P	A/C BELT # 4034	36.14
1 N	BELT TENSIONER SERP.	81.14
1 P	A/C Pulley	44.27
MATERIALS AND SUPPLIES		
TOTAL PARTS		444.87

BY LAW, YOU MAY CHOOSE ANOTHER LICENSED SMOG CHECK FACILITY TO PERFORM ANY NEEDED REPAIRS OR ADJUSTMENTS THAT THE SMOG CHECK TEST INDICATES ARE NECESSARY. A CUSTOMER WILL BE CHARGED FOR INSPECTION REGARDLESS OF PASS OR FAIL


SPECIAL REPAIRS

Anderson Automotive

2972 Anderson Way
Placerville, CA 95667
(530) 622-0446
BAR - ARD00223021 / EPA CAL000255886

Date: 8/12/21

027944



Year/Make/Model: 03 Chevy SSR License No: 30029F3 Odometer: 94197
 ESTIMATE AMT. 200
 ADD'L AUTH. AMT.
 REVISED ESTIMATE
 DATE: APPROVED BY: [Signature]
 TIME: IN PERSON PHONE
 I acknowledge NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE
 AUTHORIZED BY: B. Mautin (SIGNATURE OR INITIALS)

OPERATION	LAB. CHG.
Lubrication <input type="checkbox"/>	
Change Oil <input type="checkbox"/>	
Change Oil Filter Cart. <input type="checkbox"/>	
Service Air Cleaner <input type="checkbox"/>	
Change Trans. Oil <input type="checkbox"/>	
Adjust Transmission <input type="checkbox"/>	
Hazardous Waste <input checked="" type="checkbox"/>	3.00
Rack Front Wheel Brge <input type="checkbox"/>	
Rotate Tires <input type="checkbox"/>	
Adjust Brakes <input type="checkbox"/>	
Retain Parts <input type="checkbox"/>	
Destroy Parts <input type="checkbox"/>	

OPER. NO.	REPAIR ORDER LABOR INSTRUCTION	INTERNAL
	Replace customer supplied Rear Coil Springs, Shocks and Bump Stops	1.5hr 168.00
	Replace Rear Sway Bar link ends	1.1 125.00
	Drain and Fill Manual Transmission	.5 56.00
	Replace Brake Fluid in Brake and Clutch Systems	1.5 168.00
	REPLACE SERP. BELT, A/C BELT, MAIN BELT TENSIONER AND A/C TENSIONER PULLEY	1.5hr 168.00
	INSPECT AND ADJUST - PARKING BRAKE	1HR 112.00
	Tire pressure @ 33 psi	

QTY.	SALE	BILLING	TEARDOWN ESTIMATE - PARTS AND LABOR	Total Labor
GALS. GAS		<input type="checkbox"/> CASH	ORIGINAL ESTIMATES	797.00
QTS. OIL		<input type="checkbox"/> CHARGE	AUTHORIZED BY	Hazardous Waste Disposal 3.00
LBS. GREASE		<input type="checkbox"/> INTERNAL	PHONE DATE TIME	Special Repairs
TOTAL GAS OIL GREASE		OK'D BY	REVISED ESTIMATES REASON	Parts 444.87
RECOMMENDED SERVICE:		ADDITIONAL COSTS	AUTHORIZED BY	Tires
1.		IN PERSON	DATE TIME	Gas, Oil & Grease
2.		PHONE #		Paint & Body Shop
3.		TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within _____ days of the date shown above if I choose not to authorize the services recommended.		Sales Tax 36.70
4.				

PNP # 1634



Sierra Nevada Tire & Wheel - Placerville

659 Main St.
Placerville, CA 95667
Store: 530-622-4714 Fax: 530-622-5345
EPA: CAL000382093 B.A.R.: ARD00271713

Customer Copy

Invoice #507602

Tuesday, August 17, 2021
1:13:18 PM

Ordered on
Monday, August 16, 2021

Workorder # 528176

MAKE & MODEL		FLEET NO.	PHONE	REP	CSH	PO #	TERMS		
2005 Chevrolet Ssr Base			530-642-2463	Chris M Moor	JC		Cash		
LICENSE NO.	MILES IN/OUT	VIN	TORQUE	ENGINE SIZE	TRANSMISSION	COLOR	PRD DATE		
30029F3	94219	1GCES14H45B117453		6.0L V8 F OHV					
CATALOG	DESCRIPTION		QTY	PARTS	LABOR	DISC	FET	TOTAL	Code


LABF Labor - Front end Work -INSPECT FRONT END 1 .00 \$0.00
 WAS TOLD FRONT CONTROL ARM BUSHING ARE BAD
 HAS CUSTOMER HAS FRONT SHOCKS - WOULD LIKE INSTALLED TOO
 INSPECT AND QUOTE
 CUTSOMER SPECS FOR ALIGNMENT

FOUND RIGHT FRONT UPPER CONTROL ARM BUSHINGS COMPLETLEY WORN OUT. LOWER CONTROL ARM BUSHING TORN WITH LOTS OF MOVEMENT. CUSTOMER REQUEST FOR US TO REPLACE FRONT STRUTS. QUOTE FOR REPAIRS, CUSTOMER REQUEST AND ALIGNMENT \$1,086+TAX
 called and authorized \$1,085.00 for the following with Timothy Goehring on 8/16/2021, 9:00 AM

OP	K200269 MOO UPPER CONTROL ARM BUSHING	2	35.95					\$71.90	CM
LABM	REMOVE AND REPLACE UPPER CONTROL ARM BUSINGS	1		270.00				\$270.00	
OP	RK641134 MOO LEFT FRONT LOWER CONTROL ARM BRACKET	1	122.95					\$122.95	CM
OP	RK641135 MOO RIGHT FRONT LOWER CONTROL ARM BRACKET	1	122.95					\$122.95	CM
LABM	REMOVE AND REPLACE BOTH FRONT LOWER CONTROL ARM BRACKETS	1		250.00				\$250.00	
CSP	****CUSTOMER SUPPLIED PARTS. NO WARRANTY ON CUSTOMER SUPPLIED PARTS/LABOR**** CUSTOMER PROVIDED LOWERING STRUTS	2		.00				\$0.00	CM
LABM	REMOVE AND REPLACE BOTH FRONT STRUTS	1		160.00				\$160.00	


Welcome, We appreciate your business.

PAID BY
VISA-M/C \$1,113.97 ,*****3486
A#007837



Parts	\$317.80	Taxable	\$317.80
Labor	\$769.95	Non-Taxable	\$769.95
Freight	\$0.00	Local Sale Tax 8.25	\$26.22
Other	\$0.00		
FET	\$0.00		

TOTAL \$1,113.97



3844 E. Tanglewood Drive
Phoenix, AZ 85048


Customer Note: 2005,yellow,six
speed.117453




Quantity	SKU	Product	Price	Total Price
1	SE-10386222	10386222 Rear Bump Stop for Lowered SSRs supplier :	\$41.00	\$41.00
1	SE-ALHS	Anti-lock Brake Heat Shield supplier :	\$26.00	\$26.00
1	BIL-24-286725	Bilstein "Sport" Shock Absorbers (rear pair) supplier :	\$152.00	\$152.00
1	15765071	GM 15765071 Rear Spring Isolator supplier :	\$19.50	\$19.50
1	SE-RLS	SSR Rear Lowering Springs supplier :	\$185.00	\$185.00
1	DL-VTR3	Vinyl Tag "Close Lid First" supplier :	\$2.00	\$2.00
			Subtotal	\$425.50 (incl. tax)
			Shipping	\$86.05 via Continental US
			Payment Method	Credit Card
			Total	\$511.55

Handwritten notes in red and green ink:
- Red lines connect the quantity '1' in the first five rows to a bracket on the left.
- A green circle highlights the Bilstein row.
- "THIS BOX" is written in green next to the GM 15765071 row.
- "SHIPPING SEPARATELY" is written in red at the bottom left.

For more information on this order, contact us immediately: Phone: 480-225-2123 or E-mail: mike@simple-engineering.com




3844 E. Tanglewood Drive
Phoenix, AZ 85048



Quantity	SKU	Product	Price	Total Price
1	SE-HES-CF	SSR Hood Emblem Support - Carbon Fiber	\$140.00	\$140.00
			Subtotal	\$140.00 (incl. tax)
			Shipping	\$15.57 via Continental US
			Payment Method	Credit Card
			Total	\$155.57

If you have any questions concerning this order, contact us immediately: Phone: 480-225-2123 or E-mail: mike@simple-engineering.com

www.simple-engineering.com and thanks for being part of the SSR family!




3844 E. Tanglewood Drive
Phoenix, AZ 85048



Quantity	SKU	Product	Price	Total Price
1	SE-RCMBR	SSR 4-bolt Rear Crossmember	\$110.00	\$110.00
			Subtotal	\$110.00 (incl. tax)
			Shipping	\$38.78 via Continental US
			Payment Method	Credit Card
			Total	\$148.78

If you have any questions concerning this order, contact us immediately: Phone: 480-225-2123 or E-mail: mike@simple-engineering.com

Visit us at <https://simple-engineering.com> and thanks for being part of the SSR family!



3844 E. Tanglewood Drive
Phoenix, AZ 85048

Customer Note: 2005,yellow,six
speed.117453



Quantity	SKU	Product	Price	Total Price
1	SE-10386222	10386222 Rear Bump Stop for Lowered SSRs	\$41.00	\$41.00
1	SE-ALHS	Anti-lock Brake Heat Shield	\$26.00	\$26.00
1	BIL-24-286725	Bilstein "Sport" Shock Absorbers (rear pair)	\$152.00	\$152.00
1	15765071	GM 15765071 Rear Spring Isolator	\$19.50	\$19.50
1	SE-RLS	SSR Rear Lowering Springs	\$185.00	\$185.00
1	DL-VTR3	Vinyl Tag "Close Lid First"	\$2.00	\$2.00
			Subtotal	\$425.50 (incl. tax)
			Shipping	\$86.05 via Continental US
			Payment Method	Credit Card
			Total	\$511.55

THIS BOX

SHIPPING SEPARATELY