

1.00	59.00	59.00
1.00	49.00	49.00
1.00	309.00	309.00
1.00	154.00	154.00
1.00	121.00	121.00
1.00	4.00	4.00
3.00	20.00	60.00
1.00	209.00	209.00
1.00	49.00	49.00
1.00	39.00	39.00
1.00	22.00	22.00
1.00	4.00	4.00
1.00	199.00	199.00
		27.86

mechanical fan, belts, water pump, thermostat, clutch. All need to be replaced. Flush balance of system. During disassembly we found extremely worn serpentine system. Belt tensioner, idler and belts need to be replaced. Reassemble all components listed above. Bleed air from the cooling system.

Road Test

n/c

**[ Recommendations ]**

While we were recently servicing your vehicle we noticed some additional item(s) that will need attention soon:

- 2.) Front Brake Calipers Will Need Replaced When Front Brakes Expire.
- Next State Inspection Required by 05-31-2026

work to be done along with the necessary material and hereby grant you and/or your car or truck herein described on street, highways or elsewhere for the purpose to testing mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs one years or 12,000 miles whichever comes first. Warranty work has to be performed in cost of repair.

Labor:	763.00
Parts:	1,626.86
Sub:	2,389.86
Tax:	143.39
Total:	\$2,533.25
Bal Due:	\$2,533.25

Customer Number : 381

Date \_\_\_\_\_

Email Address: [jacksautoandaero@gmail.com](mailto:jacksautoandaero@gmail.com)

BMW Coolant Temperature Sensor	1.00	4.00	4.00
O-Ring			
Pentosin Engine Coolant	3.00	20.00	60.00
Ina belt tensioner	1.00	209.00	209.00
INA Idler Pulley	1.00	49.00	49.00
Continental Serpentine Belt	1.00	39.00	39.00
Continental A/C Belt	1.00	22.00	22.00
BMW pulley cap	1.00	4.00	4.00
Behr Fan Clutch	1.00	199.00	199.00
Shop Supplies			27.86

**[ Recommendations ]**  
 While we were recently se  
 additional item(s) that will

2.) Front Brake Calipers V  
 Expire.  
 Next State Inspection Re

[ Payments - ]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount due. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be done at our shop & cannot exceed the original cost of repair.

Vehicle Received: 5/7/2025

Signature \_\_\_\_\_ Date \_\_\_\_\_

Visit us on the web: [www.jacksautoandaero.com](http://www.jacksautoandaero.com)

Email Address: [jacksautoandaero.com](mailto:jacksautoandaero.com)

Service Advisor : Price, Jackie, Tech :

Page 1 of 1

Copyright (c) 2002

2.00 MMG INSURANCE COMPANY  
 63.00 Policy: AC12312458 - Exp Date: 7/1/2025  
 15.00 Brakes: LF(12B) LR(7B) RF(12B) RR(7B)  
 222.00 Tires: LF(9) LR(7) RF(9) RR(7)  
 Previous Odometer: 106475  
 7.86 PA Emissions Inspection 43.00  
 Oil Service 49.50  
 Tire Rotation 49.50  
 Customer States HVAC Blower Fan Intermittently 109.00  
 Fluctuates Speed.  
 Removed Passenger Side Under Dash Pane And Carpeted Center  
 Console Trim. Removed And Replaced HVAC Blower Motor Final  
 Stage Resistor. Reassemble  
 Road Test n/c

**[ Recommendations ]**

While we were recently servicing your vehicle we noticed some additional item(s) that will need attention soon:

- 1.) Cooling System Before Summer.
  - 2.) Front Brake Calipers Will Need Replaced When Front Brakes Expire.
- Next State Inspection Required by 05-31-2026

I have provided the necessary material and hereby grant you and/or your agent the right to use the vehicle on street, highways or elsewhere for the purpose to testing and inspection. I have edged on above car or truck to secure the amount of repairs and parts which ever comes first. Warranty work has to be performed in

Labor:	277.00
Parts:	322.43
Sub:	599.43
Tax:	35.97
Total:	\$635.40
Bal Due:	\$635.40

Customer Number : 381

Date \_\_\_\_\_

Shop Supplies

7.86

Previous Odometer  
 PA Emissions Inspection  
 Oil Service  
 Tire Rotation  
 Customer States HVAC  
 Fluctuates Speed.  
 Removed Passenger  
 Console Trim. Remo  
 Stage Resistor. Reas  
 Road Test

[ Recommendations ]

While we were recent  
additional item(s) the

- 1.) Cooling System F
  - 2.) Front Brake Calip
- Expire.  
Next State Inspecti

[ Payments - ]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you  
 employees permission to operate the car or truck herein described on street, highways or elsewhere for the  
 and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the  
 thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work h  
 our shop & cannot exceed the original cost of repair.

Vehicle Received: 5/2/2025

Signature \_\_\_\_\_

Date \_\_\_\_\_

Visit us on the web: [www.jacksautoandaero.com](http://www.jacksautoandaero.com)

Service Advisor: Miller, Marshall Tech

Email Address: [jacksautoan](mailto:jacksautoan)