


\*\*\* INVOICE \*\*\*



SD Tire & Wheel Miramar  
 5880 Miramar Rd.  
 San Diego, CA 92121  
 858-642-0655



Invoice #: 77461

Bill To:

[Redacted Bill To information]

Unit #: [Blank]  
 Vehicle: 2012 BENTLEY CONTINENTAL  
 GT  
 License: 8WAB202 / CA  
 Mileage: In: 18725 / Out: 18725  
 VIN #: SCBFR7ZAXCC071149  
 Torque: 107  
 Air Prs: 49.0 F / 46.0 R

Item #	Size	Description	Slmn/Tech	Qty	FET	Parts	Labor	Extended
23289	255/30R22	MICHELIN PILOT SPORT 4 S [BW] [95] [(Y)] [XL]	SN /TL	2	0.00	531.00	0.00	1062.00
19577	295/25R22	MICHELIN PILOT SPORT 4 S [BW] [97] [(Y)] [XL]	SN /TL	2	0.00	480.00	0.00	960.00
MB	MB	MOUNT & BALANCE	SN /TL	4	0.00	0.00	19.50	78.00
RBF	RBF	FREE LIFETIME TIRE ROTATION, WHEEL BALANCING & FLAT REPAIRS	SN /TL	4	0.00	0.00	0.00	0.00
24ROAD	ROADSIDE	24HR ROADSIDE ASSISTANCE, UP TO \$100.00 REIMBURSEMENT VALID FOR 1 YR FROM THE DATE ON INVOICE. CALL 855-429-2791 TO SCHEDULE SERVICE PROVIDER.	SN /TL	1	0.00	0.00	0.00	0.00
TDF	TDF	CA TIRE DISPOSAL FEE	SN /TL	4	0.00	3.00	0.00	12.00
SD		*** SPECIAL DISCOUNT GIVEN ***	SN /	1	0.00	-100.00	0.00	-100.00
JOB		EXOTIC VEHICLE ALIGNMENT	SN /TL	1	0.00	0.00	180.00	180.00
AEV	ALIGN	4- WHEEL EXOTIC VEHICLE ALIGNMENT	SN /TL	1				

NOTE: ALIGNMENT INCLUDES 30- DAY GUARANTEE  
 NOTE: CUSTOMER CONCERN:

Comments:

THANK YOU FOR YOUR BUSINESS!


All Tire Warranties are Prorated. Staggered Fitment Tires Mileage Warranty is 50% of stated amount per Mfr guidelines. Rotate Car Tires every 6000 miles. We Rotate Tires, Re-balance, and Fix Flats for Free with All New Tire and/or Wheel Purchases. Maintain Proper Air Pressure OR Warranty will be Void. Tire Damage due to low Air Pressure or Driving on a Deflated/Flat Tire will Void Warranty. Warranty Does Not Cover Damage done to the Sides of the tire, such as side impacts, cuts, bubbles, nails, etc. Tire Warranty does not cover road hazard or Vandalism. Tires and Wheels Left over 7 Days will be disposed of. Uneven/Improper wear on Tires Due to Alignment not covered under Tire Warranty. Commercial/Fleet Vehicles Not Covered under Mileage Warranty. Manufacture Warranty on Chrome Wheels is 1 year, Use only Soap & Water to Clean. Any Chemical Use on Chrome Wheels Voids Warranty. No Refunds on installed Tires and or Wheels, and Discontinued Items . 20% Cancellation fee on all special orders. All returns are subject to 15% Restock fee. Any Deposits are subject to forfeit if Canceled.

Cash:	0.00	Check:	0.00	Name Acct Auth Amount	Parts:	1934.00
Credit Card:	2355.71	On Acct:	0.00	Visa 4138 03831G 2355.71	Labor:	258.00
					Subtotal:	2192.00
Amount Tended:	\$2355.71				CA Tire Fee(ST):	7.00
Total:	- \$2355.71				Sales Tax:	156.71
Change:	\$0.00					

Total: \$2355.71

Customer Authorization:

\*\*\* INVOICE \*\*\*



SD Tire & Wheel Miramar  
 5880 Miramar Rd.  
 San Diego, CA 92121  
 858-642-0655



Invoice #: 82506

Bill To:  
 [Redacted]  
 [Redacted]

Unit #: 2012 BENTLEY CONTINENTAL  
 Vehicle: GT  
 License: 8WAB202 / CA  
 Mileage: In: 19756 / Out: 19756  
 VIN #: SCBFR7ZAXCC071149  
 Torque: 107  
 Air Prs: 49.0 F / 46.0 R

Item #	Size	Description	Slmn/Tech	Qty	FET	Parts	Labor	Extended
UVS7050	TPMS	UVS7050 UVS7055 HUF PROGRAMMABLE TPMS SENSOR DUAL BAND (MADE IN GERMANY)	BF /AD	1	0.00	57.50	0.00	57.50
JOB		TPMS TRANSFER AND REBUILD	BF /AD	1	0.00	0.00	15.00	15.00
							JOB SUBTOTAL:	15.00
JOB LF	LF	LEFT FRONT SERVICE LEFT FRONT	BF /AD	1	0.00	0.00	0.00	0.00
							JOB SUBTOTAL:	0.00

Comments:  
 THANK YOU FOR YOUR BUSINESS!

All Tire Warranties are Prorated. Staggered Fitment Tires Mileage Warranty is 50% of stated amount per Mfr guidelines. Rotate Car Tires every 6000 miles. We Rotate Tires, Re-balance, and Fix Flats for Free with All New Tire and/or Wheel Purchases. Maintain Proper Air Pressure OR Warranty will be Void. Tire Damage due to low Air Pressure or Driving on A Deflated/Flat Tire will Void Warranty. Warranty Does Not Cover Damage done to the Sides of the tire, such as side impacts, cuts, bubbles, nails, etc. Tire Warranty does not cover road hazard or Vandalism. Tires and Wheels Left over 7 Days will be disposed of. Uneven/Improper wear on Tires Due to Alignment not covered under Tire Warranty. Commercial/Fleet Vehicles Not Covered under Mileage Warranty. Manufacture Warranty on Chrome Wheels is 1 year, Use only Soap & Water to Clean. Any Chemical Use on Chrome Wheels Voids Warranty. No Refunds on installed Tires and or Wheels, and Discontinued Items . 20% Cancellation fee on all special orders. All returns are subject to 15% Restock fee. Any Deposits are subject to forfeit if Canceled.

Cash:	0.00	Check:	0.00
Credit Card:	76.96	On Acct:	0.00
Amount Tendered:		\$76.96	
Total:		-\$76.96	
Change:		\$0.00	

Name	Acct	Auth	Amount
Visa	9910	03083D	76.96

Parts:	57.50
Labor:	15.00
Subtotal:	72.50
Sales Tax:	4.46
<b>Total:</b>	<b>\$76.96</b>

Customer Authorization:



David Nutley Automotive  
 BAR Registration No. ARD298541  
 EPA Identification No. CAL000461491  
 5155 Convoy Street, Suite B  
 San Diego, CA 92111  
 (858) 774-4734  
 admin@dn-automotive.com

## Estimate #1863

Created: 3/7/2023 08:33 AM PST  
 Payment Term: On Receipt  
 Service Writer: Erika Smith

### 2012 BENTLEY Continental GT (White)

VIN: SCBFR7ZAXCC071149  
 License Plate: 8WAB202  
 Mileage: 18,958

Customer Comments	Recommendations
First visit general inspection Annual maintenance light on. Last serviced was March 2022 temp sensor not reading accurately clock not working garage door remote isn't working Drivers soft close Headliner leather is detached	ambient temp sensor missing, plug is intact behind bumper. recommend adding a sensor and routing to the correct location behind grill Engine oil change due, was brake fluid replaced in last 2 years? lower bumper to under shield hardware missing, 8 t25 screws in total

Check for needed service					
	Description	Price	QTY	HRS	Subtotal
1	Perform engine oil and brake fluid exchange. Reset service interval data			2.5	\$487.50
2	Mobil1 0w40	\$14.41	14		\$201.74
3	Oil filter Part #: 07C115562E	\$39.24	1		\$39.24
4	Drain plug Part #: N90813202 Note: W12	\$14.72	1		\$14.72
5	ATE SL Brake fluid Part #: 705802 Note: ATE Brake fluid	\$16.63	2		\$33.26
6	Undersheet screw GT Part #: N90974701	\$1.82	2		\$3.64
7	Key battery Part #: CR2032 Duracell Advanced long life	\$6.95	1		\$6.95
8	Hazardous waste disposal fee				\$4.00
9	Wiper blade Part #: 3W1955425D	\$88.18	2		\$176.36
				Tax (7.75%):	\$36.88
				<b>Total:</b>	<b>\$1,004.29</b>

Garage remote is not working

Need to discuss further this repair

Description	Subtotal
	Total: \$0.00

Driver door soft close is no longer operating



**David Nutley Automotive**  
 BAR Registration No. ARD298541  
 EPA Identification No. CAL000461491  
 5155 Convoy Street, Suite B  
 San Diego, CA 92111  
 (858) 774-4734  
 admin@dn-automotive.com

## Estimate #1863

Created: 3/7/2023 08:33 AM PST  
 Payment Term: On Receipt  
 Service Writer: Erika Smith

Driver door soft close is no longer operating					
Description	Price	QTY	HRS	Subtotal	
1 Replace drivers door latch to correct issue with soft close feature			2.5	\$487.50	
2 LH door latch Part #: 3D1837015AL	\$394.86	1		\$394.86	
			Tax (7.75%): \$30.60		<b>Total: \$912.96</b>

Remove and refit headliner for repair of detached leather covering					
Estimate for repair of headliner assembly					
Description	Price	QTY	HRS	Subtotal	
1 Remove and refit headliner for repair			5	\$975.00	
2 Repair/remove and reaffix leather on headliner.	\$995.00			\$995.00	
					<b>Total: \$1,970.00</b>

Estimates provided are an approximation of timing and charges to you for the services requested. They are based on the anticipated work to be done. It is possible for unexpected complications to cause some deviation from the original quote. You hereby authorize the repair work described in this estimate to be done along with the procurement of the necessary material(s), including permission to operate the vehicle for on-road testing or inspection. If any additional repairs are required, we will prepare a revised work order providing the cost of additional parts and labor and total revised cost. All parts are new unless specified otherwise.

Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts. There is no warranty for used parts of customer supplied parts.

You agree that we are not responsible for loss or damage to your vehicle, including loss of articles left in the vehicle, including, without limitation, in case of fire, theft, or any other cause(s) beyond our control.

### Totals only include authorized services

Parts .....	\$870.77
Labor .....	\$1,950.00
Subcontract .....	\$995.00
Subtotal .....	\$3,819.77
Fees .....	\$4.00
Tax .....	\$67.48
<b>Grand Total .....</b>	<b>\$3,887.25</b>
Paid To Date .....	(\$0.00)
<b>REMAINING BALANCE</b>	<b>\$3,887.25</b>

We are not responsible for any delays caused by unavailability of parts or delays in delivery of parts by the supplier or transporter. You have the right to know before authorizing any additional repairs what those repairs will be and what they will cost. If required repairs exceed the authorized estimated amount, we must obtain your approval to perform the repairs. We will keep you informed and perform only repairs authorized by you.

Signature \_\_\_\_\_

Authorizations		
Text by [redacted] 3/7/2023 at 6:21 PM PST	+ Check for needed service + Remove and refit headliner for repair of detached leather covering	\$3,685.82 +\$1,970.00
In App by [redacted] 3/7/2023 at 6:21 PM PST	+ Check for needed service + Garage remote is not working + Driver door soft close is no	\$1,423.32



David Nutley Automotive  
 BAR Registration No. ARD298541  
 EPA Identification No. CAL000461491  
 5155 Convoy Street, Suite B  
 San Diego, CA 92111  
 (858) 774-4734  
 admin@dn-automotive.com

## Estimate #1863

Created: 3/7/2023 08:33 AM PST  
 Payment Term: On Receipt  
 Service Writer: Erika Smith

### Authorizations

longer operating  
 - Outside temp gauge reads high  
 - Clock is not operating

### Declined

#### Outside temp gauge reads high

Description	Price	QTY	HRS	Subtotal
1 Install ambient air temp sensor. Release bumper to access harness to fit correctly.			2	\$390.00
2 Tempo sensor	\$84.26	1		\$84.26
			Tax (7.75%):	\$6.53
			<b>Total:</b>	<b>\$480.79</b>

#### Clock is not operating

Description	Price	QTY	HRS	Subtotal
1 Replace clock if needed after diagnosis			1.5	\$292.50
2 Clock	\$905.61	1		\$905.61
			Tax (7.75%):	\$70.18
			<b>Total:</b>	<b>\$1,268.29</b>



**David Nutley Automotive**  
 BAR Registration No. ARD298541  
 EPA Identification No. CAL000461491  
 5155 Convoy Street, Suite B  
 San Diego, CA 92111  
 (858) 774-4734  
 admin@dn-automotive.com

## Invoice #2404

Created: 3/19/2024 10:15 AM PDT  
 Invoiced: 3/29/2024 01:38 PM PDT  
 Payment Term: On Receipt  
 Service Writer: Erika Smith

### 2012 BENTLEY Continental GT (White)

VIN: SCBFR7ZAXCC071149  
 License Plate: 8WAB202  
 Mileage In: 21,809  
 Mileage Out: 21,811  
 PSI: FL 45 FR 45 RL 40 RR 40

Customer Comments	Recommendations
Annual service Remotes not working/need to be reprogrammed Gearshift dust shield Refer to deferred services Check wheel balance	Driver door seal is torn near sill, recommend replacement. Large battery tested at 397/520 DIN and is 7 years old. Small battery tested 180/280 DIN and is also 7 years old. Recommend replacement of both batteries. Both front lower rear control/thrust arms have popped fluid pockets, recommend replacement. All 4 front upper control arms have bushings that have separated internally, Recommend replacement. Tires are new, recommend alignment after control arm replacement. Engine air filters were very dirty and were replaced during service inspection. The air temp sensor connector is tied back with a sensor missing. Recommend correctly routing harness and installing new sensor.

Outside temp gauge reads high					
Description	Price	QTY	HRS	Subtotal	
1 Install ambient air temp sensor. Release bumper to access harness to fit correctly.			2	\$390.00	
2 Temp sensor Part #: 8Z0 820 535	\$84.26	1		\$84.26	
			Tax (7.75%):	\$6.53	Total: \$480.79

Annual service					
Inspect vehicle. Change engine oil and filter. Test vehicle batteries. Checked fluid levels. Replaced engine air filters. Replace key battery.					
Description	Price	QTY	HRS	Subtotal	
1 Perform annual service. Check and top off all fluids, replace engine air filters, set tire pressures, key battery, check and clear all fault codes in modules and reset service interval monitor			3	\$615.00	
2 Oil filter Part #: 07C115562E	\$39.24	1		\$39.24	
3 0w-40 Liqui Moly Part #: LiquiMoly Synthoil Energy A40, 0w40 Note: Engine oil 0w40	\$14.96	13		\$194.48	
4 Drain plug	\$14.72	1		\$14.72	



David Nutley Automotive  
 BAR Registration No. ARD298541  
 EPA Identification No. CAL000461491  
 5155 Convoy Street, Suite B  
 San Diego, CA 92111  
 (858) 774-4734  
 admin@dn-automotive.com

## Invoice #2404

Created: 3/19/2024 10:15 AM PDT  
 Invoiced: 3/29/2024 01:38 PM PDT  
 Payment Term: On Receipt  
 Service Writer: Erika Smith

Annual service				
	Part #: N90813202 Note: W12			
5	Engine air filter Right Part #: 3W0129620B	\$186.55	1	\$186.55
6	Engine air filter left Part #: 3W0129620C	\$186.55	1	\$186.55
7	Key battery Part #: CR2032 Duracell Advanced long life	\$6.95	1	\$6.95
8	Hazardous waste disposal fee			\$4.00
			Tax (7.75%): \$48.71	Total: \$1,296.20

Dust excluder separated				
	Description	Price	QTY	HRS Subtotal
1	Replace dust excluder			1.5 \$307.50
2	Gear selector slider Part #: 3W1713111J Note: Bentley GT and GTC gear selector dust slider	\$58.52	1	\$58.52
			Tax (7.75%): \$4.54	Total: \$370.56

Batteries are below minimum specification and should be replaced				
	Description	Price	QTY	HRS Subtotal
1	Replace both batteries. Computer work included in service.			1.8 \$369.00
2	Main systems battery Part #: MTX-49/H8	\$289.95	1	\$289.95
3	Starter battery GT/GTC late Part #: 000915105DC	\$215.43	1	\$215.43
			Tax (7.75%): \$39.17	Total: \$913.55

All upper front suspension inner bushings are torn. Lower rear arms inner bushings are leaking out internal fluid				
	Description	Price	QTY	HRS Subtotal
1	Replace all 4 upper control arms and both rear lower arms			7 \$1,435.00
2	Upper front control arm set of 4	\$960.00	1	\$960.00
3	Rear lower arm set of 2	\$800.00	1	\$800.00
4	Single use hardware	\$36.98	1	\$36.98
5	Shipping			\$28.65
			Tax (7.75%): \$139.27	Total: \$3,399.90

### 4 wheel alignment



David Nutley Automotive  
 BAR Registration No. ARD298541  
 EPA Identification No. CAL000461491  
 5155 Convoy Street, Suite B  
 San Diego, CA 92111  
 (858) 774-4734  
 admin@dn-automotive.com

# Invoice #2404

Created: 3/19/2024 10:15 AM PDT  
 Invoiced: 3/29/2024 01:38 PM PDT  
 Payment Term: On Receipt  
 Service Writer: Erika Smith

4 wheel alignment			
	Description	HRS	Subtotal
1	Perform 4 wheel alignment check and adjust. Road test to ensure quality.	2	\$410.00
			<b>Total: \$410.00</b>

3% Merchant fee for credit card usage. Removed if paid by check, debit card or exact cash.			
	Description		Subtotal
1	3% Merchant fee for credit card payment		\$206.13
			<b>Total: \$206.13</b>

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about the work performed on your vehicle.

Signature \_\_\_\_\_

Parts .....	\$3,073.63
Labor .....	\$3,526.50
Subtotal .....	\$6,838.91
Fees .....	\$238.78
Tax .....	\$238.21
<b>Grand Total .....</b>	<b>\$7,077.12</b>
Paid To Date .....	(\$0.00)

**REMAINING BALANCE \$7,077.12**

Authorizations		
Phone by [redacted] 3/21/2024 at 4:22 PM PDT	+ 3% Merchant fee for credit card usage. Removed if paid by check, debit card or exact cash.	\$7,077.12 +\$206.13
Phone by [redacted] 3/21/2024 at 4:18 PM PDT	+ Outside temp gauge reads high + Annual service + Dust excluder separated + Batteries are below minimum specification and should be replaced + All upper front suspension inner bushings are torn. Lower rear arms inner bushings are leaking out internal fluid + 4 wheel alignment	\$7,101.09

David Nutley Automotive  
 5155 Convoy Street, Suite B  
 San Diego, CA 92111  
 (858) 774-4734  
 David@davidnutleyautomotive.com  
 davidnutleyautomotive.com  
 BAR Registration No. ARD298541  
 EPA Identification No. CAL000461491

## Invoice #2942

Created: 04/23/2025 at 11:06AM  
 Invoiced: 04/25/2025 at 11:31AM  
 Payment Term: On Receipt  
 Payment Due: 04/25/2025  
 Service Writer: Erika Smith

2012 BENTLEY Continental GT (White)  
 VIN: SCBFR7ZAXCC071149  
 License Plate: 8WAB202  
 Mileage In: 24,849 mi  
 Mileage Out: 24,850 mi

Customer Comments	Recommendations
Due for service	There are faults in both banks for exhaust temperature signals, nothing were intermittent and were not causing a check engine light. The fault data was cleared.

Vehicle is due for service				
Changed engine oil and filter. Inspected vehicle. Inspected engine air filters, they appear to have been recently replaced. Measured brake fluid moisture content, 0%, OK. Power steering fluid was burnt and the reservoir was drained and refilled, will check again at next service. Checked and tested vehicle batteries, both GOOD. Replaced key battery. Checked and set tire pressures. Checked and topped off fluid levels. Checked all modules for faults and reset, OK. Reset service interval. Test drove vehicle.				
Description	Price	QTY	HRS	Subtotal
Labor: Perform service			2.2	\$484.00
Part: Key battery, AM Part #: PANASONIC 2032 LITHIUM LONG LIFE	\$6.95	1		\$6.95
Part: 0w-40 Liqui Moly Part #: LIQUIMOLY SYNTHOIL ENERGY A40, 0W40 Engine oil 0w40	\$14.96	13		\$194.48
Part: Oil filter W12 Part #: E314H01D58	\$39.24	1		\$39.24
Part: Power steering fluid Part #: LM20038 / CHF11S	\$35.87	0.6		\$21.52
			EPA: \$4.00	Estimated Tax (7.75%): \$20.32
			<b>Total: \$770.51</b>	

3% Merchant fee for credit card usage. Removed if paid by check, debit card or exact cash.	
Description	Subtotal
Fee: 3% Merchant fee for credit card payment	\$23.10
<b>Total: \$23.10</b>	

David Nutley Automotive  
5155 Convoy Street, Suite B  
San Diego, CA 92111  
(858) 774-4734  
David@davidnutleyautomotive.com  
davidnutleyautomotive.com  
BAR Registration No. ARD298541  
EPA Identification No. CAL000461491

## Invoice #2942

Created: 04/23/2025 at 11:06AM  
Invoiced: 04/25/2025 at 11:31AM  
Payment Term: On Receipt  
Payment Due: 04/25/2025  
Service Writer: Erika Smith

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about the work performed on your vehicle.

Signature \_\_\_\_\_

Labor .....	\$484.00
Parts .....	\$262.19
Subtotal .....	\$746.19
EPA .....	\$4.00
Fees .....	\$23.10
Tax .....	\$20.32
<b>Grand Total .....</b>	<b>\$793.61</b>
Paid to Date .....	(\$0.00)

**REMAINING BALANCE \$793.61**

### Appointments

11 am drop off	Bentley Service
Wed 4/23/25	