

TRUCK DIVISION

PAGE 1 OF 1
 REGION CENTRAL
 K A T
 FORT WAYNE PLANT
 103 0151705 001
 YES 103
 LINE SEQUENCE NO 001
 CRO DTW SHIP REQUEST DATE 06/01/78
 JOB NO 480894
 CHRYSLER DATE WRITTEN 06/08/78 R 825
 DATE BUILT DATE SHIPPED

67200

SHIP TO
 INTERNATIONAL HARVESTER CO
 1 IH HILLSIDE, IL
 C/O IH 3705 N 124TH
 BROOKFIELD, WISC

CHASSIS NUMBER
 H0103 HGD46303
 ENGINE NUMBER

SCT II 4X4 TT118HB 06200GVMB H01030300001			
FRAME & BUMPERS	001000	9663	C
HVY DUTY RR STEP BUMPER	001643	9652	
GR-3.73 F&4 FRT AXLE	002044	9657	CHL
FAXLE LOCKO MATIC HUB	002916	9651	0487510C91
RR WHEEL PARKING BRAKE	005007	9654	A
DIESEL DUAL HYD BRK SYS	004010	9660	A
11.75X1.18 DISC W/3.1	004738	9652	
11X2 1/4 W/15/16 WH CYL	004731	9652	
DIESEL SAGINAW SERG GR	005202	9650	
SPORT POWER STEERG WHL	005711	9650	PHL
DRIVE LINE LABOR MTG	006100	9653	
PROP SHAFT	228551	3522	
PROP SHAFT	228461	7260	
DIESEL SGL EXH SYS	007000	9660	
ELECT SYSTEM DIESEL 118W	008000	9685	AGJMQ
DIESEL 12V 40A ALTERN	008156	9650	0 6951
FRT END SHEET MTL NOT	009000	9662	AC
SPEEDOMETER & MISC	010000	9660	CC
SPARE TYRE LOCK	010444	9650	
EXT DECOR WHITE SID PNLS	-010842	9653	B
OFF ROAD TYRE/RIM PACKAG	010964	9650	
CLUTCH CONT 11IN ANG LNK	011216	9655	
633 NISSEN DIESEL	012211	9652	
RAD ASM			0489953C91
10/45 2SPD TRNSFR CASE	013145	9659	0391452C2
T428 TRANS & SP	013428	9655	
GR-3.73 RAY8 REAR AXLE	014018	9660	CF
19G STEEL FUEL TANK	015051	9669	0444421C91
FRT FLR MAT & TRANS CVR	016000	9659	BH
SCOUT BODY W/TRAVEL TOP	016022	9666	CH
DRIVER & PASSENGER SEATS	016709	9673	A
FLOOR MAT RR	PK016726	9653	AB
DELUXE EXT TRIM PKG	016835	9661	C
WEDGWOOD INTERIOR COLOR	016872	9654	B
SLIDE RR QUARTER WINDOW	016893	9653	B
LUGGAGE RACK	-016903	9652	A
FULL WIDTH FOLD RR SEAT	016915	9678	
DELUXE INTERIOR TRIM PKG	016928	9658	B
STORAGE BOX CONSOLE	016959	9652	B
5 STUD WHITE SPOKE DISC	088560	9650	
10-15-B 4PR	885608	0002	
5 STUD WHITE SPOKE DISC	092560	9650	7105080195
10-15-B 4PR	925608	0002	
10-15-B TRACKER RHL	945208	0001	7105080195
PT1 1015TS6787			7105080195
PT3 PAINT INSTR NO 101ST			
PT4 6787 BL SINGLE			
3736787			

	GWR	FRONT	FR-REAR-RR
AXLE-BRK		3,200	3,500
SPRG-AUX		3,100	3,300
TYRE-RIM		3,200	3,200
GAWR-LBS	6,200	3,100	3,100
GAWR-KGS	2,810	1,410	1,410
SUITABLE TYRE FRONT		H078-15 B	
SUITABLE RIM FRONT		15X6.00	

REAR H78-15 B
 REAR 15X6.00
 AT 32 PSI COLD SINGLE AT 32 PSI COLD SINGLE
 JOB NUMBER 480894

VEHICLE BILL
 JUN 27 1978

DANA - 20 model TRANSF2

OK 159 Q

**1978 Scout Traveler
Gen IV 5.3 Vortec LC-9 Engine**

All Fiberglass Body

Purchased Traveler in May of 2018 with a 2 ½ inch Rough Country Lift and a diesel engine. The truck was under powered and so I decided to remove the diesel engine and go with an LS based engine. There are less than 1K miles on the Scout since the LS swap. The LS Kit was purchased from Anything Scout. I then found a great mechanic to complete the swap. The engine was sourced from a 2011 Silverado. The transfer case was rebuilt prior to installation. The 6L80 transmission was also used. I followed up with a rear brake disc conversion also purchased from Anything Scout.

New since May of 2018

Interior

Emergency Brake assembly
Plastic Glove Box
Lokar Tap Shifter
Grant Steering Wheel
Dynamat Soundproofing
Complete Carpet Kit from Stock Interiors
Kenwood Bluetooth Stereo
6X9 Marine Speakers
Door seals
Window guide Kit
Seat belts
Threshold plates
Rear Liftgate Struts
Rear Liftgate Seal
Tuffy Locking Security Console
Dome Light Kit
LED accent lighting
Weathertech Cargo Mat

Exterior

5.3 LC9 Vortec Engine
6L80 6 speed Transmission
Rebuilt NP 241 C Transfer Case
Texas Speed Stage 3 Cam Package
Aluminum Radiator
Electric Fan Kit / w 4 fans
Stainless Steel Headers
Complete 3" Exhaust System
Flowmaster Muffler
Driveshafts and U-Joints
19-gallon poly plastic gas tank
Fuel Pump Kit
Sending Unit
Rear brake disc conversion
Alternator & Starter
Cruise Control
5 BF Goodrich All Terrain T/A
LT45 / 75R16
Air Conditioning Converted to 134A
Steering Joint Complete
Brake Booster & Master Cylinder
Lokar Dipsticks
Trumpet Air Horns



Mustang Dynamometer Test Report

Updates, Documentation & More At
www.MustangDyne.com
Or Call 1-330-963-5400




Trick Tuning & Performance


56959 ELK PARK DR,
ELKHART, INDIANA 46516
Phone: 574 320-3705 / - Fax: /

Date Printed : 2020/07/08
Time Printed : 00:46

Filter Mode : FIR
Filter Value : 70



Test Comments



Channel / Run	Min			Max			Avg		
	1	2	3	1	2	3	1	2	3
Wheel Torque T WC (Ft-)	255			305			287		
Wheel Power T WC (HP)	149			316			239		
AFR Sensor #1 (Ratio)	12.6			13.0			12.7		

4/3/2021

78 International Scout "Lucille" - Google Drive

78 International Scout "Lucille" - Sheet1

A	B	C	D	E	F	G	H	I
AnythingScout	Cost	Other Sources	Source	Cost				
LS Swap Kit*	\$3,270.00	Throttle Pedal Bracket	Anything Scout	\$50.00				
Fuel Pump Kit 255LPH	\$240.00	Engine (7x,xxx Miles)	August Pohl	\$2,067.00				
Exhaust Kit	\$790.00	Trans (7x,xxx Miles)	Veldman's	\$2,274.83				
Electric Fan Kit	\$515.00	T-Case NP241C	Rick's Auto Parts	\$831.00				
Fuel Tank	\$214.00	Harness	PSI	\$1,582.84				
Straps	\$55.00	Fuel Supply Kit	ScoutCo	\$310.00				
J Hooks	\$7.00	Magnaflo Muffler	Summit Racing	\$112.41				
Sending unit	\$59.00	Alternator & Starter	Napa	336.87				
Disc Brake Conversion	\$751.30	Driveshafts	Action Machine	\$633.43				
Rugged Ridge Lights	\$100.00							

Optional Parts	
TSP DOD/VVT Delete	\$366.00
TSP Stg 3 Cam Package	\$840.00
Tune	\$598.00
L62-TB66-Intake-Mani:	\$450.00 < See Notes
L62-SEP-Throttle-Body	\$200.00 < See Notes

Labor	\$3,000.00
"Get it Running" Total	\$16,348.38

Cammed Total	\$1,804.00
--------------	------------

Color Legend
Sourced (Deposit Placed)
Purchased (Not Received)
Received (Inventoried)
Picked Up (Inventoried)
Future Upgrade

Notes: Gen IV Truck manifold and TB are the same size as TBSS intake and TB. Parts NOT needed.

Roger Shuff Deposit

Chris Brown
213 North 7th St
North Webster, IN 46555
Q.brown1771@gmail.com
Friday, January 17, 2023 3:00 PM

Rough Country 2 1/2" Lift

New since 2018
 Plastic Glow Box
 Grant Steering Wheel
 Complete Carpet Kit - from Strak Interiors
 New Ken wood Stereo / Blue-tooth
 New Threshold Plates
 New Window Guides
 Weather Tech Cargo mat
 Tuffy Security Console/w lid strut

Flowmaster Muffler

BF Goodrich All Terrain Tires
 LT45/75R16
 Less than 1K / spare
 American Racing Wheels (Outlaw II)
 Grant Steering Wht
 Re-chromed Bumpers
 Wiper Conversion Kit // Premium Silicone
 Slider Window Latch Kit
 New Door seals
 New Rear Liftgate Struts
 New Rear Lift gate Seal

Veldman's Auto Parts, Inc.
25926 STATE ROAD 2

SOUTH BEND, IN 46619
1 (574) 288-4423



* See reverse side for warranty information.

Reference Number	Date
677054	01/28/20 10:16 AM
PO Number	Customer Number
	1

S O L D T O	OWEN BROWN 410 N TK WAY NORTH WEBSTER, IN 46555 574-275-9717	S H I P T O	CASH SOUTH BEND, IN 46614
----------------------------	---	----------------------------	------------------------------

Salesperson	Order Type	Tax ID/Code	Ship Via	Page
1 - 1 JOE	COUNTER SALE	IN		1

Quantity	Description	Unit Price	Ext Price
1	DEPOSIT W:386913 Invoice for deposit accepted on Work Order #386913	\$2,274.83	\$2,274.83

Notes: SP ORDER ** DOES NOT QUALIFY FOR EXT WARRANTY... NOT INSTALLING IN SAME APPLICATION ** ORDER STK # BB12349

Returns may be subject to 25% restock fee. Thank you!

Payment Totals		Payment Notes:	Totals
Charge			Freight
Cash	\$2,274.83		Discount
Check			Taxable
Credit Card			Non Tax
Debit Card			Total Tax
PayPal			\$0.00
Received by:			Invoice Amt
			\$2,274.83

AUGUST POHL AUTO PARTS
 468 W. FERRY ST
 BERRIEN SPRINGS, MI 49103
 269-471-0440 Fax: 269-471-0454

Reference Number	Date
176753	01/28/20 10:50 AM
PO Number	CustomerNumber
	1

S O L D T O	OWEN BROWN	S H I P T O	CASH
	NORTH WEBSTER, IN 46555		MI

Salesperson	Order Type	Tax ID/Code	Ship Via	Page
I - 1 ERK	DELIVERY TICKET	IN		1

Quantity	Description	Unit Price	Ext Price
1	300-15953 1U-ENGINE ASSEMBLY; Stk# B180; 9.2 VIN# 1GCRKTE31BZ317760; CC:0 ; 5.3L,LC9,GAS,4x4,DNS,ELEC,VIN 3 ; Requested:2011 SILVRD015; SILVERADO 1500 PICKUP 11 5.3L, gasoline, VIN 3 (8th digit, opt LC9); Q:506407	\$1,950.00	\$1,950.00

Notes:

30 DAY PARTS ONLY //20% RESTOCK CHARGE

Please circle Payment Type:		Delivery Date	Totals
Cash			Freight
Check			Discount
Credit Card			Taxable
Debit Card			Non Tax
			Total Tax
			\$1,950.00
			\$0.00
			\$117.00

Received by: _____ Bal Due **\$2,067.00**

Veldman's Auto Parts, Inc.
25926 STATE ROAD 2

SOUTH BEND, IN 46619
1 (574) 288-4423



* See reverse side for warranty information.

Reference Number	Date
486034	01/31/20 08:36 AM
PO Number	Customer Number
	1

S O L D T O	OWEN BROWN 410 N TK WAY NORTH WEBSTER, IN 46555 574-275-9717	S H I P T O	CASH SOUTH BEND, IN 46614	
	Salesperson		Order Type	Tax ID/Code

1 - 1 JOE	DELIVERY TICKET	IN		1
-----------	-----------------	----	--	---

Quantity	Description	Unit Price	Ext Price
1	400-01490 1U-Transmiss, Transaxle PO#25161; 79K MILES 6 MONTH PARTS LABO ; Requested:2012 SILVRDO15; Multiple rows of interchange application apply; Q:710725; W:386913	\$1,869.00	\$1,869.00
1	Core charge W:386913	\$275.00	\$275.00
1	DEPOSIT W:386913 DEPOSIT PAID ON INVOICE NUMBER 677054	(\$2,274.83)	(\$2,274.83)

BEFORE INSTALLING TRANSMISSION, FLUSH ALL LINES. REPLACE FILTER, GASKET AND FRONT PUMP SEAL WITH A NEW ONE. MUST USE MANUFACTURER'S RECOMMENDED FLUID. FAILURE TO DO SO WILL VOID WARRANTY

Notes: M67B ... ** DOES NOT QUALIFY FOR EXT WARRANTY... NOT INSTALLING IN ALIKE APPLICATION **

Returns may be subject to 25% restock fee. Thank you!

Please circle Payment Type:		Delivery Date	Totals
Cash			Freight
Check			Discount
Credit Card			Taxable \$1,869.00
Debit Card			Non Tax (\$1,999.83)
			Total Tax \$130.83
Received by:			Bal Due \$0.00



1847 PRAIRIE AVE - SOUTH BEND, IN 46613
 PHONE (574) 287-9650 - FAX (574) 232-8727
 WWW.ACTIONMACHINEINC.COM

INVOICE

DATE	INVOICE #
5/4/20	85608

BILL TO
OWEN BROWN 275-9717

SHIP TO
OWEN BROWN 275-9717

P.O. NUMBER	TERMS
	Due on receipt

QUANTITY	ITEM NUMBER	DESCRIPTION	PRICE EACH	AMOUNT
1	DS	MFG 1310/1350 SERIES 2-1/2" SHAFT 33" CL U-JOINTS PREMIUM SPICER SEALED U-JOINTS	283.86	283.86
1	SS	MFG 1310 SERIES 3" STEEL SHAFT 1-7/8" SEAL TO CL U-JOINT PICER PREMIUM SEALED U-JOINTS	320.89	320.89

ACTION MACHINE INC
 1847 PRAIRIE AVE
 SOUTH BEND, IN 46613
 574-287-9650

Sale

DRIVESHAFT PARTS & REPAIR
 CNC MACHINING
 MAINTENANCE MACHINING
 WELDING


SUBTOTAL	\$604.75
SALES TAX (7.0%)	\$28.68
TOTAL	\$633.43

RECEIVED BY X

RETURNED GOODS MUST BE ACCOMPANIED BY THIS INVOICE.
 NON-DEFECTIVE RETURNED GOODS WILL BE CHARGED A 20% RESTOCKING FEE.

CHASSIS PARTS		
DESCRIPTION	UNIT PRICE	TOTAL AMOUNT
BA8604 LF Brake Hose		45.00
m1494 Master Cylinder		30.00
shot/misc		10.00
<u>AZ</u>		
54-73 120 Reman Vacuum / Brake Booster		160.00
Spindle Washers /		7.00
Brake Line /		7.00
Spindle Nuts /		40.00
TOTAL PARTS		299.00

COMMENTS TO CUSTOMER



NOT RESPONSIBLE FOR DAMAGED WHEELS OR LOOSE WHEEL COVERS

PARTS WARRANTY - TO THE EXTENT PERMITTED BY STATE OR LOCAL LAW, ANY WARRANTIES ON THE PRODUCTS SOLD HEREIN ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES OR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

Reed's TIRE SERVICE, INC. 9:30

"HOME OF SUDDEN SERVICE" REPAIR ORDER

12671 JAMES STREET
HOLLAND, MICHIGAN 49424
Phone (616) 399-3070
Fax (616) 399-2064

• TIRES
• STRUTS
• SHOCKS

• ALIGNMENT
• COMPUTER BALANCING

29949

MICHIGAN REGISTRATION NO. F131183 - RICHARD D. BLACQUIERE, MECHANIC NO. M159626

NAME: TERRY FAELDT RECEIVED: _____ DATE: 7-17-11
 ADDRESS: 10240 SUFFOLK DR PROMISED: _____ ORDER WRITTEN BY: _____
 CITY: SPRING LAKE PHONE: 616-990-6343 TERM: MC
 YEAR: T& Int. MAKE: SCOUT MODEL: _____ PO. NO. _____ LICENSE NO. _____ SPEEDOMETER _____

OPER. NO.	REPAIR ORDER INSTRUCTIONS	LABOR CHARGE
	Align No Adjustment.	CANT 00
4	31x10.50 R15 UNIROYAL LAREDO	559.00
4	WB&US	33.24
	Roll out	45.00
	Labor to clean and Repack LF Hub, Replace LF Brake Hose Replace Master Cylinder Flush Brake System.	210.00
TOTAL PARTS		299.00
TAX		17.94
TOTAL AMOUNT		1150.18

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND HEREBY GRANT YOU AND OR YOUR EMPLOYEES PERMISSION TO OPERATE THE CAR OR TRUCK HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSES OF TESTING AND OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON ABOVE CAR OR TRUCK TO SECURE THE AMOUNT OF REPAIRS THERETO.

X _____

Invoice


Order #43001

Date: 06/11/2018 12:05:41 PDT

Thank you for your order. Please keep this invoice for your records.


Ship To:

Name:
Email Address:
Phone Number:
Fax Number:
Company:
Address:



Bill To:

Name:
Email Address:
Phone Number:
Fax Number:
Company:
Address:



Code	Product	Quantity	Price/Ea.	Total
85814	International Scout, Pickup or Travelall Side Marker Light Pigtail	1	\$7.95	\$7.95
FUELFILSEAL	Scout II & Pickup Fuel Filler Neck Hole Seal SEAL: SL489615C2	1	\$22.95	\$22.95
SL233470R91	Rubber Headed Hood Stop for 1971-80 Scout II, Terra or Traveler	2	\$3.95	\$7.90
SII-GLOVEBOX	Plastic Glove Box for 1971-80 Scout II, Terra or Traveler	1	\$48.95	\$48.95
SII-MRKR-LNSE-KIT	Marker Light Assembly for 1972-80 Scout II, Terra or Traveler & 1969-75 Pickup & Travelall CHOOSECOLOR: SL485591C1	1	\$34.95	\$34.95
SL406539C1	Standard Transmission Shift Boot Seal for 1971-80 Scout II, Terra, Traveler or IH Pickup & Travelall	1	\$33.95	\$33.95
SL487122C1	Single Stick Transfer Case Shifter Boot for 1978-80 Scout II, Terra or Traveler	1	\$43.95	\$43.95

Shipping: UPS Ground: \$20.38
 Sales Tax: \$0.00
Total: \$220.98



Scout, Traveler, Terra and Travelall are trademarks of the International Truck & Engine Corporation. Their use has been licensed under Scout Light Line Distributors, Inc. - IH PARTS AMERICA is a Scout Light Line Authorized Dealer.



IH PARTS AMERICA: Over one thousand parts in stock and ready to ship. If you don't see the part you are looking for feel free to call or email us. We have what you need! 630-274-1795

All materials on this site are copyright IH PARTS AMERICA, and may be used only with permission.
 Site Created By: Beyond Websites
 Switch to Mobile

IH Parts America Inc.
 Binder Books
 119 E. McKnight Way
 Grass Valley, CA 95949



3 14x12x6

Invoice

Date	Invoice #
6/11/2018	50978



Vehicle	P.O. No.	Terms	Ship Date	Ship Via	Salesman
	43001	COD	6/11/2018	UPS GROUND	SS

ITEM	QTY	DESCRIPTION	RATE	AMOUNT
85814	1	Marker Light Socket Pigtail	7.95	7.95T
SL489615C1	1	Rear Quarter Panel Gas Fill Hole for Scout II - Large	22.95	22.95T
SL233470R91	2	Underhood Rubber Headed Hood Stop for Scout II	3.95	7.90T
SII-GLOVEBOX	1	ABS Plastic Replacement glove box for Scout II	48.95	48.95T
SL485591C1	1	Red Marker Light Kit w/ Bezel and gaskets and frame	34.95	34.95T
SL406539C1	1	Manual Shifter Boot	33.95	33.95T
SL487122C1	1	78'-80' Scout II Transfer Case Shifter Boot	43.95	43.95T
SHIPPING/HANDLING		The cost for shipping and/or handling of any type.	20.38	20.38

Disclaimer: All products purchased carry no liability provision. Any and all damages that may arise from any claim are the sole responsibility of the buyer. ALL RETURNS ARE SUBJECT TO A 15% RESTOCK FEE. WE DO NOT ACCEPT RETURNS AFTER 30 DAYS. IF A RETURN IS NOT AUTHORIZED IT WILL BE REFUSED. ANY PROBLEMS WITH THE ORDER MUST BE REPORTED WITHIN 72 HOURS OF DELIVERY.

Subtotal	\$220.98
Sales Tax (0.0%)	\$0.00
Total	\$220.98
Payments/Credits	-\$220.98
Balance Due	\$0.00

TERMS & CONDITIONS - Payment for invoice is due at the time of the order. Accounts that remain unpaid 30 days after the date of the invoice will be assessed a service charge in the amount of one & one half percent(1.5%) per month of the total amount due. These accounts unpaid after 30 days of the date of shipment will be considered in default. Checks returned for insufficient funds will be assessed a return charge of \$40 USD. Customers with accounts in default agree to pay IH Parts America reasonable expenses, including attorney fees, court costs and collection fees by third party agencies for the fees incurred by IH Parts America in enforcing these terms and conditions. The customer agrees to indemnify and hold harmless IH Parts America from any and all claims resulting from the customers use of products that IH Parts America distributes or sells which cause damage to the customer or any third party. These terms and conditions are executed in the County of Nevada.


Phone #	Fax #	E-mail	Web Site
530-274-1795	844-270-4716	sales@ihpartsamerica.com	ihpartsamerica.com

Date: 07/17/2011

Invoice

Order #44096

Thank you for your order. Please keep this invoice for your records.



Code	Product	Quantity	Price
45366	7/16" x 1.5" Chrome Cap Bumper Bolt	4	\$
SL420209C91	Marker Light Socket & Cable for Scout II, Terra, Traveler, IH Pickup & Travelall	2	\$
TRANSHIFTEREMBLEM	Transmission or Transfer Case Shifter Knob Decals for Scout, IH Pickup or Travelall	1	\$

CHOOSEDECAL: SL2751160R2

USPS Small Flat Rate Sale
IHPA Loyalty i



**BELLE
TIRE**

06/07/2018

17:00

ELKHART #125
2624 CASSOPOLIS STREET

ELKHART, IN 46514-5132
(574) 333-2703

TID: *****271

**CREDIT CARD
SALE**

VISA
CHIP READ

CONTACT

**LIGHT LINE
PARTS**

Trademarks of the International Truck & Engine Corporation.
International Truck & Engine, Inc. - IHPA PARTS AMERICA is a Scout/Light Line Authorized Dealer.

... and ready to ship. If you don't see the part you are looking for feel free to call or email us.

... AMERICA, and may be used only with permission.
Beyond Websites
© Mobile



StockInteriors.com

"Your custom molded auto carpet source"


Thank you for your order!

Invoice No. 337645
Payment Method: Credit Card

Date: 06/16/2018 05:35 pm
Order Number: 372607002




Item Description	Price	Quantity	Total
8845 '76-'80 International Scout Traveler Molded Carpet 2 Door 4 WD Complete Kit Color: 8295-Medium Doeskin Plush Cut Pile Backing: MassBack - \$133.00 8845 - \$349.95	\$482.95	1	\$482.95
<hr/>			Subtotal: \$482.95
			Shipping Charge: +\$63.90
			Order Total: \$546.85



Your payment has been approved!

Order Number: **37706204**



Order Details

Part Name	Quantity	Price
Steering Wheel G19405	1.00	\$95.97
Sub Total:		\$95.97
Shipping:		\$0.00
Handling:		\$0.00
Tax:		\$0.00
Core:		\$0.00
Discount:		\$9.60
Total		\$86.37

Once payment has been confirmed we cannot add/remove parts from the order or change your shipping option.

Please Note: If your order has multiple parts delivered to the same address, your items may ship in separate boxes to ensure timely delivery. Don't worry, you won't be charged additional shipping fees.

Thank you for shopping and we hope to see you again.

JC Whitney
www.jcwhitney.com
customerservice@jcwhitney.com




Pacific Supply Group, Inc.

2704 SE Steele St., Portland, Oregon 97202
phone: (503) 772-0070 fax: (503) 772-1737
email: scoutparts.info@scoutparts.com

Invoice #274544

Date: Jul-06-2018



catalog	description	qty	unit price	line total
13611	Scout II Door Threshold Sill Plate	2	\$41.15	\$82.30
16353	Bumper Bolt Kit Front - Scout II	1	\$16.40	\$16.40
19211	Aero Side View Mirror - Chrome side: Left (driver) Side Note: side:Left (driver) Side	1	\$51.45	\$51.45
19211	Aero Side View Mirror - Chrome side: Right (passenger) Side Note: side:Right (passenger) Side	1	\$51.45	\$51.45
19472	Window Guide Leading Edge - New for Scout II	2	\$42.15	\$84.30

Sub Total: \$285.90

Shipping & Handling: \$23.87

Total: \$309.77

Payment - 00792C: \$309.77

PAID

PLEASE NOTE:

No returns on electrical or fuel handling items.
No returns on merchandise past 30 days of purchase.
No returns without return authorization number. Call to obtain.
All applicable returns subject to 20% restocking fee unless returned for store credit.



BELLE TIRE RECEIPT

2624 CASSOPOLIS STREET - ELKHART IN 46514-5132
(574) 333-2703



Vehicle Information

Plate #

Odometer 0



BELLE TIRE

Invoice / Receipt

Store #125

(574) 333-2703

2624 CASSOPOLIS STREET-ELKHART IN
46514-5132

Order #: 31580593 Date: 6/28/2018
Last Usr: EZV Time: 15:35
Last Prt: 6/28/2018 14:55

Salesperson SCOTT C. EVANS




Plate #: Vehicle #
Odometer: 0

Comments: 72 international scout

Product Descriptions and Notations

1	I	DISCOUNT	BELLE TIRE DISTRIBUTORS, INC. PREFERRED CUSTO DISCOUNT
2	O	78 626885	16X8 5-139.7 AR OUTLAW II MCHCC +0 AMERICAN RA
3	O	BF 15477	LT245/75R16 10E 120/117S BF ALL TERRAIN T/A KO2 I
4	I	99 OTDIN	TIRE INCLUDES WEIGHTS, RUBBER VALVE STEM AN MONTH PRORATED ROAD HAZARD WARRANTY
5	I	99 WITHMORE	LIFETIME BALANCE, ROTATION AND FLAT REPAIRS. HAND TORQUE AND TIRE DISPOSAL.
6	I	99 EXCLD	EXCLD: COMM VEHICLES, WINTER TIRES & SEASON CHANGEOVERS. WARRANTY IS NON-TRANSFERABL
8	I	99 REGISTRATION	TIRES HAVE BEEN ELECTRONICALLY REGISTERED
9	I	99 OEIN	INDIANA STATE TIRE FEE
10	I	AW CA	CHECK ALIGNMENT
11	M	99 FPA	FREEDOM PLAN ADVANTAGE AGREEMENT *** DECLINED FREEDOM PLAN ADVA
12	I	99 FPA	FREEDOM PLAN ADVANTAGE AGREEMENT

Payment By	Sls Id	Approval/Check #	\$
VISA	EZV	00115C	

Terms: C.O.D. ONLY

Mechanics / Technician

5A2 - BENJAMIN A. COY M251093

31580390

Payment Address: BELLE TIRE P.O. BOX 641612 DET

Product	Quantity	Unit Price	Amount
1	I	BF 15477	EZV
		0.00 @	193.00 0.00
LT245/75R16 10E 120/117S BF ALL TERRAIN T/A KO2 RWL			
2	I	78 626885	EZV
		0.00 @	115.99 0.00
16X8 5-139.7 AR OUTLAW II MCHCC+0 AMERICAN RACING			
3	I	99 PSI	EZV
		5.00 @	0.00 0.00
WAREHOUSE SALE TIRE INSTALLATION, MOUNT AND BALANCE			
4	I	99 DOT	
		5.00 @	0.00 0.00
DOT #'S BF11AT110818BF11AT110818 BF11AT110818BF11AT110818 BF11AT110818			
5	I	99 REGISTRATION	
		5.00 @	0.00 0.00

North Side Service Center

140 C.R. 6 West
Elkhart, IN. 46514
Phone: 574-266-4573 Fax: 574-262-3764

INVOICE

31778

INVOICE

Date: 06/28/2018

1978 International - Scout II - 3.2L, In-Line6 (198CI) VIN(Not Ave
Lic # : Odometer In : 69642

VIN # : H0103HGD46303

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
"(No Category Specified)" - HEATER HOSE 1/2 CQ1825	1.00	3.38	3.38	remove lift kit	316.00
"(No Category Specified)" - TRUMPET BIG RIG 417	1.00	67.32	67.32	Removed lift kit - Installed bushings in OE leaf springs - re installed original springs twice found out that vehicle was shimmed only on the right side . Installed new shocks, speedo not working	39.50
"(No Category Specified)" - BLOWER MOTOR 35501	1.00	78.43	78.43	Vehicle needs speedometer - Removed cable . slid cable into transmission to be sure it was engaged . speedo cable turns with no reaction on speedometer.	
"(No Category Specified)" - V-BELT-TOP COG 15420	2.00	16.43	32.86	brakes / . Removing lift kit . Speedo, Parking ?Brake . List other issues	
"(No Category Specified)" - V-BELT-TOP COG 17370	1.00	14.37	14.37	SHOCK ABSORBER - Remove & Replace - Both Front shocks	39.50
"(No Category Specified)" - V-BELT-TOP COG 17370	1.00	14.37	14.37	SHOCK ABSORBER - Remove & Replace - Both Rear	39.50
"(No Category Specified)" - EXH MAN MOUNT HDW 03410	1.00	27.18	27.18	FUEL FILTER - Remove & Replace - Diesel	39.50
Versa Trans ATF ATF	2.00	4.69	9.38	Lube, Oil, Filter (Diesel)	20.00
"(No Category Specified)" - RANCHO RS5117	2.00	69.99	139.98	WHEEL BEARING - Remove & Replace - Both, Semi-Floating Axle - [Includes: Repack and adjust Bearings and replace Seals on Full Floating Axles.]	276.50
"(No Category Specified)" - SHOCK-RS5000 RS5113	2.00	69.99	139.98	Removed both rear axles and replaced bearings and seals . Also changed brake shoes and hardware . Topped off rear end lube	
"(No Category Specified)" - OIL FILTER-HD 85784	1.00	11.52	11.52	(Combination) - WHEEL CYLINDER - Replace both - [Includes: Bleed Brakes.]	63.20
Fuel Filter Primary - Fuel Type: Diesel 86339	1.00	16.21	16.21	Refinish brake drum to within vehicle specification.	15.00
"(No Category Specified)" - FUEL 86386	1.00	11.56	11.56	Resurface and machine rear brake drums. Clean and lubricate backing plates. Road test vehicle	
Kendall Diesel Motor Oil 15W40	12.00	3.49	41.88	Refinish brake drum to within vehicle specification.	15.00
"(No Category Specified)" - WHEEL CYLINDER WCA59240	1.00	17.08	17.08	Resurface and machine rear brake drums. Clean and lubricate backing plates. Road test vehicle	
"(No Category Specified)" - WHEEL CYLINDER WCA59241	1.00	17.08	17.08	***Vehicle Memo*** 6200 lbs	
"(No Category Specified)" - STICTION ELIMINATOR 32OZ HSS32Z12	1.00	34.99	34.99	R gawr 3100 lbs	
"(No Category Specified)" - HOT SHOT DIESEL EXTREME 16OZ P040416Z12	1.00	14.99	14.99	Put lift kit and shocks with front splash pan in rear of truck	
"(No Category Specified)"	3.00	19.99	59.97	Replaced ALL THREE BELTS BECAUSE THEY WERE SQUEALING	47.40

Visit us on the web : <http://www.nssvc.com/>

Service Advisor : Klaer, Nick Tech : Miller, Mike, Klaer, Nick

Our Email Address: northsideservicecenter@gmail.com

Great people, great products, great prices!™

PAGE 3 OF 4
REF# 523996

NORTH SIDE AUTO PARTS INC
140 CR 6 WEST
ELKHART, IN 46514
574-264-4139

NORTH SIDE AUTO PARTS INC
140 CR 6 WEST
ELKHART IN 46514
574-264-4139
WWW.NSAPCO.COM
WE MAKE HYDRAULIC HOSES

R-134A
Air Conditioning Hoses

SALE



15829 MUST BE ACCOMPANIED BY THIS RECEIPT.

SEE CARQUEST STORE FOR DETAILS OF THE COAST TO COAST GUARANTEE.

Batch #: 147
06/06/19 10:12:04
APPR CODE: 204432
Trace: 3

REF#: 00000003

AMOUNT \$174.90

APPROVED

DATE	CUST. P.O. NO.	SALES ID	TEAMMATE ID	FORM OF PYMT.
6/6/2019				
7	7	4.98	2.99	0.00
3	3	7.48	4.49	0.00
2	2	4.98	2.99	0.00
1	1	13.32	7.99	0.00

Warranty, if any, constitutes the only warranty with respect to the sale of all goods. SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Seller does not authorize any person to grant any warranty or assume any liability by Seller.

DELV. ID	FREIGHT	TAXABLE AMT.	SALES TAX	TOTAL CORE	PREV. DEPOSIT

PAY THIS AMOUNT

CUSTOMER COPY

CONTINUED

THANK YOU

CUSTOMER COPY



Great people, great products, great prices!™

NORTH SIDE AUTO PARTS INC
140 CR 6 WEST
ELKHART IN 46514
574-264-4139
WWW.NSAPCO.COM
WE MAKE HYDRAULIC HOSES

PAGE 4 OF 4
REF# 523996



212019060605239000331126000052399629 MUST BE ACCOMPANIED BY THIS RECEIPT.

SEE CARQUEST STORE FOR DETAILS OF THE COAST TO COAST GUARANTEE.

INVOICE NO.	CUSTOMER NO.	DATE	CUST. P.O. NO.	SALES ID	TEAMMATE ID	FORM OF PYMT.
5239-331126	1001	6/6/2019				
* SUPERCEDE FOR: PVF 3012						
15	XKT 11508	1	1	19.98	11.99	0.00
TITAN SCRAPER 1 1/4 ERGO HANDLE						

WARRANTY DISCLAIMER: The manufacturer's warranty, if any, constitutes the only warranty with respect to the sale of all goods. SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Seller does not authorize any person to grant any warranty or assume any liability by Seller.

SHIP VIA	DELV. TIME	DELV. ID	FREIGHT	TAXABLE AMT.	SALES TAX	TOTAL CORE	PREV. DEPOSIT
				163.46	11.44		

RECEIVED BY X

10:09 AM

174.90

CUSTOMER COPY

PAY THIS AMOUNT

174.90


Super Scout Specialists, Inc.
 1318 West Main Street
 Springfield, OH 45504

Parts - Sales - Service
 Scout, Scout II, Pickup &
 Travelall
 Phone: (937) 525-0000
 Fax: (937) 525-9782

Invoice

Date	Invoice #
1/28/2019	136247

www.superscoutspecialists.com



P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
133587	Paid In Full	JR	1/28/2019	US Mail		
Quantity	Item Code	Description			Price Each	Amount
1	867874R1	Oil Pan Gasket Dana 20 Transmission			11.00	11.00
1	CTS2711	Diesel SD633 Non-Turbo Service Manual			55.00	55.00
1	Shipping	USPS			12.53	12.53
		AMOUNT			\$78.53	

Super Scout Specialists
 1318 W Main Street
 Springfield, OH 45504
 937-525-0000
 543884555890648

SALE

MID: 4800 Store: 0001 Term: 0003
 REF#: 00000006
 Batch #: 008 RRN: 902814404546
 01/28/19 09:03:30
 115510001174

AMOUNT \$78.53

APPROVED
 THANK YOU!
 CUSTOMER COPY

RETURNS MUST BE MADE WITHIN 30 DAYS. MERCHANDISE RETURNED THAT IS NOT DEFECTIVE IS SUBJECT TO A 15% RESTOCKING FEE.

Total \$78.53

Please call Super Scout Specialists for an RGA number. Packages without an RGA number will be refused. Please write the RGA number clearly on the outside of the package.

All Special Order items are not part of our inventory, therefore NON-REFUNDABLE. There will be NO RETURNS of Special Order items.

PLEASE REFER TO OUR CATALOG FOR A COMPLETE LIST OF OUR TERMS.
 NO RETURNS ON ELECTRICAL OR USED PARTS



Specializing in Classic I.H. Vehicles

2075 Business 61
 Fort Madison, Iowa 52627
 Phone (319) 372-3272
 Fax (319) 372-3281
 www.scoutconnection.com
 info@scoutconnection.com


INVOICE

CUSTOMER NO. 47238

SHUFFR

BILL TO:

SHIP TO:



DATE	SHIP VIA	F.O.B.	TERMS		
07/16/19	Delivered	Origin	[REDACTED]		
PURCHASE ORDER NUMBER	ORDER DATE	SALESPERSON	OUR ORDER NUMBER		
Verbal	07/16/19		None		
QUANTITY		ITEM NUMBER	DESCRIPTION	UNIT PRICE	AMOUNT
REQUIRED	SHIPPED				
1	1	414289C1	Pedal	30.93	30.93
2	2	362747C1SL	Pad, Pedal Clutch/Brake	18.50	37.00
1	1	464638C1	Pad, Parking Brake	15.46	15.46
1	1	478067C1	Gasket, Valve Cover 6-33	45.08	45.08
1	1	U481346C1	USED Wiper Switch	25.00	25.00
1	1	SHIPPING	U.S.P.S.	9.00	9.00
<p>THANK YOU FOR YOUR ORDER!!!</p> <p>DON'T FORGET TO CHECK OUT OUR WEB SITE:</p> <p>WWW.SCOUTCONNECTION.COM</p> <p>AND</p> <p>LIKE US ON FACEBOOK</p>					
				NonTaxable Subtotal	162.47
				Taxable Subtotal	0.00
				Tax	0.00
				Total	162.47

Thank You


Invoice

Super Scout Specialists, Inc.
6711 Dayton Springfield Rd
Enon, OH 45323


www.superscoutspecialists.com

Parts - Sales - Service
Scout, Scout II, Pickup &
Travelall
Phone: (937) 525-0000
Fax: (937) 525-9782

Date	Invoice #
8/21/2019	138415



P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
1191	Paid In Full	JR	8/21/2019	US Mail		
Quantity	Item Code	Description			Price Each	Amount
1	PP098	SHIFTER BOOT SEAL RETAINERS, SCOUT II, PICKUP TRAVELALL, STANDARD BOOT SEAL RETAINER, SCOUT II, PICKUP TRAVELALL			22.00	22.00
1	Shippine	USPS				



21201808140766800002531980000308718936

Great people, great products, great prices!™

BREMEN CARQUEST AUTO PARTS
1231 WEST PLYMOUTH
BREMEN IN 46506
574-546-5356
SERVING A WORLD IN MOTION!!!
FILTER SALE AUG. 20-25
LOCALLY OWNED AND OPERATED

PAGE 1 OF 1
REF# 308718

ANY PRODUCT RETURNED FOR CREDIT MUST BE ACCOMPANIED BY THIS RECEIPT.

SEE CARQUEST STORE FOR DETAILS OF THE COAST TO COAST GUARANTEE.

B CARQUEST PREFERRED CUSTOMER
L THANK YOU
T FOR YOUR BUSINESS
O BREMEN, IN 46506

S CARQUEST PREFERRED CUSTOMER
H THANK YOU
I FOR YOUR BUSINESS
T BREMEN, IN 46506

INVOICE NO.	CUSTOMER NO.	DATE	CUST. P.O. NO.		SALES ID	TEAMMATE ID	FORM OF PYMT.		
7668-253198	3	8/20/18	202-7047 MATT			JER	CASH		
MFG. PART NUMBER			ORDERED	SHIPPED	LIST PRICE	NET	NET CORE	EXT. AMOUNT	TAX
1 MIS FREIGHT			1	1	11.85	7.11	0.00	7.11	Y/Y
FREIGHT CHARGES									
1978 INTERNATIONAL SCOUT II 3.2L 198 CID 6 CYL DIESEL									
2 BBO 54-73120			1	1	194.99	109.99	55.00	164.99	Y/Y
CARDONE REMAN BRAKE BOOSTER									
SPECIAL ORDER (VENDOR \$LC)									
<small>WARRANTY DISCLAIMER: The manufacturer's warranty, if any, constitutes the only warranty with respect to the sale of all goods. SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Seller does not authorize any person to grant any warranty or assume any liability by Seller.</small>									
SHIP VIA	DELV. TIME	DELV. ID	FREIGHT	TAXABLE AMT.	SALES TAX	TOTAL CORE	PREV. DEPOSIT		
				172.10	12.05	55.00			

11:37 AM

RECEIVED BY

185.00 / 0.85

CUSTOMER COPY

PAY THIS AMOUNT

184.15



Great people, great products, great prices!SM
 Great people, great products, great prices!SM

NORTH SIDE AUTO PARTS INC
 140 CR 6 WEST
 ELKHART IN 46514
 574-264-4139
 WWW.NSAPCO.COM
 WE MAKE HYDRAULIC HOSES

PAGE 1 OF 1
 REF# 509446



21 [REDACTED] MUST BE ACCOMPANIED BY THIS RECEIPT.

SEEK STORE FOR DETAILS OF THE COAST TO COAST GUARANTEE.

INVOICE NO.	NO.	DATE	CUST. P.O. NO.		LIST PRICE	NET	SALES ID	TEAMMATE ID	FORM OF PYMT.		
			ORDERED	SHIPPED					DAN	VISA	
5239-323358	1001	2/14/2019	1	1	86.87	52.12			NET CORE	EXT. AMOUNT	
			1	1	11.32	6.79			0.00	52.12	
									0.00	6.79	
										Y/Y	
										Y/Y	
WARRANTY DISCLAIMER: The manufacturer's warranty, if any, constitutes the only warranty with respect to the sale of all goods. SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Seller does not authorize any person to grant any warranty or assume any liability by Seller.								TOTAL CORE	PREV. DEPOSIT		
SHIP VIA					DELV. TIME	DELV. ID	FREIGHT	TAXABLE AMT.	SALES TAX	TOTAL CORE	PREV. DEPOSIT
							58.91	4.12	63.03	63.03	

10:39 AM

RECEIVED BY X

63.03

CUSTOMER COPY

PAY THIS AMOUNT

63.03

Invoice

Super Scout Specialists, Inc.
 1318 West Main Street
 Springfield, OH 45504

Parts - Sales - Service
 Scout, Scout II, Pickup &
 Travelall
 Phone: (937) 525-0000
 Fax: (937) 525-9782

www.superscoutspecialists.com

Date	Invoice #
2/4/2019	136331



P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
02-04-2019	Paid In Full	JR	2/4/2019	UPS		
Quantity	Item Code	Description			Price Each	Amount
1	481685C1	SSII Grille			135.00	135.00
1	Shipping	UPS			42.53	42.53
					AMOUNT	\$177.53
					APPROVED	
					THANK YOU!	
					CUSTOMER COPY	
					Total	\$177.53

Super Scout Specialists
 1318 W Main Street
 Springfield, OH 45504
 937-525-0000
 543684555890648

SALE

MID: 4800 Store: 0001 Term: 0003
 REF#: 00000078
 Batch #: 013 RPN: 9035600488
 02/04/19 022755



AMOUNT \$177.53

APPROVED

THANK YOU!

CUSTOMER COPY

RETURNS MUST BE MADE WITHIN 30 DAYS. MERCHANDISE RETURNED THAT IS NOT DEFECTIVE IS SUBJECT TO A 15% RESTOCKING FEE.

Please call Super Scout Specialists for an RGA number. Packages without an RGA number will be refused. Please write the RGA number clearly on the outside of the package.

All Special Order items are not part of our inventory, therefore NON-REFUNDABLE. There will be NO RETURNS of Special Order items.

PLEASE REFER TO OUR CATALOG FOR A COMPLETE LIST OF OUR TERMS. NO RETURNS ON ELECTRICAL OR USED PARTS

Super Scout Specialists, Inc.
6711 Dayton Springfield Rd
Enon, OH 45323

www.superscoutspecialists.com

Parts - Sales - Service
Scout, Scout II, Pickup &
Travelall
Phone: (937) 525-0000
Fax: (937) 525-9782

Invoice

Date	Invoice #
6/20/2019	137836



P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
939	Paid In Full	JR	6/20/2019	UPS		
Quantity	Item Code	Description			Price Each	Amount
1	479296C1	Scout II Diesel Engine, Lower Radiator Hose			30.00	30.00
1	479332C1	Scout II Diesel Engine, Upper Radiator Hose			30.00	30.00
1	1530	H4 HEADLIGHT BULB CONVERSION, SCOUT, SCOUT II, 60S 70S PICKUP TRAVELALL - 1979 DOWN ROUND (PAIR)			99.00	99.00
1	434	LICENSE PLATE LIGHT KIT, SCOUT II			14.00	14.00
1	Shipping	UPS			22.53	22.53

Super Scout Specialists
1318 W Main Street
Springfield, OH 45504
937-525-0000
5436845556890648

SALE

MID: 4800 Store: 0001 Term: 0003
REF#: 00000007
RRN: 91713005951
06/20/19 09:46:36
CVV: 11

AMOUNT \$195.53

APPROVED
THANK YOU!
CUSTOMER COPY

RETURNS MUST BE MADE WITHIN 30 DAYS. MERCHANDISE RETURNED THAT IS NOT DEFECTIVE IS SUBJECT TO A 15% RESTOCKING FEE.

Total \$195.53

Please call Super Scout Specialists for an RGA number. Packages without an RGA number will be refused. Please write the RGA number clearly on the outside of the package.

All Special Order items are not part of our inventory, therefore NON-REFUNDABLE. There will be NO RETURNS of Special Order items.

PLEASE REFER TO OUR CATALOG FOR A COMPLETE LIST OF OUR TERMS.
NO RETURNS ON ELECTRICAL OR USED PARTS


Invoice

Super Scout Specialists, Inc.
6711 Dayton Springfield Rd
Enon, OH 45323

www.superscoutspecialists.com

Parts - Sales - Service
Scout, Scout II, Pickup &
Travelall
Phone: (937) 525-0000
Fax: (937) 525-9782

Date	Invoice #
6/24/2019	137862



P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
133797	Paid In Full	JR	6/24/2019	UPS		
Quantity	Item Code	Description			Price Each	Amount
28	26100	SEAL MATERIAL SOLD BY FOOT			2.50	70.00
1	Shipping				19.00	19.00
					AMOUNT	\$89.00

Specialists
Street
5504
45323-9890648

SALE

MID: 4800 Store: 0001 Term: 0003
REF#: 00000003
Batch #: 037 RRN: 91753003338
06/24/19 ANS EXACT MATCH 0900:17 CW: H
Trans ID: 0624MIDJOPDT51
PO#: 133797

AMOUNT \$89.00

APPROVED
THANK YOU!
CUSTOMER COPY

RETURNS MUST BE MADE WITHIN 30 DAYS. MERCHANDISE RETURNED THAT IS NOT DEFECTIVE IS SUBJECT TO A 15% RESTOCKING FEE.

Please call Super Scout Specialists for an RGA number. Packages without an RGA number will be refused. Please write the RGA number clearly on the outside of the package.

All Special Order items are not part of our inventory, therefore NON-REFUNDABLE. There will be NO RETURNS of Special Order items.

PLEASE REFER TO OUR CATALOG FOR A COMPLETE LIST OF OUR TERMS. NO RETURNS ON ELECTRICAL OR USED PARTS

Total \$89.00



Fastenal Company
 P.O. Box 1286
 WINONA, MN 55987-1286

Invoice

Date	Reference	Page
6/24/19	No. INELK222755	1
DUE DATE: 07/24/2019		

Cust. No. ELKH0816
 Cust. P.O.
 Job No.

The store serving you is
 2020 Middlebury Street


ELKHART, IN 46516
 Phone #: (574)293-6599
 Fax #: (574)293-6673

Ship To
 Picked up at Fastenal Store


Sold To
 NORFOLK SOUTHERN CORPORATION
 BOX 32
 1200 PEACHTREE ST NE
 ATLANTA, GA 30309-3579

This Order and Document are subject to the "Terms of Purchase" posted on www.fastenal.com.

Line No.	Quantity Ordered	Quantity Shipped	Quantity Backorder	Description	Control No.	Part No.	Price / Each	Amount
1	10	10		0 #4 5/8-1/4x5/16MHCSS	136158	62002	0.6930	6.93 G
2	10	10		0 #6 7/8-3/8x9/16HCSSB	136158	62008	0.9417	9.42 G



Received By



Tax Exemption
 Government

IN

Subtotal	16.35
Shipping & Handling	0.00
State Tax	0.00
County Tax	0.00
City Tax	0.00
TOTAL USD	16.35

If you re-package or re-sell this product, you are required to maintain integrity of Country of Origin to the consumer of this product.

Reasonable collection and attorneys fees will be assessed to all accounts placed for collection. No materials accepted for return without our permission.

X indicates part is a hazardous material

* indicates part was sold at a promotional or special discount price

This is your invoice.

All discrepancies must be reported within 10 days.

0

Thank You !

FASTENAL


Fastenal Company: INELK
 2020 Middlebury Street
 ELKHART, IN 46516
 (574)293-6599
 Tuesday, June 4, 2019 2:11:34 PM

Account: INELKCASH Invoice: 221806
 PO Number: cc

2173016
 2171159
 2172283


S/S FPH SMS 8 X 3/4 20 x 0.18 EA
 S/S FINISH WASH #10 40 x 0.18 EA
 8 x 1 SS OVPHSMS 30 x 0.35 EA

SUBTOTAL 21.00
 SRH CHARGE 0.00
 CITY TAX 0.00
 COUNTY TAX 1.47
 STATE TAX
 TOTAL 22.47



Regan Pugh

ITEMS SOLD 3



Thank You For Your Business

Buy online at www.fastenal.com
 No materials accepted for return without permission.
 All discrepancies must be reported within 10 days.

THANK YOU FOR SHOPPING AT
 SIX SPAN ACE
 (574) 295-5806

07/05/19 11:35AM KL 565 SALE

56	10	EA	.55	EA	
FASTENERS					\$5.50
56	10	EA	.59	EA	
FASTENERS					\$5.90
SUB-TOTAL:\$		11.40	TAX:\$.80
			TOTAL:\$		12.20
BC AMT:					\$ 12.20



PACKING SLIP




Scouter1

<https://www.ebay.com/str/scouter1>

2,651 lifetime feedback
99.7% positive feedback

★ Top Rated

Store QR code link



Order date: Jun 17, 2023

ORDER ID: 10-10186-84100

Sales record #: 15890

ITEM	QUANTITY	PRICE	TOTAL
International Harvester Scout II Terra Traveler Side Marker Light Clip + Screws (Item ID: 256063060276)	2	\$3.95	\$7.90
International Harvester Scout II NEW Door Locking Rod Anti-Rattle Sleeve (Item ID: 256018276344)	1	\$7.95	\$7.95

Buyer selected shipping service : USPS Parcel Select Ground

A message from Scouter1

Thanks for your purchase! I hope you love it!

Item subtotal	\$15.85
Shipping	\$6.60
Sales tax (eBay collected)	\$1.11
Order total**	\$23.56

International Harvester Scout II Terra Traveler Side Marker Light Clip + Screws

Return policy: Return accepted, item must be returned in 30 days. Refund will be given as Money Back. The buyer is responsible for return shipping costs.

International Harvester Scout II NEW Door Locking Rod Anti-Rattle Sleeve


Return policy: Return accepted, item must be returned in 30 days. Refund will be given as Money Back. The buyer is responsible for return shipping costs.

**Order total includes eBay collected tax. eBay collects and remits the tax to the tax authorities in accordance with applicable state law.



INVOICE

Date: 10/17/2020 Order#: 4281



Payment Method:

Shipping Method:

PayPal Express

UPS Ground

Code	Description	Qty	Price	Total
tssb	6L80/6L90/8L90 Tap Shift Switch Box [Add pigtail?:Yes] [For use with Twist MachineShrifter?:No] [Add 8L90 Tap Shift CAN Relay?:No]	1	\$200.00	\$200.00

Pink/Black - Switched Ignition/Power - Goes to any appropriate power source (power, key off, no power) power source

Subtotal: \$200.00

State Tax: \$14.00

Shipping & Handling: \$25.00

Grand Total: \$239.00

White/Black - Tap Up/Tap Down function. Goes to 6L80 / 6L90 transmission connector; position 7. Remove the seal (if there is one) in position 7 of your transmission connector (large, round connector). Insert this wire into the slot.

ECM and T43 TCM reprogramming is required for tap up/tap down function.

NOT compatible with E67 setups!

Invoice

Super Scout Specialists, Inc.
1318 West Main Street
Springfield, OH 45504

www.superscoutspecialists.com

Parts - Sales - Service
Scout, Scout II, Pickup &
Travelall
Phone: (937) 525-0000
Fax: (937) 525-9782

Date	Invoice #
2/18/2019	136498

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
02-18-2019	Paid In Full	JR	2/18/2019	US Mail		
Quantity	Item Code	Description			Price Each	Amount
1	Used Part	USED Wing Stop			10.00	10.00
2	423745C1	Door Lock Cylinder Clip/Retainer (Late) Scout II			15.77	31.54
1	489615C1	Rear Quarter Panel Gas Fill Hole Seals (Large Hole - Late Scout II and all newly replaced Quarter panels			22.00	22.00
1	Shipping	USPS			6.53	6.53

Super Scout Specialists
1318 W Main Street
Springfield, OH 45504
937-525-0000
5436845558890648

SALE

MID: 4800 Store: 0001 Term: 0003
Batch #: 023 REF#: 00000001
02/18/19 RRN: 904913004956
AVS: 52121029 08:39:53

AMOUNT \$70.07

APPROVED
THANK YOU
CUSTOMER COPY

RETURNS MUST BE MADE WITHIN 30 DAYS. MERCHANDISE RETURNED THAT IS NOT DEFECTIVE IS SUBJECT TO A 15% RESTOCKING FEE.

Please call Super Scout Specialists for an RGA number. Packages without an RGA number will be refused. Please write the RGA number clearly on the outside of the package.

All Special Order items are not part of our inventory, therefore NON-REFUNDABLE. There will be NO RETURNS of Special Order items.


PLEASE REFER TO OUR CATALOG FOR A COMPLETE LIST OF OUR TERMS. NO RETURNS ON ELECTRICAL OR USED PARTS

Total

\$70.07

Sender

Anything Scout
704 E. Lincoln
Ames IA 50010
United States



Order # S-11665

07/27/20

Quantity	Item	Price
1 x	Wiper Conversion Kit - Scout II / Premium (Silicone)	\$92.00
1 x	Slider Window Latch Kit - Scout II - White	\$14.00

Subtotal price:	\$106.00
Total tax:	\$0.00
Shipping:	\$19.09
Total price:	\$125.09

If you have any questions, please send an email to parts@anythingscout.com

Sender

Anything Scout
704 E. Lincoln
Ames IA 50010
United States



Recipient

Roger Shuff
22855 Bainbridge Drive
Elkhart IN 46514
United States

Order Number: 11704
shuffs@msn.com
+1 312-659-0009

Order # S-11704

07/29/20

Quantity	Item	Price
1 x	Complete Rear Lift Gate Seal - Traveler	\$89.00
Subtotal price:		\$89.00
Total tax:		\$0.00
Shipping:		\$19.09
Total price:		\$108.09

If you have any questions, please send an email to parts@anythingscout.com



Pacific Supply Group, Inc.

2704 SE Steele St., Portland, Oregon 97202
phone: (503) 772-0070 fax: (503) 772-1737
email: scoutparts.info@scoutparts.com

Invoice #311836

Date: Mar-08-2021

catalog	description	qty	unit price	line total
14105	Scout II Hinge Pin Rebuild Kit	4	\$6.60	\$26.40

Sub Total: \$26.40

Shipping & Handling: \$9.95

Total: \$36.35

Payment - 03944C: \$36.35


PAID

PLEASE NOTE:

No returns on electrical or fuel handling items.
No returns on merchandise past 30 days of purchase.
No returns without return authorization number. Call to obtain.
All applicable returns subject to 20% restocking fee unless returned for store credit.

Sender

Anything Scout
704 E. Lincoln
Ames IA 50010
United States



ID/GR

Order # S-14617

03/02/21

Quantity	Item	Price
1 x	Dimmer / High Beam Switch	\$24.00


Subtotal price:	\$24.00
Total tax:	\$0.00
Shipping:	\$8.50
Total price:	\$32.50

If you have any questions, please send an email to parts@anythingscout.com

ID

Sender

Anything Scout
704 E. Lincoln
Ames IA 50010
United States



IP

Order # S-15167

04/05/21

Quantity	Item	Price
1 X	Dimmer Switch Pigtail	\$9.00
Subtotal price:		\$9.00
Total tax:		\$0.00
Shipping:		\$8.50
Total price:		\$17.50

If you have any questions, please send an email to parts@anythingscout.com




Quality Restoration Services Inc

Shop: 2846 Old US 20, Elkhart, IN, 46514
Mailing: P.O. Box 2384, Elkhart, IN, 46515
Phone: 574-522-9455
Fax: 574-522-2723
info@qrsinc.biz
WWW.QRSINC.BIZ
Tax ID: 35-1867326

Invoice #: 10668
Date: 06/11/2021

P.O. #: _____
Status: Paid

Type: check
Notes: Check number 533



Total: **\$1,500.00**

Year: 1979
Make: International
Model: SCOUT
Color: BEIGE
Vin:
Stock/Ro#:
Odometer:
License:

Services Summary:
Paint & Body: \$1,500.00 - **Entire Vehicle:** Touch-up, **LT Front Door:** Repair & paint, **Inside Jam,** **RT Front Door:** Repair & paint
Repaired By: - Anthony Stech

Invoice Totals

Service Type
Paint and Body

Rate	Hours	Total
--	--	\$1,500.00

I have inspected my vehicle(s) and am satisfied that **QUALITY RESTORATION SERVICES INC** has completed repairs to my satisfaction.
TERMS: Net 30 days, past due invoices are subject to a late fee of 2% per month.

GRAND TOTAL: \$1,500.00
Amount Received: \$1,500.00
Balance Due: \$0.00



Mustang Dynamometer

Power Curve Test Results

Date/Time Printed: 2020/07/08 10:10:38 AM



VIN 78international

License 78 Scout

Year/Make/Model

1978 INTERNATIONAL

SCOUT II

Miles 0.0

Weight 4500.0

HP @ 50 MPH 19.20

Cylinders/Displacement 8 / 5.3

Cycles 4

RPM Pickup 2

Comments

Power Curve Test Results

Time Tested 2020/07/08 12:44:21 AM

Wheel Values

Maximum Power 312.7 @ 5646 RPM / 79.6MPH

with WCF 324.1

Maximum Torque 300.8 @ 4957 RPM / 63.6MPH

with WCF 311.3

Crank Values

Maximum Power 376.5 @ 5638 RPM / 79.6MPH

with WCF 390.3

Maximum Torque 300.5 @ 4595 RPM / 63.6MPH

with WCF 375.7

Sender

Anything Scout
704 E. Lincoln
Ames IA 50010
United States



ID/LS

Order # S-18980


01/03/22

Quantity	Item	Price
1x	Anything Scout Stickers	\$5.00
3x	Turn Signal Plug Connector	\$5.00
2x	Fuses - 4 Amp	\$1.50
2x	Fuses - 20 Amp	\$1.50
4x	Fuses - 14 Amp	\$1.50
2x	Dome Light Switch - Late Model Scout II - Late Model (Black)	\$13.00
5x	Dash Light Socket - Scout II	\$2.00
1x	Battery Hold Down Strap- Scout II	\$30.00
1x	Rallye Steering Wheel Horn Emblem	\$10.00

Subtotal price:	\$108.00
Total tax:	\$0.00
Shipping:	\$19.85
Total price:	\$127.85

Sender

Anything Scout
704 E. Lincoln
Ames IA 50010
United States



Order # S-25949

06/09/23


Quantity	Item	Taxes	Price
1 x	Turn Signal Cancel Cam/Horn Contact - Scout II - Tilt	\$0.00 Indiana State Tax	\$19.00
4 x	Head Light Bezel Mounting Nut	\$0.00 Indiana State Tax	\$1.00
2 x	Rear Window Track Felt - Scout II	\$0.00 Indiana State Tax	\$10.00

Subtotal price:	\$43.00
Total tax:	\$0.00
Shipping:	\$11.50
Total price:	\$54.50

If you have any questions, please send an email to parts@anythingscout.com

Super Scout Specialists Inc.
 6711 Dayton Springfield Rd
 Enon, OH 45323 US
 937-525-0000
 superscoutspecialists.com

INVOICE



INVOICE # 155839
 DATE 01/24/2023
 DUE DATE 01/24/2023
 TERMS Paid In Full

SHIP VIA
 ups

P.O. NUMBER
 12647

SALES REP
 ssm

ACTIVITY	DESCRIPTION	SKU	QTY	RATE	AMOUNT
2023cal	2023 IH Scout Calendar		1	10.95	10.95
571722C91	Stop Light Socket 78-80 Scout II		1	11.00	11.00
571721C91	Backup Socket 78-80 Scout II	B END	1	11.00	11.00
7821074CN	14A Fuse		1	1.99	1.99

PAID

SUBTOTAL 34.94
 SHIPPING 10.75
 TOTAL 45.69
 PAYMENT 45.69
 BALANCE DUE **\$0.00**

SUPER SCOUT SPECIALISTS INC
 6711 DAYTON SPRINGFIELD RD
 ENON OH 45323
 937-525-0000
 Terminal ID: *****180
 1/24/23 10:14 AM
 VISA - MANUAL
 ACCT #: *****3478
 MOTO SALE REF #: 8915
 UID: 302426581500 AUTH #: 03661D
 BATCH #: 903
 AMOUNT \$45.69
APPROVED
 CUSTOMER COPY

RETURNS MUST BE MADE WITHIN 30 DAYS OF PURCHASE. MERCHANDISE RETURNED IS SUBJECT TO A 15% RESTOCKING FEE.
 Please call Super Scout Specialists for an RGA number. Packages without and RGA number will be refused. Please write the RGA clearly on
 the outside of the package.

All Special Order items are not part of our inventory and there for NON-REFUNDABLE.
 NO RETURNS ON ELECTRICAL OR USED PARTS.




1924 S. Michigan St.
South Bend, IN 46613

SEAT COVER AND AUTO GLASS CO., INC.

(574) 288-4603

BODY REPAIR AND PAINTING



11/6 2022

CASH CHARGE YEAR MAKE BODY STYLE PHONE

X 78 SCOTT

QUAN. ARTICLES PRICE AMOUNT

Custom Interior
Pulnat
Headlines 3960⁰⁰

1/2 P 8584
1/3 CA 851

M550

VW 3478

Rec'd By _____

Tax 38⁵⁰

Address _____

Total 3998⁰⁰

TICKET No 76173 DEBIT 9055 - 2000⁰⁰
1998⁵⁰

ALL claims and returned goods MUST be accompanied by this bill

Barry Seat Cover, Auto
1924 S Michigan St
South Bend, IN 46613
574 288 4603

Sale

XXXXXXXXXXXX

VISA

Total:

1,998.50



Customer Copy
THANK YOU!

ME
KIT PLUS ROADSIDE
BENEFITS KIT IS ENCLOSED



ZIP 49664 \$ 000.68⁰⁰
02 4M
0000357333 JUN 07 2018

amazonbasics

Picked Up (Inve
Future Upgrade

OMER COPY

ricksparts.com

ATTENTION BUYER
BACK FOR WARRANTY
TERMS OF SALE!

RICK'S USED AUTO PARTS
724 BRANDY CAMP ROAD
KERSEY, PA 15846
814 885 6103
5436845558318670

DATE TIME

7/30/20 12:48 PM

CUSTOMER NO.

LINE 1

SALE



SHIP VIA Page 1

AMOUNT \$325.19

APPROVED

THANK YOU!

CUSTOMER COPY

NET PRICE EXTENSION

25.19 225.19

ORDERED PARTS!
Discount .00
Sub Total 325.19
Taxable .00

Freight: 100.00

TAX 0.00

TOTAL 325.19

TO REORDER CALL COMMERCIAL FORMS 1-800-233-0771

FORM NO. IRI/C158 - 206939

7/29/20, 4:29 PM
Page 1 of 1

405 N. Main St
NORTH WEBSTER, IN 46555
(574) 834-2835

Bank ID: 1340
Rev Card ID: 8121
Term ID: 002

Sale

[Redacted]

Total: \$ 9.19

02/11/20 13:14:08
Inv #: 001208 Appr Code: 305927
Apprvd: Online Batch#: 042001
Retrieval Ref #: 00100002

MasterCard
AID: 60000000001010
TSI: 6800
TVR: 0000000000

Customer Copy

ENCRYPTED TRANSACTION

ALL GOODS RETURNED MUST BE ACCOMPANIED BY THIS INVOICE

Auto Value North Webster
405 N. Main St
NORTH WEBSTER, IN 46555
(574) 834-2835

CERTIFICATE UNDER AGRICULTURAL PRODUCING EXEMPTION
Illegal use of this certificate subjects persons to the penalties of the Sales Tax Act. - The undersigned hereby certifies that all items, except as indicated hereon, are purchased for use or consumption in connection with the production of horticultural or agricultural products as a business enterprise and agrees to reimburse the seller the sales tax if used or consumed otherwise.

SIGNED BY PURCHASER
X

TIME DELIVERED _____

Invoice #523-55963 MasterCard StaCW
Page #1
Date: 2/11/2020 Time: 12:58:21 PM
Counterman: ML

DESCRIPTION	RECYCLE	LIST EA.	YOUR COST	EXTENSION	TAX
ALUMINUM	0.00	8.99	8.59	8.59	T

1	0.00	0.00	0.00	0.00	8.99	0.00	8.59	0.50
TOTAL UNITS	FREIGHT	LABOR	MISC.	RECYCLE TOTAL	LIST TOTAL	NON-TAXABLE	TAXABLE	TOTAL TAX

RECEIVED BY: X

9.19 **PAY THIS AMOUNT**

Auto-Wares

405 N. Main St
NORTH WEBSTER, IN 46555
(574) 834-2835

Bank ID: 1340
Rev Card ID: 8121
Term ID: 002

Sale

[Redacted]

Total: \$ 18.38

02/06/20 17:35:52
Inv #: 001193 Appr Code: 182421
Apprvd: Online Batch#: 037001
Retrieval Ref #: 20100003

MasterCard
AID: 60000000001010
TSI: 6800
TVR: 0000000000

Customer Copy

ENCRYPTED TRANSACTION

ALL GOODS RETURNED MUST BE ACCOMPANIED BY THIS INVOICE

Auto Value North Webster
405 N. Main St
NORTH WEBSTER, IN 46555
(574) 834-2835

CERTIFICATE UNDER AGRICULTURAL PRODUCING EXEMPTION
Illegal use of this certificate subjects persons to the penalties of the Sales Tax Act. - The undersigned hereby certifies that all items, except as indicated hereon, are purchased for use or consumption in connection with the production of horticultural or agricultural products as a business enterprise and agrees to reimburse the seller the sales tax if used or consumed otherwise.

SIGNED BY PURCHASER
X

TIME DELIVERED _____

Invoice #523-55847 MasterCard StaCW
Page #1
Date: 2/6/2020 Time: 5:19:49 PM
Counterman: AW

DESCRIPTION	RECYCLE	LIST EA.	YOUR COST	EXTENSION	TAX
LOW GLOSS BLACK	0.00	8.99	8.59	8.59	T
CHEVY ORANGE	0.00	8.99	8.59	8.59	T

7								
LABOR	MISC.	RECYCLE TOTAL	LIST TOTAL	NON-TAXABLE	TAXABLE	TOTAL TAX		

RECEIVED BY: X

18.38 **PAY THIS AMOUNT**

T N T Performance
 420 S Sycamore St
 SYRACUSE, IN 46567
 574-518-1167
 5436845558319116

SALE

MID: 1600 Store: 0001 Term: 0001
 REF#: 00000001
 Batch #: 036 RRN: 020516404628
 07/23/20 12:17:06
 Trans ID: 0723MDJKYPB0F
 APPR CODE: 547968

AMOUNT \$74.14

APPROVED

DEBIT MASTERCARD
 AID: A0000000041010
 TVR: 80 00 00 80 00
 TSI: 68 00

T-N-T PERFORMANCE
 420 S. Sycamore Street
 Syracuse, IN. 46567
 Phone: 574-518-1167 Fax: 574-457-1167

INVOICE
4036
 Org. Est. # 004422

Date: 07/23/2020

Qty	Sale	Ext	Labor Description	Ext
2.50	6.58	16.45	Air conditioning service	53.00
1.00	0.50	0.50	Hazardous Materials	3.00

1979 International - Scout II - LS
 Lic # :
 VIN # : H0103HGD46303

Odometer In : 1
 Odometer Out : 1

Org. Estimate 74.14 Revisions 0.00 Current Estimate 74.14

Labor:	53.00
Parts:	16.95
HazMat:	3.00
SubTotal:	72.95
Tax:	1.19
Total:	74.14
Bal Due:	\$74.14

[Payments -]
 Vehicle Received: 7/23/2020

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is two years or 24,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

JACK'S SALVAGE AUTO PARTS, INC.
 625 Metacom Ave.
 Bristol, RI 02809-5131
 Phone (401) 253-3478

30 Day Replacement Guarantee Only
 All Deposits Forfeited After 15 Days
 • 25% Restocking Charge ON ACCEPTED Returns
 • No Labor Guarantee or Warranty
 All Claims MUST Include This Invoice
 No Labor Guarantee on Seals and Gaskets
 Computerized Inventory
 No Returns on Parts Not Needed

02/03/2020 15:33:48
 Merchant ID:3936
 Device ID: 3936
 Terminal ID: PP01

Credit Sale:
 Transaction #: [REDACTED]

Amount: USD\$122.00
 SERVICE FEE: USD\$4.88
Total: USD\$126.88

STAN: 007
 Auth. Code: 531520
 Batch Number: 5
 Response: AUTH/TKT
 CVD Response: M - CVV Matches
 TRANS ID: MDJ4NS2880203
 PROCESS AS: CREDIT

CUSTOMER COPY
 THANK YOU!

SHIP TO
 OWEN BROWN
 410 NORTH T K WAY
 NORTH WEBSTER, IN 46555
 574-275-9717

3:35 PM 156717

CREDIT	PHONE NUMBER	ORDER BY	DEPARTMENT	P.O. NUMBER	DATE ORDERED
					02/03/20
DESCRIPTION	STOCK NO.	LOC.	AMOUNT		
			100.00		

GOODS RETURNED MUST BE ACCOMPANIED BY THIS INVOICE

Auto Value North Webster
 405 N. Main St
 NORTH WEBSTER, IN 46555
 (574) 834-2835

CERTIFICATE UNDER AGRICULTURAL PRODUCING EXEMPTION
 Illegal use of this certificate subjects persons to the penalties of the Sales Tax Act. - The undersigned hereby certifies that all items, except as indicated hereon, are purchased for use or consumption in connection with the production of horticultural or agricultural products as a business enterprise and agree to reimburse the seller the sales tax if used or consumed otherwise.

SIGNED BY PURCHASER
 X _____
 TIME DELIVERED _____

Invoice # 523-58142
 PO # _____
 Date: 4/17/2020

MC Stations: CW
 Page #1
 Time: 10:38:24
 Counterman: CC

DESCRIPTION	RECYCLE	LIST EA.	YOUR COST	EXTENSION	TAX
EN GLOVES MED	0.00	17.99	15.49		T
L HEAT HOSE	0.00	2.62	1.19	1.19	T
DED COOL HOSE	0.00	45.99	22.49	22.49	T
		66.60	0.00	39.17	2.74
TOTAL UNITS				TAXABLE	TOTAL TAX
				\$41.91	

RECEIVED BY: X

25.34 ✓

Sender

Anything Scout
704 E. Lincoln
Ames IA 50010
United States



Order # S-9333

02/24/20

Quantity	Item	Price
2 x	Fuel Tank J-Hook	\$7.00
1 x	Fuel Tank - Poly 19 Gallon	\$214.00
1 x	Fuel Tank Straps and J-Bolts - Scout II	\$55.00
1 x	Gas Cap, Locking - Scout II	\$24.00
1 x	LS - Scout II Electric 4 Fan Shroud	\$540.00
1 x	Fuel Sending Unit - 19 Gallon	\$59.00
1 x	LS - Exhaust System Kit (Scout II) - Exhaust Kit Alone	\$790.00
1 x	High Pressure Universal Fuel Pump Assembly - 255 LPH - Up to 630 hp	\$240.00
1 x	Complete Kit - LS Swap Scout II - Gen IV / 6L80 / NP241c / Scout II	\$3,270.00

Subtotal price:	\$5,206.00
Total tax:	\$0.00
Shipping:	\$262.00
Total price:	\$5,468.00
Total paid:	\$5,124.00

LOCAL: 786-472-8500

TOLL FREE:

1-800-293-1848

info@cobratransmission.com

COBRA TRANSMISSION
126 E CENTER AVE
SEBRING, FLORIDA 33870
USA



Cobra Transmission 1-800-293-1848
Performance and Quality Parts... Delivered.

SOLD TO:



Invoice No. 62953

Date Ordered: Sunday 16 February, 2020

Payment Method: PayPal

Products	Part #	Tax	Price (ex)	Price (inc)	Total (ex)	Total (inc)
1 x NP 241, Key & Spring Kit	331843A-2K	0%	\$13.99	\$13.99	\$13.99	\$13.99

Sub-Total: \$13.99
United States Postal Service (EMS) (Priority Mail™ Small Flat Rate Box): \$10.15
Total: \$24.14

Date Added	Status	Comments
02/16/2020 15:15:33	Processing	--none--
02/16/2020 15:15:34	Processing	Transaction ID: 42877996@0597950E Payment Type: PayPal Express Checkout (instant) Timestamp: 2020-02-16T20:15:31Z Payment Status: Completed Amount: 24.14 USD


TERMS AND CONDITIONS

1. There is no restocking fee, shipping back to us is the responsibility of the purchaser.
2. No returns or refund after 30 days.
3. No returns on electrical parts, special order parts or repair / technical manuals.
4. No returns on parts or kits that have been opened.
5. Claims on damages, errors or shortages must be reported on day of delivery.
6. For more information please click on the Shipping & Returns link.



HOFFMAN BROTHERS AUTO PARTS

314 E MARKET ST
WARSAW, IN 46580
574-267-3157



SOLD TO:
WSAWIN CASH SALE ACCOUNT
314 E MARKET ST
WARSAW
IN 46580

Thank
Meet
Th
The

REF #	ACCT #	P.O. #	SLM	PG	INV DATE	INVOICE #	TIME
	999569		TB	1	3/18/2020	M/CARD 569-090754	08:44


QTY	LINE	PART NUMBER	DESCRIPTION	LIST	COST	EXTEND	TAX
1	630	300A7514	MERIT Tubing	69.96	39.09	39.09	Y

UNITS	BATT	FRT	LABOR	MISC	CORE	NON-TAX	TAXABLE	TAX
1							39.09	2.74

RECEIVED BY: _____

PAY THIS AMOUNT ==> **41.83** ✓

INVOICE MUST ACCOMPANY RETURNED MERCHANDISE
NO RETURN OF ELECTRICAL PARTS ONCE INSTALLED




Quality Automotive Parts and Accessories



Packing Slip

Date : 04/01/2020
Order# : 000013748
Shipping : 5 Business Days - Standard
Method : Shipping



SKU	Details	Quantity	Amount
RH8-06	SAE J30 R9 fuel hose, FKM inner bore, aramid fiber reinforcement, 3/8" ID	✓ 15	\$85.65
PL-06	Hose end, push-lock, straight, -6AN, black	✓ 2	\$9.80
HS1-10	Silicone fire-retardant hose sleeve, black, 5/8" ID, Suitable for up to -8AN hose	✓ 1	\$14.40
HCP-1004	Adel mounting clamp, 5/8" ID, black EPDM, zinc-plated steel, for -6AN hose	✓ 10	\$9.90
MQ-06-06	Adapter, -6AN Male flare to 3/8" quick connect EFI male tube, black	✓ 1	\$6.90
Discount Coupon	Save 20%	1	\$-25.33
Total		30	\$101.32

Shipping Method : 5 Business Days - Standard Shipping
Tracking ID :
Payment Method : PayPal Express Checkout

Questions? Email sales@raceflux.com or call 407-613-2120



1-800-230-3030
SummitRacing.com

1-800-709-1079
PowerSportsPlace.com

• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
• 960 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
• 20 King Mill Road • McDonough, GA 30253 • 770-288-3200
• 2200 E. Interstate 20 • Arlington, TX 76018 • 682-375-2700

INVOICE

S
H
I
P
T
O

Calling Customer Service?
Please have your
invoice number ready.

INVOICE NUMBER DATE
5790248 04/12/20

CUSTOMER NUMBER PAGE
15672132 1

EXCHANGE/RETURN FORM

INVOICE NUMBER DATE
5790248-3 04/12/20

NOTE: Please read the **How to Return an Order** instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ()

Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- Q. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other, please explain

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
3	SUM-610332	EXHAUST HANGER WELD GROM		13.99	41.97 T
1	RSD-VCS6902	CLIP SET		18.00	18.00 T
1	TTN-45253	80PC VACUUM CAP ASSORTME		14.99	14.99 T
1	APF-ALL48365	#3 HOSE 24 IN. LONG		13.99	13.99 T
1	ADO-12559760	POWER BRAKE BOOSTER CONN		6.99	6.99 T
1	BAR-989549ERL	BRAKE ADAPTER -3 TO 7/16		6.64	6.64 T
** DECLARED PART VALUE THIS SHIPMENT **			102.58	U.S.D.	
** TOTAL INVOICE INDIANA SALES TAX **					10.19

Qty.	Part Number	Exchange	Refund	City	Reason Code	Explanation
3	SUM-610332					
1	RED-VCS6902					
1	TTN-45253					
1	APF-ALL48365					
1	ADO-12559760					
1	BAR-989549ERL					
** DECLARED VALUE		102.58				

PRIORITY MAIL RETURNS® SERVICE

Owen Brown
410 North Tk Way
North Webster, IN 46555
Odr: 5790248

NO POSTAGE
NECESSARY IF
MAILED IN THE
UNITED STATES

Summit Racing Equipment
Attn: Returns Dept.
3800 Mogadore Industrial Pkwy.
Mogadore, Oh. 44260-1234

USPS TRACKING NUMBER



9201 9902 3186 7045 4625 81

NOTE: If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.

*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank You! Delivery Upgrade Fee 21.50 T

Credit Card Charge 132.77

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:
GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16550411

U0003019



1-800-298-3038
SummitRacing.com
1-800-709-1078
PowerSportsPlace.com

Calling Customer Service?
Please have your
Invoice number ready.

INVOICE NUMBER: 4518597 DATE: 01/23/20

CUSTOMER NUMBER: 15672132 PAGE: 1

EXCHANGE/RETURN FORM

INVOICE NUMBER: 4518597-6 DATE: 01/23/20



NOTE: Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

Phone: ()

Reason Codes

- N. No longer need the part
- D. The part is defective, or missing a piece
- O. I am not happy with the quality of this product
- W. Part was not what I ordered
- I. I ordered the wrong part
- S. Other, please explain

INVOICE

S
H
I
P
T
O

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	MPE-11229	MUFFLER		105.05	105.05 T
** DECLARED PART VALUE THIS SHIPMENT **			105.05	U.S.D.	
** TOTAL INVOICE INDIANA SALES TAX **					7.36
					Credit Card Charge 112.41

Qty.	Part Number	Exchange	Refund	Qty.	Reason Code	Explanation
1	MPE-11229					
** DECLARED VALUE		105.05				

NOTE: If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.

*Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank You!

Owen Brown
410 North Tik Way
North Webster, IN 46555
Dir: 4518597

Summit Racing Equipment
Attn: Returns Dept.
3800 Mogadore Industrial Pkwy.
Mogadore, Oh. 44260-1234

NO POSTAGE
NECESSARY IF
MAILED IN THE
UNITED STATES

PRIORITY MAIL RETURNS® SERVICE

USPS TRACKING NUMBER



9201 9902 3186 7038 1792 43

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:
GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

S16550123

U0000736


Dirty Dingo Motorsports

Dirty Dingo Motorsports Packing Slip



Dirty Dingo Motorsports Packing Slip

Dirty Dingo Motorsports
506 E JUANITA AVE STE 3
MESA, AZ 85204



Item	Description	Price	Qty	Ext. Price
DD-LS-AC-STOCK	LS Swap AC Compressor adapter fittings for Denso 10S17F & 10S20F	\$32.99	1	\$32.99
DD-TENS-LMAC	Low Mount AC Tensioner	\$34.99	1	\$34.99

Thank You for Your Order!

Sub Total: \$67.98

Shipping: \$8.50

Total: \$76.48



INSTALLATION INSTRUCTIONS CAN BE FOUND ON OUR WEBSITE

www.dirtydingo.com

Technical Support: 480-824-1968

All returns/exchanges MUST be reported/approved within 30 days of the original invoice date.

Returns will not be accepted if installed, modified, painted, or altered in any way.

Any returned products must be in resellable condition to qualify for a refund/exchange.

PICKED BY: AW

PACKED BY: 59

Thank you for purchasing from Summit Racing Equipment. Go to www.summitracing.com for more great products.



Sales Order Packing List

3/9/2020 12:09 PM
Page 1
TRUCKHERO\MIRNAPIZ

Source ID ED112405

Recipient

1

Packing Date 3/9/2020

Package No. P1773890
Customer PO No. 908792420
Shipping Agent Code UPS
Shipping Agent Service GROUND
Closed by Packing Station GA-PACK01
External Tracking No. 1Z5212W00321813410
Calculation Weight 5

Type	No.	UPC	Description	UOM	Quantity
Item	11250.09		Interior Courtesy Lighting Kit; 07 -20 JK/JL/JT	EA	1

Fuel Tank Straps - 2 Pack - 1000000
Gas Cap Locking - 1000000
LS - 2000-2005 Ford F-150 Fuel System - 1000000
Fuel Sending Unit - 18 Gallon
LS - Exhaust System Kit (Scout II) - Exhaust Kit Alone
High Pressure Universal Fuel Pump Assembly - 255 LPH - Up to 50Psi
Complete Kit - LS 2000-2005 Ford F-150 - Gen IV 16.50 - MP/Part 1 Scout II

Rodger Swift - customer

Sender

Anything Scout
704 E. Lincoln
Ames IA 50010
United States

Feb. 20th → Needs
LS Kit by then



Order # S-9333

01/21/20

Quantity	Item	Price
2 x	Fuel Tank J-Hook <i>Returned</i>	\$7.00
1 x	Fuel Tank - Poly 19 Gallon <i>drop shipped</i>	\$214.00
(1)x	Fuel Tank Straps and J-Bolts - Scout II	\$55.00
(1)x	Gas Cap, Locking - Scout II	\$24.00
(1)x	LS - Scout II Electric 4 Fan Shroud <i>Returned difference</i>	\$540.00
1 x	Fuel Sending Unit - 19 Gallon <i>drop shipped</i>	\$59.00
1 x	LS - Exhaust System Kit (Scout II) - Exhaust Kit Alone	\$790.00
(1)x	High Pressure Universal Fuel Pump Assembly - 255 LPH - Up to 630 hp	\$240.00
1 x	Complete Kit - LS Swap Scout II - Gen IV / 6L80 / NP241c / Scout II	\$3,270.00

Subtotal price:	\$5,206.00
Total tax:	\$0.00
Shipping:	\$262.00
Total price:	\$5,468.00 ✓

Sales Receipt

Date Receipt No.

2/17/2020 38952



PERFORMANCE SYSTEMS INTEGRATION

2029 Route 88

Phone # 732 444-3277

Web Site PSICONVERSION.COM E-mail SUPPLYCHAIN@psiconversion.com




Sales Rep

Item	Qty	CK	Description	Ext. Price
HAR-1073	1	<input checked="" type="checkbox"/>	'09 - '14 LH6/LY5/LMG/LH8 (5.3L) w/ 6L80E Standalone Harness ALTERNATOR TYPE:2 PIN ALTERNATOR CONNECTOR CAM SENSOR TYPE:NON-VVT INTAKE MANIFOLD / MAP SENSOR TYPE:2009-NEWER VORTEC TRUCK INTAKE MANIFOLD / BOSCH MAP SENSOR MASS AIR FLOW TYPE (WIRING MUST MATCH SENSOR USED):LS3/LS7 MAF SENSOR (CARTRIDGE STYLE) PEDAL TYPE:VORTEC TRUCK TRANSMISSION TYPE:6L80E/6L90E ADD PSI BRAIDED LOOM KIT (BRD-1001 SAVE \$5):NO ADD A PEDAL TO YOUR HARNESS:NO ADD ENGINE GROUND KIT (SAVE \$5):YES + \$44.95 Add Engine Ground Kit (SAVE \$5)	763.95T
MOD-1007	1	<input checked="" type="checkbox"/>	ENGINE YEAR, AND VEHICLE MODEL:2012 Silverado GEN IV CAM SENSOR MODIFICATION	0.00T
MOD-1037	1	<input checked="" type="checkbox"/>	GEN IV & V VORTEC/ECOTEC3 TRUCK PEDAL CONNECTOR	0.00T
KIT-1025	1	<input checked="" type="checkbox"/>	LS Engine Ground Kit	0.00T

HARNESS AND/OR PCM FOR NON-EMISSIONS CONTROLLED VEHICLES

Subtotal

WORK ON THIS ORDER WAS PROUDLY PERFORMED BY 

Sales Tax (0.0%)

RETURNS NOT ACCEPTED WITHOUT AN RMA RETURN AUTHORIZATION NUMBER. ALL RETURNED GOODS MUST BE ACCOMPANIED BY A COPY OF THE SALES RECEIPT. RETURNS MUST BE IN NEW AND RESALABLE CONDITION.

Total

THANK YOU FOR CHOOSING PSI, YOUR LSX SPECIALIST!
PSICONVERSION.COM

Page 1 FACEBOOK.COM/PSICONVERSION

JB Conversions, Inc

Superior Gearing and Drivetrain Components.


132 Beauregard Ave. • P.O. Box 2683 • Sulphur, LA 70663
(337) 625-2379 • Fax (337) 625-8365
www.jbconversions.com

Invoice

DATE	INVOICE #
2/5/2020	20088

BILL TO:

SHIP TO:



P.O. NUMBER	TERMS	REP	SHIP	VIA	F.O.B.	PROJECT
OLO #8119	MC	OLO	2/5/2020	UPS		

QUANTITY	ITEM CODE	DESCRIPTION	PRICE EACH	AMOUNT
1	2035	NP241 Master Rebuild Kit	225.00	225.00
1	1940	Yoke-High Clearance Shorty 1310 CV (32 spline)	75.00	75.00
1	2019	Chain - (OEM Borg-Warner for NP241C/DLD)	150.00	150.00
	UPS1	UPS Ground & Handling	55.98	55.98

Thank you for your business.

TOTAL

\$505.98

Refer to back for Terms, Conditions and Warranty Information.

Packed By
NW

Dakota Digital

CRC-1000

Drive-by-Wire Voltage Controller

Introduction
You have purchased one of

Enhanced Adaptability

control features:

AT-98 Computerized Test Report

213-4828/1

PASS

10/21/2019 10:21

Operator No. 7869

859315

12V, 160A, NEG

Cell No. 1

This alternator has an internal voltage regulator

Plug Code
919

Terminals / Application: #N/A


Test Results Table:

Maximum Alternator Output:	Amps	191
Maximum Output Power:	Watts	2511
Voltage Set Point:	Volts	14.8
Leakage Current:	mAmps	0.98
Ripple Current:	Amps	45
Alternator Turns On Speed:	RPM	950
Regulator Activation Speed:	RPM	0
Secondary Regulation:	Volts	-
Tachometer Frequency:	Hz	-
Stator Voltage:	Volts	0.1
Field Current:	Amps	0.0
Lamp Style:	-	Inactive
Lamp Type:	-	Standard
LRC Delay:	Sec	2.0
Feedback (Full Load):	Volts	12.5
Feedback (Minimum Load):	Volts	1.8
Regulator Voltage (at Computer Control Function Test):	Volts	12.7

Output Current Table:

Output Current at 2000 RPM:	Amps	146
Output Current at 3000 RPM: <td>Amps</td> <td>173</td>	Amps	173
Output Current at 3500 RPM: <td>Amps</td> <td>179</td>	Amps	179
Output Current at 5000 RPM: <td>Amps</td> <td>180</td>	Amps	180
Output Current at 6000 RPM: <td>Amps</td> <td>191</td>	Amps	191
Output Current at 0 RPM: <td>Amps</td> <td>0</td>	Amps	0
Output Current at 0 RPM: <td>Amps</td> <td>0</td>	Amps	0
Output Current at 0 RPM: <td>Amps</td> <td>0</td>	Amps	0

Output tested @ 13.18955 V



MAGNAFLOW
Customer Performance Warranty
complete warranty on back)

ACE
6112
THANK YOU FOR PURCHASING
213-4828-1099

PLEASE HELPING
05/07/19
5600
CO. DETROIT

THANK YOU FOR PURCHASING
213-4828-1099

00541

01-099-015-0164

Dakota Digital

CRC-1000 Drive-by-Wire Cruise Control System

Introduction

You have purchased one of the finest cruise control systems on the market. The cruise control features:

Enhanced Adaptability

- Works with GM LS engine/trans drivetrain
- Compact design allows for more mounting locations
- Manual or automatic transmission capability
- Fully plug and play design
- Connects directly to OBD port for less wiring

Easier Installation

- Compact module
- Single unit mounting
- No clutch switch needed
- Plug and play design
- OBD adaptable for less wiring

Kit Contents/Part numbers

Item	Qty	Description	Part #
1	1	Cruise control module	CRC-1000
2	1	Switch harness	250-XXXX
3	1	Pedal interface harness	250-2769
5	1	OBD DLC Harness	250-2785

Enhanced Features

- Compact design
- Removable wiring harness with locking device
- Cruise engaged output (ground signal when engaged)

Improved Operation

- Closer, more accurate control of set speed
- Accurate coast/reduce speed
- Tap-Up, 1 MPH per tap
- Tap-Down, 1 MPH per tap
- Controlled resume rate

Recommended Tools

- Safety glasses
- Volt-Ohm meter
- Soldering iron
- Electrical tape or heat shrink



FIG. 14

Neutral Safety Switch Wiring

If your transmission controller has a neutral safety switch, use that output instead of the neutral safety switch to function properly. The shift lever must be in the Neutral position for the neutral safety switch to function properly. The shift lever must be in the Neutral position for the neutral safety switch to function properly. The shift lever must be in the Neutral position for the neutral safety switch to function properly.

Step 17: For the neutral safety switch to function properly, the shift lever must be in the Neutral position for the neutral safety switch to function properly.



WWW.DAKOTADIGITAL.COM

INSTALLATION

HND-1

1. This unit will work on turn signal shafts .30" diameter or less. For reference, a 5/16" bolt measures .312".
2. Cut existing turn signal handle to desired length.
3. Slip the new Dakota Digital handle over the existing handle.
 - o Adjust to appropriate length
4. Tighten set-screws on back side

HND-(1-7) Cruise Control Handles

HND-2

1. Find a convenient location on a flat surface.
2. Using the switch, measure and mark the location of the holes and drill three 9/32" holes in the mounting surface.
 - o Feed the wires through the middle hole and press the mounting 'legs' through the outer two holes.
3. Push the wires into the white plug. The location of each wire is labeled on the plug.
4. Connect the black and blue wires to ground.
5. The pink wire will not be used. Cut off or tie up out of the way and tape the end.
6. Insert the new handle and tighten the original screw to secure it.

HND-3

1. To gain access to the screw securing the handle, remove the steering wheel and adapter if applicable.
2. Remove the screw in the flat end of the existing turn signal handle.
3. Insert the new handle and tighten the original screw to secure it.

HND-4, 5, 6

1. If installing HND-4 in an application originally equipped with a wiper controls on the handle, the black handle be turned as the alignment tab is in a different position. Clamp chrome stalk in a vice, taking care not to damage the black plastic section on the appropriate amount, about a quarter turn counter-clockwise.
2. Grasp the original turn signal handle and pull straight out.
3. It may be necessary to wiggle the handle when pulling outward.

HND-4, 5, 6

1. The new handle will install the same way the old unit came out.
2. Remove the original turn signal lever but turn the black wire around the new handle.
3. Insert the new handle and tighten the original screw to secure it.

HND-4, 5, 6

1. If installing HND-4 in an application originally equipped with a wiper controls on the handle, the black handle be turned as the alignment tab is in a different position. Clamp chrome stalk in a vice, taking care not to damage the black plastic section on the appropriate amount, about a quarter turn counter-clockwise.
2. Grasp the original turn signal handle and pull straight out.
3. It may be necessary to wiggle the handle when pulling outward.

HND-4, 5, 6

1. The new handle will install the same way the old unit came out.
2. Remove the original turn signal lever but turn the black wire around the new handle.
3. Insert the new handle and tighten the original screw to secure it.

TECHNICAL SUPPORT
before taking more extensive correction actions for any connections on the indicated circuit, INCLUDING THE CONNECTOR, are clean and tight. Inspect the wiring in exposed wires. Finally, insure all ground wires are clean and s

AUC
468 N
BER
269-



GENERAL COMPRESSOR INSTALLATION

IMPORTANT: If compressor has failed, replacement of the condenser is strongly recommended.

Read this instruction sheet prior to starting any repairs. Follow all local, state, and federal regulations when servicing auto A/C systems.

1. Remove the compressor, receiver/drier or accumulator, orifice tube or expansion valve, from the vehicle.
2. Flush the condenser, evaporator, and hose assemblies without mufflers using non-oil based A/C flush.
 - Flush the condenser from outlet to inlet.
 - If the compressor had a major failure, the condenser and any hose with a muffler should be replaced. (The manufacturer recommends all parallel flow condensers be replaced as they are impossible to flush.)
 - On systems with an expansion valve, remove the valve before flushing the evaporator.
 - Flush the evaporator from inlet to outlet.
3. Drain the oil from the new compressor at the suction & discharge ports or drain plug. Verify correct oil type; details should be stated on the compressor label. Before adding oil charge, check specific application system requirements.
 - Refer to the under-hood decal or OEM service manual for total oil and refrigerant charge.
 - Install half of the new oil charge into the new compressor.
 - Turn the compressor shaft 8-10 full rotations using a spanner wrench. This will ensure proper lubrication for the front seal and internal parts on initial startup.
 - Install the remaining required oil in the receiver drier, condenser, and evaporator.
4. Install the new compressor, receiver/drier or accumulator, new orifice tube or expansion valve, and replace O-rings.
 - If your original compressor comes with a pressure switch, you will have to remove this switch from your original compressor and install it in your new compressor. If the pressure switch is held in by a snap ring, it also must be removed and reinstalled with the pressure switch.
5. Using a vacuum pump, evacuate the A/C system for a minimum of 1 hour.
 - After evacuating the system for 1 hour, check to see if the pressure gauges are holding below 0 on both the low and high side. Let system rest for 10 minutes. To ensure that the system is properly sealed, the vacuum readings should not change more than 5 PSI.
6. Confirm and then start the engine, open the doors & windows, and set the A/C controls on MAX AIR with high blower speed.
7. Install the proper amount of refrigerant into the system and let the gauges equalize. This will allow the refrigerant to spread the oil more evenly.

T-N-T PERFORMANCE
 420 S. Sycamore Street
 Syracuse, IN 46567
 Phone 574-678-1167 Fax 574-457-1167

INVOICE

4277

INVOICE

T-N-T Performance
 420 S Sycamore St, Syracuse IN
 46567
 574-518-1167

1979 International - Scout II - LB

Date: 10/19/2020

Customer: License No:

Order No:

Date: 10/19/2020

Company:

Odometer:


VIN:

Technician:

Odometer In: 2

Odometer Out: 2

Vehicle: 1979 International Scout



Besides improved fuel economy, handling and safety, what do these measurements mean?



CASTER is the tilt of the axis that the wheel steers around. It affects how the vehicle tracks as you drive down the road and can affect handling.



CAMBER is the angle of the tire in relation to the road surface. It affects tire wear, and handling when turning.



TOE is a measurement of how much the wheel is turned in or out from a straight-ahead position. It affects tire wear, handling and can make your steering wheel crooked.

Your vehicle has been aligned using a precision **JohnBean** wheel aligner.

2.34, United States Domestic, US2018R02



1978 Scout II

