

Buck Bros. Sunny Slope Auto LLC
 710 W Potter Ave
 Kirksville, MO. 63501-1170
 Phone: 660-665-8464 Fax: 660-665-1636

INVOICE

5822

Org. Est. # 005571

Date: 05/23/2019

1969 AMC - AMX - 290 V-8

Lic # : KB6-J4D

Odometer In : 69510

Unit # : AMX 10218

VIN # : A9C397N219774

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
MISC. PARTS, motor oil, oil filter, anti-freeze, gear lube, automatic transmission fluid, hose clamps, 5/8 & 3/4 heater hose, hose clamps, fuel hose, rear differential vent hose, brake cleaner, vacuum hose, wiper blades, SHIPPING. MISC. PARTS	1.00	402.69	402.69	Check over, Fix brakes pulls when applying brakes, Get to run correctly. 08/28/2018. Won't start, Charge battery, Needs battery, check ignition system, check fuel supply, fuel pump is bad, fuel tank is full of bad gas & some water, Needs new fuel pump, new fuel sending unit. Check rear brakes-GOOD. Remove front brake drums, Check front brakes-needs front brake shoes, front wheel cylinders, front brake hoses, front wheel bearings replaced, grease seals. Needs right outer tie rod end. Radius arm bushings-both sides. Needs carb. Needs battery hold downs, battery cables. Needs belts, needs exhaust system fixed.	580.00
Front wheel bearing & race-outer. BR2-5	2.00	15.96	31.92	Replace parts as needed.	2,320.00
Front Wheel bearing & race-inner. BR6VP-5	2.00	17.70	35.40	Replace battery, Replace battery cables, install battery hold down.	
Front Grease Seals 16659-5	2.00	17.98	35.96	Remove fuel tank, clean out inside of tank, replace fuel sending unit, pickup screen, retaining ring & gasket, replace fuel pump with re-manufactured fuel pump, install new vacuum hoses, install new carburetor, hook up new fuel line, fuel filter. Replace dist. cap & rotor, spark plug wire set. Replace thermostat & gasket, replace alternator belt, power steering belt, repair power steering hose, add new P/S fluid, replace oil sending unit, add new anti-freeze, check coolant hoses & clamps, replace heater hoses & clamps. Replace front brake shoes, front wheel bearings, races, grease seals, resurface front brake drums, wheel cylinders, front brake hoses, bleed brakes. Adjust brakes. Replace right outer tie-rod end.	
Front Brake Cylinders 37125-5, 37126-5	2.00	50.10	100.20	Replace front strut radius arm bushings, replace sway bar end links, replace front & rear shocks, Front-end alignment. Remove A/C system. Replace dash lights, console housing lens & bulb. Remove old exhaust, Install new exhaust pipes, mufflers, tail pipes, hangers. Change transmission fluid, replace filter & pan gasket, replace shifter shaft seal. Change oil & oil filter. Remove differential cover drain out old gear lube, clean out housing, re-seal rear cover, add new gear lube. replace wiper blades.	
Console Housing Light Lense 6819N	1.00	35.00	35.00		
console light bulb 3405N	1.00	2.00	2.00		
Fuel sending unit w/float 936-1503A-APD	1.00	139.10	139.10		
Fuel Tank Seal 936-1507-APD	1.00	4.95	4.95		
Fuel pick-up screen 941-3400-APD	1.00	18.98	18.98		
Fuel Tank Retainer Lock 936-1506-APD	1.00	12.35	12.35	Gasoline	65.00
Front Brake Hoses. Left & Right. 981-1601-APD	2.00	24.98	49.96	Gas 25 gallons @ 2.59	
Tie Rod End-Right Outer 101-2601-APD	1.00	32.50	32.50		
Strut Rod Bushing Kit. Pair. 100-5506E-APD	1.00	50.78	50.78		
Fuel Pump W/Vacuum for wiper motor. 941-1001D-APD	1.00	230.00	230.00		
Mr. Gasket base plate gasket 55	1.00	7.98	7.98		
Edelbrock 600 CFM Electric choke carb. 1406	1.00	389.98	389.98		
Fuel Filter FF3424DL-8	1.00	6.29	6.29		

Visit us on the web : www.buckbrothersauto.com

Our Email Address: buckglen4957@yahoo.com

Buck Bros. Sunny Slope Auto LLC
 710 W Potter Ave
 Kirksville, MO. 63501-1170
 Phone: 660-665-8464 Fax: 660-665-1636

INVOICE

5822

Org. Est. # 005571

Date: 05/23/2019

1969 AMC - AMX - 290 V-8

Lic # : KB6-J4D

Unit # : AMX 10218

VIN # : A9C397N219774

Odometer In : 69510

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Interstate Battery MT-35	1.00	119.50	119.50		
Positive battery cable-RED 781175-5	1.00	19.82	19.82		
Negative battery cable-Black 781101-5	1.00	13.70	13.70		
BELTS-Alternator, Power steering Belts. BELTS	2.00	79.41	158.82		
Oil Sending unit for dash light. OP-6613-5	1.00	19.92	19.92		
Distributor cap RR165-5	1.00	27.41	27.41		
Rotor RR169R-5	1.00	13.96	13.96		
Spark plug wire set 700156-5	1.00	44.29	44.29		
Thermostat & gasket PM195-0025-5	1.00	11.68	11.68		
Muffler 2" inlet & outlet 3756	1.00	49.95	49.95		
2" Exhaust pipe 2" Exhaust pipe	2.00	59.95	119.90		
2" Tailpipe 2" Tailpipe	2.00	69.95	139.90		
Front Sway Bar End Link Kit SL-69-8	2.00	11.51	23.02		
Classic Rear Shocks 82155-8	2.00	34.40	68.80		
Classic Front shocks 82069-RA	2.00	34.40	68.80		
Exhaust Flange Gaskets F7171-8	2.00	12.68	25.36		
Transmission filter & pan gasket kit. 1-4717-5	1.00	12.86	12.86		
mini bulb 158LLBP-6	1.00	8.20	8.20		
Instrument Panel Light Socket 5/8 EL957	5.00	5.75	28.75		
Brake shoes - Front TS-155-5	1.00	39.33	39.33		
Fel-Pro Valve cover gasket set. VS-50001-C	1.00	27.88	27.88		

Visit us on the web : www.buckbrothersauto.com

Our Email Address: buckglen4957@yahoo.com

Buck Bros. Sunny Slope Auto LLC
 710 W Potter Ave
 Kirksville, MO. 63501-1170
 Phone: 660-665-8464 Fax: 660-665-1636

INVOICE

5822

Org. Est. # 005571

Date: 05/23/2019

1969 AMC - AMX - 290 V-8
 Lic # : KB6-J4D
 Unit # : AMX 10218
 VIN# : A9C397N219774

Odometer In : 69510

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Black floor Mats	1.00	37.98	37.98		
324-Black					
Shop Supplies			24.50		



Org. Estimate 552.88 Revisions 0.00 Current Estimate 552.88

Labor:	2,900.00
Parts:	2,690.37
Sublet:	65.00
SubTotal:	5,655.37
Tax:	224.65
Total:	5,880.02
Bal Due:	\$0.00

[Payments - Check (#570) - \$5,880.02]

Vehicle Received: 8/31/2018

Customer Number : 1457

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs there. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Visit us on the web : www.buckbrothersauto.com

Our Email Address: buckglen4957@yahoo.com

Please send us a picture of your Classic AMC car for our website gallery



Kennedy American, Inc.

AMX * Javelin * Jeep * Rambler * AMC
 7100 STATE ROUTE 142 S.E.
 WEST JEFFERSON, OHIO 43162
 (614) 879-SAVE (7283)
SALES@KENNEDYAMERICAN.COM

Invoice# I009981
 Invoice Date 12/13/2007

Due Date 12/13/2007

Bill To 04109-000-CL	Ship To 04109-000-CL	Telephone# 812-246-6165	County for Sales Tax NO SALES TAX	
Ship Via UPS		Sold By JEFF A. KENNEDY	Purchase Order#	Balance Due 0.00
[REDACTED]				

Qty	Part Number	Part Description	Unit Price	Ext. Amount
1	ZSPECIAL	RH tailpipe and muffler	175.00	\$175.00
1	WS467	AMX roof rail/fixd qtr. glass weatherstrips-PAIR	199.00	\$199.00
1	WS888	outer door belt weatherstrips-PAIR	69.00	\$69.00
			Parts Total	\$416.00
			Freight	\$12.52
Packing, Handling, Insurance			Sales Tax	\$0.00
			Invoice Total	\$428.52
			Paid	\$428.52
			Balance Due	\$0.00

10/16/07 MasterCard xxxx-xxxx-xxxx-9996 112007 91855Z