



ipd wpt Customer service: 503-257-7500 or 800-444-6473  
 11744 NE AINSWORTH CIR, PORTLAND, OR 97220 USA  
 SAVAGE INTERNATIONAL L.L.C. SERVING THE AUTOMOTIVE COMMUNITY SINCE 1963

8499707

Page 1 of 1

USPS PRIORITY MAIL

w1826876

BILL TO: 1478 M7  
 DAVID M VANDENBERG  
 5699 LARKIN ST  
 VENTURA CA 93003-4237

PICK RUN # 141305 ORDER DATE 2024-01-15  
 BATCH# INVOICE DATE 2024-01-15  
 GROUP# 1826876 CUSTOMER NO. 1478367  
 CART# 166820 ENTERED BY SVCACCT  
 SLOT# PO# 608172

Bn	Item #	Quantity	Unit	Description
10b5	101308	2	EACH	Aftermarket STUD MANIFOLD 2.00
				1972 VOLVO 1800 E 180 2 DR COUPE B20F RWD M41 D-JET

EDIT KEY 15039910  
 Unit Net 2.99 5.98

(Total may include items or services included in other shipments) Invoiced merchandise: 5.98  
 Taxes: 0.56  
 Invoiced shipping: 9.50  
 Invoice subtotal: 16.04  
 Payment: \*\*\*\*\*4828: 16.04  
 Total Due: 0.00

ipd wpt Customer service: 503-257-7500 or 800-444-6473  
 11744 NE AINSWORTH CIR, PORTLAND, OR 97220 USA  
 SAVAGE INTERNATIONAL L.L.C. SERVING THE AUTOMOTIVE COMMUNITY SINCE 1963

8499684

Page 1 of 1

USPS PRIORITY MAIL

w1826874

[Redacted]

PICK RUN # 141305 ORDER DATE 2024-01-15  
 BATCH# INVOICE DATE 2024-01-15  
 GROUP# 1826874 CUSTOMER NO. 1478367  
 CART# 166820 ENTERED BY SVCACCT  
 SLOT# PO# 608171

Bn	Item #	Quantity	Unit	Description
10d5	112436	8	EACH	Aftermarket WASHER EXHAUST MANIFOLD
				1972 VOLVO 1800 E 180 2 DR COUPE B20F RWD M41 D-JET

EDIT KEY 13039894  
 Unit Net 2.95 23.60

(Total may include items or services included in other shipments) Invoiced merchandise: 23.60  
 Taxes: 2.19  
 Invoiced shipping: 0.00

ipd wpt Customer service: 503-257-7500 or 800-444-6473  
 11744 NE AINSWORTH CIR, PORTLAND, OR 97220 USA  
 SAVAGE INTERNATIONAL L.L.C. SERVING THE AUTOMOTIVE COMMUNITY SINCE 1963

7933181

Page 1 of 1

BEST FREE SHIPPING (RS)

w1745763

[Redacted]

PICK RUN # 128164 ORDER DATE 2022-12-17  
 BATCH# INVOICE DATE 2022-12-21  
 GROUP# 1745763 CUSTOMER NO. 1478367  
 CART# 149914 ENTERED BY WEBSITE  
 SLOT# PO# 564195

Bn	Item #	Quantity	Unit	Description
04c5		10	EA	Aftermarket STRAP AXLE LIMIT 122S SDN/1800 COUNTRY OF ORIGIN: US-USA 1972 VOLVO 1800 E 180 2 DR COUPE B20F RWD M41 D-JET
14d1		10	EA	Bilstein B6 BILSTEIN B6 R 122/1800 57-73 COUNTRY OF ORIGIN: DE-GERMANY 1972 VOLVO 1800 E 180 2 DR COUPE B20F RWD M41 D-JET
33c4	100979	1	EACH	IPD SB KIT 1800EIES 1 1/8 F&3/4 R COUNTRY OF ORIGIN: US-USA 1972 VOLVO 1800 E 180 2 DR COUPE B20F RWD M41 D-JET

EDIT KEY 16660693  
 Unit Net 8.46 16.92

(Total may include items or services included in other shipments) Invoiced merchandise: 625.47  
 Taxes: 57.86  
 Invoice subtotal: 683.33  
 Payment: \*\*\*\*\*5453: 683.33  
 Total Due: 0.00

Alphatech

Vintage Volvo Innovation

For those who have searched for my website in vain, I apologise, [Redacted] use of the expense.

[Redacted] have owned, maintained and rebuilt many of the PV 544 thru the 140 series, and made mods [Redacted] found replacements for unobtainable parts, [Redacted] parts using modern materials.

[Redacted] completely rebuild 544/122 fuse boxes to accept [Redacted] es, and eliminate the inevitable corrosion and [Redacted] le keeping the cover for originality. [Redacted] ove box opening springs, and Over-ri-der [Redacted] e some of my items.

[Redacted] Clutch cross shaft elastic bushings om-544's fail and wear out their mounts. I make a Delrin kit to eliminate the problem. [Redacted] 122 Wagon tailgate latches were impossible to source so I developed a Delrin replacement kit Ask me about other fixes.

I still many custom Walnut gear shift knobs for classic models.

Pete Burrows. Contact me at :  
 alphatech@carolina.rr.com

COLD HOSE

Cold Hose

3611 NW 27th Ave / Ocala FL 34475 / United States  
 352-509-3281  
 Sales@Cold-hose.com  
 coldhose.com

INVOICE

SHP TO BILL TO

ORDER NO #39432  
 ORDER DATE 03-26-2024 01:42 PM  
 PAYMENT METHOD Credit Card

[Redacted]

ITEM	SKU	QTY	TAX	UNIT PRICE	TOTAL
[Redacted] Hose Female Sold	ATC3008L	1	0%	\$ 2.99	\$ 2.99
[Redacted] # 8 90 Degree O-ring Fitting	BL1322	1	0%	\$ 11.03	\$ 11.03
[Redacted] el Flow 10x18 Condenser	44-1018	1	0%	\$ 77.94	\$ 77.94
[Redacted] nsenser Bracket Mount Kit	CS1000	1	0%	\$ 5.49	\$ 5.49



**CARFECTION PRO INC**  
619 E Ventura Blvd, Oxnard, CA 93036  
Phone: (805) 278-3913

Workfile ID: 340e5f5a  
PartsShare: 6w69c6  
Federal ID: 83-3158574

**Preliminary Estimate**

Job Number: 325

Customer: [REDACTED]

Written By: Jose Rodriguez

Policy #: [REDACTED]  
Date of Loss: [REDACTED]

Claim #: [REDACTED]  
Days to Repair: 0

Owner: [REDACTED]

Inspection Location:  
CARFECTION PRO INC  
619 E Ventura Blvd  
Oxnard, CA 93036  
Repair Facility  
(805) 278-3913 Business

Insurance Company:

**VEHICLE**

1972 VOLV 1800E 2D CPE 4- Gasoline Cascade White

VIN: [REDACTED] Interior Color: [REDACTED] Mileage In: [REDACTED] Vehicle Out: 12/3/2022  
License: [REDACTED] Exterior Color: Cascade White Mileage Out: [REDACTED]  
State: [REDACTED] Production Date: [REDACTED] Condition: [REDACTED] Job #: 325

TRANSMISSION 4 Speed Transmission PAINT Three Stage Paint

**Preliminary Estimate**

Job Number: 325

Customer: [REDACTED]

1972 VOLV 1800E 2D CPE 4- Gasoline Cascade White

**ESTIMATE TOTALS**

Category	Basis	Rate	Cost \$
Parts			22.90
Body Labor	87.8 hrs @	\$ 75.00 /hr	6,585.00
Paint Labor	90.5 hrs @	\$ 75.00 /hr	6,787.50
Paint Supplies	90.5 hrs @	\$ 48.00 /hr	4,344.00
Miscellaneous			161.00
Other Charges			85.00
Subtotal			17,985.40
Subtotal	\$ 4,506.90 @	9.2500 %	416.89
Sales Tax			18,402.29
<b>Grand Total</b>			<b>18,402.29</b>
Deduction			0.00
<b>CUSTOMER PAY</b>			<b>18,402.29</b>
<b>INSURANCE PAY</b>			

FOR YOUR PROTECTION CALIFORNIA LAW REQUIRES THE FOLLOWING TO APPEAR ON THIS FORM: ANY PERSON WHO KNOWINGLY PRESENTS FALSE OR FRAUDULENT INFORMATION TO OBTAIN OR AMEND INSURANCE COVERAGE OR TO MAKE A CLAIM FOR THE PAYMENT OF A LOSS IS GUILTY OF A CRIME AND MAY BE SUBJECT TO FINES AND CONFINEMENT IN STATE PRISON.

THE FOLLOWING IS A LIST OF ABBREVIATIONS OR SYMBOLS THAT MAY BE USED TO DESCRIBE WORK TO BE DONE OR PARTS TO BE REPAIRED OR REPLACED:  
MOTOR ABBREVIATIONS/SYMBOLS: D=DISCONTINUED PART, A=APPROXIMATE PRICE, LABOR TYPES: B=BODY LABOR, D=DIAGNOSTIC, E=ELECTRICAL, F=FRAME, G=GLASS, M=MECHANICAL, P=PAINT LABOR, S=STRUCTURAL, T=TAXED MISCELLANEOUS, X=NON TAXED MISCELLANEOUS, CCC ONE=ADJ=ADJACENT, ALIGN=ALIGN, A/M=AFTERMARKET, BLND=BLEND, CAPA=CERTIFIED AUTOMOTIVE PARTS ASSOCIATION, D&R=DISCONNECT AND RECONNECT, EST=ESTIMATE, EXT. PRICE=UNIT PRICE MULTIPLIED BY THE QUANTITY, INCL=INCLUDED, MISC=MISCELLANEOUS, NACS=NATIONAL AUTO GLASS SPECIFICATIONS, NON-ADJ=NON ADJACENT, O/H=OVERHAUL, OP=OPERATION, NO=LINE NUMBER, QTY=QUANTITY, RECOND=RECONDITION, REFIN=REFINISH, REPL=REPLACE, R&I=REMOVE AND INSTALL, R&R=REMOVE AND REPLACE, RPR=REPAIR, RT=RIGHT, SECT=SECTION, SUBL=SUBLET, LT=LEFT, W/O=WITHOUT, W/ =WITH, \*\*=DATABASE LINE WITH ENTRY, +=OTHER (IE. MOTORS DATABASE INFORMATION WAS CHANGED) \*\*\*=DATABASE LINE WITH AFTERMARKET, N=NOTES ATTACHED TO LINE, OPT OEM=ORIGINAL EQUIPMENT MANUFACTURER PARTS EITHER OPTIONALLY SOURCED OR OTHERWISE PROVIDED WITH SOME UNIQUE PRICING OR DISCOUNT.

\*CURE TIME\* MEANS THE LENGTH OF TIME THAT, PER THE ADHESIVE MANUFACTURER, THE WINDSHIELD ADHESIVE NEEDS TO CURE UNTIL THE WINDSHIELD CAN PROPERLY FUNCTION AS A SAFETY DEVICE PURSUANT TO THE FEDERAL MOTOR VEHICLE SAFETY STANDARDS AND THE VEHICLE MANUFACTURER'S SPECIFICATIONS.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.  
The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:  
BAR=Bureau of Automotive Repair, EPA=Environmental Protection Agency, NHTSA= National Highway

**Preliminary Estimate**


Job Number: 325

Customer: [REDACTED]  
1972 VOLV 1800E 2D CPE 4- Gasoline Cascade White

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1 #	Repl	Front panel		1		8.0	3.5
2		Add for Three Stage					1.4
3 #	Rpr	RT Fender				3.0	4.0
4		Add for Three Stage					1.6
5 #	Rpr	LT Fender				3.0	4.0
6		Add for Three Stage					1.6
7 #	Rpr	Windshield opening				5.0	1.5
8		Add for Three Stage					0.6
9 #	Rpr	Cowl panel				4.0	3.0
10		Add for Three Stage					1.2
11 #	Repl	Battery tray		1		3.5	1.0
12 #	Repl	Hood		1		2.0	4.0
13		Add for Three Stage					1.5
14 #	Rpr	Roof panel				6.5	5.0
15		Add for Three Stage					2.0
16 #	Rpr	RT front floor panel				7.0	3.0
17 #	Rpr	RT Door				3.0	4.0
18		Add for Three Stage					1.6
19 #	Rpr	LT Door				3.0	1.5
20		Add for Three Stage					0.6
21 #	Rpr	Back glass opening				7.5	7.0
22		Add for Three Stage					2.8
23 #	Rpr	RT Quarter panel				7.5	7.0
24		Add for Three Stage					2.8
25 #	Rpr	LT Quarter panel				6.0	5.0
26		Add for Three Stage					2.0
27 #	Rpr	Rear end panel				5.0	4.0
28		Add for Three Stage					1.6
29 #	Rpr	Trunk lid				10.00 X	0.4
30		Add for Three Stage					0.4
31 #	Repl	Cover Car		1	10.00 X		3.0
32 #	Repl	Cover Car for primer		1	50.00 T		6.0
33 #	Repl	Weld-through primer					5.0
34 #	Rpr	Color sand and buff		1	90.00 T		3.00 X
35 #	Repl	Corrosion protection		1	3.00 X		
36 #	Sub	Hazardous waste removal		1	22.90		
37 #	Repl	Information Label					
38		OTHER CHARGES					
39 #	Towing			1	85.00		
<b>SUBTOTALS</b>					<b>268.90</b>	<b>87.8</b>	<b>90.5</b>

**INVOICE**

DATE: JULY 5, 2021



SALESPERSON	P.O. NUMBER	REQUISITIONER	SHIPPED VIA	F.O.B. POINT	TERMS
Peter Bayer			USPS		Due on receipt



  

QUANTITY	DESCRIPTION	UNIT PRICE	TOTAL
1	2.5 inch Smith Tachometer	199.00	
1	4.5 inch Smith Speedometer	135.00	
1	2.0 inch Smith Water temp gauge	135.00	
1	2.0 inch Smith Oil temp gauge	135.00	
1	2.5 inch Smith Tank gauge	135.00	
1	2.5 inch Smith Oil Pressure gauge	199.00	
1	2.5 inch Smith Clock		
		<b>SUBTOTAL</b>	
		<b>SALES TAX</b>	
		<b>SHIPPING &amp; HANDLING</b>	
		<b>TOTAL DUE</b>	



**Invoice**

Invoice no.: 1047308	Date: 2022-09-19	Cust.no.: 305144	Due date: 2022-09-19	Page: 1
----------------------	------------------	------------------	----------------------	---------



Payment terms: Webshop (Prepaid)	Seller: Webb	Marked: Web 9028	Del.method: Other
----------------------------------	--------------	------------------	-------------------

Part No	Description	Order No	Qty	Price	Disc %	
654373	Front section 1800 BR196172	75174	1	1250.00		1250.00
SH	Shipping and handling	75174				312.74

Thanks for shopping with VP Autoparts, Inc.  
Your business is highly appreciated!

Sum 1 562,74  
VAT  
Rounding  
To pay: USD 1 562,74

Address: VP Autoparts, Inc.  
3225 Fortane Drive  
NORTH CHARLESTON, SC 29418-3476

Phone: (843) 760-0170  
E-mail address: sales@vp-autoparts.com  
Fax: www.vp-autoparts.com



Vintage Becker and Blaupunkt Sales and Restoration Specialist.  
411 W Lambert Road  
Suite 405  
Brea CA 92821  
Phone # 714-744-4438  
www.creativecaraudio.com  
Info@creativecaraudio.com

**PAID**  
03/07/2023

**Creative Car Audio**  
Vintage Becker & Blaupunkt Radio  
Sales & Service Specialist  
(714) 744-4438  
Info@creativecaraudio.com  
www.creativecaraudio.com  
411 W Lambert Road, Suite 405, Brea

Ticket Number	Order Number
178495	
Customer ID	Ship To
Store Customer	
Ship Back Date	Payment Method
2/28/2023	

Item Code	Description	Quantity	Price Each
Repair	Blaupunkt Frankfurt Radio Model# and Serial# not available	1	0.00
Parts	Various 9 electrolytic capacitors Backlight bulb To replace the above parts and clean the corrosion	1	39.00
Labor	Shipping	1	38.00
Shipping & Handling	Bluetooth Module, plug&play	1	85.00

*Thank you*


*We appreciate your recommendation & positive feedback on Google & Yelp*

If you have any issues using your device please call  
our help line 714-744-4438

Sales Tax (7.  
Total



EZ Electric Power Steering



The Driven Man dba American Powertrain  
3075 Poplar Grove Rd.

931-646-4836

### Pick List

Date	S.O. No.
1/8/2021	58679

Name / Address	Ship To
[REDACTED]	[REDACTED]

Picked By	Rep
	O-TDM

Picked	Backordered	Order Qty	Item	Description
		✓ 1	EZVO-11800	EZ Electric Power Steering Volvo P1800 S, E, ES - Fits even with factory A/C  *** Ask about our original style steering wheel. 1" smaller in diameter

Customer Copy + White Shop Copy + Yellow

**meineke** MEINEKE CAR CARE CENTER # 1632  
 PO BOX 7385  
 TUPELO, MS 38802  
 (662)620-0767

Invoice Number: 55747  
 Invoice Date: 5/13/16  
 Estimate ID: 085595

1972 VOLVO P 1800 SPORTS CAR 145 211 MS A18431

Tech Writer Ad Lead  
 KRT HRT REPEAT

Quantity	Item	Description	Warranty	Alt	Unit Price	Discount	Total
MEMO		****BRAKE FLUID FLUSH****					
3.00	MISOPART	BRAKE FLUID		A	9.99		29.97
1.00	LABOR	BRAKE FLUSH LABOR		A	49.98		49.98
1.00	LABOR	DISPOSAL FEE(BRAKE FLUID)		A	2.97		2.97
1.00	Discount	10% DISCOUNT		A	(8.29)	(8.29)	(8.29)

CUSTOM WHEELS MUST BE RE-TORQUED AFTER 50 MILES. WE ARE NOT RESPONSIBLE FOR BENT AND/OR DAMAGED HUB CAPS ANY OTHER DAMAGE CONCERNS MUST BE ADDRESSED BEFORE LEAVING THE PREMISES. FLUID AMOUNT QUANTITIES ON THE TICKET DO NOT ALWAYS REFLECT THE ACTUAL AMOUNT USED IN THE VEHICLE.

Total Savings: \$8.29

Method	Amount
MasterCard	86.44

Shop Supplies: 5.97  
 Total Parts: 26.97  
 Total Labor: 47.65  
 Sub Total: 80.80  
 Sales Tax: 5.84  
**Total Due: \$86.44**

**VP Autoparts Inc.**

**Packing note**

Order no: 41425 Customer no: 305144 Date: 2025-04-04

Delivery address: [Redacted]  
 Invoice address: [Redacted]

Artnr	Description	Shelf	Qty	Price	Total
147	Decal warning fan		1	\$ 4.25	\$ 4.25
19854	Workshop manual, Specific 1800E, ES, Sweden		1	\$ 5.56	\$ 5.56
<b>Total price</b>					<b>\$ 11.95</b>
<b>Total price</b>					<b>\$ 21.76</b>



**Sales Order**

Foreign Car Parts  
 3552 Jeff Homan Blvd  
 Tupelo, Ms. 38801  
 Phone: 662-844-9179  
 Fax: 662-844-9119

Order Number: 2260  
 Order Date: 05/08/2014

The Rx for your vehicle

Customer PO

Quantity	Part Number	Part Description	Brand	Unit Price	Extend
1.00	93 37 55174	THERMOSTAT	Wahler	13.24	13.24
<b>Final Payment \$18,201.42 2:25:57 PM</b>					
Addn: SALE: X MasterCard 845C \$14.20					
Total Parts: \$13.24					
Total Fees: \$14.20					
Core Charges: \$0.00					
FET: \$0.00					
Sales Tax: \$0.00					
<b>Total Charges: \$27.44</b>					
<b>Total Paid: \$14.20</b>					
<b>Total Due: \$13.24</b>					

New, non friction material parts are guaranteed for either 6 months or 6,000 miles, whichever comes first, when returned service department for adjustment or other arrangements are made after contacting us. All parts are new unless otherwise specified.

Consumer acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligation by the card member agreement with the issuer.



**MAC'S TIRE CENTER**

1123 W MAIN  
 TUPELO, MS 38801  
 800-742-7904

Invoice # 1-100478 Dealer ID# Page 1 of 1 Ref: KE  
 Date 03/10/2014 Emp: 1-12 ES / 1-12, ES  
 In Mar 10, 2014 12:40 pm  
 Out Mar 10, 2014 12:40 pm

\*\*\*\*INVOICE\*\*\*\*

Ship To: [Redacted]  
 Unit: YELLOW  
 Vehicle: 72 VOLVO 1800E  
 License: A18431  
 Mileage: 112,999  
 VIN#: 53038146  
 PO#:

Salesman	Mechanic	Part #	QTY	Description	Parts	Labor	FET
		ALK	1.00	THRUST ALIGNMENT	0.00	59.95	0.00

Card Type: MASTERCARD CCR:\*\*\*\*\*8450 Auth. # Amount: \$6

Buyer agrees to pay total amount above, according to cardholder's agreement with issuer.

\*\*\* RECHECK NUTS TORQUE ON AFTERMARKET WHEELS AFTER 100 MILES  
 CHECK VEHICLE AND WHEEL MANUFACTURERS RECOMMENDATION \*\*\*

PAYMENTS FOR ALL CHARGES ARE DUE WITHIN 30 DAYS OF PURCHASE. A FINANCE CHARGE OF 1.5% WILL BE ADDED TO ALL PAST DUE CHARGES. A 10% RESTOCKING FEE ON ALL RETURNED ITEMS AFTER 5 DAYS.

Cash:	Check:	Credit:	Charge:	Parts:
	0.00	64.30		Labor:
				Subtotal:
				Sales Tax:
<b>Net due on the 10th of the month.</b>				<b>Total:</b>

IROLL Motors, Inc  
16890 Church St.  
Bldg 11  
Morgan Hill, CA 95037

**Packing List**

Date	Invoice #
12/8/25	23254

Bill To: [Redacted] Ship To: [Redacted]

**PAID**  
12/08/25

P.O. No.	Terms	Ship Date	Ship Via	Project
		12/9/25	FLEX 2 day	

Item	Qty	Loc	Description
Handling Shipping/EXSm	1		OD switch, 1800, 70 - 73

IROLL Motors, Inc  
16890 Church St.  
Bldg 11  
Morgan Hill, CA 95037

**Packing List**

Date	Invoice #
11/13/25	23204

Bill To: [Redacted] Ship To: [Redacted]

**PAID**  
11/13/25

P.O. No.	Terms	Ship Date	Ship Via	Project
		11/14/25	USPS GND AD.	

Item	Qty	Loc	Description
41975u	1		Fuel injector holder, (4-13), used
41975s	4		Fuel Injection, small (power) by seal, Djet
960168	4		4-Prng, fuel injector hose R20 (one with fiber washer)
	8		Fiber washer, injector housing

Handling Shipping Tracking# Sales Tax 7.25% California Out of District

Phone #	Fax #	E-mail	Web Site
78-1544		mikedudek1800@gmail.com	rollmotors.com

FAST UNDERCAR VENTURA  
Parts Authority LLC  
4277 Transport St  
Ventura, CA 93003  
805-676-3400

COD Invoice No. 01UN2149

Page 1  
13:03:39 Dec 01, 2025

CUSTOMER NUMBER	COD Invoice NUMBER	COD Invoice DATE	PACKING SLIP	TERMS	WHSE
10000	01UN2149	12/01/25	01S16154001	CASH	001

ORDER DATE: 12/01/25 13:03:38 CSR: 001018 Lee Z SHIPPED VIA: 000001 DEFAULT MAP LOCATION A CARTONS: 1 OPER: LZ

ITEM	DESCRIPTION	BIN	UNIT	ORDER QTY	BACK ORDERED	INV QTY	LIST PRICE	CORE PRICE	NET PRICE	NET CORE	EXT PRICE
MIS WC	WALK CALL		BLD1	EA	1	0	1	0.00	0.00	N/C	0.00
	Payment Applied		BLD1	EA	1	0	1	0.00	0.00	N/C	0.00

TOTAL PURCHASE	TOTAL LIST	TOTAL MOSE	TOTAL CORE	FREIGHT	TAX PCT	TAX AMT	INVOICE TOTAL	PAYMENTS	BALANCE DUE
17.57	27.23	17.57	0.00	0.00		1.36	18.93		18.93

Look to Fast Undercar as the summer continues to heat up for all your A/C parts needs! Plus check out our very competitive pricing on Gates products!

FAST UNDERCAR VENTURA  
Parts Authority LLC  
4277 Transport St  
Ventura, CA 93003  
805-676-3400

COD Invoice No. 01UN2149

Page 1  
14:59:54 Dec 01, 2025

CUSTOMER NUMBER	COD Invoice NUMBER	COD Invoice DATE	PACKING SLIP	TERMS	WHSE
10000	01UN2149	12/01/25	01S16154001	CASH	001

ORDER DATE: 12/01/25 13:03:38 CSR: 001018 Lee Z SHIPPED VIA: 000001 DEFAULT MAP LOCATION A CARTONS: 1 OPER: LZ

\*\*\* Duplicate Copy \*\*\* COLLECT AT DELIVERY

Dept: 001 WALK IN Contact: / Credit Card Order. Route: DEFAULT ROUTE Direction:

ITEM	DESCRIPTION	BIN	UNIT	ORDER QTY	BACK ORDERED	INV QTY	LIST PRICE	CORE PRICE	NET PRICE	NET CORE	EXT PRICE
MIS 9146183011	relay		BLD1	EA	1	0	1	27.23	0.00	17.57	0.00
	Vendor: BOB										
MIS WC	WALK CALL		BLD1	EA	1	0	1	0.00	0.00	N/C	0.00
	Payment Applied										18.93

> Credit Card = ( 18.93) \*\*\*\*\*1111 VISA 12/35 12/01/25 <

TOTAL PURCHASE	TOTAL LIST	TOTAL MOSE	TOTAL CORE	FREIGHT	TAX PCT	TAX AMT	INVOICE TOTAL	PAYMENTS	BALANCE DUE
17.57	27.23	17.57	0.00	0.00		1.36	18.93	18.93	0.00

Look to Fast Undercar as the summer continues to heat up for all your A/C parts needs! Plus check out our very competitive pricing on Gates products!

ALL US FIRST & FIX IT FAST!

CUSTOMER NAME: WALK IN

Signature: \_\_\_\_\_

\*\*\*\* COD \*\*\*\*\* COD \*\*\*\*

CUSTOMER NUMBER	PACKING SLIP	COD Invoice NUMBER	DATE	TOTAL PURCHASE	TOTAL CORE	FREIGHT	TAX	PAYMENTS
10000	01S16154001	01UN2149	12/01/25	17.57	0.00	0.00	1.36	18.93

FAST UNDERCAR-VENTURA  
4277 Transport St  
Ventura, CA 93003

COD Invoice BALANCE DUE: 0.00  
Credit Card Order CSR: Lee Z

VP Autoparts Inc.

Packing note

Order no: 23869 Customer no: 305144 Date: 2024-03-06

Delivery address: N/A N/A 5599 Larkin St 93003 Ventura United States of America

Invoice address: N/A N/A 5599 Larkin Street 93003 VENTURA United States of America

Artnr	Description	Shelf	Qty	Price	Total
223191	radiator hose Amazon/1800 B33/140 87-72		1	\$ 18.40	\$ 18.40
680765	radiator hose Amazon/1800E/ES/140 lower		1	\$ 15.11	\$ 15.11
	Price, delivery ()			\$ 14.95	\$ 14.95
<b>Total price</b>					<b>\$ 48.46</b>
Total price					\$ 48.46

VP Autoparts Inc.

Packing note

Order no: 18173 Customer no: 305144 Date: 2023-02-04

Delivery address:

Invoice address:

Artnr	Description	Shelf	Qty	Price	Total
134	Decal Heater control 1800		1	\$ 4.25	\$ 4.25
94524	Air hose Volvo 1800 defroster air duct		1	\$ 27.67	\$ 27.67
684548	Air intake grille Volvo 1800 70-73		1	\$ 83.58	\$ 83.58
	Price, delivery ()			\$ 25.95	\$ 25.95
<b>Total price</b>					<b>\$ 131.47</b>
Total price					\$ 131.47

VP Autoparts Inc.

Packing note

Order no: 22377 Customer no: 305144 Date: 2023-11-06

Delivery address:

Invoice address:

Artnr	Description	Shelf	Qty	Price	Total
430119-AC1	Camshaft bearing kit,Volvo 218/330 (AC1)		1	\$ 26.33	\$ 26.33
418677	Expansion plug D = 42 mm		1	\$ 2.02	\$ 2.02
	Price, delivery ()			\$ 14.95	\$ 14.95
<b>Total price</b>					<b>\$ 43.30</b>
Total price					\$ 43.30

VP Autoparts Inc.

Packing note

Order no: 23163 Customer no: 305144 Date: 2024-01-14

Delivery address:

Invoice address:

Artnr	Description	Shelf	Qty	Price	Total
1218634	Rear Flange with seal ring 818/820		1	\$ 39.06	\$ 39.06
	Price, delivery ()			\$ 14.95	\$ 14.95
<b>Total price</b>					<b>\$ 54.01</b>
Total price					\$ 54.01

VP Autoparts Inc.

Packing note

Order no: 23542 Customer no: 305144 Date: 2024-02-18

Delivery address:

Invoice address:

Artnr	Description	Shelf	Qty	Price	Total
943663	Rubber casing VR Injection 1800		1	\$ 49.90	\$ 49.90
960282	FAT BAR B16/200 10x888 "GATES"		1	\$ 8.36	\$ 8.36
685697	Wiper arm 1800E/ES 71-72 RH		1	\$ 33	\$ 33
	Price, delivery ()			\$ 25.95	\$ 25.95
<b>Total price</b>					<b>\$ 117.21</b>
Total price					\$ 117.21

VP Autoparts Inc.

Packing note

Order no: 9681 Customer no: 305144 Date: 2022-10-31

Delivery address:

Invoice address:

Artnr	Description	Shelf	Qty	Price	Total
685946	Emblem 1800E/ES/164 72-73 front		1	\$ 52.78	\$ 52.78
884804	Emblem 1800E tail panel "1800E"		1	\$ 43.89	\$ 43.89
685811	Emblem 1800E/ES tail panel "Volvo"		1	\$ 46.67	\$ 46.67
	Price, delivery ()			\$ 25.95	\$ 25.95
<b>Total price</b>					<b>\$ 169.29</b>
Total price					\$ 169.29

The following comment was also sent to: no


VP Autoparts Inc.

Packing note

Order no: 3628 Customer no: 305144 Date: 2021-07-12

Delivery address:

Invoice address:



Artnr	Description	Shelf	Qty	Price	Total
671328	Clip back rest 1800/140/164		6	\$ 1.67	\$ 10.02
	Price, delivery ()		1	\$ 12.95	\$ 12.95
	Price, delivery ()		-1	\$ 4	-\$ 4
<b>Total price</b>					<b>\$ 18.97</b>
Total price					\$ 18.97

VP Autoparts Inc.

Packing note


Order no: 10416 Customer no: 305144 Date: 2022-12-27

Delivery address:

Invoice address:

Carfection Pro Inc.  
Carfection Pro Inc.  
5599 Linden Street  
93036 DINNARD  
United States of America

Carfection Pro Inc.  
Carfection Pro Inc.  
5599 Linden Street  
93033 VENTURA  
United States of America



Artnr	Description	Shelf	Qty	Price	Total
673459	Rubber seal vent. window 1800 64-72 LH		1	\$ 44	\$ 44
673460	Rubber seal vent. window 1800 64-72 RH		1	\$ 39.50	\$ 39.50
	Price, delivery ()		1	\$ 20.95	\$ 20.95
<b>Total price</b>					<b>\$ 104.45</b>
Total price					\$ 104.45



VP Autoparts Inc.

Packing note

Order no: 17941 Customer no: 305144 Date: 2023-01-19

Delivery address:

Invoice address:



Artnr	Description	Shelf	Qty	Price	Total
664270	Screw door hinge P1800		1	\$ 7.90	\$ 7.90
672152	Rubber seal Door 1800 61-29 LNR/RH		2	\$ 31	\$ 62
	Price, delivery ()		1	\$ 16.95	\$ 16.95
<b>Total price</b>					<b>\$ 86.85</b>
Total price					\$ 86.85


VP Autoparts Inc.

Packing note

Order no: 10400 Customer no: 305144 Date: 2022-12-24

Delivery address:

Invoice address:



Artnr	Description	Shelf	Qty	Price	Total
661345	Gasket doortock/body AZ/P1800		2	\$ 4.56	\$ 9.12
276613	Rear view mirror Door/Amazon/1800/140 72-		1	\$ 83.33	\$ 83.33
	Price, delivery ()		1	\$ 20.95	\$ 20.95
<b>Total price</b>					<b>\$ 113.40</b>
Total price					\$ 113.40



VP Autoparts Inc.

Packing note

Order no: 10393 Customer no: 305144 Date: 2022-12-23

Delivery address:

Invoice address:



Artnr	Description	Shelf	Qty	Price	Total
665124	Grommet Rear panel 1800 61-72		2	\$ 11.11	\$ 22.22
665121	Grommet Front section 1800 61-72		2	\$ 9.56	\$ 19.12
6723655	Gasket set Door handle 1800S/E 1967-		1	\$ 9.89	\$ 9.89
664545	Gasket Trunk handle 1800		1	\$ 2.11	\$ 2.11
	Price, delivery ()		1	\$ 16.95	\$ 16.95
<b>Total price</b>					<b>\$ 70.29</b>
Total price					\$ 70.29

VP Autoparts Inc.

Packing note

Order no: 10437 Customer no: 305144 Date: 2022-12-28

Delivery address:

Invoice address:



Artnr	Description	Shelf	Qty	Price	Total
668311	Rubber guard Bumper section 1800		4	\$ 22.50	\$ 90
	Price, delivery ()		1	\$ 20.95	\$ 20.95
<b>Total price</b>					<b>\$ 110.4</b>
Total price					\$ 110.4

VP Autoparts Inc.

Packing note

Order no: 10399 Customer no: 305144 Date: 2022-12-24

Delivery address:

Invoice address:



Artnr	Description	Shelf	Qty	Price	Total
68596	Board trunk 1800C kit Spc		1	\$ 132.78	\$ 132.78
	Price, delivery ()		1	\$ 45.95	\$ 45.95
<b>Total price</b>					<b>\$ 178.73</b>
Total price					\$ 178.73


VP Autoparts Inc.

Packing n

Order no: 17947 Customer no: 305144 Date: 2023-01-1

Delivery address:

Invoice address:



Artnr	Description	Shelf	Qty	Price	Tot
66476	Plug floor section 1800 plastic		12	\$ 1.10	\$ 13.20
66819	Plug inner sill P1800 (small)		2	\$ 0.80	\$ 1.60
66825	Plug inner sill P1800 (large)		1	\$ 1	\$ 1
	Price, delivery ()		1	\$ 12.95	\$ 12.95
<b>Total price</b>					<b>\$ 28.75</b>
Total price					\$ 28.75



VP Autoparts Inc.

Packing note

Order no: 10398 Customer no: 305144 Date: 2022-12-24

Delivery address:

Invoice address:



Artnr	Description	Shelf	Qty	Price	Total
665041	Gasket Head light rim 1800		2	\$ 17.78	\$ 35.56
684967	Fastener Radiator grille 1800 72-73		1	\$ 4.16	\$ 4.16
	Price, delivery ()		1	\$ 12.95	\$ 12.95
<b>Total price</b>					<b>\$ 52.67</b>
Total price					\$ 52.67



VP Autoparts Inc.

Packing

Order no: 24839 Customer no: 305144 Date: 2024-05-

Delivery address:

Invoice address:



Artnr	Description	Shelf	Qty	Price	
68305	Fuel filter hose 1800E/ES 72-73		1	\$ 105.03	\$ 105.03
683564	Rubber seal 1800 fuel cap w/o hole		1	\$ 11.11	\$ 11.11
	Price, delivery ()		1	\$ 30.95	\$ 30.95
<b>Total price</b>					<b>\$ 147.09</b>
Total price					\$ 147.09



VP Autoparts Inc.

Packing note

Order no: 10347 Customer no: 305144 Date: 2022-12-19

Delivery address:

Invoice address:



Artnr	Description	Shelf	Qty	Price	Total
669796-PAIR	Bushing Wiper 1800 PAIR		1	\$ 17.56	\$ 17.56
660297	Gasket 122/1600 wiper axle		2	\$ 2.89	\$ 5.78
125	Decal reflex door -73		2	\$ 4.33	\$ 8.66
195	Decal ATE Bremsgerät		1	\$ 5	\$ 5
	Price, delivery ()		1	\$ 12.95	\$ 12.95
<b>Total price</b>					<b>\$ 49.95</b>
Total price					\$ 49.95


VP Autoparts Inc.

Packing no

Order no: 20779 Customer no: 305144 Date: 2023-07-20

Delivery address:

Invoice address:




Artnr	Description	Shelf	Qty	Price	Tot
671892	Windshield Wiper 1800 green w blue top		1	\$ 236.20	\$ 236.20
	Price, delivery (Shipping cannot be calculated)		1	\$ 0.01	\$ 0.01
<b>Total price</b>					<b>\$ 236.21</b>
Total price					\$ 236.21

**VP Autoparts Inc.**


**Packing note**

Order no: 10366 Customer no: 305144 Date: 2022-12-21

Delivery address:



Invoice address:



Artnr	Description	Shelf	Qty	Price	Total
664741	Anchorage Front fender 1800 LH		1	\$ 3.89	\$ 3.89
MN4	Nut M4x0,7x3		2	\$ 0.11	\$ 0.22
668258	Door glass scraper seal P1800		2	\$ 27.78	\$ 55.56
672147	Rubber seal Trunk 1800S/E		1	\$ 40.95	\$ 40.95
	Price, delivery ()		1	\$ 25.95	\$ 25.95
<b>Total price</b>					<b>\$ 126.57</b>
<b>Total price</b>					<b>\$ 126.57</b>

18/12/22 12:31 AM

Packing note

**VP Autoparts Inc.**

**Packing note**

Order no: 18035 Customer no: 305144 Date: 2023-01-27

Delivery address:



Invoice address:



Artnr	Description	Shelf	Qty	Price	Total
684967	Fastener radiator grille 1900 72-71		5	\$ 3.54	\$ 17.70
	Price, delivery ()		1	\$ 12.95	\$ 12.95
<b>Total price</b>					<b>\$ 30.65</b>
<b>Total price</b>					<b>\$ 30.65</b>

18/12/22

**HEADLINER P1800 JENSEN, S, E**

*Instructions and Advice*

This is only a general understanding of how to assemble a headliner.

**Preparation:**

At least one week before mounting the headliner you should unpack and unfold the headliner and place it in a spot with room temperature. Many other cars & brands with a "hanging" headliner it is recommended to be placed in the sun for a while to get rid of wrinkles and other material "prints" which has arisen during storage. This will also help the material to become softer when mounting. This preparation method can be applied to almost all vinyl headliners.

**Tools & Accessories**

**Tools:**  
Staple gun  
Ruler  
Measuring Tape

**Accessories:**  
Possibly Glue

The mounting should be done in a temperate place to simplify the process. For help it could be good to have a heat gun or a small heating fan, just beware of the overheating danger. If the windows and the seats are disassembled the replacing of the headliner will be easier.

**Lets go!**

**Mounting on frame:**

The headliner is made of a piece of Vinyl with a High Frequency welded pattern. On the back of the headliner there is a mark where u should place the frame. **NOTE** this is only an approximation of the placement, not a cutting line! The headliner must be measured to be centered correctly on the frame. When u are satisfied with the placement on the frame the headliner can be stapled or glued onto the frame. Cut the excess and mount the outer lacing on the frame. Place the roof bows in the channels on the headliner. Put the clips into place on the frame.

**Mounting in car:**

If the windshield is disassembled the mounting of the headliner will be easier. Bring the headliner in through the windshield frame or the door opening. Fit in the headliner, easier with two people: Hang up the headliner with the roof bows, fit the clips, push into place. In the early models chassis 7999 the headliner is mounted with screws.

18/12/22

Packing note

**VP Autoparts Inc.**


**Packing note**

Order no: 18034 Customer no: 305144 Date: 2023-01-27

Delivery address:



Invoice address:



Artnr	Description	Shelf	Qty	Price	Total
687299	Lock spring Door handle 1800/140/164 67		2	\$ 2.40	\$ 4.80
951333	Pin ES door handle 1800 72-73		2	\$ 0.98	\$ 1.96
9452093	Headlight Lucas tri-bar H4		2	\$ 69.30	\$ 138.60
	Price, delivery ()		1	\$ 25.95	\$ 25.95
<b>Total price</b>					<b>\$ 171.31</b>
<b>Total price</b>					<b>\$ 171.31</b>

18/12/22

# *CREATIVE CAR AUDIO SHOP*

Vintage Becker & Blaupunkt Radio Restoration, Sales & Service Specialist

Thank you for your purchase.

Blaupunkt Frankfurt "Y", "Z" or "A" Series Bluetooth Streaming with 6 Pin Instruction

1-Remove the cover from the back of the radio, plug the Bluetooth connector into your radio AUX port and mount the microphone.