



**93 AUTO**  
 31071 DIVISION  
 New Haven, MI. 48048  
 Phone: 586-925-7222

INVOICE

9399

Org. Est. # 014375

MICHIGAN REGISTRATION:

F166725

Proposed completion date:

8/4/2022

**INVOICE**

Printed Date: 08/11/2022

Work Completed: 08/11/2022

2004 Saab - 9-3 Arc - 2L, In-Line4 (122CI) VIN(Y)

Lic #: BWR 234 - MI

Odometer In : 106855

VIN #: YS3FD79Y6 46016070

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
Flex Pipe 17943	1.00	31.76	31.76	CUSTOMER STATES THAT EXHAUST IS LOUD REMOVE AND REPLACE BROKEN FLEX PIPE	150.00
VALUCRAFT POLY-V BELT/Serpentine Belt 405K5	1.00	19.66	19.66	CUSTOMER STATES PLEASE CHECK FAN BELT. REMOVE AND REPLACE CORRODED AND DRY ROTTED DRIVE BELT	100.00
Front rotor 34267	2.00	72.79	145.58	Replace front pads and rotors Replaced front brake pads and rotors	187.00
Front pads gold Dg972	1.00	45.00	45.00	Replace rear pads and rotors Replaced rear pads and rotors	187.00
Rear rotor vented 45403	2.00	63.18	126.36	Replace engine subframe Replace Sway Links	495.00 132.00
Rear brake pads ceramic Dg1095c	1.00	60.78	60.78	Replace Sway Links LEFT BRAKE LIGHT BULB REPLACE	0.00
Subframe USED	1.00	495.00	495.00	LEFT BRAKE LIGHT BULB REPLACE WHEEL BEARING - Remove & Replace - Sedan Front, One Side - [Includes: Pack Bearings (where applicable).]	110.00
SWAY BAR link 1880477	2.00	31.98	63.96		
Duralast / Wheel Bearing/Hub Assembly-Front DL513191	1.00	99.20	99.20		
Shop Supplies			20.00		

Original Estimate Amount: 2,534.74

YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTUER OR DISTRIBUTOR BECAUSE WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU.

Save \_\_\_\_\_ Discard \_\_\_\_\_ Signature \_\_\_\_\_

I hereby authorize the above repair work to be done along with the necessary materials, and hereby grant you and/or your employee permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. **X**

Labor: 1,361.00  
 Parts: 1,107.30  
 Sublet: 0.00

Estimated Increased Total: \$ \_\_\_\_\_  
 Authorized by: **X** \_\_\_\_\_  
 Mechanic's Name & Michigan Certification Number  
 Repairs Performed by:  
 Will, Mike; Brian, Zewatski M269432

**-CERTIFICATION-**  
 ALL REPAIRS AND PARTS LISTED WERE FURNISHED IN COMPLIANCE WITH THE MICHIGAN AUTO REPAIR ACT (P.A. 300) ALL PARTS ARE NEW UNLESS OTHERWISE STATED.

ALL REPAIRS PROPERLY COMPLETED  
 Company Authorized Representative:

**X** \_\_\_\_\_

Sub: 2,468.30  
 Tax: 66.44  
 Total: \$2,534.74  
 Bal Due: \$0.00

[ Payments - paypal - \$2,534.74 ]