

Federated



FISHER AUTO PARTS, INC.
4913 JONESTOWN ROAD
HARRISBURG, PA 17109
717-652-5920



SOLD TO:

CASH
4913 JONESTOWN Rd

Harrisburg
PA 17109

**** WE'RE EXPANDING! ****
adding 2600sq ft of inventory
to better serve your needs
starting MAY 2025

REF #	ACCT #	P.O. #	SLM	PG	INV DATE	TYPE	INVOICE #	TIME
	999337		LJK	1	5/08/2025	DISCVR	337-729737	15:59

QTY	LINE	PART NUMBER	DESCRIPTION	LIST	COST	EXTEND	TAX
1	1976	657 42077	Oldsmobile Toronado 7.5L V8 OHV GAS 4BBL CARB S MOTORMITE Brake Master Cylinder Reservoir Cap Gasket	15.43	11.48	11.48	Y


TOTAL UNITS: 1

BATT	FRT	LABOR	MISC	CORE	NON-TAX	TAXABLE	TAX
						11.48	.69

RECEIVED BY: _____

PAY THIS AMOUNT ==> 12.17

INVOICE MUST ACCOMPANY RETURNED MERCHANDISE
NO RETURN OF ELECTRICAL PARTS ONCE INSTALLED



Quality Automotive Parts and Accessories

Federated



FISHER AUTO PARTS, INC.

4913 JONESTOWN ROAD
HARRISBURG, PA 17109
717-652-5920



SOLD TO:
PROFESSIONAL MECHANIC/HARRISBU
4913 JONESTOWN RD

HARRISBURG
PA 17109

THANK YOU to all our
wonderful customers! from
Fisher Auto Parts
Mon-Fri 7am-5pm Sat 8-12

REF #	ACCT #	P.O. #	SLM	PG	INV DATE	TYPE	INVOICE #	TIME
	684691		LJK	1	6/17/2024	VISA	337-704375	15:43

QTY	LINE	PART NUMBER	DESCRIPTION	LIST	COST	EXTEND	TAX
1976		Oldsmobile Toronado	7.5L V8 OHV GAS 4BBL CARB S				
1	290	15570	DAYCO BELTS/HOS Accessory Drive Belt	44.62	25.53	25.53	Y
1	290	15450	DAYCO BELTS/HOS Accessory Drive Belt	31.69	18.13	18.13	Y
1	290	15610	DAYCO BELTS/HOS Accessory Drive Belt	41.44	23.71	23.71	Y

TOTAL UNITS: 3

BATT	FRT	LABOR	MISC	CORE	NON-TAX	TAXABLE	TAX
						67.37	4.05

RECEIVED BY: _____

PAY THIS AMOUNT ==> 71.42

INVOICE MUST ACCOMPANY RETURNED MERCHANDISE
NO RETURN OF ELECTRICAL PARTS ONCE INSTALLED

Quality Automotive Parts and Accessories



248 South Progress Avenue, Harrisburg, PA 17109
 Call (717) 545-9034
 Calculate Online 24/7 at:
 www.DickWolfesGarage.com

Invoice

Invoice # 21058
 Work Order # 62936
 Invoice Date 12/19/2023 12:08 PM
 Service Advisor ALW
 Technician MEL

Description 1976 Oldsmobile Toronado Brougham V8 7.5L
 CC-435CID VIN S
 Odometer 72,201

Plate PA LMA7859
 VIN 3Y57S6M714648

Concern

Customer Concerns
 Concerns- Vehicle blew a power steering line. Also had to jump it to get out of the parking lot when it was picked up last time.
Technician/Service Notes:
 Vehicle still needs carb. rebuilt and accelerator pump not working properly. Customer advised they would do the work themselves.

Service

State Inspection
 Insurance Company/Expires
 PA/EA159514
 Expiration Date 6/25/2024
 NAIC: 37915

Brake Readings- LF: 6R RF: 6R LR: 6R RR: 4R
 Tire Readings- LF: 10 RF: 11 LR: 11 RR: 11
 Old Mileage- Out of State Vehicle Color: Brown
 Sticker #: A1402653017 Expiration Date: 12/2024
 Annual State Inspection Sticker

Emissions Inspection
 Sticker #: IM441046887
 Expiration Date: 12/2024
 PA STATE EMISSIONS STICKER

Lube, Oil & Filter Service - Blended Oil
 Drain and refill engine oil, change engine oil filter and lubricate chassis grease fittings and friction points as required. Check and top off fluid levels, additional charges may apply where fluids are required. Complete a complimentary visual vehicle inspection.
 Labor
 SAE 30
 Oil Filler

Power Steering Hose- Pressure
 Remove and Replace components as required to access and install new power steering pressure hose. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.
 Labor
 Power Steering Pressure Line Hose
 Power Steering Fluid

1 Unit Sub **\$45.95**

1 Unit Sub **\$32.35**

6 Quart 1 Unit Sub **\$60.87**

Discount **(\$6.66)**
 Sub **\$118.27**



**COMMONWEALTH OF PENNSYLVANIA
 VEHICLE EMISSIONS INSPECTION REPORT**

Test Date/Time: 12/18/2023 @ 16:36

Year: 1976	Make: OLDSMOBILE	Model: TORONADO
VIN: 3Y57S6M714648	Engine Size (cc): 7500	Cylinders: 8
License: LMA7859	Inspection Type: Initial	Estimated Test Weight: N/A
County: DAUPHIN	Inspection Type: Initial	Record Number: 1905
EMISSIONS CONTROL SYSTEMS VISUAL/FUNCTIONAL INSPECTION		
Air Int. System: N/A	Catalytic Converter: PASS	Fuel Cap Integrity: PASS
EGR System: PASS	Evaporative Control System: PASS	
PCV System: PASS	Fuel Inlet Restrictor: PASS	
OBD EMISSIONS INSPECTION		
MIL BULB KOEO: N/A	OBD FAULT CODE RESULT: N/A	
MIL BULB KOER: N/A	OBD READINESS RESULT: N/A	
MIL COMMAND STATUS: N/A	OBD-IM CHECK RESULT: N/A	

OVERALL TEST RESULTS: PASSED

Emissions Control Systems Visual/Functional Inspection: **PASS**
 OBD Emissions Inspection: **N/A**
 Sticker: **IM441046887**
 TIN: **51397386**

RETAIN THIS DOCUMENT FOR YOUR RECORDS.

Vehicle tested in accordance with Pa. Code Title 67, Chapter 177

EMISSIONS INSPECTION STATION	
STATION #: B04	INSPECTOR NAME: MARK E. LENKER
ADDRESS: Dick Wolfes Garage 248 South Progress Avenue Harrisburg, PA 17109	SOFTWARE VERSION: 2103
PHONE: 717-545-9034	FIRMWARE VERSION:
	EQUIPMENT #: NE000876
VEHICLE EMISSIONS INSPECTION QUESTIONS: For additional information, please contact the Customer Hotline at (800) 265-0921.	
Inspector's Signature:	



248 South Progress Avenue, Harrisburg, PA 17109
 Call/Text (717) 545-3034
 Schedule Online 24/7 at:
 www.DickWolfeGarage.com

Invoice

Bill To

Invoice # 20990
 Work Order # 62370
 Invoice Date 12/11/2023 1:29 PM
 Service Advisor ALW
 Technician MEL

F

Plate PA LMA7859
 VIN 3Y57S6M714648

Description 1976 Oldsmobile Toronado Brougham V8 7.5L
 7456CC 455CID VIN S
 Odometer 16,279

Concern

Customer Concerns

Concerns- PA State Inspection & Emissions. NO tire rotation. Power windows do not work. They briefly worked after I picked up the vehicle. Install new wiper on the passenger side. The new one is on the front floor. Please save the old one. The blower motor seems to work on one speed only. Please let me know if it can be fixed and what is involved with that. The A/C belt is not installed. I would like to try and get the A/C operable prior to next summer. Please set the timing and adjust carb as needed. It wants to stall when moving from a complete stop.

Technician/Service Notes:

Service

Diagnose- Driveability

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges. Found: For a/c system to work would need to retro-fit system and check for additional leaks. Traced wiring to find faulty power window relay, recommend replacement. Blower switch had broken contacts, recommend replacement or cleaning and re-trying. Recommend the Carb to be rebuilt. Leaking oil and trans fluid, would need cleaned to locate source. Leaking valve stem, recommend replacement.

Diagnostics

Sub \$338.00

Relay

Remove and Replace components as required to access and install new power window relay. Retest and verify repair as required. Perform final road test where applicable.

Labor

Relay 1 Unit

Sub \$78.51

Valve Stem

Remove and Replace components as required to access and install new valve stem. Retest and verify repair as required. Perform final road test where applicable.

Labor

Valve Stem 1 Unit

Sub \$44.67

Please Note

Some wheels require lug nut re-torque. Ask your Service Consultant for details. Keeping your tires properly inflated and rotated will assist in maximizing tire wear life and vehicle handling.

Electrical System General Service

Remove and Replace components as required to access and remove blower motor switch, disassemble and clean all contacts. Reassemble and install. Retest and verify repair as required. Perform final road test where applicable.

Labor

Sub \$137.53

Total Parts	\$77.18
Total Labor	<u>\$521.53</u>
Total Before Taxes & Miscellaneous Charges	\$598.71

FICKEN WIPER SERVICE
 132 CALVERT AVENUE
 West Babylon, NY 11704 US
 631-587-3332
 sales@wiperman.com

Invoice

BILL TO

SHIP TO

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
1012748	11/02/2023	\$44.00	11/30/2023	Credit Card	

SHIP DATE	SHIP VIA	TRACKING NO.	MAKE	YEAR
11/02/2023	USPS	9405511206216470277560	Olds	1976

ACTIVITY	QTY	RATE	AMOUNT
Blades, Trico Trico wiper Blades 18" Pin Type	2	18.00	36.00
8. Shipping:7. USPS Priority USPS Priority Mail	1	8.00	8.00

~~BALANCE DUE~~ **\$44.00**

PAID

PAID



FISHER AUTO PARTS, INC.

4913 JONESTOWN ROAD
HARRISBURG, PA 17109
717-652-5920



SOLD TO:
CASH
4913 JONESTOWN Rd

Harrisburg
PA 17109

THANK YOU to all our
wonderful customers! From
Fisher Auto Parts
Mon-Fri 7am-5pm Sat 8-12

REF #	ACCT #	P.O. #	SLM	PG	INV DATE	TYPE	INVOICE #	TIME
	999337		LJK	1	7/27/2024	VISA	337-707766	11:00

QTY	LINE	PART NUMBER	DESCRIPTION	LIST	COST	EXTEND	TAX
1	290	15620	DAYCO BELTS/HOS Accessory Drive Belt	22.85	14.94	14.94	Y

TOTAL UNITS: 1

BATT	FRT	LABOR	MISC	CORE	NON-TAX	TAXABLE	TAX
						14.94	.90

RECEIVED BY: _____

PAY THIS AMOUNT ==> 15.84

INVOICE MUST ACCOMPANY RETURNED MERCHANDISE
NO RETURN OF ELECTRICAL PARTS ONCE INSTALLED



FISHER AUTO PARTS, INC.

4913 JONESTOWN ROAD
 HARRISBURG, PA 17109
 717-652-5920



SOLD TO:
 PROFESSIONAL MECHANIC/HARRISBU
 4913 JONESTOWN RD

 HARRISBURG
 PA 17109

THANK YOU to all our
 wonderful customers! from
 Fisher Auto Parts
 Mon-Fri 7am-5pm Sat 8-12

REF #	ACCT #	P.O. #	SLM	PG	INV DATE	TYPE	INVOICE #	TIME
	684691		DD	1	7/20/2024	VISA	337-707140	11:36

QTY	LINE	PART NUMBER	DESCRIPTION	LIST	COST	EXTEND	TAX
-1	290	15570	DAYCO BELTS/HOS ORIG INV: 704375 2024/06/17 PO#: Accessory Drive Belt	47.78	25.53	-25.53	Y
-1	290	15450	DAYCO BELTS/HOS Accessory Drive Belt	31.69	18.13	-18.13	Y
-1	290	15610	DAYCO BELTS/HOS ORIG INV: 704375 2024/06/17 PO#: Accessory Drive Belt	44.37	23.71	-23.71	Y
-1	120	20-840 PS840	A-1 MISC PART CORE Power Steering Pump		19.00	-19.00	Y

TOTAL UNITS: -4

BATT	FRT	LABOR	MISC	CORE	NON-TAX	TAXABLE	TAX
				-19.00		-86.37	-5.19

RECEIVED BY: _____

PAY THIS AMOUNT ==> -91.56

INVOICE MUST ACCOMPANY RETURNED MERCHANDISE
 NO RETURN OF ELECTRICAL PARTS ONCE INSTALLED

Quality Automotive Parts and Accessories



FISHER AUTO PARTS, INC.

4913 JONESTOWN ROAD
HARRISBURG, PA 17109
717-652-5920



SOLD TO:
TORONADO
4913 JONESTOWN Rd

Harrisburg
PA 17109

THANK YOU to all our
wonderful customers! from
Fisher Auto Parts
Mon-Fri 7am-5pm Sat 8-12

REF #	ACCT #	P.O. #	SLM	PG	INV DATE	TYPE	INVOICE #	TIME
	999337		LJK	1	6/28/2024	VISA	337-705503	16:09

QTY	LINE	PART NUMBER	DESCRIPTION	LIST	COST	EXTEND	TAX
	1976	Oldsmobile Toronado	7.5L V8 OHV GAS 4BBL CARB S				
1	120	20-840 PS840	A-1 MISC PART Power Steering Pump	78.79	55.98	55.98	Y
1	120	20-840 PS840	A-1 MISC PART CORE Power Steering Pump		19.00	19.00	Y

TOTAL UNITS: 2

BATT	FRT	LABOR	MISC	CORE	NON-TAX	TAXABLE	TAX
				19.00		74.98	4.50

RECEIVED BY: _____

PAY THIS AMOUNT ==> 79.48

INVOICE MUST ACCOMPANY RETURNED MERCHANDISE
NO RETURN OF ELECTRICAL PARTS ONCE INSTALLED



FISHER AUTO PARTS, INC.

4913 JONESTOWN ROAD
HARRISBURG, PA 17109
717-652-5920



SOLD TO:
HILLPA Cash Sale Account
4913 JONESTOWN Rd

Harrisburg
PA 17109

THANK YOU to all our
wonderful customers! from
Fisher Auto Parts
Mon-Fri 7am-5pm Sat 8-12

REF #	ACCT #	P.O. #	SLM	PG	INV DATE	TYPE	INVOICE #	TIME
	999337		LJK	1	3/25/2024	CASH	337-697083	14:32

QTY	LINE	PART NUMBER	DESCRIPTION	LIST	COST	EXTEND	TAX
1	658	MO78	MOTORAD Engine Oil Filler Cap	14.75	7.66	7.66	Y

TOTAL UNITS: 1

BATT	FRT	LABOR	MISC	CORE	NON-TAX	TAXABLE	TAX
						7.66	.46

RECEIVED BY: _____

PAY THIS AMOUNT ==> 8.12
 AMOUNT TENDERED ==> 10.00
 AMOUNT CHANGE ==> 1.88

INVOICE MUST ACCOMPANY RETURNED MERCHANDISE
NO RETURN OF ELECTRICAL PARTS ONCE INSTALLED

Quality Automotive Parts and Accessories



FISHER AUTO PARTS, INC.

4913 JONESTOWN ROAD
HARRISBURG, PA 17109
717-652-5920



SOLD TO:

7173191536
4913 JONESTOWN Rd

Harrisburg
PA 17109

THANK YOU to all our
wonderful customers! from
Fisher Auto Parts
Mon-Fri 7am-5pm Sat 8-12

REF #	ACCT #	P.O. #	SLM	PG	INV DATE	TYPE	INVOICE #	TIME
	999337		JH	1	4/02/2024	CASH	337-697797	15:59

QTY	LINE	PART NUMBER	DESCRIPTION	LIST	COST	EXTEND	TAX
7.5L	V8	OHV GAS 4BBL CARB S					
1		657 47034	MOTORMITE Pcv Valve Elbow	8.95	6.78	6.78	Y

TOTAL UNITS: 1

BATT	FRT	LABOR	MISC	CORE	NON-TAX	TAXABLE	TAX
						6.78	.41

RECEIVED BY: _____

PAY THIS AMOUNT ==>	7.19
AMOUNT TENDERED ==>	8.00
AMOUNT CHANGE ==>	.81

INVOICE MUST ACCOMPANY RETURNED MERCHANDISE
NO RETURN OF ELECTRICAL PARTS ONCE INSTALLED

Quality Automotive Parts and Accessories