

\*\*\*VOICE\*

469740

**AutoNation**

Tag #: 380

AutoNation Chevrolet West Austin

Customer #: 6153921

11400 Research Blvd.  
AUSTIN, TX 78759  
(512) 338-2420

Cell:

Email:

Service Advisor: 4062 JACOB WATSON

COLOR		YEAR	MAKE/MODEL		VIN		LICENSE		MILEAGE IN	MILEAGE OUT
RAPID BLUE		20	CHEVROLET CORVETTE		1G1Y82D48L5113568				115	119
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY	
30OCT20 D			19:00 13NOV20			CASH	23NOV20	10NOV20	23NOV20	

OPTIONS: SOLD-STK:L5113568 ENG:6.2L 8 Cyl TRN:A

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty. We also offer quality non-OE parts that fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP\*."

Non-GM parts and accessories are not covered under the GM New Vehicle Limited Warranty nor is any damage caused by the installation thereof. GM is not responsible for the consequences of installing any non-GM equipment, parts or accessories on the vehicle, including the possibility that part or all of the GM New Vehicle Limited Warranty may be voided. A list of non-GM parts is available to you upon request.

Dealer is not authorized to perform recall repairs for non-Dealer brand vehicles and Dealer's Vehicles Safety and Condition Inspection and/or service does not include a review of possible pending recalls or service campaigns issued by manufacturers of other makes and models.

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL  
A C/S: THERE IS A MESSAGE ON DISPLAY THAT HOOD IS NOT LATCHED AND THE VEHICLE IS RESTRICTED TO 26MPH.

CAUSE:

105 TRIM/BODY

9717 COSTAS, MICHAEL LIC#: TECH570

WC

1 84806924 ACTUATOR

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A:

115 THE F125 FRONT STOWAGE COMPARTMENT LATCH ACTUATOR WAS GETTING POWER AND GROUND BUT IT WAS NOT ACTIVATING. TAC CASE# 9-6354422413.

1410350 7.00

HOOD LATCH ACTUATOR REPLACEMENT (ST)

DUE TO THE COMPLEXITY OF THE SYSTEM THAT EMPLOYS 2 CONTROL MODULES TO ACTIVATE THE ACTUATOR (ONE TO CONTROL THE B+ FEED RELAY AND ONE TO CONTROL THE GROUND FEED RELAY), WE WERE LEAD ON A WILD GOOSE CHASE FOR THE PROBLEM. FOLLOWING DOCUMENT # 5248289, TEST 3 HAS ONE ACTIVATE THE RELAYS USING THE DOOR SWITCH. SINCE THE DRIVER DOOR SWITCH CANT BE REACHED WHILE TESTING ON THE PASSENGER SIDE, I WAS USING THE SCAN TOOL TO COMMAND THE ACTUATOR AND NOT GETTING THE ACTUATOR RELAY 2 TO ACTIVATE. WITH THE HELP OF TAC TRIED ACTIVATING THE ACTUATOR USING THE SWITCH IN THE FRONT COMPARTMENT WHILE TESTING FOR POWER AND GROUND TO THE ACTUATOR RIGHT THERE WITH A TEST LIGHT. WHEN WE SAW WE HAD POWER AND GROUND, WE TRIED STRIKING THE ACTUATOR AND GOT IT TO WORK. REPLACED THE ACTUATOR AND VERIFIED OPERATION. WORKING OK AT THIS TIME.

\*\*\*\*\*

B Customer requested to have Multi Point Inspection performed this visit

MULTI-A Customer requested to have Multi Point Inspection performed this visit

9717 COSTAS, MICHAEL LIC#: TECH570

CCMPI

GBATT BATTERY TESTS GOOD AT THIS TIME - NO

ATTENTION NEEDED AT THIS TIME

9717 COSTAS, MICHAEL LIC#: TECH570

(N/C)  
(N/C)  
0.00

0.00 0.00

NOTICE OF WORKER'S LIEN PURSUANT TO TEXAS PROPERTY CODE s. 70.001

The undersigned, being the person who has paid for repairs to the vehicle described in this Repair Invoice, understands that if the Dealership relinquishes possession of the vehicle in return for payment via a check, money order or credit card transaction that is stopped or dishonored due to insufficient funds, no funds, or because the account does not exist or has been closed, the worker's lien continues to exist and the Dealership is entitled to possession of the vehicle in accordance with S. 9.609 of the Texas Business & Commerce Code until the amount due is paid.

Customer X \_\_\_\_\_ Date \_\_\_\_\_

**WARRANTY STATEMENT AND DISCLAIMER:** PLEASE SEE THE REVERSE SIDE OF THIS REPAIR INVOICE FOR THE DEALERSHIP'S LIMITED WARRANTY.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DATE \_\_\_\_\_ CUSTOMER SIGNATURE \_\_\_\_\_

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE \_\_\_\_\_

\*SHOP SUPPLY COSTS:  
We have added a charge equal to 14.99% of the total cost of labor and parts, not to exceed \$59.99 to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.

DESCRIPTION	LABOR AMOUNT	
PARTS AMOUNT		
GAS, OIL, LUBE		
SUBLET AMOUNT		
MISC. CHARGES		
TOTAL CHARGES		
LESS INSURANCE		
SALES TAX		
PLEASE PAY THIS AMOUNT		



\*INVOICE\*

469740

**AutoNation**

Tag #: 380

AutoNation Chevrolet West Austin

Customer #:6153921

11400 Research Blvd.  
AUSTIN, TX 78759  
(512) 338-2420

Cell:

Email:

Service Advisor: 4062 JACOB WATSON

Cell:		Email:		SERIAL NUMBER			LICENSE		MILEAGE IN		MILEAGE OUT		
COLOR	YEAR	MAKE/MODEL			VIN			LICENSE		MILEAGE IN		MILEAGE OUT	
RAPID BLUE	20	CHEVROLET CORVETTE			1G1Y82D48L5113568					115		119	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED		READY			
30OCT20 D			19:00 13NOV20			CASH	23NOV20	10NOV20		23NOV20			

OPTIONS: SOLD-STK:L5113568 ENG:6.2L 8 Cyl TRN:A

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty. We also offer quality non-OE parts that fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP\*."

Non-GM parts and accessories are not covered under the GM New Vehicle Limited Warranty nor is any damage caused by the installation thereof. GM is not responsible for the consequences of installing any non-GM equipment, parts or accessories on the vehicle, including the possibility that part or all of the GM New Vehicle Limited Warranty may be voided. A list of non-GM parts is available to you upon request.

Dealer is not authorized to perform recall repairs for non-Dealer brand vehicles and Dealer's Vehicles Safety and Condition Inspection and/or service does not include a review of possible pending recalls or service campaigns issued by manufacturers of other makes and models.

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
			CC			0.00	0.00
			GTIRE MPVI: TIRE TREAD GREEN (NOTATION ONLY - NO WORK NEEDED)				
			9717 COSTAS, MICHAEL LIC#: TECH570			0.00	0.00
			CC				
			GBK MPVI: BRAKE LINING GREEN (NOTATION ONLY - NO WORK NEEDED)				
			9717 COSTAS, MICHAEL LIC#: TECH570			0.00	0.00
			CC				0.00
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	0.00
115 DOES NOT APPLY 0.00 LOW MILEAGE VEHICLE. MPI DOES NOT APPLY.							
*****							
C** UPON TECH INSPECTION FOUND SERVICE SUSPENSION LIGTH IS ON ON ROAD TEST							
CAUSE: 105 TRIM/BODY							
			9717 COSTAS, MICHAEL LIC#: TECH570				(N/C)
			WC				(N/C)
			1 84842056 F-(S) ACCELEROMETER				0.00
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE C:	0.00
115 CODE C1031(11) SET IN ELECTRONIC SUSPENSION CONTROL MODULE.							
SERVICE SUSPENSION SYSTEM MESSAGE WOULD BE ON MOST OF THE TIME DRIVING THE VEHICLE AROUND THE PARKING LOT. 8020320 2.20							
ELECTRONIC SUSPENSION WHEEL RIGHT FRONT VERTICAL ACCELEROMETER REPLACEMENT (ST)							
OBSERVED THAT THE SENSOR SCAN TOOL READING WOULD READ 0 mv WHEN THE REST OF THE SENSORS WOULD READ 2600 mv. REMOVED THE RF WHEEL/TIRE AND WIGGLED THE HARNESS UNTIL I SAW THAT THE READING WOULD JUMP TO 2600 mv. THE PART OF THE HARNESS WIGGLED IS RIGHT UP AGAINST THE SENSOR AND IS PART OF THE SENSOR. ORDERED THE ACCELEROMETER. INSTALLED TIRE AND PARKED IN LOT. WHEN PART CAME IN, HAD TO RACK THE VEHICLE UP AGAIN AND RAISE TO REPLACE PART. CLEARED CODES AND TEST DROVE TO VERIFY OPERATION.							
*****							

NOTICE OF WORKER'S LIEN PURSUANT TO TEXAS PROPERTY CODE s. 70.001

The undersigned, being the person who has paid for repairs to the vehicle described in this Repair Invoice, understands that if the Dealership relinquishes possession of the vehicle in return for payment via a check, money order or credit card transaction that is stopped or dishonored due to insufficient funds, no funds, or because the account does not exist or has been closed, the worker's lien continues to exist and the Dealership is entitled to possession of the vehicle in accordance with S. 9.609 of the Texas Business & Commerce Code until the amount due is paid.

Customer X \_\_\_\_\_ Date \_\_\_\_\_

**WARRANTY STATEMENT AND DISCLAIMER:** PLEASE SEE THE REVERSE SIDE OF THIS REPAIR INVOICE FOR THE DEALERSHIP'S LIMITED WARRANTY.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DATE \_\_\_\_\_ CUSTOMER SIGNATURE \_\_\_\_\_ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE \_\_\_\_\_

**\*SHOP SUPPLY COSTS:**  
We have added a charge equal to 14.99% of the total cost of labor and parts, not to exceed \$59.99 to the Repair Order for shop supplies used in connection with this repair.

**ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.**

DESCRIPTION	LABOR AMOUNT	PARTS AMOUNT	GAS, OIL, LUBE	SUBLET AMOUNT	MISC. CHARGES	TOTAL CHARGES	LESS INSURANCE	SALES TAX	PLEASE PAY THIS AMOUNT



\*INVOICE\*

469740

**AutoNation**

Tag #: 380

AutoNation Chevrolet West Austin

Customer #:6153921

11400 Research Blvd.  
AUSTIN, TX 78759  
(512) 338-2420

Cell:

Email:

Service Advisor: 4062 JACOB WATSON

COLOR	YEAR	MAKE/MODEL			VIN		LICENSE	MILEAGE IN	MILEAGE OUT
RAPID BLUE	20	CHEVROLET CORVETTE			1G1Y82D48L5113568			115	119
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
30OCT20 D			19:00 13NOV20			CASH	23NOV20	10NOV20	23NOV20

OPTIONS: SOLD-STK:L5113568 ENG:6.2L 8 Cyl TRN:A

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty. We also offer quality non-OE parts that fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP\*."

Non-GM parts and accessories are not covered under the GM New Vehicle Limited Warranty nor is any damage caused by the installation thereof. GM is not responsible for the consequences of installing any non-GM equipment, parts or accessories on the vehicle, including the possibility that part or all of the GM New Vehicle Limited Warranty may be voided. A list of non-GM parts is available to you upon request.

Dealer is not authorized to perform recall repairs for non-Dealer brand vehicles and Dealer's Vehicles Safety and Condition Inspection and/or service does not include a review of possible pending recalls or service campaigns issued by manufacturers of other makes and models.

LINE OPCODE TECH TYPE HOURS

D\*\* UPON TECH INSPECTION FOUND FEILD BULLINT#20236880

CAUSE:

105 TRIM/BODY

9717 COSTAS, MICHAEL LIC#: TECH570

WC

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: (N/C)

115 INTERNAL SOFTWARE MISALIGNMENT MAY CAUSE FALSE CODES TO SET.

9105266 0.50

TRANSMISSION CONTROL MODULE REPROGRAMMING WITH SPS.

SPS PROGRAMMING WCC 18YY50861070.

FOLLOWED BULLETIN PROCEDURE.

\*\*\*\*\*

**AutoNation**

NOTICE OF WORKER'S LIEN PURSUANT TO TEXAS PROPERTY CODE s. 70.001

The undersigned, being the person who has paid for repairs to the vehicle described in this Repair Invoice, understands that if the Dealership relinquishes possession of the vehicle in return for payment via a check, money order or credit card transaction that is stopped or dishonored due to insufficient funds, no funds, or because the account does not exist or has been closed, the worker's lien continues to exist and the Dealership is entitled to possession of the vehicle in accordance with S. 9.609 of the Texas Business & Commerce Code until the amount due is paid.

Customer X \_\_\_\_\_ Date \_\_\_\_\_

**WARRANTY STATEMENT AND DISCLAIMER:** PLEASE SEE THE REVERSE SIDE OF THIS REPAIR INVOICE FOR THE DEALERSHIP'S LIMITED WARRANTY.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DATE \_\_\_\_\_ CUSTOMER SIGNATURE \_\_\_\_\_ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE \_\_\_\_\_

\*SHOP SUPPLY COSTS:

We have added a charge equal to 14.99% of the total cost of labor and parts, not to exceed \$59.99 to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	LABOR AMOUNT	TOTALS
	0.00	
	PARTS AMOUNT	
	0.00	
	GAS, OIL, LUBE	
	0.00	
	SUBLET AMOUNT	
	0.00	
	MISC. CHARGES	
	0.00	
TOTALS	TOTAL CHARGES	0.00
	LESS INSURANCE	
	0.00	
	SALES TAX	
TOTALS	PLEASE PAY THIS AMOUNT	0.00



\*INVOICE\*

494685

**AutoNation**

Tag #: **W465**

AutoNation Chevrolet West Austin

11400 Research Blvd.  
AUSTIN, TX 78759  
(512) 338-2420

Customer #: **6153921**

Service Advisor: **9715 PATRICK MOORE**

Cell:	Email:								
COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT			
RAPID BLUE	20	CHEVROLET CORVETTE	1G1Y82D48L5113568		1437	1437			
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
30OCT20 D			WAIT 08FEB22			CASH	07FEB22	07FEB22	07FEB22
OPTIONS: SOLD-STK:L5113568 ENG:6.2L 8 Cyl TRN:A									

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty. We also offer quality non-OE parts that fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP\*."

Non-GM parts and accessories are not covered under the GM New Vehicle Limited Warranty nor is any damage caused by the installation thereof. GM is not responsible for the consequences of installing any non-GM equipment, parts or accessories on the vehicle, including the possibility that part or all of the GM New Vehicle Limited Warranty may be voided. A list of non-GM parts is available to you upon request.

Dealer is not authorized to perform recall repairs for non-Dealer brand vehicles and Dealer's Vehicles Safety and Condition Inspection and/or service does not include a review of possible pending recalls or service campaigns issued by manufacturers of other makes and models.

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	Oil, Filter and Lube						
	Mail Oil, Filter and Lube						
	9809	WC					
	1 12706595	(S) FILTER					(N/C)
	10 19370233	OIL					(N/C)
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	(N/C)
*****							
B	VEHICLE SAFETY CONDITION INSPECTION INCLUDED						
	MULTI-I VEHICLE SAFETY CONDITION INSPECTION INCLUDED						
	9809	CC			0.00	0.00	
	GBATT BATTERY TESTS GOOD AT THIS TIME - NO ATTENTION NEEDED AT THIS TIME						
	9809	CC			0.00	0.00	
	GTIRE MPVI: TIRE TREAD GREEN (NOTATION ONLY - NO WORK NEEDED)						
	9809	CC			0.00	0.00	
	GBK MPVI: BRAKE LINING GREEN (NOTATION ONLY - NO WORK NEEDED)						
	9809	CC			0.00	0.00	
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	0.00
*****							
EST: 162.41 07FEB22 09:17 SA: 9715							
CONTACT: *****							

NOTICE OF WORKER'S LIEN PURSUANT TO TEXAS PROPERTY CODE S. 70.001

The undersigned, being the person who has paid for repairs to the vehicle described in this Repair Invoice, understands that if the Dealership relinquishes possession of the vehicle in return for payment via a check, money order or credit card transaction that is stopped or dishonored due to insufficient funds, no funds, or because the account does not exist or has been closed, the worker's lien continues to exist and the Dealership is entitled to possession of the vehicle in accordance with S. 9.609 of the Texas Business & Commerce Code until the amount due is paid.

Customer X \_\_\_\_\_ Date \_\_\_\_\_

**WARRANTY STATEMENT AND DISCLAIMER:** PLEASE SEE THE REVERSE SIDE OF THIS REPAIR INVOICE FOR THE DEALERSHIP'S LIMITED WARRANTY.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DATE \_\_\_\_\_ CUSTOMER SIGNATURE \_\_\_\_\_ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE \_\_\_\_\_

**\*SHOP SUPPLY COSTS:**  
We have added a charge equal to 14.99% of the total cost of labor and parts, not to exceed \$59.99 to the Repair Order for shop supplies used in connection with this repair.

**ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.**

LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00



## Multi-Point Inspection

Repair Order #		Customer Name				Advisor Name / #			
Mileage:	Vehicle:	Year:	Make:	Model:	Technician Name / #				
	N/A	Check O.K.	Needs Attention	Needs Immediate Attention		N/A	Check O.K.	Needs Attention	Needs Immediate Attention
Warning Lamps Operate & Remain Off	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Belts Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wipers Operation & Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Cooling Hoses Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Lights Operation & Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Fuel System Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Engine Oil Level & Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Engine Air Filter Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Engine Coolant Level & Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Cabin Air Filter Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Brake Fluid Level & Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Fluid Leaks Inspection	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Steering Fluid Level & Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Drive Axles/Boots Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Washer Fluid Level	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Steering & Suspension Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission Fluid Level & Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Exhaust System Inspection	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Battery Inspect, Test & Attach Printout	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Differential Fluid Level & Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Tire And Brake Inspection:**

**LF**

Brake Lining ☐ mm

Tire Tread ☐ 32nds

Wear Pattern ☐

Tire Pressure ☐ psi

**LF DOT** \_\_\_\_\_

**LR**

Brake Lining ☐ mm

Tire Tread ☐ 32nds

Wear Pattern ☐

Tire Pressure ☐ psi

**LR DOT** \_\_\_\_\_

**RF**

Brake Lining ☐ mm

Tire Tread ☐ 32nds

Wear Pattern ☐

Tire Pressure ☐ psi

**RF DOT** \_\_\_\_\_

**RR**

Brake Lining ☐ mm

Tire Tread ☐ 32nds

Wear Pattern ☐

Tire Pressure ☐ psi

**RR DOT** \_\_\_\_\_

DOT represents the date the tire was manufactured. 0216 = 2nd week in January 2016

DOT represents the date the tire was manufactured. 0216 = 2nd week in January 2016

Yes ☐ N/A ☐ Service Reminder Reset

**PRIME ITEM CONCERNS (Quote for Customer Requested Items)**

	Item and Description	Hrs.	Labor \$\$	Original Equip. Parts	Precision Part Options	Total \$\$	SOP	Authorized	
								Y	N
								Y	N
								Y	N
								Y	N
								Y	N
								Y	N
								Y	N
								Y	N
	TOTALS							Y	N

**May I review the results of the technicians multipoint inspection with you now?**

SAFE	RELIAB	MAINTEN	Item and Description	Hrs.	Labor \$\$	Original Equip. Parts	Precision Part Options	Total \$\$	SOP	Authorized	
										Y	N
										Y	N
										Y	N
										Y	N
										Y	N
										Y	N
										Y	N
										Y	N
										Y	N
			Would you like me to price these items for you?	TOTALS							
			Total of Prime and ASR								

**Method of Customer Approval:**

Time and Date of Approval:

Est. Tax & Misc.	
------------------	--

GRAND TOTAL:	
--------------	--

The Multi-Point Inspection ("MPI") is provided as a complimentary service to you and is limited in scope. There may be mechanical, equipment or system issues which were not detected by the MPI. A complete vehicle diagnostic/inspection is available for an additional charge.

**AutoNation.**