




R & C TOWING AND REPAIR CO.
105 LITWIN RD
WHEELERSVILLE, VA 24382
Phone: 276-228-7597 Fax: 276-228-7592

PAYMENT DUE UPON RECEIPT OF SERVICES
Invoice Amount: \$1,377.33
Authorization: _____
Reference: _____

Print Date: 09/20/2016
Previous Balance: \$1,377.33
Amount: \$1,377.33

Balance Due:

SALE AMOUNT

\$1418.65

CUSTOMER COPY

Firestone
AUTO CARE

Store# 909088
In: 02/18/22 09:35AM
Out: 02/19/22 05:45PM

Store# 909088

Gibson's Service Center
650 West Main St.
Abingdon, VA 24210
Phone: 276-525-4844 Fax: 276-525-4898
Honest Quality Professional

INVOICE
45832

Printed Date: 11/29/2022
1971 CADILLAC - EL DORADO -

Work Completed: 11/29/2022
Lic #: 89804

VIN #: 6936710410813
Odometer In: 88215
Odometer Out: 88215

GIBSON'S SERVICE CENTER
650 WEST MAIN ST
ABINGDON VA 24210
276-525-4844

INV # [REDACTED] 11:54
[REDACTED]
*****5417
BASE AMT: \$46.12

SUC Fee: USD \$1.51
TOTAL AMT: \$47.63
Resp: APPROVAL 020532
Code: 23331 020532
Ref #: 582333615324128
TransID: 582333615324128
App Name: VISA DEBIT
TID: A0000000031010
TST: 0000000000
ATC: 0000
IC: 6800
IAD: 7735AFACT7B44FF
06010005000000

Thank you!
CUSTOMER COPY

Ext	Labor Description	Ext
28.14	CUSTOMER REQUEST CHANGE OIL AND FILTER AND PERFORM A MULTI POINT INSPECTION	15.00
1.41	CHANGED OIL AND FILTER AND PERFORMED A MULTI POINT INSPECTION	
	OIL CHANGED ALL FLUIDS CHECKED, TIRES GAUGED, ALL ELSE LOOKS GOOD AT THIS TIME	
	CUSTOMER HAS HIS OWN FILTER	

Org. Estimate 0.00
Revisions 0.00
Current Estimate 0.00

Labor:	16.00
Parts:	28.55
SubTotal:	44.55
Tax:	1.57
Total:	46.12
Bal Due:	\$0.00

If you have any concerns, please inform William Gibson

Visit us on the web: www.gibsonautoservice.com
Service Advisor: PARKER, JAY Tech: GIBSON, JOSH OZ

Email Address: gibsonservice@gmail.com
Page 1 of 1

Exterior

☐ Head-

QTY

DESCRIPTION

PRICE

Mirror Glue 3 29
 Batt. cable 10 95
 75 BATTERY 77.95
 Batt. Kit 12.02
 MIRROR KIT

6
 6
 6

6
 6
 6
 6
 6
 6

paid
 Visa

DON'S GARAGE, INC.
 332 Front Street SW
 ABINGDON, VIRGINIA 24210
 (276) 628-6869

15130

DATE 8/2/04
 PROMISED

A.M.

P.M.

ODOMETER IN

ODOMETER OUT

DESCRIPTION OF WORK

AMOUNT

☐ LUBE ☐ CHANGE OIL ☐ OIL FILTER ☐ TUNE-UP ☐ TRANS. ☐ DIFF.

No Start
 Exhaust Manifold (leaking)
 Rear view mirror installed (Glove Box)
 air shocks need air
 tighten up BOTH Belts A/C And ALT
 Replace Rear view Mirror Replace 2.5 hrs
 Battery + Hold down Kit for Battery.
 Remove rear wheels Clean Rear Brakes
 + Sand ~~Brakes~~ Broken Replace Drums.

(MAY BE CONTINUED ON OTHER SIDE)

TOTAL PARTS

104.21

ACCESSORIES

LITERS/GALS. OF GAS @

TOTAL LABOR

100.00

LITERS/QTS. OF OIL @

TOTAL PARTS

104.21

kg/LBS. OF GREASE @

ACCESSORIES

GAS, OIL
AND GREASE

Exhaust Repair

SUBLET REPAIRS

97.50

EPA / WASTE DISPOSAL

TAX

4.69

TOTAL ACCESSORIES

SAVE OLD PARTS?

☐ YES ☐ NO

SIGNATURE

TOTAL
 THANK YOU

\$306.40

72 CAD.

DONS GARAGE INC
332 FRONT ST.
ABINGDON, VA 24210
276-628-6869
27020039831001

COPY
11/10/2004 19:00
Sale:
Transaction # 1
Card Type: VISA
Acc: *****6925
Entry: Swiped
Sale: 947.21
Reference No.: 0001
Auth. Code: 035371
Response: AP

THANK YOU
HAVE A GOOD DAY
ALL SALES ARE FINAL

pd. 11-10-04
VISA

DESCRIPTION	PRICE
LT	16 81
Wash Cover	29 49
RAD. CAP	7 82
Wash Cover	1 36
BL. PAINT	4 29
	2 29
STAT	7.95
WASHER	.78
R RAD. HOSE	28.99
ER " " "	23.71
Lamps	4 00
ET	119.77
manifold set	34.05
3 points	7.10
VAC. SPARK ADVANCE	16 40
oil	15 00
oil Filter	6 00
TOTAL PARTS	294 96
ACCESSORIES	
TOTAL ACCESSORIES	

DON'S GARAGE, INC.
332 Front Street SW
ABINGDON, VIRGINIA 24210
(276) 628-6869

15328

DATE
10-18-04
PROMISED
A.M.
P.M.
ODOMETER IN
73583
ODOMETER OUT

SERIAL NUMBER 6936710410813	MOTOR NUMBER 500	TERMS
DESCRIPTION OF WORK		AMOUNT
☐ LUBE ☐ CHANGE OIL ☐ OIL FILTER ☐ TUNE-UP ☐ TRANS. ☐ DIFF.		
ALT. light came on - Belt Brake Put TAG on FRT. - installed tag CK. Heater & Air Flow Rear Bot Bolt in Left Head Broke. Remove Intake + Left Head. Remove Bolt from Intake + Replace new Bolt. Replace Intake + Head + gasket sets. Replace thermostat, upper + lower Rad. Hoses. Replace Points, VAC. Advance. change oil + Filter. 14 hrs.		
_____ LITERS/GALS. OF GAS @		TOTAL LABOR 560 00
_____ LITERS/QTS. OF		TOTAL PARTS 294 96
_____ kg/LBS. OF GREASE		ACCESSORIES
MACHINE WORK ON HEAD		GAS, OIL AND GREASE
I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.		SUBLET REPAIRS 77 50
EPA / WASTE DISPOSAL		TAX 14 75
SAVE OLD PARTS? ☐ YES ☐ NO		TOTAL 947 21
SIGNATURE		THANK YOU



DON'S GARAGE, INC.
332 FRONT ST SW
ABINGDON, VA 24210
PHONE: (276) 628-6869

Merchant ID: 0788856

Sale

XXXXXXXXXXXX6925

VISA

Entry Method: Swiped

Total: \$ 226.74

03/31/06 10:34:01

Inv#: 000003 Appr Code: 035418

Apprvd: Online Batch#: 000037

Excellent Copy
THANK YOU!
PLEASE COPY AGAIN!

DESCRIPTION	PRICE
Shocks K.R	112.00
Spring K.R	87.70

DON'S GARAGE, INC.
332 Front Street SW.
ABINGDON, VIRGINIA 24210
(276) 628-6869

16742

	DATE 3-30-06
	PROMISED A.M. P.M.
	ODOMETER IN
	ODOMETER OUT

SERIAL NUMBER	MOTOR NUMBER 500	TERMS
---------------	---------------------	-------

DESCRIPTION OF WORK	AMOUNT
☐ LUBE ☐ CHANGE OIL ☐ OIL FILTER ☐ TUNE-UP ☐ TRANS. ☐ DIFF.	
installed new Air shocks and customer supplied springs. Filled shocks to 70 psi. Adjustment may be needed.	
Labor 2.0hr	

Paid VISA on
3-30-06 of 226.74

(MAY BE CONTINUED ON OTHER SIDE)

TOTAL PARTS	LITERS/GALS. OF GAS @	TOTAL LABOR	100.00
ACCESSORIES	LITERS/QTS. OF OIL @	TOTAL PARTS	120.70
	kg/LBS. OF GREASE @	ACCESSORIES	
		GAS, OIL AND GREASE	
		SUBLET REPAIRS	
		EPA / WASTE DISPOSAL	
		TAX	6.04
TOTAL ACCESSORIES	SAVE OLD PARTS? ☐ YES ☐ NO	TOTAL	226.74
	SIGNATURE	THANK YOU	

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

QTY.	PART NO. AND DESCRIPTION	PRICE	
8	SPARK PLUGS	20 00	
1	FUEL FILTER	3 51	
1	RTV	5 50	
5	DEXRON	12 50	
1	Fuel Line 1ft	3 00	
	1 bulb 1157		

PD. 8-23-05
MasterCard

DON'S GARAGE, INC.
332 Front Street SW
ABINGDON, VIRGINIA 24210
(276) 628-6869

1613

[REDACTED]		DATE	8-23-05
		PROMISED	
		A.M.	
		P.M.	
		ODOMETER IN	74,965
		ODOMETER OUT	
YEAR, MAKE AND MODEL		LICENSE NUMBER	89804
1971 Cadillac ELDORADO			
SERIAL NUMBER	MOTOR NUMBER	TERMS	
6936710410413	500 CU. IN.		

DESCRIPTION OF WORK		AMOUNT
☐ LUBE ☐ CHANGE OIL ☐ OIL FILTER ☐ TUNE-UP ☐ TRANS. ☐ DIFF.		
Transmission Service 1.4		
Tune-up, R/R Carb to replace filter 2.0		
tail light burned out .2		
head light adjustment .3		
fuel Lines Leaking AT GAS TANK 1.0		
Replace fuel Lines At tank		
TOTAL PARTS		44 51
ACCESSORIES		
LITERS/GALS. OF GAS @		
LITERS/QTS. OF OIL @		
kg/LBS. OF GREASE @		
TOTAL LABOR		225 40
TOTAL PARTS		44 51
ACCESSORIES		
GAS, OIL AND GREASE		
SUBLET REPAIRS		
EPA / WASTE DISPOSAL		
TAX		2 22
TOTAL ACCESSORIES		
TOTAL		272 13
THANK YOU		

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

SAVE OLD PARTS? ☐ YES ☐ NO

SIGNATURE