



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
5/10/2024	JF7322

Name / Address

Vehicle Info
1970 Pontiac Trans Am 228870N114833 White

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Repair Labor	Starter diagnostic. Checked timing. Timing is good. Looked for vacuum leaks, checked good. Need to drive on longer test drive to heat up starter. Then try to start it. Test drove the car to get hot and tested starter. Timing is set for the cam and should not be adjusted for the hot starting issue. The repair would be a high torque starter and heavier gauge starter wiring.	1.8	146.00	262.80
Repair Labor	STARTER AND WIRING REPLACEMENT Removed the old starter and installed the new starter. Repaired the rest of the wiring at the starter. Built new heavy duty positive and negative cables for the starter.	2.8	146.00	408.80
Parts	ATK High Torque Starter 369600	1	330.76	330.76T
Shipping	Shipping	1	11.99	11.99
Parts	2 gauge battey cable per foot	5	4.99	24.95T
Parts	Battery cable end	2	2.99	5.98T
Parts	Cable eyelets	2	1.99	3.98T
Repair Labor	ELECTRICAL AND LIGHTING DIAGNOSTIC Lighting Diagnostic. Found bad brake light switch. Ordered the part. Found bad headlight bulb. Ordered a pair of bulbs. Found fuse and ground issues. Ordered the proper fuses and developing a ground plan.	1	146.00	146.00
Subtotal				
Sales Tax (7.0%)				
Total				
Payments/Credits				
Balance Due				

JFrazzar
SPORTS CAR SERVICES
3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Name / Address
Jonathan Walters
515 E. Henry St.
Savannah, GA 31401



• 1200 Southeast Avenue • Tallmadge, OH 44278 • 330-630-0250
 • 950 East Glendale Avenue • Sparks, NV 89431 • 775-352-8787
 • 29 King Mill Road • McDonough, GA 30253 • 770-288-3200
 • 2200 E. Interstate 20 • Arlington, TX 76018 • 882-375-2700

Calling Customer Service?
 Please have your
 invoice number ready.

INVOICE

INVOICE NUMBER DATE
 4667054 10/22/21
 CUSTOMER NUMBER PAGE
 23653616 1

EXCHANGE/RETURN FORM

INVOICE NUMBER DATE
 4667054-7 10/22/21

NOTE: Please read the *How to Return an Order* instructions on the back of this form. Please indicate how you wish us to handle your return by checking either the exchange or refund column beside the part number on the list below. Include the reason code for the return. Please provide your daytime phone number in case we need additional information. Please be certain that you complete the additional exchange information form on the back of this sheet.

S
O
L
D
T
O

S
H
I
P
T
O

JONAT WALTERS
 515 E HENRY ST
 SAVANNAH GA 31401-6926
 (802) 522-7917
 MOBILE PH
 BRIANNA GA

Phone: ()

Reason Codes

M. No longer need the part
 D. The part is defective, or missing a piece
 Q. I am not happy with the quality of the product
 W. Part was not what I ordered
 I. I ordered the wrong part
 O. Other, please explain

Exchange	Refund	Qty	Reason Code	Explanation

** DECLARED VALUE 28.99

Qty.	Part Number	Part Description	Status*	Unit Price	Extended Amt.
1	OPG-DLK006	*COMP DOME LIGHT ASSEMBL		28.99	28.99 T
	****.COM CATALOG ****	****.COM CATALOG ****	****	.COM CATALOG ****	
				28.99 U.S.D.	2.88

** DECLARED PART VALUE THIS SHIPMENT **
 ** TOTAL INVOICE GEORGIA SALES TAX **

NOTE: If you wish to return an item, see instructions on the back of this form and complete the attached Exchange/Return Form.
 *Explanation of status column codes: B/O = backorder C/S = cancel ship S/S = shipped separate

Thank You!
 Delivery & Handling 11.99 T
 Credit Card Charge 43.85

Jonathan Walters
 515 E Henry St
 Savannah, GA 31401
 Order: 4667054

PRIORITY MAIL RETURNS® SERVICE

NO POSTAGE
 NECESSARY IF
 MAILED IN THE
 UNITED STATES

Summit Racing Equipment
 Attn: Returns Dept.
 2200 East Interstate 20
 Arlington, Tx. 76018-9804



9201 9902 3186 9000 3122 76

YOU CAN TRACK YOUR ORDERS FROM OUR WAREHOUSE TO YOUR DOOR:
 GO TO WWW.SUMMITRACING.COM AND CLICK THE ORDER STATUS LINK.

B66001022 CCU U0001486

Barry's Muffler & Brake Center



barrysmuffler.com

Barry's Muffler & Brake Center
 8506 Ferguson Ave
 Savannah, 31406
 United States

Phone: (912) 352-1052
 Fax: (912) 352-9224
 barrysmuffler.com

Invoice

BILL TO

Invoice Number: 10103
 P.O./S.O. Number: 70 TransAm
 Invoice Date: March 15, 2019
 Payment Due: March 15, 2019
 Amount Due (USD): \$1,428.16

Product	Quantity	Price	Amount
Pinion Seal	1	\$24.60	\$24.60
Gear Oil	1	\$22.00	\$22.00
Flowmaster FX	2	\$75.00	\$150.00
2.5" pipe	1	\$50.00	\$50.00
Xpipe	1	\$60.00	\$60.00
Evacuation System	1	\$117.85	\$117.85
Muffler	1	\$200.00	\$200.00
Labor	1	\$760.00	\$760.00
Labor			
Subtotal:			\$1,384.45
GA tax 7%:			\$43.71
Total:			\$1,428.16
Amount Due (USD):			\$1,428.16

pd
Cash

Tucker & Sons Service Center
 902 Montgomery St.
 Savannah, GA. 31401
 Phone: 912-236-2954 Fax: 912-236-4262

INVOICE
 18484

INVOICE

Vehicle Received: 04/14/2017 Invoice Date: 04/14/2017

1970 PONTIAC - TRANS AM - 400 CID V8
 Lic #: ENA 436 - VT Odometer In : 0

Cust ID : 4662

VIN #:

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
HEADER GASKET SET 1424	1.00	57.58	57.58	CHECK- RUNS ROUGH/ RICH ENGINE RUNS ON/DIESELS	190.00
HEADER COLLECTOR GASKET 301	1.00	7.98	7.98	ADJUST CARBURETOR RESET IGNITION TIMING ADJUST BASE IDLE	
Shop Supplies			3.28	REPAIR EXHAUST LEAK REPLACE HEADER GASKET Hazardous Materials	380.00 10.00

PAID 450.00 CASH
 253.66 CASH 2000
 (SP)

Org. Estimate 653.66 Revisions 0.00 Current Estimate 653.66

Labor:	570.00
Parts:	68.84
SubTotal:	638.84
HazMat:	10.00
Tax:	4.82
Total:	653.66
Bal Due:	\$653.66

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____ Time _____
 Written By: PRESCOTT, STEVE - Technicians : Please Select, Technician; TURNER



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
1/16/2025	JF8099

Name / Address

Vehicle Info
1970 Pontiac Trans Am 228870N114833 White

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Cust Issue	Mileage in 30670 1. Hood scoop door is creating constant draw 2. When starting, starter does not disengage 3. Engine will not start and run on its own either. PLEASE LOOK THIS WHOLE CAR OVER Client was here last time for same issue on starter and is acting like the Hood scoop is our fault. REPORT WHAT YOU NEED	1	0.00	0.00
Repair Labor	Joe Frazzar INITIAL DIAGNOSTIC Starter would not engage. Acted as if the solenoid is not actuating. Pushed the car into the shop. Found fuel residue around the carburetor. Checked a spark plug it was fuel fouled. Removed all of the spark plugs to allow the engine to dry. Pulled the dipstick to check oil level. Oil is gas fouled. Car requires new spark plugs and an oil change. Lifted the car to inspect the starter. Starter has failed, part ordered.	1	0.00	0.00

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
5/10/2024	JF7322

Name / Address

Vehicle Info
1970 Pontiac Trans Am 228870N114833 White

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
	Removed lower dash trim, steering column mounting bracket and steering column. Removed the instrument cluster bezel and cluster. Found Burn marks on printed circuit. Removed bulbs and tested. Replaced as needed. Replaced the printed circuit board. Repaired one bulb socket that is different from the rest of the sockets. Reinstalled the instrument cluster. Reinstalled the steering column and support bracket. Installed the new headlight bulbs. Repaired the problematic wiring in the trunk. Tested all lighting. Lighting functions as designed. Test drove and brought back. Allowed the car to sit and tested starter. Car cranked up normally every time. Replaced the battery.			
Parts	Printed circuit supplied by the client			
Parts	Dash light bulbs supplied by client	1	0.00	0.00T
Parts	AZ Silverstar Headlight bulb H6024ST list \$46.25	1	0.00	0.00T
Parts	AZ Stoplight Switch DR496 list \$28.68	2	30.99	61.98T
Parts	OR Fuse Assortment AGC1ZP	1	20.83	20.83T
Parts	OR Super Start Extreme Battery 24EXT list \$364.39	1	5.29	5.29T
		1	0.00	0.00T
	COMPLETE TICKET			
Subtotal				\$3,133.23
Sales Tax (7.0%)				\$36.57
Total				\$3,169.80
Payments/Credits				\$0.00
Balance Due				\$3,169.80



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
5/10/2024	JF7322

Name / Address

Vehicle Info
1970 Pontiac Trans Am
228870N114833
White

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Repair Labor	<p>WIRING REPAIRS</p> <p>Corrected power supply at the fuse box. There was a bad connection at the fuse box. Fixed this. Power is now at the switch but not transferring through the switch. Installed new brake light switch. Turn signal inspection. Both would react when turn signal was on. Found faulty wiring in the trunk. Turn signal would double blink if the running lights were on. Found LED tag lights, that to be taken out of the circuit. No change. Tested ground side. Weak ground at the tail lights. Found pulsating ground throughout the lighting system. Determined there isn't a chassis or body ground. Fabricated a chassis ground and a body ground. Double blink is gone. Dome light on when braking was corrected by the wiring repair at the fuse box. Had power at the dome light with new bulb but does not receive ground. Removed door ajar switch and applied ground to the circuit and the dome light worked. Cleaned switch and door jam and reinstalled the switch. Door functioned as designed. Rpeated the procedure on the passenger side switch. Dome illuminated when either the drivers or the passenger side door is opened.</p>	10.7	146.00	1,562.20

Subtotal
Sales Tax (7.0%)
Total
Payments/Credits
Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
5/10/2024	JF7322

Name / Address	Vehicle Info
	1970 Pontiac Trans Am 228870N114833 White

Item	Description	Qty	Rate	Total	P.O. No.	Tech	Tech 2
					BRIAN		
Cust Issue	Mileage in 30636 1. Get in trunk and replace lock cylinder 2. Slow to crank when hot 3. Check electrical issues. Hit brakes and the interior light comes on. Turn signal causes one of the gauges has a heart beat movement. Right headlight comes and goes. Dashlights don't work. Dome light does not come on when door is opened. 4. Tach registers twice as fast as it actually is fix this. 5. Hood release function. Hard at times. Need car back by the 8th	1	0.00	0.00			
Repair Labor	TRUNK LOCK REPAIR Drilled out trunk lot. Need to order different lock cylinder. Trimmed material from new lock assembly. Installed the lock assembly and tested function. Functions as designed.	1.5	146.00	219.00			
Parts	NPD Trunk lock with keys C-2187-3D with shipping	1	68.67	68.67			
					Subtotal		
					Sales Tax (7.0%)		
					Total		
					Payments/Credits		
					Balance Due		